



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALIZED COST OF REPAIRS



MSIG INSURANCE SINGAPORE P/L 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Fong Choon Hon James ADDRESS : 135 Sunset Way #03-11 Singapore 597158 TEL : 97584787	WIP : 56634 EXCESS : DATE: 18-Jan-18
VEH NO :	SKR5199C	DATE IN :	CONTACT PERSON : RONALD 6395 7875
CHASSIS NO :	JM6GJ1031F0147493	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA6 SDN 2.5L	DATE REG.: 12-Feb-15	POLICY NO. :

NATURE OF WORKS

<u>Parts Description</u>					
NO	QTY			REVISED	PRICES
1	RHS SIDE MIRROR ASSY	1	MG44P-69-121J	\$ 759.30	\$ 759.30
2	COVER(RHS), SIDE MIRROR	1	MGHP9-69-1N1A62		\$ 83.00
3	LAMP(RHS), SIDE TURN	1	MGHP9-69-122C		\$ 105.70
4	SEAL(RHS), SIDE MIRROR	1	MGHP9-69-115		\$ 12.60
5	GARNISH(RHS), SIDE MIRROR	1	MGJR9-69-15YB		\$ 110.70
6	GUARD(RHS), STONE	1	MGHP9-50-4P2A	\$ 16.50	\$ 16.50
7	GASKET(LHS), TAILLAMP	1	MGHK1-51-163	\$ 27.70	\$ 27.70
8	GASKET(RHS), TAILLAMP	1	MGHK1-51-153	\$ 27.70	\$ 27.70
			TOTAL PARTS	\$ 831.20	\$ 1,143.20
			LESS 10%	\$ 83.12	\$ 114.32
			TOTAL PARTS COST	\$ 748.08	\$ 1,028.88

Labour Description

1		TO REPLACE RHS SIDE MIRROR ASSY. TO REPAIR REAR BUMPER, RHS REAR FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 630.00	\$ 1,260.00
2		TO RESPRAY RHS SIDE MIRROR COVER, REAR BUMPER AND RHS REAR FENDER.	\$ 1,200.00	\$ 1,800.00
3	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
4	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
5	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
		TOTAL LABOUR	\$ 2,180.00	\$ 3,760.00
		TOTAL PARTS	\$ 748.08	\$ 1,028.88
		TOTAL	\$ 2,928.08	\$ 4,788.88
		LESS EXCESS	\$ -	\$ -
		TOTAL AFTER EXCESS	\$ 2,928.08	

GST 7%	\$ 204.97	\$ -
GRAND TOTAL	\$ 3,133.05	\$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)