

KIM KEAT MOTOR CO
 Blk 10 Ang Mo Kio Industrial Park 2A
 Avenue 5 #05-34 AMK Autopoint
 Singapore 568047
 Tel:64833167 Fax:64835764

*Not Authorised
 11/Jan 2017
 Resurvey After Repair*

17 Jan 2017

AIG Asia Pacific Insurance Pte Ltd
 Survey Dept.

Re: Quotation for damaged to FBA6446D.

Item	Description of Parts	Qty	Amount	
1.	Handle Bar	1pc	155.00	X
2.	Meter Assy	1pc	1280.00	✓
3.	Signal Lamp Assy Front R	1pc	80.00	✓
4.	Signal Lamp Assy Front L	1pc	80.00	✓
5.	Fork Protector L	1pc	35.00	✓
6.	Fork Tube L & R	2pcs	650.00	?
7.	Oil Seal Set L & R	2set	65.00	?
8.	Radiator Assy	1pc	880.00	?
9.	Footrest Bar Front L	1pc	85.00	✓
Total			\$ 3310.00	
Less 10%			- 331.00	
Sub-total			\$ 2979.00	
Nett Item				
10.	Handle Balancer	1pair	80.00	✓
11.	Levers	1pair	150.00	✓
12.	Number Plate Front	1pc	10.00	✓
13.	Engine Guard	1pair	150.00	✓
14.	Wrap	1roll	50.00	✓
15.	Muffler Assy	1pc	1380.00	✓
16.	Coolant	2bottle	50.00	?
17.	Fork Oil	1bottle	10.00	?
18.	Transport Fee		50.00	✓
19.	Labour		200.00	15cl
Grand Total			\$ 5109.00	

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: