



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLS 7450 X

Not Authorized
6/1/87

Parts	(a) Cost / List Price Items	\$	3,313.54
	Plus/Less 25%	\$	828.39
	Total of Cost / List	\$	2,485.16
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	45.00
Total Parts Cost		\$	2,530.16
Labour		\$	1,020.00
Total		\$	3,550.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 19/1/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Lc Date: 19/1/18



ESTEEM PERFORMANCE PTE LTD


Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :	SLS 7450 X	Submit By :	Carmen Lim
Make & Model :	TOYOTA PRIUS	Year Manufacture :	2017
Chassis No. :	JTEGD56M007149909	Engine No. :	
		Cost / List	

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper <i>Am</i>	1	\$596.10		✓
2	Front bumper clip <i>Am</i>	10	\$40.00		✓
3	Front bumper reinforcement <i>R</i>	1	\$455.95		X
4	Front bumper side retainer LH <i>Sm</i>	1	\$81.90		X
5	Front bumper side retainer RH <i>Did</i>	1	\$81.90		✓
6	Front bumper bracket LH <i>R</i>	1	\$278.90		X
7	Front bumper bracket RH <i>R</i>	1	\$278.90		X
8	Front bumper sponge	1	\$89.80		?
9	Front bumper sensor	1	\$411.79		?
10	Front bumper lamp RH <i>Sm</i>	1	\$998.30		X
11	Front number plate <i>Ry</i>	1	\$45.00	S.N	✓
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Vehicle No. : SLS 7450 X Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.