



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 23.01.2018

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2180J TOYOTA VELLFIRE (2017)

To Supply

- | | | | | |
|---------|---------------------------------|----|----------|------|
| 1) 1pc | Rear bumper | \$ | 1,780.57 | DE ✓ |
| 2) 1pc | Rear bumper right side retainer | \$ | 92.40 | me ✓ |

Sub total parts	\$	1,872.97
Less: 25% discount	\$	(468.24)
	\$	1,404.73

L/charges

- | | | |
|--|----|-----------------------|
| 1) To remove and replace rear bumper. | \$ | 250.00 200 |
| 2) To putty, respray painting rear bumper in pearl white. | \$ | 300.00 250 |

Sub total L/charges	\$	550.00
Estimated Total	\$	1,954.73

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Up 90000068
2 days
P/P
24/01/18 @ 1050
Resury by part