



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr LEE KWAY LIANG  BLK 248 BISHAN ST 22 #20-362 SINGAPORE 570248  Contact No Mobile: 96273528	Cust No/Name	/Mr LEE KWAY LIANG
	Reg No/Reg Date	SKR574K / 14/01/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AFH001227
	Engine No	3A92UBX9462
	Make/Model	MIT/ATTRAGE 1.2 CVT MIVEC
	Colour/Trim	A06 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	19/01/2018/ 13:27		465 / Tay Jian Ye	20040			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 TO RENEW REAR BUMPER , BOOTLID, WELD AND CUT END PANEL , FLOOR PANEL REPAIR REAR BOTH FENDER								3300.00
E PNT88000 TO TRANSFER REAR BOOTLID MECHASIM AND TRIM TO NEW PART								200.00
E PNT88000 TO REMOVE AND REFIT REAR PARKING SENSOR								50.00
E PNT88000 TO REMOVE AND REFIT REAR BOOT TRIMS TO FACILIATE REPAIR								200.00
E PNT98000 PAINT WORK SPRAY REAR BUMPER, BOOTLID, END PANEL, FLOOR PANEL, REAR BOTH FENDER								2940.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								200.00
M SUNDRY TO APPLY ANTI COROSSION ON AFFECTED PORTION								120.00
M SUNDRY TO APPLY BODY SEALANT ON AFFECTED PORTION								200.00
M SUNDRY TO SUPPLY C&C LOGO								50.00
M SUNDRY TO SUPPLY REVERSE SENEOR								220.00
M SUNDRY SUNDRIES								50.00
M	BRACKET,RR BUMPER,LH				1.00	27.00	00.00	27.00
M	BRACKET,RR BUMPER,RH				1.00	27.00	00.00	27.00
M	FACE,RR BUMPER				1.00	740.00	00.00	740.00
M	CLIP,FR BUMPER				10.00	3.00	00.00	30.00
M	HINGE,TRUNK LID,LH				1.00	201.00	00.00	201.00
M	HINGE,TRUNK LID,RH				1.00	201.00	00.00	201.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.