

ASS. REC. BY:

REF: CS/MSG18001260/T1qd3

Special Instruction:

SUNVEY

Meinmen

Taufik

ASSIGNMENT (Office)

From (Person):

Jocelyn Ng

of

MSIG

Date/Time:

22/01/2018 @ 10:53am

Estimated Cost:

Bill to:

①

TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKH 61122

Insured:

at Workshop m/s

Performance

Tel:

9116 5199

of

303 Alexandra Road

Policy No:

82886178 4SMF

Claim No:

546753

Sum Insured:

Excess:

\$700.00

Make of Veh:

(Client's Record)

D.O.A. 11/12/2017

23/01/2018 @ 10-10-30am owner waiting

CA / REV

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:15am @ 22/01/18

Person Contacted:

Meinmen

Vehicle IN ①

Date/Time	Action/Instruction (✓) Estimate
	SKH 61122-X
24/1/18 @ 3.42pm	revert to Jocelyn Ng via Meinmen.
24/1/18 @ 5.07pm	Kenny Ong informed C/A via Meinmen.
24/1/18 @ 5.11pm	informed Meinmen C/A to ex: \$700 by cash.
26/1/18 @ 5.37pm	2nd revert to Jocelyn Ng via Meinmen. (supplementary)
28/1/18 @ 7.17pm	Kenny Ong informed C/A at \$11254.10 via Meinmen.

Tajfik

REF: MS16

ASSIGNMENT

From: _____ Date: **23/01/2018**

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SKH 61122**

at Workshop/s: **Performance**

of: **303 Alexandra Rd**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: **\$700.00**

(Client's Record): **Merina**

Make of Veh: **10-10:30am Owner waiting**

(Policy Condition):

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
-----	-----

Ball or Marker Value: **945K**

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **7** days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Van No: **SKH 61122** Reg: **2012 DEC**

Type: ☒ M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **BMW 520i** cc: **1997.**

Colour: **Blue** A.O. Insured / Std / NI / NA

So. Reading: **75097.** T-Radio Insured / Std / NI / NA

Eng No: _____

C.No: **WBAXG12070DX52345**

Gen. Cond: **3** Good / Fair / Poor / Burnt

Steering: **3** In order / Jammed / Leaked / Burnt or

Brake: **3** In order / Jammed / Leaked / Burnt or

Mod: **3** Nil / SRM / STD Air / Rim or

Tyre Size: **225/55R17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Continental**

Front: **6** mm Rear: **6** mm

R.Bal: **6** mm L.Bal: **6** mm

D.O.A. **PM L** D.O. **23/1/18 @ 10:50**

Survey held at: **PM L**

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

29/6/18 @ 11:01am confirmed with Caroline final Rg \$11224.10, 7 days by email.

(Red \$ 8904.20, 44%)


29/6/2018

RECEIVED 29 JUN 2018

Date/Time File Pass of: **24/6/18** ☐ Prel. Report ☐ Final Report

Date/Time File Return of: _____

Days Of Repair: **7**

Resurvey No. of Trip: **1**

Survey Fee: _____

Report Format: **WER-TP**

Lump Sum / T.B. / **11224.10**

Add Fee: ☐ Site Insp ☐ Interview ☐ Tech. Insp ☐ Test & Insp





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18001260/T1qd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 22-01-2018	
			Code : MSG	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SKH 6112Z	
Policy No.	S28861784SMF	Coverage (\$)	0.00	
Claim No.	546753	Excess (\$)	700.00	
Assign From	MERIMEN (JOCELYN NG)	Assign Date	22/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/12/2017	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Dec 2017		22 Jan 2018 10:53 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	BANDU JAYANATH WEWALAARACHCHI, ID: S2668891D, Tel: +6597535149, Email: BANDUW@GMAIL.COM		
Vehicle Reg. No.:	SKH6112Z	Date of Loss:	11/12/2017 20:00 - :59
Claim Type:	OD / 546753	Policy/Cover Note No.:	S28861784SMF (Comprehensive) Coverage: 28/12/2016 - 27/12/2017
		Excess:	S\$700.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/01/2018]		
Driver/Custodian:	BANDU JAYANATH WEWALAARACHCHI (52 / Male), NRIC: S2668891D, Tel: +6597535149		
Adj Asg. Remarks:	Please revert, thank you. Owner waiting 10am tmr		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 29 June 2018 11:01 AM
To: PBSP; SUR; Taufikh (LKKAUTO)
Subject: RE: 3RD Reminder: FINAL REPORT / SKH6112Z

Dear Caroline,

WITHOUT PREJUDICE

Confirm final fig \$11,224.10 before excess \$700.00 & GST and 7 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Thursday, 28 June 2018 3:56 PM
To: SUR <sur@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: 3RD Reminder: FINAL REPORT / SKH6112Z

3RD Reminder

From: PBSP
Sent: Wednesday, 18 April 2018 3:14 PM
To: taufikh@lkkauto.com; SUR
Subject: FINAL REPORT / SKH6112Z

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 6,468.00

Total Parts : 4,756.10

Total Labour & Parts : 11,224.10

Repair days: 7

Thank you.

Regards,
Caroline

C/o Performance Motors Limited - Body and Paint


Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	19 Jan 2018 16:21	Clim Veh Model Changed	(204864) BMW 520I 2.0 D/AB 2WD 4DR GAS/D NAV (A).	[I] Jocelyn Ng Shin Bun
2	19 Jan 2018 16:21	Clim Created	Reg No: SKH6112Z, Policy No: S28861784SMF, Acct Date: 2017/12/11, Claim Type: OD, Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Performance Motors Limited (Alexandra), Ins.Status => Incoming Claim. Created from SAS:MP ML17163347	[I] Jocelyn Ng Shin Bun
3	22 Jan 2018 09:25	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):a if c	[I] Jocelyn Ng Shin Bun
4	22 Jan 2018 09:25	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/01/23	[I] Jocelyn Ng Shin Bun
5	22 Jan 2018 09:25	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Jocelyn Ng Shin Bun
6	22 Jan 2018 10:24	Assignment 1st Accessed		[A] Ho Pei Fang
7	22 Jan 2018 10:51	Adj Assignment Cancelled	Survey - Owner waiting 10am tmr (ET-East, AL-Unable to survey PML, DC-Morning station in office)	[I] Jocelyn Ng Shin Bun
8	22 Jan 2018 10:51	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Jocelyn Ng Shin Bun
9	22 Jan 2018 10:53	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert, thank you. Owner waiting 10am tmr	[I] Jocelyn Ng Shin Bun
10	22 Jan 2018 10:53	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/01/23	[I] Jocelyn Ng Shin Bun
11	22 Jan 2018 10:53	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Jocelyn Ng Shin Bun
12	22 Jan 2018 11:08	Assignment 1st Accessed		[A] Nivitha Govindasamy
13	22 Jan 2018 15:18	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
14	24 Jan 2018 15:37	Adj Rpt Initiated		[A] SHIAU CHAN
15	24 Jan 2018 15:40	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/21	[A] SHIAU CHAN
16	24 Jan 2018 15:40	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/21	[A] SHIAU CHAN
17	24 Jan 2018 15:42	Adj Mandate Request	Cur.Req:15818.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	24 Jan 2018 17:02	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/21. Mandate Remarks: A IF C	[I] Keny Ong Thiam Beng
19	24 Jan 2018 17:02	Adj Mandate Set	Approved:10547.85:A IF C	[I] Keny Ong Thiam Beng
20	26 Jun 2018 17:37	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/21	[A] SHIAU CHAN
21	26 Jun 2018 17:37	Adj Mandate Request	Cur.Req:11224.10:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY AP PROVE ON CHECK ITEMS & SUPPLEMENTARY.	[A] SHIAU CHAN
22	28 Jun 2018 14:17	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/21. Mandate Remarks: A IF C	[I] Keny Ong Thiam Beng
23	28 Jun 2018 14:17	Adj Mandate Set	Approved:11224.10:A IF C	[I] Keny Ong Thiam Beng

Date From



Date To



Audit Type

None

Go

ACTIVITY

[22/01/2018 10:25] Ho Pei Fang:
Merina confirmed survey appt tmr @ 10am, owner waiting.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1704494	24/01/2018 15:37	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKH6112Z		10.70
1711819	19/01/2018 16:24	Motor	MSIG Insurance (Singapore) Pte. Ltd.	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	SKH6112Z	546753	xx.xx

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 26 Jun 2018

Preliminary Advice

Vehicle No	: SKH6112Z	Accident Date	: 11/12/2017
Make	: BMW 520I	Policy No.	: S28861784SMF
Assignment Date	: 22/01/2018	Excess	: S\$700.00
Date of Inspection	: 23/01/2018	Est. Duration of Repair	: 7.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,128.30	(ESTIMATE \$19,384.40 + SUPPLEMENTARY \$743.90)
Revised Amount	:S\$	11,224.10	(INCLUSIVE OF CHECK ITEMS & SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	11,224.10	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	95,000.00
COE / PARF Rebate	:S\$	73,433.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,567.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON CHECK ITEMS & SUPPLEMENTARY.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 24 January 2018 5:11 PM
To: Merina Chia San San
Cc: SUR
Subject: VEHICLE SKH 6112Z (DOA: 11/12/2017)

Dear Merina,

As instructed by our client, please proceed to repair the insured vehicle **SKH 6112Z (Excess \$700/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	19 Jan 2018 16:21	Cim Veh Model Changed	(204864) BMW 520I 2.0 D/AB 2WD 4DR GAS/D NAV (A).	[I] Jocelyn Ng Shin Bun
2	19 Jan 2018 16:21	Cim Created	Reg No: SKH6112Z. Policy No: S28861784SMF. Acct Date: 2017/12/11. Claim Type: OD. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Performance Motors Limited (Alexandra). Ins.Status => Incoming Claim. Created from SAS:MPML17163347	[I] Jocelyn Ng Shin Bun
3	22 Jan 2018 09:25	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):a if c	[I] Jocelyn Ng Shin Bun
4	22 Jan 2018 09:25	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/01/23	[I] Jocelyn Ng Shin Bun
5	22 Jan 2018 09:25	Adj Mandate Set	Approved:25000.00,Reinsp:Adj decides.	[I] Jocelyn Ng Shin Bun
6	22 Jan 2018 10:24	Assignment 1st Accessed		[A] Ho Pei Fang
7	22 Jan 2018 10:51	Adj Assignment Cancelled	Survey - Owner waiting 10am tmr (ET-East, AL-Unable to survey PML, DC-Morning station in office)	[I] Jocelyn Ng Shin Bun
8	22 Jan 2018 10:51	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Jocelyn Ng Shin Bun
9	22 Jan 2018 10:53	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert, thank you. Owner waiting 10 am tmr	[I] Jocelyn Ng Shin Bun
10	22 Jan 2018 10:53	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/01/23	[I] Jocelyn Ng Shin Bun
11	22 Jan 2018 10:53	Adj Mandate Set	Approved:25000.00,Reinsp:Adj decides.	[I] Jocelyn Ng Shin Bun
12	22 Jan 2018 11:08	Assignment 1st Accessed		[A] Nivitha Govindasamy
13	22 Jan 2018 15:18	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
14	24 Jan 2018 15:37	Adj Rpt Initiated		[A] SHIAU CHAN
15	24 Jan 2018 15:40	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/21	[A] SHIAU CHAN
16	24 Jan 2018 15:40	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/21	[A] SHIAU CHAN
17	24 Jan 2018 15:42	Adj Mandate Request	Cur.Req:15818.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	24 Jan 2018 17:02	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/21. Mandate Remarks: A IF C	[I] Keny Ong Thiam Beng
19	24 Jan 2018 17:02	Adj Mandate Set	Approved:10547.85:A IF C	[I] Keny Ong Thiam Beng

ACTIVITY

[22/01/2018 10:25] Ho Pei Fang:
Merina confirmed survey appt tmr @ 10am, owner waiting.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1704494	24/01/2018 15:37	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKH6112Z		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 24 Jan 2018

Preliminary Advice

Vehicle No	: SKH6112Z	Accident Date	: 11/12/2017
Make	: BMW 520I	Policy No.	: S28861784SMF
Assignment Date	: 22/01/2018	Excess	: S\$700.00
Date of Inspection	: 23/01/2018	Est. Duration of Repair	: 7.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,384.00
Revised Amount	:S\$	10,547.85
Check Items (Estimated)	:S\$	5,270.15
Total	:S\$	15,818.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	95,000.00
COE / PARF Rebate	:S\$	73,433.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,567.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.
WE HAVE NOT AUTHORISE REPAIR.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8891D
Vehicle Details	
Vehicle No.:	SKH6112Z
Vehicle to be Exported:	No
Intended De-registration Date:	24 Jan 2018
Vehicle Make:	B.M.W.
Vehicle Model:	520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	B1300376N20B20B
Chassis No.:	WBAXG12070DX52345
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$41,446.00
Original Registration Date:	28 Dec 2012
First Registration Date:	28 Dec 2012
Transfer Count:	0
Actual ARF Paid:	\$41,446.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2022
PARF Rebate Amount:	\$29,012.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$97,000.00
COE Rebate Amount:	\$44,421.00
Total Rebate Amount:	\$73,433.00

The information contained herein is correct as at 24 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GfA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	12/12/2017 13:37
Date Of Accident	11/12/2017 20:45
Exact Location Of Accident	AYE ENTRY (CITY) OPP NUH
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKH6112Z
Insured/Policyholder	
Name Of Registered Owner	BANDU JAYANATH WEWALAARACHCHI
NRIC No	S2668891D
Email Address	BANDUW@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97535149
Alternative Phone No	OFFICE-67787995
Vehicle Particulars	
Manufacturer	BMW
Model	520
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	S28861784SMP
Cover Note Number	
Driver	
Name of Driver	BANDU JAYANATH WEWALAARACHCHI
NRIC No	S2668891D
Date Of Birth	12/07/1965
Occupation	INDOOR
Date Of Driving Pass	23/05/1996
Driving Experience	21 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97535149
Fax Number	
Contact Number	OFFICE-67787995
Email Address	BANDUW@GMAIL.COM

Address	234A SERANGOON AVENUE 2#11-141
Postcode	551234
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM8025L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	
Name of Driver	LOGENDRAN VIJAYAKUMAR
NRIC/Passport Number	S8532144G
Contact Number	91440830
Address	BLK 499C TAMPINES AVE 9 #07-278
Postcode	523499
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	3

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan 12 DEC 2017

12 DEC 2017



A: SKH 61127

B: Ym 8025L

Describe Circumstances of the Accident

I was returning home from work. As I approached AYE entry (to city direction), I stopped for vehicles approaching from the right.

A few seconds later, a Lorry knocked my car from behind and my car was thrown a few feet to the front.

Declaration

We declare the foregoing particulars are true in every respect.


 Policyholder's Signature / Date &
 Time 12 DEC 2017

Driver's Signature (If driver is not the policyholder) / Date
 & Time



Witnessed by Reporting Centre
 Personnel 12 DEC 2017

Sonly
331 10am

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 1974015894 GST Reg. No M2-0020081-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63390100 (Sales & Admin)
63390111 (AfterSales)
Fax: 64747772

280, Tampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63198888 (AfterSales)
Fax: 63443772

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/510 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

20 JAN 2013

GST REG. NO : M2 - 0020081 - X

ESTIMATE

1.3 DEC 2017

Estimate No. : b1 45139
Date Estimated : 13/12/2017
Prepared By : Merina Chia San San

Page No. : 1 of 3

- ESTIMATE REPAIR FOR -
Bandu Jayanath Wewalaarachchi
234A Serangoon Avenue 2
#11-141

Singapore 551234

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKH6112Z	DX52345	28/12/2012	520iA	0

DESCRIPTION

VALUE

To replace rear bumper, tail end panel, bootlid including attachments etc and to knock out dented area caused by accident

2550 5,100.00

To paint rear bumper, tail end panel and bootlid

2537 2,819.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 271.00

To reconnect electrical components and wirings at the rear section including conduct checks for proper function.

300 354.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To remove and install wire harness, control units and battery at the rear section to facilitate panel replacement.

451? 531.00

To replace bootlid smart opener control unit, top and bottom sensor lines including program and conduct checks for proper function.

561? 661.00

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

451? 531.00

To carry out body cavity preservation.
(For cut panel).

100 451 531.00

Sundries.

150.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401519N GST Reg. No M2-0020081-X



305, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747773

292, Kampong Arang Road
East Coast Centre
Singapore 438190
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/338 (Motorrad)
Fax. 64794601 (AfterSales)
64795824 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45139
Date Estimated : 13/12/2017
Prepared By : Merina Chia San San

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKH6112Z	DX52345	28/12/2012	520iA	0

Total Labour 1: 11,302.00

DESCRIPTION	QTY	PRIC	VALUE
EXHAUST TRIM CHROME	2	114.45	228.90
TAIL END PANEL	1	817.30	817.30
LH BOOTLID HINGE	1	110.85	110.85
RH BOOTLID HINGE	1	110.85	110.85
BOOTLID	1	1,563.30	1,563.30
Set of mount	1	62.60	62.60
RR BUMPER GUIDE BOTTOM CENTRE	1	57.50	57.50
RR BUMPER CTR GUIDE	1	65.75	65.75
RR BUMPER LH MOUNT	1	141.65	141.65
RR BUMPER RH MOUNT	1	141.65	141.65
RR BUMPER CARRIER	1	696.80	696.80
RR BUMPER PANEL PRIMED (PDC)	1	1,431.40	1,431.40
RR BUMPER TOW HOOK COVER PRIMED	1	23.25	23.25
RR BUMPER ADAPTER	1	46.80	46.80
EMBLEM GROMMET	2	0.80	1.60
MODEL LETTERING 520i	1	61.05	61.05
BMW EMBLEM	1	67.80	67.80
STRIKER BOOT LID	1	52.25	52.25
TRUNK LID LOCK TOP	1	425.35	425.35
TRUNK LID POWER LOCK DRIVE	1	572.30	572.30
HEAT INSULATOR BUMPER REAR LH	1	31.30	31.30
HEAT INSULATOR BUMPER REAR RH	1	31.30	31.30
LH GUTTER STRIP	1	16.40	16.40
RH GUTTER STRIP	1	16.40	16.40
BOOTLID SEALING	1	112.45	112.45
SENSOR WIRE FOR SMART OPENER TOP	1	42.10	42.10
SENSOR WIRE FOR SMART OPENER BOTTOM	1	40.50	40.50
DECOUPLING RING PDC TORQUE CONVERTE	4	4.95	19.80
BUMPER PDC SENSOR (A76 TIEFSEEBLAU)	2	363.05	726.10
BLIND RIVET AVIBVLB	40	0.55	22.00
SCREW (SF PLUS M5X15)	2	0.55	1.10
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	281.55
PUNCH RIVET N4	8	0.55	4.40
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(S/L) SEAM SEAL 300ML	1	33.80	33.80

Total Parts : 8,082.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401599M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747777

280, Kembangan Road
East Coast Centre
Singapore 438190
Tel. 63190888 (AfterSales)
Fax. 63447777

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/338 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45139
Date Estimated : 13/12/2017
Prepared By : Merina Chia San San

Page No. : 3 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKH6112Z	DX52345	28/12/2012	520iA	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Client: ☒ Third Party / Uninsured Motorist / Other Settlement

Regn No. 23/1/18 @ 1050 Claim No. 700

Date & Time 23/1/18 @ 1050 Excess SG 700

Surveyor's Name Tan Jiah Regt 1050

Surveyor's Tel 97495849 Authorized Yes / No C

Authorized Date Revert Time 0 / 12 P.M. Yes / No

RE-SURVEY PARTS PHOTO - SUPPORT 0 / 12 P.M. Yes / No

Surveyor's E-mail tanjiah@lkkauto.com

Est. of Working Days 6-7 days

Signature
25/1/18

Labour 1	:	11,302.00
Parts	:	8,082.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,356.88
Grand Total	:	20,740.88

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

2017.0.30

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45139
Date Estimated : 13/12/2017
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
Bandu Jayanath Wewalaarachchi
234A Serangoon Avenue 2
#11-141

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 551234

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKH6112Z	DX52345	28/12/2012	520iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# PLUG BLACK D=5MM *	0.90	7.00		6.30 <i>rw</i>
# BUMPER PDC SENSOR A83 GLACIERSILBER *	368.80	2.00		737.60 <i>rw</i>

Total Labour :
Total Parts : 743.90
Total Labour & Parts : 743.90



FINAL REPORT

Estimate No. : b1 45139
 Date Estimated : 13/12/2017
 Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
 Bandu Jayanath Wewalaarachchi
 234A Serangoon Avenue 2
 #11-141

- ACCOUNT - 66
 MSIG Insurance (S) Pte Ltd
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

Singapore 551234

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKH6112Z	DX52345	28/12/2012	520iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, boot lid include making good the tail end panel and knocking out dents caused by the accident	2550.00		2,550.00	
To spray paint rear bumper, tail end panel and boot lid	2537.00		2,537.00	
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00	
To reconnect electrical components and wirings at the rear section include conducting checks for proper function	300.00		300.00	
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00	
* To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00	
* To carry out body cavity preservation. (Per panel)	100.00		100.00	
Sundries.	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,563.30	1.00		1,563.30
RR BUMPER GUIDE BOTTOM CENTRE	57.50	1.00		57.50
RR BUMPER CTR GUIDE	65.75	1.00		65.75
RR BUMPER CARRIER	696.80	1.00		696.80
RR BUMPER PANEL PRIMED (PDC)	1,431.40	1.00		1,431.40
RR BUMPER ADAPTER	46.80	1.00		46.80
EMBLEM GROMMET	0.80	2.00		1.60
MODEL LETTERING 520i	61.05	1.00		61.05
BMW EMBLEM	67.80	1.00		67.80
# PLUG BLACK D=5MM *	0.90	7.00		6.30
DECOUPLING RING PDC TORQUE CONVERTE	5.05	4.00		20.20
# BUMPER PDC SENSOR A83 GLACIERSILBER *	368.80	2.00		737.60

SUPPLEMENTARY ITEMS

Total Labour :	6,468.00
Total Parts :	4,756.10
Total Labour & Parts :	11,224.10
Deduction for Excess :	700.00
Total Repair Costs less Excess:	10,524.10
GST @7%:	736.69
Grand Total :	11,260.79

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Dec 2017		22 Jan 2018 10:53 Edit Adj Rpt	S\$11,224.10 Edit Estimates	S\$11,224.10 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	BANDU JAYANATH WEWALAARACHCHI, ID: S2668891D, Tel: +6597535149, Email: BANDUW@GMAIL.COM								
Vehicle Reg. No.:	SKH6112Z	Date of Loss:	11/12/2017 20:00 - :59 [59 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 546753	Policy/Cover Note No.:	S28861784SMF (Comprehensive) Coverage: 28/12/2016 - 27/12/2017						
		Excess:	S\$700.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 21/02/2018]								
Driver/Custodian:	BANDU JAYANATH WEWALAARACHCHI (52 / Male), NRIC: S2668891D, Tel: +6597535149								
Adj Asg. Remarks:	Please revert, thank you. Owner waiting 10am tmr								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (28/06/2018): Alert - Adj Mandate Approved (S\$11224.10) - SKH6112Z - Claim Handler: Jocelyn Ng... - MSIG_SG (24/01/2018): Alert - Adj Mandate Approved (S\$10547.85) - SKH6112Z - Claim Handler: Jocelyn Ng...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKH6112Z (546753)
OD
Dec 11 2017 8:00PM
[BANDU JAYANATH WEWALAARACHCHI]
Performance Motors Limited

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	12/12/17 15:11	Accident Statement		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/01/18 15:40	Adjuster Immediate Advice		Load HTM	
2	26/06/18 17:37	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/01/18 15:41	Odometer Reading		Load JPG	
2	24/01/18 15:41	Chassis Number		Load JPG	
3	24/01/18 15:41	General View		Load JPG	
4	24/01/18 15:41	General View		Load JPG	
5	24/01/18 15:41	General View		Load JPG	
6	24/01/18 15:41	General View		Load JPG	
7	24/01/18 15:41	General View		Load JPG	
8	24/01/18 15:41	General View		Load JPG	
9	24/01/18 15:41	General View		Load JPG	
10	24/01/18 15:41	General View		Load JPG	
11	24/01/18 15:41	General View		Load JPG	
12	24/01/18 15:41	General View		Load JPG	
13	24/01/18 15:41	General View		Load JPG	
14	24/01/18 15:41	General View		Load JPG	
15	24/01/18 15:41	General View		Load JPG	
16	24/01/18 15:41	General View		Load JPG	
17	24/01/18 15:41	General View		Load JPG	
18	24/01/18 15:41	General View		Load JPG	
19	24/01/18 15:41	General View		Load JPG	
20	24/01/18 15:41	General View		Load JPG	
21	24/01/18 15:41	General View		Load JPG	
22	24/01/18 15:41	General View		Load JPG	
23	24/01/18 15:41	General View		Load JPG	
24	24/01/18 15:41	General View		Load JPG	
25	24/01/18 15:41	General View		Load JPG	
26	24/01/18 15:41	General View		Load JPG	
27	24/01/18 15:41	General View		Load JPG	
28	24/01/18 15:41	General View		Load JPG	
29	24/01/18 15:41	General View		Load JPG	
30	24/01/18 15:41	General View		Load JPG	
31	24/01/18 15:41	General View		Load JPG	
32	24/01/18 15:41	General View		Load JPG	
33	24/01/18 15:41	General View		Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
				☒
34	24/01/18 15:41	General View	 Load JPG	☒
35	24/01/18 15:41	General View	 Load JPG	☒
36	24/01/18 15:41	General View	 Load JPG	☒
37	24/01/18 15:41	General View	 Load JPG	☒
38	24/01/18 15:41	General View	 Load JPG	☒
39	24/01/18 15:41	General View	 Load JPG	☒
40	24/01/18 15:41	General View	 Load JPG	☒
41	24/01/18 15:41	General View	 Load JPG	☒
42	28/06/18 09:45	Reinspection Photo	 Load JPG	☒
43	28/06/18 09:45	Reinspection Photo	 Load JPG	☒
44	28/06/18 09:45	Reinspection Photo	 Load JPG	☒
45	28/06/18 09:45	Reinspection Photo	 Load JPG	☒
46	28/06/18 09:45	Reinspection Photo	 Load JPG	☒
47	28/06/18 09:45	Reinspection Photo	 Load JPG	☒
48	28/06/18 09:45	Reinspection Photo	 Load JPG	☒
49	28/06/18 09:45	Reinspection Photo	 Load JPG	☒
50	28/06/18 09:45	Reinspection Photo	 Load JPG	☒
51	28/06/18 09:45	Reinspection Photo	 Load JPG	☒
52	28/06/18 09:45	Reinspection Photo	 Load JPG	☒
53	28/06/18 09:45	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/01/18 16:29	PARF COE	 Load PDF	
2	19/01/18 16:29	Enquire Transfer Fee Details	 Load PDF	
3	22/01/18 09:22	Estimate Repair Cost + GIA Report+ CI + DL + IC	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/01/18 15:41	ESTIMATE	 Load PDF	
2	26/06/18 17:31	REVISED ESTIMATE	 Load PDF	
3	26/06/18 17:31	SUPPLEMENTARY LIST	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	12/12/17 15:11	Accident Statement	 Load HTM	
2	19/01/18 18:24	Addendum Sheet	 Load TIF	
3	19/01/18 18:26	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	12/12/17 13:48	Accident Photo	 Load JPG	☒
2	12/12/17 13:48	Accident Photo	 Load JPG	☒
3	12/12/17 13:48	Accident Photo	 Load JPG	☒
4	12/12/17 13:48	Accident Photo	 Load JPG	☒
5	12/12/17 13:48	Accident Photo	 Load JPG	☒
6	12/12/17 13:48	Accident Photo	 Load JPG	☒
7	12/12/17 13:48	Accident Photo	 Load JPG	☒
8	12/12/17 13:48	Accident Photo	 Load JPG	☒
9	12/12/17 13:48	Accident Photo	 Load JPG	☒
10	12/12/17 13:48	Accident Photo	 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
				☒
11	12/12/17 13:48	Accident Photo	 Load JPG	☒
12	12/12/17 13:48	Accident Photo	 Load JPG	☒
13	12/12/17 13:48	Accident Photo	 Load JPG	☒
14	12/12/17 13:48	Accident Photo	 Load JPG	☒
15	12/12/17 13:48	Accident Photo	 Load JPG	☒
16	12/12/17 13:48	Accident Photo	 Load JPG	☒
17	12/12/17 13:48	Accident Photo	 Load JPG	☒
18	12/12/17 13:48	Accident Photo	 Load JPG	☒
19	12/12/17 13:48	Accident Photo	 Load JPG	☒
20	12/12/17 13:48	Accident Photo	 Load JPG	☒
21	12/12/17 13:48	Accident Photo	 Load JPG	☒
22	12/12/17 13:48	Accident Photo	 Load JPG	☒
23	12/12/17 13:48	Accident Photo	 Load JPG	☒
24	12/12/17 13:48	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	12/12/17 13:46	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18001260/QD3Q2

Date: 02/07/2018

REFERENCE

Insured/Claimant: BANDU JAYANATH WEWALAARACHCHI

Policy No: S28861784SMF

Date of Loss: 11/12/2017

Nature of Claim: OD

Claim No: 546753

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKH6112Z

Make & Model: BMW 520I, 2.0 D/AB 2WD 4DR GAS/D NAV (A)

Engine No: B1300376N20B20B

Reg. Date: 28/12/2012 (Man. Year: 2012)

Chassis No: WBAXG12070DX52345

Colour: Blue

Odometer: 75097 km

Engine Capacity: 1997 cc

Market Value/New Car Price: S\$95,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,976.30	4,906.10	4,070.20	45.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,152.00	6,318.00	4,834.00	43.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,128.30	11,224.10	8,904.20	44.24
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	19,428.30	10,524.10	8,904.20	45.83
+ GST 7.00/7.00% (S\$)	1,359.98	736.69	623.29	45.83
Nett Amount (S\$)	20,788.28	11,260.79	9,527.49	45.83

INSPECTION

Date of Assignment: 22/01/2018

Date Inspected: 23/01/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jul 2018)
Parts:	143	BMW 520i 2.0 D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKH6112Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	2		*EXHAUST TRIM CHROME	Not Necessary	228.90 FS	*- FS
3	1		*TAIL END PANEL	Not Necessary	817.30 FS	*- FS
4	1		*LH BOOTLID HINGE	Repair	110.85 FS	*- FS
5	1		*RH BOOTLID HINGE	Repair	110.85 FS	*- FS
6	1		*BOOTLID	Bent	1,563.30 FS	*1,563.30 FS
7	1		*SET OF MOUNT	Not Necessary	62.60 FS	*- FS
8	1		*RR BUMPER GUIDE BOTTOM CENTRE	Deformed	57.50 FS	*57.50 FS
9	1		*RR BUMPER CTR GUIDE	Deformed	65.75 FS	*65.75 FS
10	1		*RR BUMPER LH MOUNT	Not Necessary	141.65 FS	*- FS
11	1		*RR BUMPER RH MOUNT	Not Necessary	141.65 FS	*- FS
12	1		*RR BUMPER CARRIER	Bent	696.80 FS	*696.80 FS
13	1		*RR BUMPER PANEL PRIMED (PDC)	Deformed	1,431.40 FS	*1,431.40 FS
14	1		*RR BUMPER TOW HOOK COVER PRIMED	Not Necessary	23.25 FS	*- FS
15	1		*RR BUMPER ADAPTER	Deformed	46.80 FS	*46.80 FS
16	2		*EMBLEM GROMMET	Necessary	1.60 FS	*1.60 FS
17	1		*MDEL LETTERING 520i	Necessary	61.05 FS	*61.05 FS
18	1		*BMW EMBLEM	Necessary	67.80 FS	*67.80 FS
19	1		*STRIKER BOOT LID	Not Necessary	52.25 FS	*- FS
20	1		*TRUNK LID LOCK TOP	Not Necessary	425.35 FS	*- FS
21	1		*TRUNK LID POWER LOCK DRIVE	Not Necessary	572.30 FS	*- FS
22	1		*HEAT INSULATOR BUMPER REAR LH	Not Necessary	31.30 FS	*- FS
23	1		*HEAT INSULATOR BUMPER REAR RH	Not Necessary	31.30 FS	*- FS
24	1		*LH GUTTER STRIP	Not Necessary	16.40 FS	*- FS
25	1		*RH GUTTER STRIP	Not Necessary	16.40 FS	*- FS
26	1		*BOOTLID SEALING	Not Necessary	112.45 FS	*- FS
27	1		*SENSOR WIRE FOR SMART OPENER TOP	Not Necessary	42.10 FS	*- FS
28	1		*SENSOR WIRE FOR SMART OPENER BOTTOM	Not Necessary	40.50 FS	*- FS
29	4		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	20.20 FS	*20.20 FS
30	2		*BUMPER PDC SENSOR (A76 TIEFSEEBLAU)	Not Necessary	726.10 FS	*- FS
31	1		*BLIND RIVET AVIBVLB (40 PCS)	Not Necessary	22.00 FS	*- FS
32	2		*SCREW (SF PLUS M5X15)	Not Necessary	1.10 FS	*- FS
33	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Not Necessary	281.55 FS	*- FS
34	8		*PUNCH RIVET N4	Not Necessary	4.40 FS	*- FS
35	1		*(DG) CLEANER R1 (100ML)	Not Necessary	23.85 FS	*- FS
36	1		*(S/L) SEAM SEAL 300ML	Not Necessary	33.80 FS	*- FS
37	7		*PLUG BLACK D=5MM	Necessary	6.30 FS	*6.30 FS
38	2		*BUMPER PDC SENSOR A83 GLACIERSILBER	Not Working	737.60 FS	*737.60 FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	8,976.30	4,906.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER ,TAIL END PANEL ,BOOTLID INCLUDING ATTACMNENTS ETC AND TO KNOCK OUT DENTED AREA CAUSED BY ACCIDENT	New	5,100.00	2,550.00
2	TO PAINT REAR BUMPER ,TAIL END PANEL AND BOOTLID	New	2,819.00	2,537.00
3	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
4	TO RECONNECT ELECTRICAL COMPONENTS AND WIRINGS AT THE REAR SECTION INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	354.00	300.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	0.00
6	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
7	TO REMOVE AND INSTALL WIRE HARNESS ,CONTROL UNITS AND BATTERY AT THE REAR SECTION TO FACILITATE PANEL REPLACEMENT	New	531.00	0.00
8	TO REPLACE BOOTLID SMART OPENER CONTROL UNIT ,TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION	New	661.00	0.00
9	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
10	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	100.00
Gross Labour Cost (\$\$)			11,152.00	6,318.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >