

AXA - PIP

Jumani

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper X repair			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips X			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover X			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor X			\$ 135.70
	Rear Bumper Rubber Mat X			\$ 50.00
				\$ 185.70
	Labour Charge			
	Panel Beating			\$ 380.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 50.00
	R/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 750.00
	ESTIMATE TOTAL			\$ 2,461.58
	Kalin LKKK M 19/1/18 1525 hrs. 2 Days. P/P After Repair photo			
	LKK Auto Consultants hence notify the Repairer of the following:			
	• To resurvey before/after spray painting			
	• To display damaged part(s) during resurvey			
	• Parts prices are subject to confirmation			
	• Third party survey is on a "Without Prejudice" basis			
	• No illegal modification(s) is allowed			
	• Supplementary items; must be resurveyed and is subject to final approval from Insurance Company			
	Acknowledged by Repairer			
	Signature:			
	Date:			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.