

ASS. REC. BY:

REF: CS/FCI18001264/R1rd3n2 Special Instructions

Surveyor

Rasul

ASSIGNMENT (Office)

AWS

From (Person): Screne Ler

of

FCI

Date/Time

19/01/18 @ 6.39pm

Estimated Cost

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 2127E

Insured:

SHA 4049J

at Workshop m/s

CYS Automobile

Tel:

6219 2098

of 38, Woodlands Ind. Park East 1# 07-17

Policy No:

Claim No:

D18000559MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 17/01/2018

CA / REV / REP. / REV 24 HRS 'w/p'

H.O.D. Endorsement:

Date/Time:

9.16am @ 22/01/18

Person Contacted:

Wei Sin

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate	
	GBE 2127E-NA/HP16018628/Y	D.O.A: 01/10/2016
	SHA 4049J-CS/FCI17021832/Arbe2	D.O.A: 08/11/2017
	Sent preli through email	
	Confirm \$3394.84, 4 days (Red: \$828.87, 19%).	16/04/18

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GBE 2127E
 at Workshop n/s CYS
 of 38, unmarked Ind Pk East #2017
 Insured: FCI / TP
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS b/d

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBE 2127E Yr Regn: 2015 SEP
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: NISSAN NV 350 2.5 C.C. 2488
 Colour: GREY A/C: Insured / Std / NI / NA
 Sp. Reading: 868 15 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JN1MC2E 262000 3922
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: NR / S/Rim / STD A/Rim or
 Tyre Size: F: 195R15C
 R: 1
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 17/01/18 D.O.I. 22/01/18
 Survey held at: CYS
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S FR
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 16 APR 2018

Date/Time File Pass to?

1) typist

Date/Time File Return to?

2) _____

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - PS - SI

Photos:

Others:

TOTAL

135
50
50
59
294

Report Format :

Lump Sum / I.B.I. (\$) TP
3394.84

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Weekend (\$)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18000559MFSH

Our Ref: CS/FCI18001264/R1rd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBE 2127E .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22/01/2018 at the premises of M/s CYS AUTOMOBILE SERVICE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,223.71</u> .
Revised Estimate Amount	: S\$ <u>2,919.10</u> .
"Check" Items Amount	: S\$ <u>475.74</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at n/s front portion.



Yours faithfully
RASUL
Automotive Assessor

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	18-01-2018	Our Ref No. D18000559MFSH
Accident Date	17-01-2018	Claim Type. Third Party
Insured Vehicle	SHA4049J	Third Party Vehicle. GBE2127E
Survey Location	38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK	
Contact Person.	MS TEE WEE SIN	
Contact No.	62192098/ 0	Fax No. 62192096
Survey Type	DIRECT SETTLEMENT: EST PROVIDED - \$4,223.71	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYS AUTOMOBILE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/233999)



PRI Documents



Close



PRI Header Details

Claim No	D18000559MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CYS AUTC
Workshop Name	CYS AUTOMOBILE SERVICES PTE LTD (Contact Person : MS TEE WEE SIN)	Survey Location & Contact Details	38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADM Mobile: 0 , Phone: 62192098 , Fax: 62192096 EmailId: CYSAUTO@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT: EST PROVIDED - \$4,223.71		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA4049J	TP Vehicle No	GBE2127E
PRI Recieved Date	19-01-2018 03:23:42 PM	Surveyor Appointed Date	19-01-2018 06:40:17 PM	Surveyor Accept Date	22-01-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	22-01-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No : A05041/2001E

GST Reg. NO: 20-0105041-E

MR SOL MART PTE LTD
74 SUNGEI KADUT LOOP
SINGAPORE 729513

POLICY NO : THIRD PARTY CLAIMS
YOUR REF : SHA 4049 J (FIRST CAPITAL)
OUR REF : TP 5859
VEHICLE NO : GBE 2127 E
MAKE/MODEL : NISSAN NV350
DATE OF ACCIDENT : 17.01.18

SURVEY BY

DATE : 19.01.18

- 1 PC FRONT CORNER PANEL LH
- 1 PC FRONT GRILLE
- 1 PC FRONT GRILLE EMBLEM
- 1 PC HEADLAMP ASSY LH
- 1 PC FRONT BUMPER
- 1 PC FRONT BUMPER FOG LAMP GARNISH LH
- 1 PC FRONT BUMPER SIDE RETAINER LH
- 1 PC FRONT BUMPER REINFORCEMENT
- 1 PC FRONT BUMPER TOWING COVER
- 1 PC FRONT BUMPER STEP GARNISH LH

477.74 X NETT
455.00 ? CRA
73.60 ? CRA
403.00 CRA
514.70 ?
107.80 CRA
147.00 ?
630.00 ?
21.00 X
72.50 CRA

S\$ 2,902.34

LESS 10%

290.23

S\$ 2,612.11

- 1 SET FRONT DOOR STICKER
- 1 PC FRONT BUMPER FOG LAMP LH

S\$ 30 60.00 S/NETT

321.60 CRA

S\$ 381.60

TO CHECK WIRING FUNCTION

S\$ 30.00

LABOUR CHARGES

600.00 400

TO PUTTY AND SPRAY PAINTING CHARGES

600.00 300 450

S\$ 4,223.71

SIN DOLLARS: FOUR THOUSAND TWO HUNDRED TWENTY-THREE AND CENTS SEVENTY-ONE ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Rasa
Hp 90010068
4 days
23/1/18 P/P
22/01/18 P1225
Resurvey by paint



進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR SOL MART PTE LTD
74 SUNGEI KADUT LOOP
SINGAPORE 729513

POLICY NO : THIRD PARTY CLAIMS
YOUR REF : SHA 4049 J (FIRST CAPITAL)
OUR REF : TP 5859
VEHICLE NO : GBE 2127 E
MAKE/MODEL : NISSAN NV350
DATE OF ACCIDENT : 17.01.18

SURVEY BY

DATE : 19.01.18

- 1 PC FRONT CORNER PANEL LH
- 1 PC FRONT GRILLE
- 1 PC FRONT GRILLE EMBLEM
- 1 PC HEADLAMP ASSY LH
- 1 PC FRONT BUMPER
- 1 PC FRONT BUMPER FOG LAMP GARNISH LH
- 1 PC FRONT BUMPER SIDE RETAINER LH
- 1 PC FRONT BUMPER REINFORCEMENT
- 1 PC FRONT BUMPER TOWING COVER
- 1 PC FRONT BUMPER STEP GARNISH LH

2403.60

2163.74

LESS 10%

327.60

- 1 SET FRONT DOOR STICKER
- 1 PC FRONT BUMPER FOG LAMP LH

TO CHECK WIRING FUNCTION

LABOUR CHARGES

TO PUTTY AND SPRAY PAINTING CHARGES

880.00

p/p - \$3394.84

477.74 X NETT
455.00 ?
73.60 ?
403.00 CRA
514.70 ?
107.80 CRA
147.00 ?
630.00 ?
24.00 X
72.50 CRA

S\$ 2,902.34

290.23

S\$ 2,612.11

S\$ 30 88.00 S/NETT

321.60 CRA

S\$ 381.60

S\$ 30.00

600.00 400

600.00 300 450

S\$ 4,223.71

SIN DOLLARS: FOUR THOUSAND TWO HUNDRED TWENTY-THREE AND CENTS SEVENTY-ONE ONLY

YOUR FAITHFULLY

CYS AUTOMOBILE SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasa
Hp 90010068

4 days

p/p

22/01/18 P125

Resurvey by paint



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18001264/R1rd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4049J	Veh. Inspected	GBE 2127E	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18000559MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	19/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350 2.5	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JN1MC2E26Z0003922	Colour	GREY	
Odometer	86815	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	MICHELIN	6 mm	
L/H Front Tyre	195 R15C	MICHELIN	6 mm	
R/H Rear Tyre	195 R15C	MICHELIN	6 mm	
L/H Rear Tyre	195 R15C	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/01/2018	Inspection Date	22/01/2018	
Survey held at	CYS AUTOMOBILE SERVICES PTE LTD 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 2127E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT CORNER PANEL LH (N)	NOT NECESSARY	477.74	-
1	FRONT GRILLE (N)	CRACKED	455.00	455.00
1	FRONT GRILLE EMBLEM (N)	NECESSARY	73.60	73.60
1	HEADLAMP ASSY LH (N)	CRACKED	403.00	403.00
1	FRONT BUMPER (N)	TORN	514.70	514.70
1	FRONT BUMPER FOG LAMP GARNISH LH (N)	CRACKED	107.80	107.80
1	FRONT BUMPER SIDE RETAINER LH (N)	CUT	147.00	147.00
1	FRONT BUMPER REINFORCEMENT (N)	BENT	630.00	630.00
1	FRONT BUMPER TOWING COVER (N)	SERVICEABLE	21.00	-
1	FRONT BUMPER STEP GARNISH LH (N)	CRACKED	72.50	72.50
	LESS 10% DISCOUNT		-290.23	-240.36
			2,612.11	2,163.24
SPECIAL NETT ITEMS				
1	SET FRONT DOOR STICKER (SN)	NECESSARY	60.00	30.00
1	FRONT BUMPER FOG LAMP LH (SN)	CRACKED	321.60	321.60
			381.60	351.60
LABOUR				
	TO CHECK WIRING FUNCTION.		30.00	30.00
	LABOUR CHARGES.		600.00	400.00
	TO PUTTY AND SPRAY PAINTING CHARGES.		600.00	450.00
			1,230.00	880.00
GRAND TOTAL			4,223.71	3,394.84
RECOMMENDED COST OF REPAIRS				3,394.84

Report Ref No. CS/FCI18001264/R1rd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.