

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: CHINA TAIPING INSURANCE	DATE	: 18/01/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLN9932K	Asher.	
MODEL	: TOYOTA VIOS E AUTO		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>			
DATE		: 17-Jan-18	
TIME		: 19:30HRS	
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Buckled.</i>	1	\$ 645.00	\$ 645.00
2	BOOT LID LOGO <i>Ken</i>	1	\$ 69.00	\$ 69.00
3	BOOT LID TOP LOCK <i>Pang d</i>	1	\$ 135.00	\$ 135.00
4	BOOT LID LOWER LOCK <i>Ken</i>	1	\$ 89.00	\$ 89.00
5	BOOT LID WEATHER STRIP <i>lit</i>	1	\$ 213.00	\$ 213.00
6	BOOT LID HINGE <i>Ken</i>	2	\$ 113.00	\$ 226.00
7	REAR BUMPER <i>Deland</i>	1	\$ 536.00	\$ 536.00
8	REAR BUMPER BRACKET <i>LH Bend</i>	2	\$ 63.00	\$ 126.00
9	REAR BUMPER REFLECTOR <i>Ken</i>	2	\$ 110.00	\$ 220.00
10	REAR BUMPER SIDE RETAINER(FRONT) <i>Ken</i>	2	\$ 115.00	\$ 230.00
11	REAR BUMPER SIDE RETAINER(REAR)	2	\$ 65.00	\$ 130.00
12	REAR NUMBER PLATE GARNISH <i>Ken</i>	1	\$ 165.00	\$ 165.00
13	REAR NUMBER PLATE GARNISH LAMP(SET) <i>Ken</i>	1	\$ 103.00	\$ 103.00
14	TAIL LAMP <i>Coked</i>	2	\$ 380.00	\$ 760.00
15	TAIL LAMP PANEL <i>Pegis</i>	2	\$ 168.00	\$ 336.00
16	REAR FENDER INNER TRIM <i>Ken</i>	2	\$ 332.00	\$ 664.00
17	REAR END PANEL <i>Deland</i>	1	\$ 712.00	\$ 712.00
18	REAR END PANEL TOP GARNISH <i>Deland</i>	1	\$ 135.00	\$ 135.00

585

459.80

574.80

569.50

19	REAR FLOOR PANEL <i>Rejis</i>	1	\$ 722.30	\$ 722.30	<i>+</i>
20	REAR FLOOR PANEL TOP BOARD <i>torn</i>	1	\$ 362.70	\$ <u>362.70</u>	<i>156.50</i>
21	REAR FLOOR PANEL SIDE TOP BOARD <i>new</i>	2	\$ 133.00	\$ 266.00	<i>+</i>
22	SPARE TYRE BOLT <i>new</i>	1	\$ 78.30	\$ 78.30	<i>+</i>
23	SPARE TYRE TOOL SPONGE <i>new</i>	1	\$ 195.00	\$ 195.00	<i>+</i>
24	REAR EXHAUST PIPE <i>?</i>	1	\$ 680.00	\$ 680.00	<i>+</i>
25	REAR EXHAUST MOUNTING <i>new</i>	4	\$ 56.00	\$ 224.00	<i>+</i>
26	REAR EXHAUST INSULATOR	1	\$ 89.50	\$ 89.50	<i>+</i>

3330.60
2497.85

TOTAL PRICE \$ 8,111.80

LESS 25% \$ 2,027.95

SUB TOTAL PRICE \$ 6,083.85

	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
2	BOOT LID SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
3	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00	<i>✓</i>
4	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00	<i>+</i>
5	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 180.00	\$ 180.00	<i>60.</i>
6	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 180.00	\$ 180.00	<i>+</i>
7	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00	<i>✓</i>
8	REVERSE SENSOR <i>Rejis</i>	1	\$ 220.00	\$ 220.00	<i>200.</i>

300

TOTAL \$ 640.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, WELD, CUT, KNOCK, GRAZE, ADJUST, REPLACE NEW PARTS	\$ 1,400.00	<i>800</i>	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX ADJACENT PANELS	\$ 1,200.00	<i>700.</i>	
3	TO SPRAY TUFF COAT AND RUST PROOF ADJACENT PANELS	\$ 250.00	<i>60.</i>	
4	WIRING/ BULB CHECKING	\$ 120.00	<i>30</i>	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	<i>50.</i>	
6	REMOVE AND REFIX REAR EXHAUST	\$ 350.00	<i>X</i>	
7	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	<i>X</i>	

8	TRANSFER BOOT LID MECHANISM	\$	150.00	60.	
TOTAL		\$	3,710.00	1700	

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,723.85
TOTAL LABOUR COST : \$ 3,710.00
TOTAL REPAIR COST : \$ 10,433.85

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAY :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :

SURVEYED BY :

CONTACT NUMBER :

FAX NUMBER :

Adrian Lj
h/s 19/01/18
06 Days.

Total: 4497.95

h/s: 3.6K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: