

INS. CASE OWNER:

CC 3 TP 1800

LKK:

IDAC:

Surveyor:

Fulwin

DOI:

ASSIGNMENT

18/1/18

Date / Time:

18/1/18

Registered in Merimen:

27/1/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SHC 855P

Claim No. : _____

Name of Insured : _____

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II : \$\$ D.O.A : 18/1/18

Place of Accident : _____

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : _____

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : _____

(V/L- YES / NO)

Insured Liability : % Final ? Yes / No

SHC 68794

INSRS:
WSP:
Tel :
Liability :
RMKS:

Premier

INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time		STAGE	DATE / PIC
	SHC 68794 - 2	Non-Reporting ltr (1st):	
	SHC 855P - inspection report / Karpal Ann. 18/1/18	Non-Reporting ltr (2nd):	
	insured under FU # 11 cancelled	Non-Reporting ltr (Final):	
	INDEPENDENT REPORT	Notification ltr (if non-pickup):	
		Call OE	
		After call ltr to OE:	
		Documentation Check List: Handler Typist	
	100	Notification ltr (if non-pickup)	
	50	After call ltr to OE:	
	50	Authorisation To Act:	
	20	Release Voucher:	
	80	Final Repair Bill:	
	300	Car Rental Invoice:	
		Towing Invoice	
		LTA / GIA :	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

RECEIVED 9 MAR 2018

10% d3c
5/3/18

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	TP	\$S 830.00	(2 days) Reduction: %
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed)	BOLA S/N No.:
Repair Cost:	\$S -		
Loss of Rental (LOR):	\$S -	(days)	
Loss of Use (LOU):	\$S -	(\$ x days)	
Loss of Income (LOI):	\$S -	(\$ x days)	
LOR only ☐	LOU only ☐	LOR + LOU ☐	LOR + LOI ☐ (Tick only one)
GIA/LTA Search:	\$S -		
Medical:	\$S -		
Disbursement:	\$S -	(e.g. Tow/ Independent)	
Legal Cost:	\$S -		
Total:	\$S -	Global Sum \$S:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	\$S -	Name 1:	-
Payee 2: (Strike if N.A.)	\$S -	Name 2:	-
Payee 3: (Strike if N.A.)	\$S -	Name 3:	-

COPY SENT 18/1/18

 1) Claim status: Normal/Reject/Private Settle
 2) Report Format:
 3) Survey fee: \$ 240.00

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

19-Jan-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6879 G

1 pc	Rear bumper <i>X Rep</i>	\$ 696.00
1 pc	Rear bumper lower cover <i>X su</i>	\$ 206.00
		\$ 902.00
	Less 10%	\$ 90.20
		\$ 811.80

S/NETT

1 set	Rear bumper clips <i>22</i>	\$ 48.00 <i>X</i>
1 pc	Rear bumper top protector <i>rec</i>	\$ 80.00 <i>50</i>
	Sundry	\$ 50.00 <i>X 20</i>
	To dismantle / replace/test reverse sensor to new bumper and reset to the same	\$ 120.00 <i>X 20</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 <i>X 20</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same	\$ 450.00 <i>100</i>
	To putty and spray painting on rear bumper, bootlid, bootlid lower garnish, rear o/s fender	\$ 200.00 <i>180</i>
		\$ 1,939.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kohli 16/1/18

19/1/18 1630hr

2 Reps.

PIP

After Repair photo

24/1/18
initial PIP \$ 330 / 2 Reps

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after body painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal action/claim is allowed
- Supplemental vehicle must be resurveyed and in writing to final approval from Insurance Company

Accepted by Repairer

Signature:

Date:

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

19-Jan-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6879 G

1 pc	Rear bumper <i>X</i>	\$	696.00
1 pc	Rear bumper lower cover <i>X</i>	\$	206.00
		\$	902.00
	Less 10%	\$	90.20
		\$	811.80

S/NETT

1 set	Rear bumper clips	\$	48.00 <i>X</i>
1 pc	Rear bumper top protector	\$	80.00 <i>50</i>
	Sundry	\$	50.00 <i>X</i>
	To dismantle / replace/test reverse sensor to new bumper and reset to the same	\$	120.00 <i>X</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 <i>X</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same	\$	450.00 <i>100</i>
	To putty and spray painting on rear bumper, bootlid, bootlid lower garnish, rear o/s fender	\$	200.00 <i>180</i>
		\$	1,939.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin 1/11/18
19/1/18 1630hr
2 Pairs
PIP
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	29 May 2015 / 09:12:38	Receipt No.:	AACCK001-AX239-150529-000003
Asset Type:	Vehicle	Transaction Amount:	\$65,428.00
Asset ID:	SHC6879G	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150529091238534459		
Vehicle No.:	SHC6879G		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	29 May 2015		
Original Registration Date:	29 May 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5593617		
Engine No.:	D4FDEH313348		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2014		
Open Market Value:	\$21,451.00		
Minimum PARF Benefit:	\$8,719.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	29 May 2015 09:12:38		
COE No.:	2015052901002468E		
COE Expiry Date:	28 May 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$50,756.00		
Lifespan Expiry Date:	28 May 2023		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
PREMIER AUTOMOTIVE SERVICES PTE LTD		Ref : CC3/TP18001278/K1hb3q2		
23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		Date : 12-03-2018		
		Code : TP451		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SHC 6879G	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	19/01/2018	
2. Vehicle Particulars & Condition				
	Make & Model	KIA OPTIMA	c.c	1685
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	KNAGM414MF5593617	Colour	SILVER
	Odometer	272214	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/65 R16	MAXXIS	7 mm
	L/H Front Tyre	205/65 R16	MAXXIS	7 mm
	R/H Rear Tyre	205/65 R16	MAXXIS	7 mm
	L/H Rear Tyre	205/65 R16	MAXXIS	7 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	18/01/2018	Inspection Date	19/01/2018
	Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
		ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6879G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	696.00	-
1	REAR BUMPER LOWER COVER	SERVICEABLE	206.00	-
	LESS 10% DISCOUNT		-90.20	-
			811.80	-
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			178.00	50.00
	<u>LABOUR</u>			
	TO DISMANTLE /REPLACE/TEST REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.	NOT NECESSARY	120.00	-
	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK - OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SAME.INCLUSIVE OF THE REPAIR OF REAR BUMPER .		450.00	100.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER,BOOTLID ,BOOTLID LOWER GARNISH ,REAR O/S FENDER .		200.00	180.00
			950.00	280.00
	GRAND TOTAL		1,939.80	330.00
	RECOMMENDED COST OF REPAIRS			330.00

Report Ref No. CC3/TP18001278/K1hb3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.