

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

19-Jan-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6879 G

1 pc	Rear bumper <i>X Repair</i>	\$ 696.00
1 pc	Rear bumper lower cover <i>X</i>	\$ 206.00
		<hr/>
		\$ 902.00
	Less 10%	\$ 90.20
		<hr/>
		\$ 811.80

S/NETT

1 set	Rear bumper clips	\$ 48.00 <i>X</i>
1 pc	Rear bumper top protector	\$ 80.00 <i>50</i>
	Sundry	\$ 50.00 <i>X</i>
	To dismantle / replace/test reverse sensor to new bumper and reset to the same	\$ 120.00 <i>X</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 <i>X</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same	\$ 450.00 <i>100</i>
	To putty and spray painting on rear bumper, bootlid, bootlid lower garnish, rear o/s fender	\$ 200.00 <i>180</i>
		<hr/>
		\$ 1,939.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin 16/1/18
19/1/18 1630hrs
2 Days.
PIP
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: