

INS. CASE OWNER:

CC3 / QBE1 8001279, Plea 3n2

LKK:

IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

( YES / NO )

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time: 25/1/18

Confirm with: GARY

Confirm by: AWK

Repair Cost:

HS S\$ 3,000

(

4

days)

Reduction:

49

%

Email

Call

FINAL SETTLEMENT

Date/Time: 28/2/18

Confirm with: GARY

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost:

0/18

S\$ 3,240.00

OID CHANGED LONE H1 TP.

Loss of Rental (LOR):

S\$ 421.70

(

5

days)

x 284.34

Loss of Use (LOU):

S\$ -

(\$

x

days)

Loss of Income (LOI):

S\$ 200.00

(\$ 40

x

5

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 3,823.70

Global Sum S\$:

FINAL PAYMENT

Date/Time: 28/2/18

Confirm with: GARY

Email

Call

Payee 1:

S\$ 3,823.70

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

RECEIVED 09 MAR 2018

COPY SENT  
9/3/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

2400

Kalvin

REF

ASSIGNMENT

SHB 87915

15 Jan 2014

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / NV / MV

No. Inspected Vehicle No.

at Workshop / ms

SP

Insured

Policy No.

Claims No.

Sum Insured

Excess

Client's Record

Make of Veh.

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.



Bal. on Market Value

IDAC Accident Report Consistent? Yes or No

DIA / PR Seen Consistent? Yes or No

Est. Repairs 4 days Res Yes or No

LUM SUPT 80 % 3 Val Yes or No

CA / REV / REP / 24 HRS

Date

Person Contacted

Vehicle IN / OUT

Date / Time

Action / Instruction

25/1/14, Contacted Lp & Jsum / 4 Apr. (RED 1st 2,890.50 49%)

QPE

Truck / Motor / Motorcycle / Bus / Van / Lorry / M.O. / Prime Mover

Truck / Trailer

Make

KRA option

168r

Colour

silver

Ins / Std / NI / NA

SP Reading

338338

Ins / Std / NI / NA

Eng No

C No

1CNA 6M414ME54r3676

Gen. Cond. Good / Fair / Poor / Burnt

Steering / Inboard / Jammed / Leaked / Burnt / or

Brake / Inboard / Jammed / Leaked / Burnt / or

Mod. Nil / S Rim / STD A Rim / or

Tyre Size

F

205/65R16

R

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO / or

Maxxis

Front

R Bal

7

Rear

R Bal

7

L Bal

7

L Bal

7

D.O.A.

19/1/18

D.O.A.

19/1/18

Survey held at

Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop / or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time File Return



Prelim Report



Final Report

Date/Time File Return

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transit Fee

Add Fee:



Date / Time



Date / Time



Date / Time



Date / Time

Report Format

Lump Sum / I.B No.






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC3/QBE18001279/K1ea3		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 22-01-2018		
		Code : QBE		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	XB 1881Y	Veh. Inspected	SHB 8791S	
Policy No.	8-V0011328-MVA-R002	Coverage (\$)	0.00	
Claim No.	VC011116	Excess (\$)	0.00	
Assign From		Assign Date	22/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	19/01/2018	Inspection Date	19/01/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

## Mei Kwan (LKKAUTO)

---

**From:** Joyce Foo <joyce.foo@qbe.com>  
**Sent:** Tuesday, 6 February, 2018 11:26 AM  
**To:** Mei Kwan (LKKAUTO)  
**Cc:** Vic (LKKAUTO); Asher Sng (LKKAUTO); Admin A  
**Subject:** RE: Direct Settlement - Accident Involving XB1881Y (OI : QBE - VC1116 ) AND SHB8791S (TP : LKK REF - CC3/QBE18001279/K1ea3) on 19/01/2018 [VC011116]  
**Attachments:** XB1881Y.pdf  
**Follow Up Flag:** Follow up  
**Flag Status:** Completed  
**Categories:** HMK

Our Ref. VC011116

Hi Mei Kwan


Attached OI GIA's report for your retention.

Thank You & Best Regards

---

Joyce Foo  
Senior Assistant - Claims  
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd  
Phone: +65 6477 1184  
Email: joyce.foo@qbe.com  
Visit us on the web at [www.qbe.com.sg](http://www.qbe.com.sg)



---

**From:** Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]  
**Sent:** Tuesday, 6 February, 2018 10:15 AM  
**To:** Joyce Foo <joyce.foo@qbe.com>  
**Cc:** Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** RE: Direct Settlement - Accident Involving XB1881Y (OI : QBE - VC1116 ) AND SHB8791S (TP : LKK REF - CC3/QBE18001279/K1ea3) on 19/01/2018

Dear Joyce,

We refer to the above matter.

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHB 8791S at M/s Premier Automotive Services Pte Ltd – Changi.

Enclosed for your perusal is:

- TP GIA report
- Photographs of TP vehicle in its damaged condition
- Estimated cost of repair
- Preliminary Advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


-----  
IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Text size + -

**Enquire Transaction History****Transaction History Details**

Log Date/Time:	15 Jan 2014 / 09:35:53	Receipt No.:	AACCK001-AX239-140115-000008
Asset Type:	Vehicle	Transaction Amount:	\$73,143.00
Asset ID:	SHB8791S	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140115093553578396		
Vehicle No.:	SHB8791S		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	15 Jan 2014		
Original Registration Date:	15 Jan 2014		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414ME5453676		
Engine No.:	D4FDDH308888		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2013		
Open Market Value:	\$19,615.00		
Minimum PARF Benefit:	\$7,269.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	15 Jan 2014 09:35:53		
COE No.:	2014011501000884G		
COE Expiry Date:	14 Jan 2022		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$60,888.00		
Lifespan Expiry Date:	14 Jan 2022		

Land Transport Authority



**VOCATIONAL LICENCE**  
 Licence No: S1362522J  
 Name: LEONG YEOW KEONG  
 Issue Date: 29/8/2011  
 Please visit [www.lta.gov.sg](http://www.lta.gov.sg) to check the status of this vocational licence

REPUBLIC OF SINGAPORE DRIVING LICENCE

S1362522J



LEONG YEOW KEONG  
 Date of Birth: 05 Jan 1959  
 Issue Date: 07 Feb 2003



REPUBLIC OF SINGAPORE

IDENTITY CARD NO: S1362522J



LEONG YEOW KEONG  
 梁有强  
 Race: CHINESE  
 Date of Birth: 05-01-1959  
 Country of Birth: SINGAPORE  
 Sex: M

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10311 Mid Drive, Singapore 575701.

Type	Description	Issue Date
02	TAXI VL	03/10/1989




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS/ES


Class	Description	Pass Date
Class 2B	Motorcycles not exceeding 200 cc	27 Sep 1982
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	27 Mar 1978
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms	04 Jul 1983
Class 5	Motor Vehicles which are not constructed themselves to carry any load and the weight of which unladen exceeds 2500 kilograms	21 Nov 1983

NP 428A


Licence No: S1362522J



1985



NRC No: S1362522J



Blood Group: B-  
 Date of Issue: 15-02-1994

APRIL 1964 RIVERVALE CRESCENT #7-101  
 SINGAPORE 641166  
 NRC No: S1362522J  
 Date: 10-07-1990  
 No: 2070141



Text size + -

**Enquire Transaction History****Transaction History Details**

Log Date/Time:	15 Jan 2014 / 09:35:53	Receipt No.:	AACCK001-AX239-140115-000008
Asset Type:	Vehicle	Transaction Amount:	\$73,143.00
Asset ID:	SHB8791S	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140115093553578396		
Vehicle No.:	SHB8791S		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	15 Jan 2014		
Original Registration Date:	15 Jan 2014		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414ME5453676		
Engine No.:	D4FDDH308888		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2013		
Open Market Value:	\$19,615.00		
Minimum PARF Benefit:	\$7,269.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	15 Jan 2014 09:35:53		
COE No.:	2014011501000884G		
COE Expiry Date:	14 Jan 2022		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$60,888.00		
Lifespan Expiry Date:	14 Jan 2022		



## Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number** : 5095103893

**Cover** : Third Party

1. Index mark and Registration Number of Vehicle

: **SHB8791S**

Chassis Number

: KNAGM414ME5453676

2. Name of Policyholder

: PREMIER TAXIS PTE. LTD.

3. Effective Date of Insurance

: 20 Oct 2017

4. Expiry Date of Insurance

: 19 Oct 2018

5. Persons or Classes of Persons entitled to drive\*

(a) The Policyholder.

(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use\*

(a) Use as a Taxi.

(b) Use for social domestic and pleasure purposes.

**This Policy does not cover**

(a) Use for racing, pace-making, reliability trial or speed-testing.

(b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third- Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)

: N/A

EXCESS (SECTION II)

: S\$3,500

INSURE WITH COE

: N/A

HIRE PURCHASE COMPANY

: N/A

SUM INSURED

: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)

Date of Issue : 16 Oct 2017 17:13 hrs

**For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED**

**Countersigned By:**



\_\_\_\_\_  
**Authorised Officer**



\_\_\_\_\_  
**Chief Executive**

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

Q&F

19-Jan-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8791 S

1 pc	Rear bumper	x repair	\$	696.00
1 pc	Rear bumper o/s side bracket	x	\$	16.00
1 pc	Rear o/s fender	/	\$	1,205.00
1 pc	Rear o/s fender inner shield	x	\$	120.00
1 pc	Rear winscreen moulding	/	\$	87.00
1 pc	Rear o/s door	/	\$	791.00
1 pc	Rear o/s door hinge @\$34.00	x	\$	68.00
1 pc	o/s rocker panel garnish	x repair	\$	286.00
1 pc	Rear o/s wheel cover	/	\$	116.00
			\$	3,385.00
			Less 10%	\$ 338.50
			\$	3,046.50

### S/NETT

1 set	Rear bumper clips	x	\$	48.00
1 set	Rear o/s fender inner shield	/	\$	28.00
1 pc	Rear o/s fender sticker	/	\$	60.00
1 pc	Sealant	/	\$	50.00
1 set	o/s door sticker	/	\$	100.00
1 pc	o/s rocker panel garinish clips	x	\$	28.00

19-Jan-18

**ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8791 S**

Sundry	\$	<del>50.00</del> 20
To check wheel alignment	\$	<del>80.00</del> X
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	<del>180.00</del> 50
To dismantle and refit the rear windscreen	\$	<del>120.00</del> 100
To dismantle and refit the inner component of the rear o/s door into new shell door	\$	<del>150.00</del> 50
To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heat on the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the same	\$	<del>950.00</del> 600
To putty and spray painting on rear bumper, rear o/s fender, rear o/s door, o/s rocker panel garnish	\$	<del>800.00</del> 720
To apply rustproofing on the repaired and replaced panels.	\$	<del>200.00</del> 50
	\$	<u>5,890.50</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**



Kalishetty  
19/1/18 1420hrs.  
4 Days.  
L/S  
After Repair phh

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

Q&F

19-Jan-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8791 S

1 pc	Rear bumper	x repair	\$ 696.00
1 pc	Rear bumper o/s side bracket	x sue	\$ 16.00
1 pc	Rear o/s fender	—	\$ 1,205.00
1 pc	Rear o/s fender inner shield	x sue	\$ 120.00
1 pc	Rear winscreen moulding	—	\$ 87.00
1 pc	Rear o/s door	—	\$ 791.00
2 pc	Rear o/s door hinge @\$34.00	x sue	\$ 68.00
1 pc	o/s rocker panel garnish	x repair	\$ 286.00
1 pc	Rear o/s wheel cover	—	\$ 116.00
			\$ 3,385.00
Less 10%			\$ 338.50
			\$ 3,046.50

### S/NETT

1 set	Rear bumper clips	x "	\$ 48.00
1 set	Rear o/s fender inner shield	+ "	\$ 28.00
1 pc	Rear o/s fender sticker	—	\$ 60.00
1 pc	Sealant	—	\$ 50.00
1 set	o/s door sticker	—	\$ 100.00
1 pc	o/s rocker panel garinish clips	x "	\$ 28.00

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

19-Jan-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8791 S

Sundry	new	\$	50.00 <sup>20</sup>
To check wheel alignment		\$	80.00 X 21
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 50
To dismantle and refit the rear windscreen		\$	120.00 100
To dismantle and refit the inner component of the rear o/s door into new shell door		\$	150.00 50
To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heat on the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the same		\$	950.00 <del>600</del> 600
To putty and spray painting on rear bumper, rear o/s fender, rear o/s door, o/s rocker panel garnish		\$	800.00 720
To apply rustproofing on the repaired and replaced panels.		\$	200.00 50
		\$	<u>5,890.50</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Ka hi LKK  
19/1/18 1420hrs.

4 Days.

L/S  
After Repair photo

25/1/18  
cont. 4/5 \$3000 / 4 Days  
11




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC3/QBE18001279/K1ea3n2	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 12-03-2018	
		Code : QBE	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	XB 1881Y	Veh. Inspected	SHB 8791S
Policy No.	8-V0011328-MVA-R002	Coverage (\$)	0.00
Claim No.	VC011116	Excess (\$)	0.00
Assign From		Assign Date	19/01/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KNAGM414ME5453676	Colour	SILVER
Odometer	338338	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	205/65 R16	MAXXIS	7 mm
L/H Front Tyre	205/65 R16	MAXXIS	7 mm
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	19/01/2018	Inspection Date	19/01/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8791S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	696.00	-
1	REAR BUMPER O/S SIDE BRACKET	SERVICEABLE	16.00	-
1	REAR O/S FENDER	DENTED	1,205.00	1,205.00
1	REAR O/S FENDER INNER SHIELD	SERVICEABLE	120.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	87.00	87.00
1	REAR O/S DOOR	DENTED	791.00	791.00
2	REAR O/S DOOR HINGE @\$34.00	SERVICEABLE	68.00	-
1	O/S ROCKER PANEL GARNISH	TO REPAIR SEE LABOUR	286.00	-
1	REAR O/S WHEEL COVER	GRAZED	116.00	116.00
	LESS 10% DISCOUNT		-338.50	-219.90
			3,046.50	1,979.10
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	SET REAR O/S FENDER INNER SHIELD (SN)	NOT NECESSARY	28.00	-
1	REAR O/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SEALANT (SN)	NECESSARY	50.00	50.00
1	SET O/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	O/S ROCKER PANEL GARNISH CLIPS (SN)	NOT NECESSARY	28.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			364.00	230.00
<b><u>LABOUR</u></b>				
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO DISMANTLE AND REFIT THE REAR WINDSCREEN.		120.00	100.00
	TO DISMANTLE AND REFIT THE INNER COMPONENT OF THE REAR O/S DOOR INTO NEW SHEEL DOOR.		150.00	50.00

Report Ref No. CC3/QBE18001279/K1ea3n2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.TO CUT/WELD AND HEAT ON THE REAR O/S FENDER.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE SAME.INCLUSIVE OF THE REPAIR OF REAR BUMPER AND O/S ROCKER PANEL GARNISH.		950.00	600.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER,REAR O/S FENDER,REAR O/S DOOR,O/S ROCKER PANEL GARNISH.		800.00	720.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		200.00	50.00
			2,480.00	1,570.00
	<b>GRAND TOTAL</b>		<b>5,890.50</b>	<b>3,779.10</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,000.00</b>

Report Ref No. CC3/QBE18001279/K1ea3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.