	From (Person): Elaine cheaner of EQI Dete/Time: 22/01/18@ 9.460	m
	Estimated Cost: Bill to:	
(OI) ff Ws/TP RES/OD RES/EVA/INV/MV/CS	
	To Inspect Vehicle No: GBD 1866S Insured:	
	at Workshop m/s 73B Motor Repairs Tel: 6154 8007	
	of 160 Sin Ming Drive # 08-03	
	Policy No: Claim No: DM18HO00148-EC	
	Sum Insured: Excess: \$3,500.00	
	Make of Veh:	
	(Chem's Accord)	
	CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:	
_	Date/Time: 10:01am@ 22/118 Person Contacted: UVY Vehicle IN OUT	
	Date/Time Action/Instruction () Estimate	
	GBO 18EER - X	
	13/1/18@ 11.40m vevert to time Cheong by emil.	
	15/1/80 4.44 traine cheans informed e/A. on is bass by enzil.	
	15/1/80 4.44 traine cheone informed e/A. on 13 bass by enail.	ro
	The state of the s	

ASS. REC. BY:	•
Kenneth AS	SSIGNMENT
From: Date: Estimated Cost: OD hTP / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: at Workshop m/s of / 984 00 / 26 W Insured: Policy No. Claims No.	Veh No: GBD 1865 Yr Regn: 07, 19 Type: M.Car/M.Cycle / Bus / Van / Korry Taxi / Prime Mover / Truck / Trailer or Make: N/S Cabra cc 2953 Colour Silve A/C: Insured / Std / NI / NA Sp.Reading 173/35 T/Radio: Insured / Std / NI / NA Eng/No: C/No: JN/SC2F247.885545 Gen Cond: Read Selet Bank 18
Sum insured: Excess: 3500) (Client's Record) Make of Veh; (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: 45k IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: / O days Res.: Yes or No Lum Sum: 20 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Gen. Cond: Good Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modi: Nill S/Rim / STD A/Rim or Tyre Size: F: 75 / Sor / 5 R: / 3 / / 3 x 8 (D) BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHT SU / PIR / SUMI / TOYO / YOKO or Front Rear R/Bai. 9 mm L/Bai. 9 mm L/Bai. 9 mm D.O.A. / 2 / / / / / / / D.O.I. 2 / / / / / / / / / / / / / / / / / /
Date / Time Action / Instruction 23/1 File PGSS - Callers Cate/Tane, File Pass to? Prell. Report Date 177 3 Mary Pass to? Report Record Cate/Time, File Return to? Add Fee: Report Format : OD	The U/C / Chassis frame / Body Structure affected due to collision. Tys Of Repair: (O Survey Fee: 300 Transportation: Site Insp (\$) _ \$ + R\$ _ \$I Interview (\$) Photos Tech Invs (\$) Others
2011 Sum 7 LBX: (5	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Amiliated to redefaulth inc	Ref: CS/EQI1800128	11/Kad3	
Q INSURANCE COM	PANY LTD	Ref : CS/EQI1800128) I/Nqu3	
MAXWELL ROAD				
17-00 TOWER BLOCK	K	Date: 22-01-2018		
IND COMPLEXSING	APORE 069110			
		Code: EQI		
	Policy Par	ticulars - OWN DAMAGE		
Insured Veh.		Veh. Inspected	GBD 1866S	
Policy No.		Coverage (\$)	0.00	
Claim No.	DM18HO00148-EC	Excess (\$)	3,500.00	
Assign From	ELAINE CHEONG	Assign Date	22/01/2018	
	Vehicle	Particulars & Condition	生工化学生 经	
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
	C	onditions of Tyres	No. of the second	
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
	Des	cription of Damages		
		eneral information		
Accident Date	12/01/2018	Inspection Date	22/01/2018	
Survey held at	160 Sin Ming Drive #08-0	3		
l <u> </u>	T & B MOTOR REPAIRS	SERVICES PTE LTD		
Repairer	,			

Nivitha (LKK Auto)

From:

Elaine Cheong <elaine.cheong@eqinsurance.com.sg>

Sent:

Monday, 22 January 2018 9:46 AM

To:

'assignments'

Subject:

FW: OD Claim of Vehicle: GBD1866S (CLAIM REF: DM18HO00148-EC)

Attachments:

Vehicle GBD1866S_Estimate.pdf; OI - GBD1866S.pdf

Dear All,

Please refer to the attached.

Kindly contact Ms Judy from M/s T & B Motor Repairs Services Pte Ltd to arrange for the survey.

We enclosed the following documents for your perusal:

- Our insured, GBD1866S GIA report
- Repair estimate

Policy excess: \$500.00

Kindly acknowledge receipt. Thank you.

Regards,

Elaine Cheong

Senior Executive | Claims

eqnsurance

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 62234190 www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

you've got a friend

From: t n b motor [mailto:tbmotor@hotmail.sg] **Sent:** Saturday, January 20, 2018 12:13 PM

To: Elaine Cheong

Subject: Re: OD Claim of Vehicle: GBD1866S

Dear Elaine,

Kindly refer to attached for the estimate and PIs help to arrange for survey, Thanks

Best Regards, Judy Ong

T & B Motor Repairs Services Pte Ltd

1.60 Sin Ming Drive #08-03 Sin Ming AutoCity Singapore 575722 Tel:6454 8007 / 6458 0296 Fax:6554 2640

From: t n b motor < tbmotor@hotmail.sg>
Sent: Friday, January 19, 2018 1:43 PM

To: weiyin.tan@eqinsurance.com.sg; janet.tan@eqinsurance.com.sg; Elaine.cheong@eqinsurance.com.sg

Subject: OD Claim of Vehicle: GBD1866S

Dear all / Motor Claim Dept,

Kindly help to arrange for PRI, attached herewith the GIA report. Pls advise, Thanks

Best Regards, Judy Ong

T & B Motor Repairs Services Pte Ltd 160 Sin Ming Drive #08-03 Sin Ming AutoCity Singapore 575722 Tel:6454 8007 / 6458 0296 Fax:6554 2640

eqnsurance

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 62234190 www.eginsurance.com.sg





Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: t n b motor [mailto:tbmotor@hotmail.sg]
Sent: Saturday, January 20, 2018 12:13 PM

To: Elaine Cheong

Subject: Re: OD Claim of Vehicle: GBD1866S

Dear Elaine,

Kindly refer to attached for the estimate and Pls help to arrange for survey, Thanks

Best Regards, Judy Ong

T & B Motor Repairs Services Pte Ltd 160 Sin Ming Drive #08-03 Sin Ming AutoCity Singapore 575722 Tel:6454 8007 / 6458 0296 Fax:6554 2640

From: t n b motor < tbmotor@hotmail.sg Sent: Friday, January 19, 2018 1:43 PM

To: weiyin.tan@eqinsurance.com.sg; janet.tan@eqinsurance.com.sg; Elaine.cheong@eqinsurance.com.sg

Subject: OD Claim of Vehicle: GBD1866S

Dear all / Motor Claim Dept,

Kindly help to arrange for PRI, attached herewith the GIA report. PIs advise, Thanks

Best Regards, Judy Ong

T & B Motor Repairs Services Pte Ltd 160 Sin Ming Drive #08-03 Sin Ming AutoCity Singapore 575722 Tel:6454 8007 / 6458 0296

Fax:6554 2640

Nivitha (LKK Auto)

From:

Elaine Cheong <elaine.cheong@eqinsurance.com.sg>

Sent:

Monday, 22 January 2018 9:53 AM

To:

'assignments'

Subject:

RE: OD Claim of Vehicle: GBD1866S (CLAIM REF: DM18HO00148-EC) - AMENDED

you've got a friend

Dear All,

Policy excess should be \$500.00 + \$3,000.00 (Young & Inexperienced excess) = \$3,500.00.

Thank you.

Regards,


Elaine Cheong

Senior Executive | Claims

eqnsurance

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 62234190 www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Elaine Cheong

Sent: Monday, January 22, 2018 9:46 AM

To: 'assignments'

Subject: FW: OD Claim of Vehicle: GBD1866S (CLAIM REF: DM18HO00148-EC)

Dear All,

Please refer to the attached.

Kindly contact Ms Judy from M/s T & B Motor Repairs Services Pte Ltd to arrange for the survey.

We enclosed the following documents for your perusal:

- Our insured, GBD1866S GIA report
- Repair estimate

Policy excess: \$500.00

Kindly acknowledge receipt. Thank you.

Regards,

Elaine Cheong

Senior Executive | Claims

From:

Denise Tay (LKKAuto)

Sent:

Thursday, 25 January 2018 5:15 PM

To:

'tbmotor@hotmail.sg'

Cc:

SUR

Subject:

RE: GBD 1866S OD EQI

Dear Judy,

Please noted the excess is policy excess \$500 + \$3000 (Young & inexperienced excess) = \$3500/-

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)

Sent: Thursday, 25 January 2018 5:04 PM

To: tbmotor@hotmail.sg
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBD 1866S OD EQI

Dear Judy,

Please note it's on lump sum basis.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>denisetay@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)

Sent: Thursday, 25 January 2018 4:59 PM

To: tbmotor@hotmail.sg
Cc: SUR <sur@lkkauto.com>
Subject: GBD 1866S OD EQI

Dear Judy,

As instructed by our client, please proceed to repair the insured vehicle GBD 1866S (Excess \$3,500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

From:

٠.

Denise Tay (LKKAuto)

Sent:

Thursday, 25 January 2018 5:04 PM

To:

tbmotor@hotmail.sg

Cc:

SUR

Subject:

RE: GBD 1866S OD EQI

Dear Judy,

Please note it's on lump sum basis.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>denisetay@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)

Sent: Thursday, 25 January 2018 4:59 PM

To: tbmotor@hotmail.sg Cc: SUR <sur@lkkauto.com> Subject: GBD 1866S OD EQI

Dear Judy,

As instructed by our client, please proceed to repair the insured vehicle GBD 1866S (Excess \$3,500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>denisetay@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From:

Denise Tay (LKKAuto)

Sent:

Thursday, 25 January 2018 4:59 PM

To:

٠,

tbmotor@hotmail.sg

Cc:

SUR

Subject:

GBD 1866S OD EQI

Dear Judy,

As instructed by our client, please proceed to repair the insured vehicle GBD 1866S (Excess \$3,500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>denisetay@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From:

Elaine Cheong <elaine.cheong@eqinsurance.com.sg>

Sent:

Thursday, 25 January 2018 4:44 PM Shiau Chan (LKKAuto); assignments

To: Cc:

SUR

Subject:

RE: OD Claim of Vehicle: GBD1866S (CLAIM REF: DM18HO00148-EC)

Attachments:

RE: OD Claim of Vehicle: GBD1866S (CLAIM REF: DM18HO00148-EC)

Dear Shiau Chan,

We refer to your preliminary advice of 23.01.18.

Please proceed to authorise repair at lump sum of \$14,900.00 as proposed.

Thank you.

Regards,


Elaine Cheong

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 62234190 www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies o

you've got a friend

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]

Sent: Wednesday, January 24, 2018 3:08 PM

To: Elaine Cheong; assignments

Cc: SUR

Subject: RE: OD Claim of Vehicle: GBD1866S (CLAIM REF: DM18HO00148-EC)

Dear Elaine,

As per your requested.

Please find the attached of estimate marking.

Best Regards,

Shiau Chan (Ms) | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)

Sent: Tuesday, 23 January 2018 11:40 AM

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Tuesday, 23 January 2018 11:40 AM

To:

'Elaine Cheong'; assignments

Cc:

SUR

Subject:

RE: OD Claim of Vehicle: GBD1866S (CLAIM REF: DM18HO00148-EC)

Attachments:

CSEQI18001281Kqd3.pdf

Dear Elaine,

Enclosed herewith preliminary advice of GBD 1866S.

We have not authorise repair.

Kindly advise on authorisation.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 22 January 2018 10:20 AM

To: 'Elaine Cheong' <elaine.cheong@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: OD Claim of Vehicle: GBD1866S (CLAIM REF: DM18HO00148-EC)

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Elaine Cheong [mailto:elaine.cheong@eqinsurance.com.sg]

Sent: Monday, 22 January 2018 9:46 AM

To: 'assignments' < assignments@lkkauto.com>

Subject: FW: OD Claim of Vehicle: GBD1866S (CLAIM REF: DM18HO00148-EC)

Dear All,

Please refer to the attached.

Kindly contact Ms Judy from M/s T & B Motor Repairs Services Pte Ltd to arrange for the survey.

We enclosed the following documents for your perusal:

Our insured, GBD1866S - GIA report



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: DM18HO00148-EC

Date: 23rd January 2018

Our Ref: CS/EQ118001281/Kqd3

The Motor Claims Department

EQ Insurance

Attn: Elaine

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. GBD 1866S .

We thank you for the instruction on 22/01/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/01/2018 at the premises of M/s ____ T & B MOTOR ____ and have the following to report:-

Workshop Estimate Amount	: <u>S</u> \$	30,706.20	 :
Revised Estimate Amount	: <u>S\$</u>	7,265.93	
"Check" Items Amount	: <u>\$\$</u>	11 <u>,380.1</u> 9	<u> </u>
Lump Sum Repair Estimate Amount	: S\$	14,900.00	
Market Value	: S\$	45,000.00	
LTA Reimbursement Value	: S\$	9,782.00	
Nett Value	: S\$	35,218.00	
Nett value			

Description of Damage:

The vehicle sustained damages at the

front portion.


Comments/ Present Status: Damages consistent.

Repair cost economical.

We have NOT authorize repair.

Yours faithfully

KENNETH KONG Licensed Appraiser



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0126W
Vehicle Details	
Vehicle No.:	GBD1866S
Vehicle to be Exported:	No
Intended De-registration Date:	23 Jan 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	ZD30339804K
Chassis No.:	JN1SC2F24Z0855975
Maximum Power Output:	•
Open Market Value:	\$25,081.00
Original Registration Date:	22 Jul 2014
First Registration Date:	22 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$1,255.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	. The second of
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jul 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$15,068.00
COE Rebate Amount:	\$9,782.00
Total Rebate Amount:	\$9,782.00

The information contained herein is correct as at 23 Jan 2018

MLHM18007630-017 Lai Huat (Meng Kee) Motor Pte Ltd - Sia Ming ENTRY DATE & TIME: 15/01/2018 18:11 SUBMITTED BY Jenny Lim Lai Foong

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

. '.

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

	ACCIDENT STATEMENT	
Date Of Report	15/01/2018 18:11	
Date Of Accident	12/01/2018 22:00	
Exact Location Of Accident	SOON LEE ROAD	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBD1866S	•
Insured/Policyholder		
Name Of Registered Owner	GTM ALUMINIUM PTE LTD	
Co Reg No	- 198400126W	
Email Address	NOEMAIL	
Mobile Phone No		
Alternative Phone No	OFFICE-62611311	

Vehicle Particulars

Manufacturer NISSAN Model **CABSTAR**

Exact Purpose for which vehicle was being used at COMPANY USE time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

COMMERCIAL VEHICLE Vehicle Category

Insurance Company

Name of Insurance Company EQ INSURANCE COMPANY LTD

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

DMCPHQ17-003638 **Policy Number**

Cover Note Number

Driver

Name of Driver DAVAMANI MANIKANDAN

NRIC No. G6541945P Date Of Birth 15/10/1988 Occupation **OUTDOOR** Date Of Driving Pass 02/08/2017

Driving Experience 0 YEAR AND 5 MONTH

Gender MALE

(LOCAL) +65-86525926 Mobile Number

Fax Number

Contact Number

NOEMAIL EMail Address

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

7 Number of Passengers (Including Driver)

Passenger 1

NAME:

: ALI HOSSAIN

GENDER:

: MALE

Passenger 2

NAME:

: MANINAN ABDUL

GENDER:

: MALE

Passenger 3

NAME:

: KHAN HABES

GENDER:

: MALE

Passenger 4

NAME:

: MAJHI SOMON

GENDER:

: MALE

Passenger 5

NAME:

: SUJAN SHEIKH

GENDER:

: MALE

Passenger 6

NAME:

: ISLAM ASHRAFUL

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes against whom?

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Was there any audio recorded?

YES

NO NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YP5359C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

13-11-13. 1 18 of & Boton Recairs Services F

-1465 6554 1640 # 1 3

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material
 facts may allow insurance companies to <u>repudiate policy flability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
 companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

1 understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and fransfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (I) processing, handling and/or dealing with my claims including the settlement of the daims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling analor dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims.
- (c) the information so collected under (d) above may be shared / disclosed:
 - (I) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyhoider's Signature Date & Time:

1.5 JAN 2018

Driver's Signature

(if driver is not the policyholder)
Date & Time 4 F 2444

15 JAN 2018

J.

Reporting Centre Personnel's Signature Name: NRIC/FIN No

Jenny Lim S6927273H

	Sketch Plan Pg. 2		
-01418,18116 UT & B Wetch	Feca is Selvies F]	;+65 6664 2640 =	
KETCH PLAN			
	<u></u>		
			_
	2555	N 5 3731 085	
DESCRIBE CIRCUMSTANCES OF TH	E ACCIDENT		
81cf 10, 21 M6		Y HOUR I WAS	
	soun live Road to	King Jeck Line	
WHIE I was	approaching the	fraffic there is a	
long infront of	me also moving	x- Junction	
		mean 1 could not	
4.1	V 1		ust_
hit on yestige	1 COMP and of the	he lonry the floot on Aheav was	
a larry apposit	suddenly make		
11		rfsikt lovvy	
	· ha		
			_
, , , , , , , , , , , , , , , , , , ,			
DECLARATION			
/We declare the foregoing politiculors :	are true in every respect.		
	D. mani Verder !.	Mr.	
Policyholder's Signature	Driver's Signature	Reporting Centre Personnel's Signature	
Date & Time: 15 JAN 2018	(If driver is not the policyholder) Date & Time: 1 5 JAN 2018	Name: NRIC/FIN No.: Jenny Lim S6927273H	

T & B MOTOR REPAIRS SERVICES PTE LTD

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No.: 6458 0296 / 6454 8007 Fax No.: 6554 2640

E-Mail: tbmotor@hotmail.sg Buss. Reg. No.: 199001597D

WITHOUT PREJUDICE

GTM ALUMINIUM PTE LTD 60 KIAN TECK ROAD 628793

Attention: Motor Claim Department

Not Nother Selling 8? Estimate: ES003285

Resure Afre Park Date: 15/01/2018

(x & 3500/ Chassis/Eng#:
Accident Date: 12/01/2018

Accident Date: 12/01/2018

Claim No.: Reference:

Policy No.: DMCPHQ17-003638

Fal: 62564315 S/N Particular Quantity

Unit Price

Amount S\$

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17.	1 1 1 1 1 1 1 1 1 1	LIST ITEMS: FRONT WINDSCREEN GLASS FRONT WINDSCREEN GLASS TOP MOULDIN FRONT WINDSCREEN GLASS SIDE MOULDIN FRONT WINDSCREEN GLASS SIDE MOULDIN FRONT WINDSCREEN GLASS PILLAR R/H FRONT WINDSCREEN PILLAR TOP INNER GOOD FRONT WIPER PANEL FRONT WIPER PANEL FRONT PANEL FRONT GRILLE FRONT GRILLE FRONT GRILLE FRONT SIDE MIRROR RH FRONT SIDE MIRROR BRACKET RH FRONT SIDE GARNISH RH FRONT WISCREEN PILLAR LH FRONT WISCREEN GLASS PILLAR INNER GOOFFONT SIDE MIRROR LH FRONT SIDE MIRROR BRACKET LH	NG R/H NG L/H ARNISH R/H ARNISH LH	1,090.10 102.85 102.85 102.85 1,811.04 155.87 1,811.04 1553.97 1,553.97 1,553.97 1,636.46 1,39.05 1,88.98 1,122.43 1,211.09 1,811.04 1,811.04 1,811.04 1,811.04 1,811.04 1,811.04 1,811.04 1,811.04 1,811.04 1,811.04
20. 21.	1 1	FRONT SIDE MIRROR BRACKET COVER L/H FRONT SIDE GARNISH LH		S ₁ 33.00 2
21. 22.	1	FRONT SIDE GARNISH LH FRONT HEAD LAMP R/H	197	520.74 S
23.	1	FRONT HEAD LAMP LOWER GARNISH R/H	A	82.50
4.	1	FRONT HEAD LAMP L/H	777	CM 520.74
5.	1	FRONT HEAD LAMP LOWER GARNISH L/H	•	70d 122.43 520.74 82.50 62.50 62.50 71 82.50
		List Total S\$:		10,466.57
		30.00% Discount S\$:		3,139.97
			LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting	7,326.60
			To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	CONTINUE /
			Acknowledged by Repairer Signature:	

Amount S\$

T & B MOTOR REPAIRS SERVICES PTE LTD

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No.: 6458 0296 / 6454 8007 Fax No.: 6554 2640

E-Mail: tbmotor@hotmail.sg Buss. Reg. No.: 199001597D

WITHOUT PREJUDICE

GTM ALUMINIUM PTE LTD

60 KIAN TECK ROAD

Quantity

628793

S/N

Attention: Motor Claim Department

Particular

Estimate: ES003285

Date : 15/01/2018 Vehicle Num. : GBD1866S

Make/Model: NISSAN CABSTAR

Chassis/Eng#:

Accident Date: 12/01/2018

Claim No. : Reference :

Policy No.: DMCPHQ17-003638

Unit Price

NETT ITEMS: Me 71.06 CABSTAR EMBLEM LN 1.536.15 \$3052 FRONT DOOR RH FRONT DOOR TOP HINGE RH 71.61 X 3. FRONT DOOR LOWER HINGE RH 71.61 X rt 770.00 🗶 5. FRONT DOOR CLOSET RH ∽ 166.21 X 6. FRONT DOOR WEATHERSTRIP RH 7. FRONT DOOR GLASS OUTER MOULDING RH 149.82 x 231.90 FRONT DOOR INNER LOCK RH 8. 5 85.14 X FRONT DOOR INNER LOWER RUBBER R/H Q 1,536.15 x 10. FRONT DOOR LH FRONT DOOR TOP HINGE LH N 71.61 11. n 71.61 x 12 FRONT DOOR LOWER HINGE LH 1 770.00 X 13. FRONT DOOR CLOSET LH as 166.21 \$0 lsn 14. FRONT DOOR WEATHERSTRIP LH Su 149.82 X FRONT DOOR GLASS OUTER MOULDING LH 15. 1 rin 255.09 85.14 16. FRONT DOOR INNER LOCK LH 17. FRONT DOOR INNER LOWER RUBBER L/H CN 1,689.90 204.71 18 FRONT DASHBOARD 1 19. FRONT GROVE Se 127.60 FRONT GROVE COVER 20. cns 986.26 21. 1 FRONT DASHBOARD INSTRUMENT PANEL 6.05 Me 22. FRONT GRILLE CLIPS 24.20 CPA 364.65 FRONT DASHBOARD LOWER GARNISAH R/H 23. 24 1 STEERING SHAFT HOUSING ASSY 1,279.08 X 582.12 X 25. STEERING COUPLING 96.03 BRAKE BOOSTER BRACKET 26. 1 78.32 BRAKE BOOSTER AIR PIPE 27. 1 ³41.66 28. BRAKE BOOSTER PUMP 12,033.66 Nett Total S\$: 10.00% Discount S\$: 1,203.37 10,830.29

T & B MOTOR REPAIRS SERVICES PTE LTD

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No.: 6458 0296 / 6454 8007 Fax No.: 6554 2640

E-Mail: tbmotor@hotmail.sg

Buss. Reg. No.: 199001597D

WITHOUT PREJUDICE

GTM ALUMINIUM PTE LTD 60 KIAN TECK ROAD

628793

Attention: Motor Claim Department

Estimate: ES003285

Date: 15/01/2018 Vehicle Num.: GBD1866S

Make/Model: NISSAN CABSTAR

Chassis/Eng#:

Accident Date: 12/01/2018

Claim No.: Reference:

Policy No.: DMCPHQ17-003638

S/N	Quantity	Particular	Unit Price	Amount S\$
		SPECIAL NETT ITEMS :		£.
1.	1	FRONT WINDSCREEN SPRAY NOSSEL R/H		26.07
2.	1	FRONT WINDSCREEN SPRAY NOSSEL L/H		CM 26.07
3.	1	FRONT WIPER ARM RH		Se 113.41
1 .	1	FRONT WIPER BLADE ARM R/H		31.57
5.	1	FRONT WIPER ARM LH		Pm 113.41
5.	1	FRONT WIPER BLADE LH		31.57
7.	1	AIRCON BLOWER ASSY		CPN 559.24
8.	1	AIRCON COOLING COIL ASSY		54 1,010.68
9.	1	AIRCON HEATER BLOWER ASSY	Cri	4 1,441.66
10.	1	BRAKE BOOSTER		Sn 1,474.11
11.	4	BRAKE BOOSTER PIPE	105.38	Sin 421.52
		Special Nett Total S\$:		5,249.31
		LABOUR:		
	1	1. TOWING	60.00	60.00
	1	2. REMOVE & REFIX FRONT WINDSCREEN AND SUPPLY	200.00	200.00
	1	3. REMOVE & REFIX FRONT R/H & L/H DOOR WINDSCREEN	300.00	NN 300.00
	1	4. REMOVE & REFIT FRONT DASHBOARD & REPLACE	480.00	480.00
		5. REMOVE & REFIT BRAKE BOOSTER, MASTER PUMP & BRAKE		
	1	PIPE & STEERING SHAFT COUPLING AND CHECK BRAKE SYSTEM	800.00	800.00
	1	6. REMOVE & REFIX AIRCON SYSTEMAND TOP-UP GAS	320.00	320.00
	1	7. CHECK & REPAIR WIRING	160.00	160.00
	1	8. SPRAY PAINT ON FRONT CABIN	2,000.00	2,000.00
	1	9. REMOVE & REFIX UPHOLSTERY	480.00	480.00
	1	10. LABOUR CHARGE FOR REPAIRING, ADJUSTING, KNOCKING,	2,500.00	2,500.00
		WELDING THE DAMAGED PARTS, STRAIGHTEN THE ABOVE		
		Labour Total S\$:		7,300.00
Sing[Dollars : Thirt	y Thousand Seven Hundred Six & Cents Twenty Only		
		E. & O.E.	Total S\$:	30,706.20

for T & B MOTOR REPAIRS SERVICES PTE LTD

31378.53

========

T&B MOTOR REPAIRS SERVICES PTE LTD

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No.: 6458 0296 / 6454 8007 Fax No.: 6554 2640

E-Mail: tbmotor@hotmail.sg Buss. Reg. No.: 199001597D

WITHOUT PREJUDICE

GTM ALUMINIUM PTE LTD 60 KIAN TECK ROAD

628793

Attention: Motor Claim Department

Supplementary Estimate: ES003316

Date : 15/01/2018 Vehicle Num. : GBD1866S Make/Model : NISSAN CABSTAR

Chassis/Eng#:

Accident Date : 12/01/2018

Claim No.: Reference:

Policy No.: DMCPHQ17-003638

S/N	Quantity	Particular	Unit Price Amount S\$
1. 2. 3.	1 1 1	LIST ITEMS : FRONT SIDE PANEL RH FRONT SIDE PANEL LH IU BRACKET	Bn 467.59 × 467.59 × Mn 25.00 ×
,		List Total S\$: 30.00% Discount S\$:	960.18 288.05
			672.13

SingDollars: Six Hundred Seventy-Two & Cents Thirteen Only

E. & O.E.

Total S\$:

672.13 ========

SERVICES PTE LTD



5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 19	9607198R GST Reg. No. 19-96	607198-R
		Affiliated to Federation Internal	ionale Des Experts En Autom	obile
EQ	INSURANCE COM	IPANY LTD	Ref : CS/EQI1800128	31/Kqd3e2
#17	AXWELL ROAD -00 TOWER BLOC D COMPLEXSING		Date: 27-03-2018	
			Code: EQI	
1.		Policy Particu	lars :- OWN DAMAGE	
	Insured Veh.		Veh. Inspected	GBD 1866S
	Policy No.	DMCPHQ17-003638	Coverage (\$)	0.00
	Claim No.	DM18HO00148-EC	Excess (\$)	3,500.00
	Assign From	ELAINE CHEONG	Assign Date	22/01/2018
2.		Vehicle Par	ticulars & Condition	
	Make & Model	NISSAN CABSTAR	c.c	2953
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	JN1SC2F24Z0855975	Colour	SILVER
	Odometer	173155	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Condi	tions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	175/80 R15	YOKOHAMA	9 mm
	L/H Front Tyre	175/80 R15	YOKOHAMA	9 mm
	R/H Rear Tyre	165 R13X8 (D)	YOKOHAMA	9/9 mm
	L/H Rear Tyre	165 R13X8 (D)	YOKOHAMA	9/9 mm
4.		Descrip	tion of Damages	A PART AND A PROPERTY OF THE PARTY OF THE PA
	THE VEHICLE SU	STAINED DAMAGES AT THE F	RONT PORTION.	The state of the s
	DAMAGES SEE D	FTAILS.		
5 .		· · · · · · · · · · · · · · · · · · ·	al Information	
	Accident Date	12/01/2018	Inspection Date	22/01/2018
	Survey held at	160 Sin Ming Drive #08-03		
	Repairer	T & B MOTOR REPAIRS SER	VICES PTE LTD	
5a.			Remarks 🤳 🗥 🙀	
		ALUE IS S\$45,000.00(EST. AVE CE TO YOUR INSTRUCTIONS,		EPAIRS.

Estimate Days of Repair

10 Working Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 1866S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT WINDSCREEN GLASS	CRACKED	1,090.10	1,090.10
1	FRONT WINDSCREEN GLASS TOP MOULDING	NECESSARY	102.85	102.85
1	FRONT WINDSCREEN GLASS SIDE MOULDING R/H	NECESSARY	102.85	102.85
1	FRONT WINDSCREEN GLASS SIDE MOULDING L/H	NECESSARY	102.85	102.85
1	FRONT WINDSCREEN GLASS PILLAR R/H	BENT	1,811.04	1,811.04
1	FRONT WINDSCREEN PILLAR TOP INNER GARNISH R/H	SERVICEABLE	155.87	-
1	FRONT WIPER PANEL	TO REPAIR SEE LABOUR	544.06	_
1	FRONT WIPER PANEL TOP RUBBER	DISTORTED	48.95	48.95
1	FRONT PANEL	BENT	1,553.97	1,553.97
1	FRONT GRILLE	MISSING	636.46	636.46
1	FRONT GRILLE LOGO	MISSING	39.05	39.05
1	FRONT SIDE MIRROR RH	CRACKED	188.98	188.98
1	FRONT SIDE MIRROR BRACKET RH	BENT	211.09	211.09
1	FRONT SIDE MIRROR BRACKET COVER R/H	MISSING	33.00	33.00
1	FRONT SIDE GARNISH RH	CRACKED	122.43	122.43
1	FRONT W/SCREEN PILLAR LH	TO REPAIR SEE LABOUR	1,811.04	_
1	FRONT W/SCREEN GLASS PILLAR INNAR GARNISH LH	SERVICEABLE	150.00	-
1	FRONT SIDE MIRROR LH	CRACKED	188.98	188.98
1	FRONT SIDE MIRROR BRACKET LH	DISTORTED	211.09	211.09
1	FRONT SIDE MIRROR BRACKET COVER L/H	SERVICEABLE	33.00	-
1	FRONT SIDE GARNISH LH	DENTED	122.43	122.43
1	FRONT HEAD LAMP R/H	MTG CRACKED	520.74	520.74
1	FRONT HEAD LAMP LOWER GARNISH R/H	SERVICEABLE	82.50	-
1,	FRONT HEAD LAMP L/H	MTG CRACKED	520.74	520.74
1	FRONT HEAD LAMP LOWER GARNISH L/H	SERVICEABLE	82.50	-
1	FRONT SIDE PANEL RH (ADDITIONAL)	TO REPAIR SEE LABOUR	467.59	-
1	FRONT SIDE PANEL LH (ADDITIONAL)	BUCKLED	467.59	467.59
1	IU BRACKET (ADDITIONAL)	NECESSARY	25.00	25.00
	LESS 30% DISCOUNT		-3,428.03	-2,430.06
			7,998.72	5,670.13

Report Ref No. CS/EQI18001281/Kqd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

y	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	NETT ITEMS			
1	CABSTAR EMBLEM (N)	NECESSARY	71.06	71.06
1	FRONT DOOR TOP HINGE RH (N)	TO REPAIR SEE LABOUR	71.61	
1	FRONT DOOR LOWER HINGE RH (N)	TO REPAIR SEE LABOUR	71.61	
1	FRONT DOOR CLOSET RH (N)	TO REPAIR SEE LABOUR	770.00	
1	FRONT DOOR WEATHERSTRIP RH (N)	SERVICEABLE	166.21	
1	FRONT DOOR GLASS OUTER MOULDING RH (N)	SERVICEABLE	149.82	
1	FRONT DOOR INNER LOCK RH (N)	DENTED	231.90	231.90
1	FRONT DOOR INNER LOWER RUBBER R/H (N)	SERVICEABLE	85.14	
1	FRONT DOOR LH (N)	TO REPAIR SEE LABOUR	1,536.15	
1	FRONT DOOR TOP HINGE LH (N)	TO REPAIR SEE LABOUR	71.61	
1	FRONT DOOR LOWER HINGE LH (N)	TO REPAIR SEE LABOUR	71.61	
1	FRONT DOOR CLOSET LH (N)	TO REPAIR SEE LABOUR	770.00	
1	FRONT DOOR GLASS OUTER MOULDING LH (N)	SERVICEABLE	149.82	
1	FRONT DOOR INNER LOCK LH (N)	TO REPAIR SEE LABOUR	255.09	
1	FRONT DOOR INNER LOWER RUBBER L/H (N)	SERVICEABLE	85.14	
1	FRONT DASHBOARD (N)	CRACKED	1,689.90	1,689.90
1	FRONT GROVE (N)	SERVICEABLE	204.71	
1	FRONT GROVE COVER (N)	SERVICEABLE	127.60	
1	FRONT DASHBOARD INSTRUMENT PANEL (N)	CRACKED	986.26	986.26
4	FRONT GRILLE CLIPS @\$6.05 (N)	NECESSARY	24.20	24.20
1	FRONT DASHBOARD LOWER GARNISHAH R/H (N)	CRACKED	364.65	364.65
1	STEERING SHAFT HOUSING ASSY (N)	TO REPAIR SEE LABOUR	1,279.08	
1	STEERING COUPLING (N)	SERVICEABLE	582.12	
1	BRAKE BOOSTER BRACKET (N)	TO REPAIR SEE LABOUR	96.03	
1	BRAKE BOOSTER AIR PIPE (N)	SERVICEABLE	78.32	
1	BRAKE BOOSTER PUMP (N)	SERVICEABLE	341.66	
	LESS 10% DISCOUNT		-1,033.13	-336.80
- 1			9,298.17	3,031.17

Report Ref No. CS/EQI18001281/Kqd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

ty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR RH (LOCAL REPAIR) (SN)	DENTED	1,536.15	150.00
1	FRONT DOOR WEATHERSTRIP LH (50%) (SN)	CUT	166.21	83.11
	LESS 10% DISCOUNT		-170.24	-
			1,532.12	233.11
	SPECIAL NETT ITEMS		· <u>-</u>	
1	FRONT WINDSCREEN SPRAY NOSSEL R/H (SN)	SERVICEABLE	26.07	-
1	FRONT WINDSCREEN SPRAY NOSSEL L/H (SN)	CRACKED	26.07	26.07
1	FRONT WIPER ARM RH (SN)	SERVICEABLE	113.41	-
1	FRONT WIPER BLADE ARM R/H (SN)	SERVICEABLE	31.57	-
1	FRONT WIPER ARM LH (SN)	SERVICEABLE	113.41	-
1	FRONT WIPER BLADE LH (SN)	SERVICEABLE	31.57	-
1	AIRCON BLOWER ASSY (SN)	CRACKED	559.24	559.24
1	AIRCON COOLING COIL ASSY (SN)	SERVICEABLE	1,010.68	-
1	AIRCON HEATER BLOWER ASSY (SN)	CRACKED	1,441.66	1,441.66
1	BRAKE BOOSTER (SN)	SERVICEABLE	1,474.11	-
4	BRAKE BOOSTER PIPE @\$105.38 (SN)	SERVICEABLE	421.52	-
1			5,249.31	2,026.97
	LABOUR			
	LABOUR CHARGE FOR REPAIRING, ADJUSTING, KNOCKING, WELDING THE DAMAGED PARTS, STRAIGHTEN THE ABOVE. INCLUSIVE OF THE REPAIR OF FRONT WIPER PANEL, FRONT WISCREEN PILLAR LH, FRONT DOOR TOP HINGE RH, FRONT DOOR LOWER HINGE RH,FRONT DOOR CLOSET RH, FRONT DOOR LH, FRONT DOOR TOP HINGE LH, FRONT DOOR LOWER HINGE LH, FRONT DOOR CLOSET LH, FRONT DOOR INNER LOCK LH, STEERING SHAFT HOUSING ASSY, BRAKE BOOSTER BRACKET AND FRONT SIDE PANEL RH.		2,500.00	1,400.00
	TOWING.		60.00	60.00
	REMOVE & REFIX FRONT WINDSCREEN AND SUPPLY.		200.00	120.00
	REMOVE & REFIX FRONT R/H & L/H DOOR WINDSCREEN.	NOT NECESSARY	300.00	-
	REMOVE & REFIX FRONT DASHBOARD & REPLACE.		480.00	280.00
	REMOVE & REFIT BRAKE BOOSTER , MASTER PUMP & BRAKE PIPE & STEERING SHAFT COUPLING AND CHECK BRAKE SYSTEM.		800.00	150.00
	REMOVE & REFIX AIRCON SYSTEM AND TOP-UP GAS.		320.00	100.00

Report Ref No. CS/EQI18001281/Kqd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty Description of Parts	Condition	Esilmate By Workshop (5)	Our Adjusted (\$)
CHECK & REPAIR WIRING.		160.00	20.00
SPRAY PAINT ON FRONT CABIN.		2,000.00	1,200.00
REMOVE & REFIX UPHOLSTERY.		480.00	120.00
		7,300.00	3,450.00
GRAND TOTAL		31,378.32	14,411.38

RECOMMENDED COS (TO ITS PRE-ACCIDE	ST OF LUMP SUM REP NT CONDITION)	AIR8	10,300,00
LESS EXCESS		100	3,500,00
NETT LIABILITY		1/8/4/4/1	6,800.00

Report Ref No. CS/EQI18001281/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part, Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.