

22/03/2003

ASS. REC. BY:

REF: CS/MSG18001283/719d3m2 Special Instructions:

Surveyor: Taufik ASSIGNMENT (Office)From (Person): Katherine Wong of MSIG Date/Time: 22/1/18 @ 11:52am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB 8096T Insured: SJY 7903Zat Workshop m/s Ding Auto Tel: 9239 4128of Blk 10, # 01-20, Sin Ming Ind-Est & C.Policy No: MSG/VPCP/17-002149 Claim No: MSG/V/18-00729

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 18/01/2018(Client's Record) 249 jalan Boon LayCA / REV / REP. / REV 24 HRS Wp R.O.D. Endorsement: _____Date/Time: 2:29pm @ 22/1/18 Person Contacted: _____ Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLB 8096T-X
	SJY 7903Z-X
23/1/18 @ 2:39pm	revised to Katherine Wong via Meimen.
28/3/18 @ 10:53am	Taufik finalised with Kenneth US \$1200, 3 days.
	(Red \$ 519.75, 812)

Service *Tanphu*

REF:

MS16

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / FR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: _____ % 3 Val: Yes or No
CA / REV / REP. / 24 HRS
WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLB8096T Yr Regn: 2016 April
Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Altis Yr: 1598
Colour: Silver A/O: Insured / Std / NI / NA
Sp. Reading: 133143 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MK053REH 104538575
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/55R16
R: 205/55R16
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Triangle
Front: _____ Rear: _____
R/Bal: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A: _____ D.O.I: 22/1/18
Survey held at: Ding Hup Boon Lay
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop
R/T M/S
The U/C / chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

E-mail w/s for resurvey photos

15/9/2018, 3 days - email to w/s.

RECEIVED 2 MAY 2018

[Signature]
23/5/2018

Date/Time: File Pass to?

1) 14/5 12pm

Date/Time: File Return to?

2) _____

Report Format:

Lump Sum / I.B.

☐ : Preli. Rep't
☐ : Final Rpt.

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Insp (\$)
☐ Weekend (\$)

Survey Fee

Transportation

8 - RS (\$)

Photos

Chart

TOTAL

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18001283/T1qd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 22-01-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJY 7903Z	Veh. Inspected	SLB 8096T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	22/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/01/2018	Inspection Date	22/01/2018	
Survey held at	249 JLN BOON LAY			
Repairer	DING AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2018 09:43 Sendback Est	22 Jan 2018 09:59 \$6,419.75	22 Jan 2018 11:52 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	Hitachi Capital Asia Pacific Pte Ltd, Co. Reg. No.: 199400399N		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLB8096T	Date of Loss:	18/01/2018 17:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	Coverage: 30/09/2017 - 29/09/2018
Vehicle Reg. No. (Insured):	SJY7903Z	Policy No. (Claimant):	999995061
		Excess:	
Repairer:	Ding Auto Pte Ltd (HQ) Blk 10, #01-20, Sin Ming Industrial Estate Sector C, 575645 Sin Ming - Tel: 64521208		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/01/2018]		
Driver/Custodian (Insured):	TUAN ABDUL RAHIM BIN MOHAMED (), NRIC: S1619502B		
Adj Asg. Remarks:	Please Survey - Car in at 249 Jalan Boon Lay. Thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Celine Fong (LKKAUTO)

From: Kenneth Ding <kenneth.ding@dingauto.sg>
Sent: Wednesday, 28 March 2018 10:53 AM
To: Taufikh (LKKAUTO); 'Accounts Ding Auto'; SUR
Cc: 'JingFeng'; 'Vivian'; 'Yvonne Wong'
Subject: RE: 85008071/SLB8096T- FINALIZE AMOUNT AND AFTER PAINT PHOTO

Dear Taufikh,

Noted, we accept the offer.

Thank you so much.

Best Regards,
Kenneth Ding
HP: 92313123
Fax: 6452 0614

From: Taufikh (LKK Auto) [mailto:taufikh@lkkauto.com]
Sent: Tuesday, March 27, 2018 5:59 PM
To: 'Accounts Ding Auto'; 'SUR'
Cc: kenneth.ding@dingauto.sg; 'JingFeng'; 'Vivian'; 'Yvonne Wong'
Subject: RE: 85008071/SLB8096T- FINALIZE AMOUNT AND AFTER PAINT PHOTO

Hi,

COR I/s \$1200 , 3 days.

Regards
Taufikh
Lkk Auto

From: Accounts Ding Auto [mailto:accounts@dingauto.sg]
Sent: Friday, 16 March 2018 3:04 PM
To: Taufikh (LKKAUTO); SUR
Cc: kenneth.ding@dingauto.sg; JingFeng; Vivian; Yvonne Wong; Admin-D (LKKAUTO)
Subject: Re: 85008071/SLB8096T- FINALIZE AMOUNT AND AFTER PAINT PHOTO

Dear all,

Please advice the finalize amount for this case as we still have not receive any update from you till today.

Kindly check and update us as soon as possible.

Thank you so much.

Yours Sincerely,
Fang XinYi Michelle
Office Contact : 92394128
Ding Auto Pte Ltd

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 23 Jan 2018

Preliminary Advice

Insured Vehicle No	: SJY7903Z	Accident Date	: 18/01/2018
TP Vehicle No	: SLB8096T	Assignment Date	: 22/01/2018
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 3
Date of Inspection	: 22/01/2018		
Inspection At	: DING AUTO		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,419.75
Revised Amount	:S\$	970.75
Check Items (Estimated)	:S\$	586.50
Total	:S\$	1,557.25

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to deny policy liability.
4. The signing and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any tales reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) to the relevant authorities.
7. This report and copies of this report will, for a fee, be made available upon application by interested parties.
8. By forwarding of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available to relevant authorities.

ACCIDENT STATEMENT

Date Of Report 19/01/2018 17:16
 Date Of Accident 18/01/2018 17:45
 Exact Location Of Accident BLK 11 UPPER BOON KENG ROAD OPENSOURCE CARPARK
 Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLB8096T
 Insured/Policyholder
 Name Of Registered Owner LCRF PTE LTD
 Co Reg No 201624597K
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-31584255
 Vehicle Particulars
 Manufacturer TOYOTA
 Model COROLLA ALTIS CLASSIC 1.6 CVT
 Exact Purpose for which vehicle was being used at time of accident PRIVATE HIRER
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR
 Insurance Company
 Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 999995061
 Cover Note Number
 Driver
 Name of Driver LEE TEE HOCK
 NRIC No S7329456H
 Date Of Birth 17/08/1973
 Occupation OUTDOOR
 Date Of Driving Pass 01/08/2000
 Driving Experience 17 YEARS AND 5 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-92394128
 Fax Number
 Contact Number
 Email Address NOEMAIL

Was driver an employee of the Insured's Company? NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: UNKNOWN
 GENDER: FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJY7903Z
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver TUAN ABDUL RAHIM BIN MOHAMED
 NRIC/Passport Number S1619502B
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

UPPER BOON KENG BLK 11

SKETCH PLAN



A = SLB 8096
B = SSY 79032
Tuan Abdul
Rahim Bin
Mohamed
S1619 502B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/1/18 at 5-45pm I was travelling along Upper Boonkeng Road. I was within my lane and the vehicle SSY 79032 suddenly came out from parking lot and collided onto my front portion. No one was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Ding Auto Pte Ltd (Co. Reg. No 201311788Z)

Blk 10, #01-20, Sin Ming Industrial Estate Sector C

Singapore 575645

Tel: 64521208 Fax: 64520614 Email: admin@dingauto.sg; ding@dingauto.sg; kenneth.ding@dingauto.sg

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)**TUAN ABDUL RAHIM BIN MOHAMED**

NIL

Singapore

Claimant Insurer: AIG Asia Pacific Insurance Pte. Ltd.**PARTICULARS OF CLAIM**

Claim Type: THIRD PARTY
 Policy No:
 Vehicle Reg. No.: SLB8096T
 Party At Fault: THIRD PARTY
 Driver (TP): LEE TEE HOCK

Ref. No:
 Date of Loss: 18/01/2018
 Driveable?

Make/Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC
 CVT (A)

Vehicle Reg. Date: 22/04/2016

Vehicle Colour: SILVER

Engine No: 1ZRY209783

Odometer: 1 KM

Chassis No: MR053REH104538875

Paint Type:

Total Loss? NO

Est. Duration of
 Repair (day)

5

Description of
 Accident/Loss

REFER TO STATEMENT

Present Location: DING AUTO PTE LTD (HQ)

Tan Jinh 974 95749
22/1/18 @ 1215
3 days sure@lkkauto.com
Resurvey after repair
lumpsum

COST OF CLAIMS

Parts

Miscellaneous Items

Labour

Paintwork Labour

Towing

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Amount

2,949.75

0.00

3,470.00

0.00

0.00

Gross Total (\$\$)**6,419.75****+ GST 7.00% (\$\$)****449.38****Nett Amount (\$\$)****6,869.13****This claim is handled by: YOU JING FENG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Jan 2018)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ding Auto Pte Ltd/SLB8096T/22/01/2018 09:59
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	de *215.00 F
2	1		*SPONGE FRONT	0.00	de 0.00	de *80.00 F ✓
3	1		*FRONT BUMPER REINF	0.00	bt 0.00	? *150.00 F ✓
4	1		*FRONT REINF ARM RHS	0.00	0.00	X *45.00 F
5	1		*FRONT REINF ARM LHS	0.00	0.00	X *45.00 F
6	1		*SUPPORT PANEL	0.00	0.00	X *220.00 F
7	1		*HEAD LAMP RHS LHS	0.00	0.00	X *280.00 F
8	1		*RADIATOR GRILLE	0.00	0.00	X *220.00 F
9	1		*FRONT FENDER RHS LHS	0.00	0.00	RY *150.00 F
10	1		*FRONT FENDER RHS EMBLEM LHS	0.00	0.00	new *25.00 F
11	1		*BONNET	0.00	0.00	X *380.00 F
12	1		*BONNET HINGE LHS	0.00	0.00	X *45.00 F
13	1		*BONNET HINGE RHS	0.00	0.00	X *45.00 F
14	1		*HEAD LAMP LHS	0.00	0.00	q *280.00 F ✓
15	1		*FOG LAMP COVER	0.00	0.00	cut *65.00 F
16	1		*FOG LAMP	0.00	0.00	X *180.00 F
17	1		*AIR DUCT	0.00	0.00	X *85.00 F
18	1		*AIR RESONATOR	0.00	0.00	X *55.00 F

F=Franchise part.

Sub Total (S\$)	790	2,565.00
+ Margin on L,N Items 15.00% (S\$)		384.75
Total Parts (S\$)	908.50	2,949.75

Ding Auto Pte Ltd/SLB8096T/22/01/2018 09:59. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New	300 1,500.00
2	SPRAY PAINTING ON FRONT BUMPER ,REINF ,FENDER RHS /LHS , BONNET ,SUPPORT PANEL	New	300 1,200.00
3	CHECK WIRING AND ADJUST HEAD LAMP AIM	New	20 120.00
4	RUSH PROOFING	New	X 150.00
5	R&R CONDENSER AND REFILL AIRCON GAS	New	X 150.00
6	ALIGNMENT FRONT CHASSIS	New	X 350.00
Gross Labour Cost (S\$)			620 3,470.00

Ding Auto Pte Ltd/SLB8096T/22/01/2018 09:59. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

908.50
 620.
 1528.50
 4591200
 30495

Ding Auto Pte Ltd (Co.Reg No:201311788Z)
 Blk 10, #01-20, Sin Ming Industrial Estate Sector C
 Singapore 575645

Tel: 64521208 Fax: 64520614 Email: admin@dingauto.sg;ding@dingauto.sg;kenneth.ding@dingauto.sg

TP INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

TUAN ABDUL RAHIM BIN MOHAMED

NIL

Singapore

Claimant Insurer: **AIG Asia Pacific Insurance Pte. Ltd.**

PARTICULARS OF CLAIM

Claim Type: **THIRD PARTY**
 Policy No:
 Vehicle Reg. No.: **SLB8096T**
 Party At Fault: **THIRD PARTY**
 Driver (TP): **LEE TEE HOCK**

Ref. No:
 Date of Loss: **18/01/2018**
 Driveable?

Make/Model: **TOYOTA COROLLA ALTIS, 1.6 CLASSIC** Vehicle Reg. Date: **22/04/2016**
 CVT (A)

Vehicle Colour: **SILVER**
 Engine No: **1ZRY209783**
 Odometer: **1 KM**

Chassis No: **MR053REH104538875**

Paint Type:
 Total Loss? **NO**
 Est. Duration of
 Repair (day) **5**

Tan Jinh 974 95749
- up 22/1/18 @ 1715
3 days sure@kkauto.com
Resumy after repair.
Wang

Description of
 Accident/Loss: **REFER TO STATEMENT**
 Present Location: **DING AUTO PTE LTD (HQ)**

COST OF CLAIMS

	Amount
Parts	2,949.75
Miscellaneous Items	0.00
Labour	3,470.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	6,419.75
+ GST 7.00% (S\$)	449.38
Nett Amount (S\$)	6,869.13

This claim is handled by: **YOU JING FENG**

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

22/01/2018, 09:5

REPAIR DETAILS

Reference

Part Source: MRM-SG

Parts: 143

Labour: Repairer's

Print Code: Ding Auto Pte Ltd/SLB8096T/22/01/2018 09:59

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Version: 1.0 (Last Synchronised: 22 Jan 2018)

TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)

(Price-denominated Standard List)

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	de *215.00 F
2	1		*SPONGE FRONT	0.00	0.00	? *80.00 F ✓
3	1		*FRONT BUMPER REINF	0.00	0.00	? *150.00 F ✓
4	1		*FRONT REINF ARM RHS	0.00	0.00	X *45.00 F
5	1		*FRONT REINF ARM LHS	0.00	0.00	X *45.00 F
6	1		*SUPPORT PANEL	0.00	0.00	X *220.00 F
7	1		*HEAD LAMP BHS RHS	0.00	0.00	X *280.00 F
8	1		*RADIATOR GRILLE	0.00	0.00	X *220.00 F
9	1		*FRONT FENDER RHS LHS	0.00	0.00	RY *150.00 F
10	1		*FRONT FENDER LHS EMBLEM	0.00	0.00	RY *25.00 F
11	1		*BONNET	0.00	0.00	X *380.00 F
12	1		*BONNET HINGE LHS	0.00	0.00	X *45.00 F
13	1		*BONNET HINGE RHS	0.00	0.00	X *45.00 F
14	1		*HEAD LAMP LHS	0.00	0.00	? *280.00 F ✓
15	1		*FOG LAMP COVER	0.00	0.00	cut *65.00 F
16	1		*FOG LAMP	0.00	0.00	X *180.00 F
17	1		*AIR DUCT	0.00	0.00	X *85.00 F
18	1		*AIR RESONATOR	0.00	0.00	X *55.00 F

F=Franchise part.

Sub Total (S\$) 2,565.00
 + Margin on L,N Items 15.00% (S\$) 384.75
 Total Parts (S\$) 2,949.75

Ding Auto Pte Ltd/SLB8096T/22/01/2018 09:59. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Part \$ 815 + 10% = 896.50
 Labour \$ 620
 Total \$ 1516.5 - 20% / 45
 = \$ 1213.20

22/01/2018, C

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New	300 1,500.00
2	SPRAY PAINTING ON FRONT BUMPER ,REINF ,FENDER RHS /LHS , BONNET ,SUPPORT PANEL	New	300 1,200.00
3	CHECK WIRING AND ADJUST HEAD LAMP AIM	New	20 120.00
4	RUSH PROOFING	New	X 150.00
5	R&R CONDENSER AND REFILL AIRCON GAS	New	X 150.00
6	ALIGNMENT FRONT CHASSIS	New	X 350.00
Gross Labour Cost (\$\$)			3,470.00

Ding Auto Pte Ltd/SLB8096T/22/01/2018 09:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

6.20

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001283/T1QD3N2

Date: 25/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VPCP/17-002149	
Claimant Vehicle No :	SLB8096T	Insured Vehicle No :	SJY7903Z	
Date of Loss:	18/01/2018	Nature of Claim:	TP	Claim No: MSC/V/18-000129

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB8096T	Engine No:	1ZRY209783
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Chassis No:	MR053REH104538875
Reg. Date:	22/04/2016 (Man. Year: 2015)	Odometer:	133143 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,949.75	937.25	2,012.50	68.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	620.00	2,850.00	82.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,419.75	1,557.25	4,862.50	75.74
Approved Total (Overridden) (\$\$)		1,200.00		
(\$\$)	6,419.75	1,200.00	5,219.75	81.31
+ GST 7.00/7.00% (\$\$)	449.38	84.00	365.38	81.31
Nett Amount (\$\$)	6,869.13	1,284.00	5,585.13	81.31

INSPECTION

Date of Assignment:	22/01/2018 Present Location:	Ding Auto Pte Ltd (HQ)
Date Inspected:	22/01/2018 Inspected At:	Ding Auto Pte Ltd (HQ)
		Blk 10, #01-20, Sin Ming Industrial Estate Sector C
		Singapore 575645

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 May 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB8096T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	215.00 F	*215.00 F
2	1		*SPONGE FRONT	Deformed	80.00 F	*80.00 F
3	1		*FRONT BUMPER REINF	Bent	150.00 F	*150.00 F
4	1		*FRONT REINF ARM RHS	Not Necessary	45.00 F	*- F
5	1		*FRONT REINF ARM LHS	Not Necessary	45.00 F	*- F
6	1		*SUPPORT PANEL	Not Necessary	220.00 F	*- F
7	1		*HEAD LAMP RHS	Not Necessary	280.00 F	*- F
8	1		*RADIATOR GRILLE	Not Necessary	220.00 F	*- F
9	1		*FRONT FENDER RHS	Repair	150.00 F	*- F
10	1		*FRONT FENDER RHS EMBLEM	Necessary	25.00 F	*25.00 F
			FRONT FENDER LHS EMBLEM			
11	1		*BONNET	Not Necessary	380.00 F	*- F
12	1		*BONNET HINGE LHS	Not Necessary	45.00 F	*- F
13	1		*BONNET HINGE RHS	Not Necessary	45.00 F	*- F
14	1		*HEAD LAMP LHS	Cracked	280.00 F	*280.00 F
15	1		*FOG LAMP COVER	Cut	65.00 F	*65.00 F
16	1		*FOG LAMP	Not Necessary	180.00 F	*- F
17	1		*AIR DUCT	Not Necessary	85.00 F	*- F
18	1		*AIR RESONATOR	Not Necessary	55.00 F	*- F

F=Franchise part.

Sub Total (S\$)	2,565.00	815.00
+ Margin on L,N Items 15.00/15.00% (S\$)	384.75	122.25
Total Parts (S\$)	2,949.75	937.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New	1,500.00	300.00
2	SPRAY PAINTING ON FRONT BUMPER ,REINF ,FENDER RHS /LHS , BONNET ,SUPPORT PANEL	New	1,200.00	300.00
3	CHECK WIRING AND ADJUST HEAD LAMP AIM	New	120.00	20.00
4	RUSH PROOFING	New	150.00	-
5	R&R CONDENSER AND REFILL AIRCON GAS	New	150.00	-
6	ALIGNMENT FRONT CHASSIS	New	350.00	-
Gross Labour Cost (\$\$)			3,470.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >