

INS. CASE OWNER:

CL

cc 3, Asm 18001286, Kja3s2

LKK:

IDAC:

smART
269.9

SURVEYOR:

Kenneth

DOI:

ASSIGNMENT

19-01-18

Date / Time:

19-01-18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

CB7783G

Name of Insured:

Ren Quan Transport

Insured Tel No.:

HP:

Excess Sec II :SS

1,500.00

D.O.A.:

18-01-18

Claim No.:

S8m007G8

Policy No.:

P1656875

Make / Model:

Isuzu

Place of Accident:

Slip Rd at Canberra Way, Canberra
Link

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

W SHABRI

Driver Tel No.:

86524315

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHC5791G



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans-Cab



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

2/1/18
JOMSHC5791G - CC3/AXA 11023134/KHC262: 00A:10/11/18
RECEIVED 18 JUN 2018
CB7783G X

30/1/18

to obtain VID' mpe & DL & check validity of
ID's Vocational DL.
RECEIVED 24 AUG 2018

30/4/2018

5:30pm pickup

Spoke to OSD (Mr Lu) at 8652 4315, DID confirmed about the
accident statement. Informed VID about the TP claim. DID advise
the HCD issue and mention his employer deduct his \$700 H for
insurance premium

2/5/2018

10:25am pickup

Spoke to OI (owner of Ren Quan Transport) at 9665 9336. Informed
him about the TP claim. OI agree and aware the HCD issue.
Letter to OI

8/5/2018

Spoke to OI. OI request us, request those document from his
workshop

10/5/2018

15/5/2018

18-6-18

KW document from SCAuto
documents received from OI repair workshop. UPLOADED IN RUM
FOR MANDATE

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	3/2/18/2018 vic-ox 2/18
Documentation Check List:	Handler Typist
Notification ltr (if non-pickup)	☒ ☐
After call ltr to OI:	☒ ☐
Authorisation To Act:	☒ ☐
Release Voucher:	☒ ☐
Final Repair Bill:	☒ ☐
Car Rental Invoice:	☒ ☐
Towing Invoice	☒ ☐
LTA / GIA :	☒ ☐
Medical Bill:	☒ ☐
PIR:	☒ ☐
Mandate/Reject Instruction:	☒ ☐
LOD	☒ ☐
Payment Breakdown Form:	☐ ☐
Post-Repair Photos:	☐ ☐
Others:	☐ ☐

PRELIMINARY ADVICE

Date/Time:

26/1

Sent By:

JOM

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

1-6-18

Confirm with:

RTMKSCJW

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

8,399.50

Loss of Rental (LOR):

S\$

405.84

4

days) 101.46

Loss of Use (LOU):

S\$

200

(\$50 x 4

days)

Loss of Income (LOI):

S\$

200

(\$50 x 4

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

7.45

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

9,012.79

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Price 1:

S\$

9,012.79

Name 1:

TRANS-CAB AUTO SERVICES PTE LTD

Price 2: (Strike if N.A.)

S\$

X

Name 2:

X

Price 3: (Strike if N.A.)

S\$

X

Name 3:

X

CONFIDENTIAL

ASS. REC. BY:

REF: AM

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

03 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: PHC 5796Yr Regn: 12, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Peroduac.c. 1995Colour: White

A/C: _____

Insured / Std / NI / NA

Sp. Reading: 487902

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIABL15AUC 280911Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: Giti215/60R16R: ExlkenBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 18/1/18D.O.I. 19/1/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/1File pass to Corbure7/6/1861 Dmg & 78501 Car frame Tarnish C3+1 x 101.46 + 200)R (\$41,547.07/84%)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC3/ASM18001286/Kja3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 22-01-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	CB 7783G	Veh. Inspected	SHC 5791G	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M007E8	Excess (\$)	0.00	
Assign From		Assign Date	22/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/01/2018	Inspection Date	19/01/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5791G - AXA**AAD1801-212***Not Authorised
C1 Reg & 78501*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC5791G - CANDY
VF1ABL15AUC280911
RENAULT
LATITUDE
18.01.2018
AXA

PART**LIST**

1	1	BUMPER COVER REAR	\$	<i>B</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Not/lt</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>D11</i> 113.47 ✓
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Su</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Su</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>Su</i> 43.61 X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Su</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Su</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>Su</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	<i>B</i> 777.52 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1	BOOT REAR	\$	<i>B</i> 2,872.68 ✓
14	1	BOOT FINISHER	\$	<i>Su</i> 470.06 X
15	1	BOOT WHEATERSTRIP	\$	<i>D11</i> 323.05 ✓
16	1	BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35 ✓
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Su</i> 493.35 X
18	1	BOOT BADGE 'RENAULT'	\$	<i>R</i> 225.36 ✓
19	1	BOOT BADGE	\$	<i>R</i> 225.36 ✓
20	1	BOOT STRUT LH	\$	<i>Su</i> 276.08 X
21	1	BOOT STRUT RH	\$	<i>Su</i> 276.08 X
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84 X
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84 X
24	1	BOOT INNER TRIM	\$	<i>Su</i> 586.45 X
25	1	BOOT SWITCH	\$	<i>Su</i> 168.13 X
26	1	BOOT LOCK	\$	<i>R</i> 202.67 X
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40 X
28	2	LICENCE PLATE LAMP	\$	<i>CM</i> 50.52 ✓
29	2	BOOT RUBBER PLUG	\$	<i>Su</i> 221.81 X
30	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Su</i> 671.45 X
31	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13 X
32	1	WHEELARCH REAR LH	\$	<i>Su</i> 543.47 X
33	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Su</i> 671.45 X
34	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5791G - AXA**AAD1801-212**

35	1	WHEELARCH REAR RH	\$	543.47 X
36	1	TAILLAMP RH	\$	552.55 ✓
37	1	TAILLAMP PANEL RH	\$	986.70 X
38	1	TAILLAMP LH	\$	552.55 ✓
39	1	TAILLAMP PANEL LH	\$	986.70 X
40	1	OUTER PANEL REAR (End Panel)	\$	1,471.77 X
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	404.56 X
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	2,189.88 X
43	1	SPARE WHEEL PANEL TRIM	\$	612.21 X
44	1	EXHAUST REAR	\$	7,489.05 X
45	1	EXHAUST CAP REAR	\$	230.49 X

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Specical Nett

1	1SET	PARKING AID	\$	700.00 ✓
2	1SET	REAR BUMPER CLIP	\$	66.00 ✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00 ✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	10.00 X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	20.00 X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	10.00 X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	20.00 X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00 X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00 ✓
10	1	EXHAUST MOUNTING REAR	\$	17.82 X
11	1SET	BOOT FINISHER CLIP	\$	24.20 X
12	1	BOOT STICKER "Trans-cab"	\$	30.00 ✓
13	1	BOOT STICKER "6555-3333"	\$	30.00 ✓
14	1	BOOT INNER TRIM CLIP	\$	45.00
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00
17	1	FENDER INNER TRIM CLIP LH	\$	28.00
18	1	FENDER INNER TRIM CLIP LH	\$	28.00
19	1	TAILLAMP CLIP RH	\$	5.00
20	1	TAILLAMP CLIP LH	\$	5.00
21	2	REAR WINDSCREEN SELANT	\$	80.00
22	1	WINDSCREEN MOULDING	\$	100.00
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-212**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5791G - AXA

25	1	SPARE TYRE	\$	<i>Sn</i> 330.00 <i>X</i>
26	1	FENDER ADVERTISEMENT STICKER RR LH	\$	<i>nn</i> 300.00 <i>X</i>
27	1	FENDER ADVERTISEMENT STICKER RR RH	\$	<i>nn</i> 300.00 <i>X</i>
28	1	BOOT ADVERTISEMENT STICKER	\$	<i>nn</i> 300.00 <i>150sn</i>
29	1	BUMPER ADVERTISEMENT STICKER	\$	<i>nn</i> 200.00 <i>80sn</i>

TOTAL	\$	3,325.02
TOTAL PARTS	\$	35,607.07

Putty And Spray Painting Of The Affected Portion.	\$	5,600.00 <i>60cl</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	<i>50cl</i> 5,400.00 <i>60cl</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>3cl</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>6cl</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>6cl</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
Towing Fees	\$	<i>nn</i> 120.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-212**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5791G - AXATo check steering geometry and computer
wheel alignment

\$

220.00 X

To remove and replace corporate sticker

\$

330.00 *601***TOTAL \$ 13,790.00****Over All Total \$ 49,397.07****(PARTS BY PARTS)****Repair Days****15 Days***3 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts purchased subject to inspection
- Third party involvement in accident must be noted
- No illegal modifications
- Fully signed and stamped
- Is subject to the R.O. of the repairer

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M007E8
Our ref: CC3/ASM18001286/Kja3

Date: 25.01.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC 5791G


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19.01.2018 at the premises of M/s Trans-cab Auto Services Pte Ltd (Ang Mo Kio) and have the following to report:-

Workshop Estimate Amount	: S\$	49,397.07
Revised Estimate Amount	: S\$	7,850.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser



PROCEED DS

Type

🔗 Question

Message

MANDATE APPROVED

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M007E8
Our ref: CC3/ASM18001286/Kja3

Date: 25.01.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


SHC 5791G

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19.01.2018 at the premises of M/s Trans-cab Auto Services Pte Ltd (Ang Mo Kio) and have the following to report:-

Workshop Estimate Amount	: S\$	49,397.07
Revised Estimate Amount	: S\$	7,850.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Rear Portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 3.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	CB 7783G (Insd veh)	Model:	RENAULT
	SHC 5791G (TP veh)		LATITUDE 2.0L DCI AUTO
Date of Accident:	18/01/2018		D/AB 4DR

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$	52,854.86	
Final Repair Cost	:	\$	8,399.50	
Loss of Token Sum	:	\$	200.00	4 days at \$50.00 per day
Rental (if any)	:	\$	405.84	4 days
LTA / GIA Search Fee	:	\$	7.45	

Others: : \$

Final Settlement Sum : \$ 9,012.79

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks
PLEASE SEND THE CHEQUE PAYMENT TO TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST 63 SINGAPORE 569111

Payment Instruction: Payee's Breakdown			
1)	TRANS-CAB AUTO SERVICES PTE LTD	: \$	9,012.79

NUR SHAQILAH BTE ABDOL
WAHAB

27/08/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

SERVICE REQUESTS

MESSAGES

CLAIMS

<<

Service Request Details

Claim	S8M007E8
Reference	
CC3/ASM18001286/Kia3s2	Date
January 18, 2018	Request Date
January 23, 2018	Due Date
October 31, 2018	Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)	Type of Loss
Third Party Vehicle Damage	Services

Vehicle Information	
Incident Vehicle Registration #	SHC5791G
Service Address	TPVD RENAULT
Model	LATTITUDE 2.0
Primary Contact/Insured	
REN QUAN TRANSPORT BLK 356 YISHUN RING ROAD, 760356, Singapore 96659336	
Claim Handler	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	July 6, 2018
OID DL WP VL.pdf	Forms / Claim Documents	Driver's License / IDP	LKK AUTO CONSULTANTS PTE LTD (TP)	May 18, 2018
GIA CB7783G INSD.PDF	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	January 23, 2018
EMAIL ATTACHED ESTIMATE & GIA TP.msg	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	January 23, 2018
P1656875_RN_00036_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	LOH Cynthia	January 23, 2018
P1656875_CI_00036_0020_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	LOH Cynthia	January 23, 2018

SERVICE REQUESTS

MESSAGES

CLAIMS

Service Request Details

Claim	S8M007E8	Vehicle Information	
	Reference	Incident Vehicle	SHC5791G
	CC3/ASM18001286/Kia 	Registration #	Make Service Address
	January 18, 2018	Request Date	TPVD RENAULT
	January 23, 2018	Due Date	Model LATITUDE 2.0
	October 31, 2018	Vendor Name	Primary Contact/Insured
	LKK AUTO CONSULTANTS PTE LTD (TP)	Type of Loss	REN QUAN TRANSPORT BLK 356 YISHUN RING ROAD, 760356, Singapore 96659336
	Third Party Vehicle	Services	Claim Handler



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SHC5791G

Registration State

SINGAPORE

Mileage

487922

Purchase Date

mm/dd/yyyy

Registration Date *

12/11/2014

Age of Vehicle

3

CATEGORY

Manufacturing Year

POLICY INFORMAT...

ASSESSMENT INFO...

2014

CATEGORY

Driver Name

FNOL INFORMATI...

HOCK BENG NEO

CATEGORY

Make

POST SURVEY INF...

CATEGORY	Engine No	FNOL INFORMATI... 0
POLICY INFORMAT...		POST SURVEY INF ...
ASSESSMENT INFO...	M9R8839C002293	CATEGORY Driver License #
CATEGORY	Engine Capacity	FNOL INFORMATI...
POLICY INFORMAT...		POST SURVEY INF ...
ASSESSMENT INFO...	1995 cc	CATEGORY License Type
CATEGORY	Sum Insured	FNOL INFORMATI...
POLICY INFORMAT...		POST SURVEY INF ...
ASSESSMENT INFO...	0	CATEGORY License Issue Date
CATEGORY	Market Value	FNOL INFORMATI...
POLICY INFORMAT...		POST SURVEY INF ...
ASSESSMENT INFO...	0	CATEGORY License Expiration Date
		FNOL INFORMATI...
		POST SURVEY INF ...
CATEGORY	Address	

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Front left side

GITI 9mm

Rear left side

FALKEN 8mm

Front right side

GITI 9mm

Rear right side

FALKEN 8mm

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details				Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio		Parts & Labour	Miscellaneous	Summary	Parts			
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	
		1	1			BUMPER COVER REAR			Bent	1108.46		10		997.61	
		2	1			BUMPER LOWER REAR			Dented	768.84		10		691.96	
		3	1			BUMPER BRACKET CTR REAR			Damaged	113.47		10		102.12	
		4	1			BUMPER BRACKET SIDE RH REAR			Serviceable	0		10		0	
		5	1			BUMPER RETAINER RH REAR			Serviceable	0		10		0	
		6	1			BUMPER REFLECTOR RH			Serviceable	0		10		0	
		7	1			BUMPER BRACKET SIDE LH REAR			Serviceable	0		10		0	
		8	1			BUMPER RETAINER LH REAR			Serviceable	0		10		0	
		9	1			BUMPER REFLECTOR LH			Serviceable	0		10		0	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	 24	1			BOOT INNER TRIM			Serviceable	0		10	0	0
	 25	1			BOOT SWITCH			Serviceable	0		10	0	0
	 26	1			BOOT LOCK			Repair	0		10	0	0
	 27	1			BOOT LOCK CATCH			Repair	0		10	0	0
	 28	2			LICENCE PLATE LAMP			Cracked	25.26		10		45.47
	 29	2			BOOT RUBBER PLUG			Serviceable	0		10	0	0
	 30	1			FENDER PANEL INNER TRIM REAR LH			Serviceable	0		10	0	0
	 31	1			FENDER PANEL REAR LH			Repair	0		10	0	0
	 32	1			WHEELARCH REAR LH			Serviceable	0		10	0	0
	 33	1			FENDER PANEL INNER TRIM REAR RH			Serviceable	0		10	0	0
	 34	1			FENDER PANEL REAR RH			Repair	0		10	0	0
	 35	1			WHEELARCH REAR RH			Serviceable	0		10	0	0
	 36	1			TAILLAMP RH			Cracked	552.55		10		497.3
	 37	1			TAILLAMP PANEL RH			Repair	0		10	0	0
	 38	1			TAILLAMP LH			Cracked	552.55		10		497.3

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
☐	5		TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	60	0	0	Reviewing	
☐	6		TO REPAIR AND REALIGN REAR EXHAUST PIPE.	0	0	0	Reviewing	
☐	7		TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	0	0	0	Reviewing	
☐	8		TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	0	0	0	Reviewing	
☐	9		TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	0	0	0	Reviewing	
☐	10		TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	0	0	0	Reviewing	
☐	11		TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	0	0	0	Reviewing	
☐	12		TOWING FEES.	0	0	0	Reviewing	
☐	13		TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	0	0	0	Reviewing	
☐	14		TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	0	0	0	Reviewing	
☐	15		TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	0	0	0	Reviewing	

SERVICE REQUESTS

MESSAGES

CLAIMS

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR	Reviewing		3	
☐		2	SET PARKING AID	Reviewing	700	SHORTED	
☐		3	SET REAR BUMPER CLIP	Reviewing	66	NECESSARY	
☐		4	SET BUMPER BRACKET CTR CLIP	Reviewing	33	NECESSARY	
☐		5	SET BUMPER BRACKET SIDE CLIP RH RR	Reviewing	0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
 	14	BOOT STICKER "6555-3333"	Reviewing	30	NECESSARY	
 	15	BOOT INNER TRIM CLIP	Reviewing	0	NOT NECESSARY	
 	16	SET FENDER WHEELARCH REAR RH CLIP	Reviewing	0	NOT NECESSARY	
 	17	SET FENDER WHEELARCH REAR LH CLIP	Reviewing	0	NOT NECESSARY	
 	18	FENDER INNER TRIM CLIP LH	Reviewing	0	NOT NECESSARY	
 	19	FENDER INNER TRIM CLIP LH	Reviewing	0	NOT NECESSARY	
 	20	TAILLAMP CLIP RH	Reviewing	0	NOT NECESSARY	
 	21	TAILLAMP CLIP LH	Reviewing	0	NOT NECESSARY	
 	22	REAR WINDSCREEN SEALANT	Reviewing	0	NOT NECESSARY	

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary	Claim Amount	\$9,782.35	Claim Amount	\$9,782.35	

CATEGORY	ESTIMATE	REVISED AMOUNT
----------	----------	----------------

Labour	\$1,370.00	\$1,370.00
--------	------------	------------

Miscellaneous	\$1,155.00	\$1,155.00
---------------	------------	------------

Spare Parts	\$7,257.35	\$7,257.35
-------------	------------	------------

Submit for Review

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
------	-------	------	--------	--------	---------	--------

		1	Reviewing	7850		
FINAL LUMP SUM						