

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5791G - AXA**AAD1801-212***Not Authorised
C/By & 78502*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5791G - CANDY

VF1ABL15AUC280911

RENAULT

LATITUDE

18.01.2018

AXA**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>B</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Not in</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>D11</i> 113.47 ✓
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Su</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Su</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>Su</i> 43.61 X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Su</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Su</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>Su</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	<i>B</i> 777.52 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1	BOOT REAR	\$	<i>B</i> 2,872.68 ✓
14	1	BOOT FINISHER	\$	<i>Su</i> 470.06 X
15	1	BOOT WHEATERSTRIP	\$	<i>D11</i> 323.05 ✓
16	1	BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35 ✓
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Su</i> 493.35 X
18	1	BOOT BADGE 'RENAULT'	\$	<i>Re</i> 225.36 ✓
19	1	BOOT BADGE	\$	<i>Re</i> 225.36 ✓
20	1	BOOT STRUT LH	\$	<i>Su</i> 276.08 X
21	1	BOOT STRUT RH	\$	<i>Su</i> 276.08 X
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84 X
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84 X
24	1	BOOT INNER TRIM	\$	<i>Su</i> 586.45 X
25	1	BOOT SWITCH	\$	<i>Su</i> 168.13 X
26	1	BOOT LOCK	\$	<i>R</i> 202.67 X
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40 X
28	2	LICENCE PLATE LAMP	\$	<i>CM</i> 50.52 ✓
29	2	BOOT RUBBER PLUG	\$	<i>Su</i> 221.81 X
30	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Su</i> 671.45 X
31	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13 X
32	1	WHEELARCH REAR LH	\$	<i>Su</i> 543.47 X
33	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Su</i> 671.45 X
34	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-212**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5791G - AXA

35	1	WHEELARCH REAR RH	\$	<i>Sh</i> 543.47 <i>X</i>
36	1	TAILLAMP RH	\$	<i>ng</i> 552.55 <i>✓</i>
37	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70 <i>X</i>
38	1	TAILLAMP LH	\$	<i>ng</i> 552.55 <i>✓</i>
39	1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70 <i>X</i>
40	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77 <i>X</i>
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sh</i> 404.56 <i>X</i>
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i> 2,189.88 <i>X</i>
43	1	SPARE WHEEL PANEL TRIM	\$	<i>Sh</i> 612.21 <i>X</i>
44	1	EXHAUST REAR	\$	<i>R</i> 7,489.05 <i>X</i>
45	1	EXHAUST CAP REAR	\$	<i>R</i> 230.49 <i>X</i>

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Specical Nett

1	1SET	PARKING AID	\$	<i>Shom</i> 700.00 <i>✓</i>
2	1SET	REAR BUMPER CLIP	\$	<i>na</i> 66.00 <i>✓</i>
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 <i>✓</i>
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 <i>X</i>
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>na</i> 20.00 <i>X</i>
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 <i>X</i>
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>na</i> 20.00 <i>X</i>
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00 <i>X</i>
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 <i>✓</i>
10	1	EXHAUST MOUNTING REAR	\$	<i>Sh</i> 17.82 <i>X</i>
11	1SET	BOOT FINISHER CLIP	\$	<i>na</i> 24.20 <i>X</i>
12	1	BOOT STICKER "Trans-cab"	\$	<i>na</i> 30.00 <i>✓</i>
13	1	BOOT STICKER "6555-3333"	\$	<i>na</i> 30.00 <i>✓</i>
14	1	BOOT INNER TRIM CLIP	\$	<i>na</i> 45.00
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>na</i> 35.00
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>na</i> 35.00
17	1	FENDER INNER TRIM CLIP LH	\$	<i>na</i> 28.00
18	1	FENDER INNER TRIM CLIP LH	\$	<i>na</i> 28.00
19	1	TAILLAMP CLIP RH	\$	<i>na</i> 5.00
20	1	TAILLAMP CLIP LH	\$	<i>na</i> 5.00
21	2	REAR WINDSCREEN SELANT	\$	<i>na</i> 80.00
22	1	WINDSCREEN MOULDING	\$	<i>na</i> 100.00
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Sh</i> 385.00

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-212**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5791G - AXA

25	1	SPARE TYRE	\$	330.00 <i>X</i>
26	1	FENDER ADVERTISEMENT STICKER RR LH	\$	300.00 <i>X</i>
27	1	FENDER ADVERTISEMENT STICKER RR RH	\$	300.00 <i>X</i>
28	1	BOOT ADVERTISEMENT STICKER	\$	300.00 <i>150.00</i>
29	1	BUMPER ADVERTISEMENT STICKER	\$	200.00 <i>80.00</i>

TOTAL	\$	3,325.02
TOTAL PARTS	\$	35,607.07

Putty And Spray Painting Of The Affected Portion.	\$	5,600.00 <i>660.00</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	5,400.00 <i>500.00 660.00</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>30.00</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>60.00</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>60.00</i>
To repair and realign rear exhaust pipe.	\$	170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 <i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 <i>X</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 <i>X</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 <i>X</i>
Towing Fees	\$	120.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 <i>X</i>

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-212**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5791G - AXATo check steering geometry and computer
wheel alignment

\$

220.00 X

To remove and replace corporate sticker

\$

330.00 601

TOTAL \$ 13,790.00**Over All Total \$ 49,397.07****(PARTS BY PARTS)****Repair Days****15 Days****3 days**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplementary services are subject to final approval from LKK Auto Consultants

Acknowledged by Repairer

Signature:

Date: