

ASS. REC. BY:

REF:

CS/118001288/Kgd3n2

Special Instruction:

SUPERVISOR:

Kenneth

ASSIGNMENT (Office)

From (Person):

C. Meenachi

of

III

Date/Time: 22/01/18 @ 8:44am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 4983Y

Insured:

at Workshop m/s

Lim Tan Motor

Tel: 6452 0893

of Blk 176 Sin Ming Drive #03-09/10

Policy No: M492427

Claim No:

MC20173177

Sum Insured:

Excess:

NIL 600

Make of Veh:

(Client's Record)

D.O.A. 06/11/2017

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 22/01/2018

Person Contacted:

Richard

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBC 4983Y-X
23/1/18 @ 1.17pm	Revert to Meene via Meenmen.
23/1/18 @ 2.17pm	Meene informed C/A via Meenmen.
23/1/18 @ 3.31pm	Informed Richard C/A & EX: \$600 by email.
17/4/18 @ 8.26am	Confirm by email (Ref 8924, 26/1)

ASS. REC. BY:

REF: TII /

Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

GIA / PR Seen: _____

Est. Repairs: _____

Lum Sum: _____

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

23/1

File pass to Catherine

RECEIVED 27 APR 2018

Date/Time, File Pass to?

11/2/14

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) _____

☐

: Prel. Report

☐

: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

250

10

260

Veh No: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Colour: _____

Sp. Reading: _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: Yokohama

R: Maxxis

225/70R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. _____

L/Bal. _____

D.O.A. _____

Rear

R/Bal. _____

L/Bal. _____

D.O.I. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CS/III18001288/Kqd3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 22-01-2018		
		Code : III2		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		GBC 4983Y
Policy No. M492427		Coverage (\$)		0.00
Claim No.		Excess (\$)		600.00
Assign From MEENACHI		Assign Date		22/01/2018
2. Vehicle Particulars & Condition				
Make & Model		c.c		
Engine No.		Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 06/11/2017		Inspection Date		
Survey held at				
5a. Remarks				

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: C. Meenachi

Date: 23 Jan 2018

Preliminary Advice

Vehicle No	: GBC4983Y	Accident Date	: 06/11/2017
Make	: SSANGYONG ACTYON SPORTS	Policy No.	: M492427
Assignment Date	: 22/01/2018	Excess	: S\$600.00
Date of Inspection	: 22/01/2018	Est. Duration of Repair	: 4.00
Inspection At	: LIM TAN MOTOR PTE LTD (HQ) BLK 176 SIN MING DRIVE #03-09/10, SIN MING AUTO CARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,524.00
Revised Amount	:S\$	3,254.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,254.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	44,000.00
COE / PARF Rebate	:S\$	27,587.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,413.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : WE HAVE NOT AUTHORISE REPAIR.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jan 2018 15:37 Sendback Est	19 Jan 2018 15:46 S\$3,524.00	22 Jan 2018 08:44 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	URBAN REDEVELOPMENT AUTHORITY , Co. Reg. No.: T08GB0064C		
Vehicle Reg. No.:	GBC4983Y	Date of Loss:	06/11/2017 03:00 - :59
Claim Type:	OD	Policy/Cover Note No.:	M492427 (Comprehensive) Coverage: 20/09/2017 - 19/09/2018
		Excess:	
Repairer:	Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care, 575721 Sin Ming - Tel: 6452 0893		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by C. Meenachi - 6347 6073]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/01/2018]		
Driver/Custodian:	MOHD MOHAIMIN BIN ABU BAKAR (65 / Male), NRIC: S0055294A, Tel: +6591134627		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 23 January 2018 3:31 PM
To: richard@ltm.sg
Cc: SUR
Subject: VEHICLE GBC 4983Y (DOA: 06/11/2017)

Dear Richard,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **GBC 4983Y (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	19 Jan 2018 15:35	Clim Veh Model Changed	(205145) SSANGYONG ACTYON SPORTS 2.0 D/CAB 2.0 AT AIRBAG 2WD (A).		[R] Ang Wei Guang, Richard
2	19 Jan 2018 15:35	Clim Created	Reg No: GBC4983Y, Policy No: M492427, Acct Date: 2017/11/06, Claim Type: OD, Insurer: India International Insurance Pte Ltd (HQ), Workshop: Lim Tan Motor Pte Ltd (HQ), Created from SAS:MLTM17162889-01		[R] Ang Wei Guang, Richard
3	19 Jan 2018 15:46	Clim Submitted	3524.00.		[R] Ang Wei Guang, Richard
4	22 Jan 2018 08:44	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[I] Gabriel Wee
5	22 Jan 2018 08:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/31		[I] Gabriel Wee
6	22 Jan 2018 08:44	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.		[I] Gabriel Wee
7	22 Jan 2018 10:27	Assignment 1st Accessed			[A] Nivitha Govindasamy
8	22 Jan 2018 11:46	Clim Registration Modified	Excess: -> 600.00.		[I] C. Meenachi
9	23 Jan 2018 10:13	Adj Adjuster Assigned	[None] -> KENNETH KONG		[A] Nivitha Govindasamy
10	23 Jan 2018 13:12	Adj Rpt Initiated			[A] SHIAU CHAN
11	23 Jan 2018 13:14	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/31		[A] SHIAU CHAN
12	23 Jan 2018 13:16	Adj Mandate Request	Cur.Reg:3254.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT A UTHORISE REPAIR.		[A] SHIAU CHAN
13	23 Jan 2018 14:12	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/31. Mandate Remarks: Excess \$600.00		[I] C. Meenachi
14	23 Jan 2018 14:12	Adj Mandate Set	Approved:3254.00:Excess \$600.00		[I] C. Meenachi

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1700346	19/01/2018 15:35	Motor	Lim Tan Motor Pte Ltd (HQ)	Lim Tan Motor Pte Ltd (HQ)	GBC4983Y		xx.xx
1702876	23/01/2018 13:12	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBC4983Y		10.70

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type

Statutory Board

Owner ID

0064C

Vehicle Details

Vehicle No.

GBC4983Y

Vehicle to be Exported

Yes

Intended De-registration Date

11 Dec 2017

Vehicle Make

SSANGYONG

Vehicle Model

ACTYON SPORTS D/CAB 2.0 6AT 2WD 4DR D/AB

Primary Colour

White

Manufacturing Year

2012

Engine No.

67196022516120

Chassis No.

KPADA1ETSCP139735

Maximum Power Output

-

Open Market Value

\$19,192.00

Original Registration Date

20 Sep 2012

First Registration Date

20 Sep 2012

Transfer Count

0

Actual ARF Paid

\$19,192.00

Intended PARF Rebate Details

PARF Eligibility

No

PARF Eligibility Expiry Date

-

PARF Rebate Amount

\$0.00

Intended COE Rebate Details

COE Expiry Date

19 Sep 2022

COE Category

C - Goods Vehicle & Bus

COE Period(Years)

10

QP Paid

\$57,809.00

COE Rebate Amount

\$27,587.00

Total Rebate Amount

\$27,587.00

The information contained herein is correct as at 11 Dec 2017

OK



Lim Tan Motor Pte Ltd

Block 176 Sin Ming Drive # 03-09/10/06 Sin Ming Autocare Singapore 575721

Tel : 65-64520893 Fax : 65-64589127 Email : sales@ltm.sg

Website : www.ltm.sg

Co.Reg No. : 199307277D GST Reg No. : M2-0119086-0

Survey By _____

INSURER: India International Insurance Pte Ltd (HQ)

Date / Time 22 JAN 2013

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	M492427	Date of Loss:	06/11/2017
Vehicle Reg. No.:	GBC4983Y	Driveable?	
Driver Age/Info:	65 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	URBAN REDEVELOPMENT AUTHORITY		
Driver:	MOHD MOHAIMIN BIN ABU BAKAR		

Make/Model:	SSANGYONG ACTYON SPORTS, 2.0 D/CAB 2.0 AT AIRBAG 2WD (A)	Vehicle Reg. Date:	20/09/2012
Vehicle Colour:	WHITE	Chassis No:	KPADA1ETSCP139735
Engine No:	67196022516120		
Odometer:	93419 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	14 days		

Not Authored
6/11/17
Presumy After Paint
Rec n/s *fax: 62564315*

Description of Accident/Loss

ON THE ABOVE DATE, TIME AND LOCATION, I WAS DRIVING MY COMPANY VEHICLE, GBC4983Y AND WAS DRIVING INSIDE ALONG CHUA CHU KANG AVE 3. UPON REACHING NEAR BLK 473, I THEN REALISED THAT THE ROAD WAS A DEAD END. AS THE ROAD WAS NARROW, I THEN SLOWLY REVERSE MY VEHICLE AND TRY TO DO A 3-POINT TURN BUT IT WAS UNSUCCESSFUL. THEREFORE, I CONTINUE TO REVERSE TOWARDS TO A COVER DROP OFF POINT. WHILE REVERSING AND TURNING INTO THE DROP-OFF POINT AREA, MY VEHICLE ACCIDENTALLY COLLIDED ONTO A PILLAR WHICH RESULTED DAMAGES TO MY VEHICLE REAR PORTION. THERE WASN'T ANY VISIBLE DAMAGES FOUND ON THE PILLAR ITSELF. THAT'S ALL.

Present Location: LIM TAN MOTOR PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	2,384.00
Miscellaneous Items	10.00
Labour	530.00
Paintwork Labour	600.00
Towing	0.00
Gross Total (S\$)	3,524.00
+ GST 7.00% (S\$)	246.68
Nett Amount (S\$)	3,770.68

This claim is handled by: ANG WEI GUANG, RICHARD

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 19 Jan 2018)**Parts:** M1-SUV SSANGYONG ACTYON SPORTS 2.0 D/CAB 2.0 AT AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Lim Tan Motor Pte Ltd/GBC4983Y/19/01/2018 15:46**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	10.00	0.00	<i>B</i> *650.00 FL —
2	1		*TAILGATE	10.00	0.00	<i>B</i> *1,450.00 FL —
3	1		*TAILGATE EMBLEM	10.00	0.00	<i>m</i> *84.00 FL —
4	1		*TAILGATE ACTYON SPORTS EMBLEM	10.00	0.00	<i>m</i> *65.00 FL —
5	1		*TAILGATE SSANGYONG EMBLEM	10.00	0.00	<i>m</i> *65.00 FL —
6	2		*REAR BUMPER RETAINER	10.00	0.00	<i>D.Y</i> *96.00 FL —
7	1		*REAR BUMPER REVERSE SENSOR	0	0.00	<i>R</i> *200.00 FS —
8	1		*70KM/H STICKER	0	0.00	<i>Mc</i> *15.00 FS —

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	2,625.00
- List Item Discount on L Items (\$\$)	241.00
Total Parts (\$\$)	2,384.00

Lim Tan Motor Pte Ltd/GBC4983Y/19/01/2018 15:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO PUTTY AND SPRAY PAINTING.	New	400 600.00
<u>Labour Items</u>			
2	TO TRANSFER TAILGATE FITTINGS.	New	60 80.00
3	LABOUR CHARGES.	New	400 450.00
Gross Labour Cost (S\$)			1,130.00

Lim Tan Motor Pte Ltd/GBC4983Y/19/01/2018 15:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



Lim Tan Motor Pte Ltd

Block 176 Sin Ming Drive # 03-09/10/06 Sin Ming Autocare Singapore 575721

Tel : 65-64520893 Fax : 65-64589127 Email : sales@ltm.sg

Website : www.ltm.sg

Co.Reg No. : 199307277D GST Reg No. : M2-0119086-0

Survey By

INSURER:

India International Insurance Pte Ltd (HQ)

Date / Time

22 JAN 2013

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	M492427	Date of Loss:	06/11/2017
Vehicle Reg. No.:	GBC4983Y	Driveable?	
Driver Age/Info:	65 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	URBAN REDEVELOPMENT AUTHORITY		
Driver:	MOHD MOHAIMIN BIN ABU BAKAR		

Make/Model:	SSANGYONG ACTYON SPORTS, 2.0 D/CAB 2.0 AT AIRBAG 2WD (A)	Vehicle Reg. Date:	20/09/2012
Vehicle Colour:	WHITE	Chassis No:	KPADA1ETSCP139735
Engine No:	67196022516120		
Odometer:	93419 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4 days		

Not Notified
1/2/18 Presum. After Paint
Rec n/s *fax: 62564315*

Description of Accident/Loss

ON THE ABOVE DATE, TIME AND LOCATION, I WAS DRIVING MY COMPANY VEHICLE, GBC4983Y AND WAS DRIVING INSIDE ALONG CHUA CHU KANG AVE 3. UPON REACHING NEAR BLK 473, I THEN REALISED THAT THE ROAD WAS A DEAD END. AS THE ROAD WAS NARROW, I THEN SLOWLY REVERSE MY VEHICLE AND TRY TO DO A 3-POINT TURN BUT IT WAS UNSUCCESSFUL. THEREFORE, I CONTINUE TO REVERSE TOWARDS TO A COVER DROP OFF POINT. WHILE REVERSING AND TURNING INTO THE DROP-OFF POINT AREA, MY VEHICLE ACCIDENTALLY COLLIDED ONTO A PILLAR WHICH RESULTED DAMAGES TO MY VEHICLE REAR PORTION. THERE WASN'T ANY VISIBLE DAMAGES FOUND ON THE PILLAR ITSELF. THAT'S ALL.

Present Location: LIM TAN MOTOR PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	2,384.00
Miscellaneous Items	10.00
Labour	530.00
Paintwork Labour	600.00
Towing	0.00
Gross Total (\$\$)	3,524.00
+ GST 7.00% (\$\$)	246.68
Nett Amount (\$\$)	3,770.68

This claim is handled by: ANG WEI GUANG, RICHARD

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO PUTTY AND SPRAY PAINTING.	New	600.00
<u>Labour Items</u>			
2	TO TRANSFER TAILGATE FITTINGS.	New	80.00
3	LABOUR CHARGES.	New	450.00
Gross Labour Cost (S\$)			1,130.00

Lim Tan Motor Pte Ltd/GBC4983Y/19/01/2018 15:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Jan 2018)

Parts: M1-SUV SSANGYONG ACTYON SPORTS 2.0 D/CAB 2.0 AT AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Lim Tan Motor Pte Ltd/GBC4983Y/19/01/2018 15:46

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	10.00	0.00	<i>By</i> *650.00 FL —
2	1		*TAILGATE	10.00	0.00	<i>By</i> *1,450.00 FL —
3	1		*TAILGATE EMBLEM	10.00	0.00	<i>m</i> *84.00 FL —
4	1		*TAILGATE ACTYON SPORTS EMBLEM	10.00	0.00	<i>m</i> *65.00 FL —
5	1		*TAILGATE SSANGYONG EMBLEM	10.00	0.00	<i>m</i> *65.00 FL —
6	2		*REAR BUMPER RETAINER	10.00	0.00	<i>D.Y</i> *96.00 FL —
	1		*REAR BUMPER REVERSE SENSOR	0	0.00	<i>RJ</i> *200.00 FS —
8	1		*70KM/H STICKER	0	0.00	<i>Mc</i> *15.00 FS —

F=Franchise part, S=SpecNott, L=ListItemDisc.

Sub Total (S\$)

2,625.00

- List Item Discount on L Items (S\$)

241.00

Total Parts (S\$)

2,384.00

Lim Tan Motor Pte Ltd/GBC4983Y/19/01/2018 15:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Parts \$ 2410.00

-10% 241.00

\$ 2169.00

SN \$ 215.00

Misc 10.00

Lab \$ 860.00

\$ 3254.00

-20% 650.80 2603.20

\$ 2603.20

LS \$ 2600.00

X \$600

APPROVED

16 APR 2018

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III18001288/KQD3N2

Date: 02/05/2018

REFERENCE

Insured/Claimant: URBAN REDEVELOPMENT AUTHORITY

Policy No: M492427

Date of Loss: 06/11/2017

Nature of Claim: OD

Claim No: MC20173177

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC4983Y
Make & Model: SSANGYONG ACTYON SPORTS, 2.0 D/CAB 2.0 AT AIRBAG 2WD (A) Engine No: 67196022516120
Reg. Date: 20/09/2012 (Man. Year: 2012) Chassis No: KPADA1ETSCP139735
Colour: White Odometer: 94169 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$44,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/70 R16 Rear Tyre Size: 225/70 R16
Front Left Side: Yokohama 9 mm Rear Left Side: Maxxis 7 mm
Front Right Side: Yokohama 9 mm Rear Right Side: Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,384.00	2,384.00	0.00	0.00
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	530.00	460.00	70.00	13.21
Paintwork Labour	600.00	400.00	200.00	33.33
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,524.00	3,254.00	270.00	7.66
Approved Total (Overridden) (S\$)		2,600.00		
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	3,524.00	2,000.00	1,524.00	43.25
+ GST 7.00/7.00% (S\$)	246.68	140.00	106.68	43.25
Nett Amount (S\$)	3,770.68	2,140.00	1,630.68	43.25

INSPECTION

Date of Assignment: 22/01/2018 Present Location:

Date Inspected: 22/01/2018 Inspected At:

Lim Tan Motor Pte Ltd (HQ)
Lim Tan Motor Pte Ltd (HQ)
Blk 176 Sin Ming Drive #03-09/10, Sin
Ming Auto Care
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 May 2018)
Parts:	M1-SUV	SSANGYONG ACTYON SPORTS 2.0 D/CAB 2.0 AT AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC4983Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	650.00 FL	*650.00 FL
2	1		*TAILGATE	Bent	1,450.00 FL	*1,450.00 FL
3	1		*TAILGATE EMBLEM	Necessary	84.00 FL	*84.00 FL
4	1		*TAILGATE ACTYON SPORTS EMBLEM	Necessary	65.00 FL	*65.00 FL
5	1		*TAILGATE SSANGYONG EMBLEM	Necessary	65.00 FL	*65.00 FL
6	2		*REAR BUMPER RETAINER	Distorted	96.00 FL	*96.00 FL
7	1		*REAR BUMPER REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
8	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	2,625.00	2,625.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	241.00	241.00
Total Parts (\$\$)	2,384.00	2,384.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO PUTTY AND SPRAY PAINTING.	New	600.00	400.00
<u>Labour Items</u>				
2	TO TRANSFER TAILGATE FITTINGS.	New	80.00	60.00
3	LABOUR CHARGES.	New	450.00	400.00
Gross Labour Cost (S\$)			1,130.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >