

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05716

Vehicle Insured : SLK3415S
Accident Date : 18-Jan-2018

Date : 19-Jan-2018

Our Ref : 218020 (AIG) / CHAN

PAGE : 1

NAARAYANAN S/O SOMA RAAMASAMY
11 ROSEWOOD DRIVE
#04-23
Singapore 737939

*Not Authorized
1/19/8?
Resurvey After Paint*

ESTIMATED COST OF REPAIR FOR BMW520I SKG6890R

- =====
- | | |
|--------|------------------------------|
| 1 pc | Rear n/s door |
| 1 pc | N/s rocker garnish |
| 12 pcs | N/s rocker garnish clip |
| 1 pc | Rear n/s fender |
| 1 pc | Rear bumper fascia |
| 1 pc | Rear n/s sport rim |
| 1 pc | Rear n/s shock absorber |
| 1 pc | Rear n/s knuckle arm |
| 1 pc | Rear n/s knuckle bearing hup |
| 1 pc | Rear n/s wheel bearing |
| 1 pc | Rear n/s top arm |
| 1 pc | Rear n/s lower arm |
| 1 pc | Rear n/s trust arm |

R	1,604.55	X
nd	387.05	✓
nd	45.60	✓
R	1,625.05	X
Build	1,302.60	✓
nd	684.10	✓
	481.90	?
B	1,210.75	✓
B	165.75	✓
nd	173.00	✓
	466.00	?
	919.30	?
	396.20	?

	9,461.85	
Less 10% :	946.19	

8,515.66

nd 80.00 X

To apply undersealing

To dismantle and lower rear undercarriage

250.00 ?

To check and adjust wheel alignment

65.00 *601*

To putty and spray replaced parts

1,200.00 *8001*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Con't Page 2 ...

Acknowledged by Repairer

Signature:

Date: -

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLK3415S

Page : 2

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

600
1,000.00

To transfer rear n/s sport rim

50.00 *20*

Total : -----
S\$11,160.66
=====

Singapore Dollars Eleven Thousand One Hundred
and Sixty and Cents Sixty Six Only