

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

22 JAN 2018

Estimate No. : b1 45591

Page No. : 1 of 2

Date Estimated : 22/01/2018

Prepared By : Han Kwan Yong

- ESTIMATE REPAIR FOR -Tan Chee Hua Clemence (Chen ZhiHua)
50 Lorong 40 Geylang
#02-16

Singapore 398074

- ACCOUNT - 40000Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLG8229B	G753470	14/10/2016	420iA GC	0

DESCRIPTIONVALUETo replace rear bumper & attachments including to knock out
dented area caused by the accident

850 1,275.00

To respray rear bumper

934 1,038.00

To replace bootlid smart opener top and
bottom sensor lines including program and conduct checks for
proper function.

561? 661.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct checks for
proper function.

150 177.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries.

? 80.00

Total Labour 1: **3,408.00**DESCRIPTIONQTYPRICVALUE

RR BUMPER CARRIER ECE

1 422.30

? 422.30

REINFORCEMENT BUMPER REAR BOTTOM

1 65.50

? 65.50

RR BUMPER TRIM STRIP (LUXURY LINE)

1 146.30

aut 146.30

REAR BUMPER CENTRE GUIDE

1 54.05

? 54.05

RR LH RETAINING STRIP FOR TRIM STRI

1 12.95

? 12.95

RR RH RETAINING STRIP FOR TRIM STRI

1 12.95

? 12.95

REAR BUMPER PANEL PRIMED (ZWEIF/LIN

1 1,105.65

de 1,105.65

RR BUMPER LH SIDE GUIDE

1 46.90

? 46.90

REAR PDC HOLDER SET (PDC & PMA)

1 62.50

? 62.50

REAR SILENCER HEAT SHIELD

1 32.45

? 32.45

SENSOR WIRE FOR SMART OPENER TOP

1 42.10

? 42.10

SENSOR WIRE FOR SMART OPENER BOTTOM

1 40.50

? 40.50

DECOUPLING RING PDC TORQUE CONVERTE

2 4.95

nei 9.90

PDC SENSOR MELBOURNEROT (A75

2 368.80

? 737.60

(DG) ADHESIVE SET K6

1 53.05

nei 53.05

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45591
Date Estimated : 22/01/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLG8229B	G753470	14/10/2016	420iA GC	0

Total Parts : 2,844.70

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 5/2/18 @ 1055 Claim No. _____
Date&Time 5/2/18 @ 1055 Excess S\$ _____
Surveyor's Name Taufik Sign Taufik
Surveyor's Tel 97495441 Authorised Yes / No _____
Authorised Date WP Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____
Surveyor's E-mail taufik@lkkauto.com
No. of Working Days Recommend 3 days

Labour 1	:	3,408.00
Parts	:	2,844.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	437.69
Grand Total	:	6,690.39

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **