

# MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

|                                                    |                     |          |                   |
|----------------------------------------------------|---------------------|----------|-------------------|
| TO                                                 | : AXA INSURANCE     | DATE     | : 22/01/2018      |
| ATTENTION                                          | : MOTOR CLAIMS DEPT | JOB TYPE | : T/P CLAIM       |
| ESTIMATE REPORT :                                  |                     |          |                   |
| <u>VEHICLE DETAILS</u>                             |                     |          |                   |
| VEHICLE NO                                         | : SLG4896B          | Vic      |                   |
| MODEL                                              | : VOLKSWAGEN GOLF   |          |                   |
| CHASSIS NO                                         |                     |          | WVWZZ21K29WS09837 |
| <u>ACCIDENT DETAILS</u>                            |                     | DATE     | : 18-01-2018      |
|                                                    |                     | TIME     | : 08:00 HRS       |
| THIRD PARTY REQUESTOR / CONTACT : MS HONG / SHARON |                     |          |                   |

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                           | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|---------------------------------------|-----|-----------------|------------------|
| 1   | REAR BUMPER <i>2nd</i>                | 1   | \$ 1,250.00     | \$ 1,250.00      |
| 2   | REAR BUMPER BEAM <i>2nd</i>           | 1   | \$ 230.00       | \$ 230.00        |
| 3   | REAR BUMPER RETAINER LH <i>me</i>     | 1   | \$ 89.00        | \$ 89.00         |
| 4   | REAR BUMPER REINFORCEMENT <i>Best</i> | 1   | \$ 560.00       | \$ 560.00        |
| 5   | TAIL LAMP LH <i>2nd</i>               | 1   | \$ 485.00       | \$ 485.00        |
| 6   | AIR VENT LH <i>new 2nd</i>            | 1   | \$ 189.00       | \$ 189.00        |
| 7   | REAR END PANEL <i>2nd</i>             | 1   | \$ 730.00       | \$ 730.00        |
| 8   | REAR END PANEL TOP GARNISH <i>2nd</i> | 1   | \$ 210.00       | \$ 210.00        |
| 9   | EXHAUST PIPE <i>me</i>                | 1   | \$ 1,320.00     | \$ 1,320.00      |

2440

TOTAL PRICE \$ 5,063.00

2196

LESS 0% \$ -

SUB TOTAL PRICE \$ 5,063.00

## SPECIAL NETT ITEMS

| S/N | DESCRIPTION                                      | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|--------------------------------------------------|-----|-------------|--------------|
| 1   | REAR BUMPER CLIPS <i>me</i>                      | 1   | \$ 20.00    | \$ 20.00     |
| 2   | REAR BUMPER LOWER LID <i>2nd</i>                 | 1   | \$ 550.00   | \$ 550.00    |
| 3   | TAIL LAMP CLIPS (SET) <i>me</i>                  | 1   | \$ 20.00    | \$ 20.00     |
| 4   | REAR END PANEL INSULATION SEAL <i>new</i>        | 1   | \$ 180.00   | \$ 180.00    |
| 5   | REAR END PANEL TOP GARNISH CLIPS(SET) <i>2nd</i> | 1   | \$ 20.00    | \$ 20.00     |

|   |                                   |   |           |                                 |
|---|-----------------------------------|---|-----------|---------------------------------|
| 6 | REVERSE SENSOR (4 PCS) <i>R2d</i> | 1 | \$ 220.00 | \$ <del>220.00</del> <i>200</i> |
|---|-----------------------------------|---|-----------|---------------------------------|

780

TOTAL \$ 1,010.00

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

|   |                                                                 |                                   |  |
|---|-----------------------------------------------------------------|-----------------------------------|--|
| 1 | PANEL BEATING, REMOVING AND REPLACING PARTS                     | \$ <del>1,000.00</del> <i>300</i> |  |
| 2 | SPRAY PAINTING TO AFFECTED AREA                                 | \$ <del>1,000.00</del> <i>400</i> |  |
| 3 | WIRING CHECK                                                    | \$ <del>250.00</del> <i>30</i>    |  |
| 4 | TUFF COAT                                                       | \$ <del>250.00</del> <i>40</i>    |  |
| 5 | REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR                | \$ <del>180.00</del> <i>x 30</i>  |  |
| 6 | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING            | \$ <del>60.00</del> <i>40</i>     |  |
| 7 | CONDUCT WATER LEAKAGE TEST                                      | \$ 150.00 <i>x</i>                |  |
| 8 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET | \$ 180.00 <i>x</i>                |  |

TOTAL

\$3,070.00

840

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 6,073.00  
TOTAL LABOUR COST : \$ 3,070.00  
TOTAL REPAIR COST : \$ 9,143.00

**APPROVED DETAILS**

EXCESS :  
NO. OF WORKING DAYS :  
RE-SURVEY :  
PART BY PART OR LUMP SUM :  
DATE & TIME OF SURVEY :  
SURVEYED BY :  
CONTACT NUMBER :  
FAX NUMBER :

*Adrian L*  
*2/s 23/01/18*  
*03 days*

*total: 3816*  
*2/s: 31c*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: