

ASS. REC. BY

REF: CS/III18001332/Kgd3 n2

Meenimen

Kenneth
C. Meenachi

ASSIGNMENT (Office)

III

22/01/2018 @ 8.44am

Estimated Cost

21111

TP+WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 4983Y

Insured

at Workshop no:

Lim Tan Motor

Tel:

6452 0893

at BIK 176, Sin Ming Drive #03-09/10

Policy No:

M 48 6583

Claim No:

MC20173204

Sum Insured

Excess

600

Make of Veh:

D.O.A

05/05/2017

(Client's Record)

CA / REV

REP. / REV 24 HRS

R.O.D. Information

Date/Time

9.15am @ 22/1/18

Person Contacted

Richard

Vehicle IN/OUT

Date/Time

Action/Inspection

✓

Estimate

GBC 4983Y - CS/III18001288/Kgd3

- D.O.A: 06/11/2017

23/1/18 @ 1.26pm revert to Meena via Meenimen.

23/1/18 @ 2.27pm Meena informed C/A via Meenimen.

23/1/18 @ 3.31pm Informed Richard C/A & ET: \$600 by email.

1746 L / Day @ 17500 Confirmed by email (Red \$742, 30%)

ASS. REC. BY:

REF:

T4 /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / ☒ REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

23/1 File pass to G+H

RECEIVED 27 APR 2018

Veh No:

GBC 49834

Yr Regn:

09, 12

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Pick Up

Make:

Isang Yang

c.c.

1998

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

94169

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KPADA 1ET SCP139735

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: ☒ Nil / ☐ PS/Rim / ☐ STD A/Rim or

Tyre Size:

F: YOKO

225/70R16

R: Magna's

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

7

mm

L/Bal.

9

mm

L/Bal.

7

mm

D.O.A.

5/5/17

D.O.I.

22/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1) 23/4 to 23/5

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

250

10

260

Report Format:

MER-00

Lump Sum / I.B.1: (\$

1750



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS/III18001332/Kqd3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 23-01-2018



Code : III2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBC 4983Y
Policy No.	M846583	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (C.MEENACHI)	Assign Date	23/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/05/2017	Inspection Date	22/01/2018
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: C. Meenachi

Date: 23 Jan 2018

Preliminary Advice

Vehicle No	: GBC4983Y	Accident Date	: 05/05/2017
Make	: SSANGYONG ACTYON SPORTS	Policy No.	: M486583
Assignment Date	: 22/01/2018	Excess	: S\$0.00
Date of Inspection	: 22/01/2018	Est. Duration of Repair	: 5.00
Inspection At	: LIM TAN MOTOR PTE LTD (HQ) BLK 176 SIN MING DRIVE #03-09/10, SIN MING AUTO CARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,492.00
Revised Amount	:S\$	2,242.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,242.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	44,000.00
COE / PARF Rebate	:S\$	27,587.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,413.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : WE HAVE NOT AUTHORISE REPAIR.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jan 2018 15:53 Sendback Est	19 Jan 2018 15:56 \$2,492.00	22 Jan 2018 08:43 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	URBAN REDEVELOPMENT AUTHORITY, Co. Reg. No.: T08GB0064C		
Vehicle Reg. No.:	GBC4983Y	Date of Loss:	05/05/2017 12:00 - :59
Claim Type:	OD	Policy/Cover Note No.:	M486583 (Comprehensive)
		Excess:	
Repairer:	Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care, 575721 Sin Ming - Tel: 6452 0893		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by C. Meenachi - 6347 6073]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/01/2018]		
Driver/Custodian:	FARALI KHAN BABU KHAN (63 / Male), NRIC: S0057851G, Tel: +6592276317		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 23 January 2018 3:31 PM
To: 'richard@itm.sg'
Subject: VEHICLE GBC 4983Y (DOA: 05/05/2017)

Dear Richard,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **GBC 4983Y (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	19 Jan 2018 15:52	Clim Veh Model Changed	(205145) SSANGYONG ACTYON SPORTS 2.0 D/CAB 2.0 AT AIRBAG 2WD (A).	[R] Ang Wei Guang, Richard
2	19 Jan 2018 15:52	Clim Created	Reg No: GBC4983Y, Policy No: M486583, Acct Date: 2017/05/05, Claim Type: OD, Insurer: India International Insurance Pte Ltd (HQ), Workshop: Lim Tan Motor Pte Ltd (HQ). Created from SAS:MLTM17165511-01	[R] Ang Wei Guang, Richard
3	19 Jan 2018 15:56	Clim Submitted	2492.00.	[R] Ang Wei Guang, Richard
4	22 Jan 2018 08:43	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[I] Gabriel Wee
5	22 Jan 2018 08:43	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/31	[I] Gabriel Wee
6	22 Jan 2018 08:43	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[I] Gabriel Wee
7	22 Jan 2018 10:28	Assignment 1st Accessed		[A] Nivitha Govindasamy
8	23 Jan 2018 10:11	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Nivitha Govindasamy
9	23 Jan 2018 13:24	Adj Rpt Initiated		[A] SHIAU CHAN
10	23 Jan 2018 13:25	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/31	[A] SHIAU CHAN
11	23 Jan 2018 13:26	Adj Mandate Request	Cur.Req:2242.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT A UTHORISE REPAIR.	[A] SHIAU CHAN
12	23 Jan 2018 14:22	Clim Registration Modified	Excess: -> 600.00.	[I] C. Meenachi
13	23 Jan 2018 14:22	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/31	[I] C. Meenachi
14	23 Jan 2018 14:22	Adj Mandate Set	Approved:2242.00.	[I] C. Meenachi

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1700389	19/01/2018 15:52	Motor	Lim Tan Motor Pte Ltd (HQ)	Lim Tan Motor Pte Ltd (HQ)	GBC4983Y		xx.xx
1702892	23/01/2018 13:24	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBC4983Y		10.70

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Statutory Board
Owner ID	0064C

Vehicle Details

Vehicle No.	GBC4983Y
Vehicle to be Exported	Yes
Intended De-registration Date	11 Dec 2017
Vehicle Make	SSANGYONG
Vehicle Model	ACTYON SPORTS D/CAB 2.0 6AT 2WD 4DR D/AB
Primary Colour	White
Manufacturing Year	2012
Engine No.	67196022516120
Chassis No.	KPADA1ETSCP139735
Maximum Power Output	-
Open Market Value	\$19,192.00
Original Registration Date	20 Sep 2012
First Registration Date	20 Sep 2012
Transfer Count	0
Actual ARF Paid	\$19,192.00

Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	19 Sep 2022
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
QP Paid	\$57,809.00
COE Rebate Amount	\$27,587.00
Total Rebate Amount	\$27,587.00

The information contained herein is correct as at 11 Dec 2017

OK



Lim Tan Motor Pte Ltd

Block 176 Sin Ming Drive # 03-09/10/06 Sin Ming Autocare Singapore 575721

Tel : 65-64520893 Fax : 65-64589127 Email : sales@ltm.sg

Website : www.ltm.sg

Co.Reg No. : 199307277D GST Reg No. : M2-0119086-0

Survey By

Date / Time 22 JAN 2013

INSURER: India International Insurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	M486583	Date of Loss:	05/05/2017
Vehicle Reg. No.:	GBC4983Y	Driveable?	
Driver Age/Info:	63 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	URBAN REDEVELOPMENT AUTHORITY		
Driver:	FARALI KHAN BABU KHAN		

Make/Model:	SSANGYONG ACTYON SPORTS, 2.0 D/CAB 2.0 AT AIRBAG 2WD (A)	Vehicle Reg. Date:	20/09/2012
Vehicle Colour:	WHITE	Chassis No:	KPADA1ETSCP139735
Engine No:	67196022516120		
Odometer:	93449 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10/5		

Not Authored
1/1/17 @ ?
Resurvey After Paint
N/S Acc

Description of Accident/Loss: ON THE ABOVE DATE, TIME & LOCATION, I WANTED TO REVERSE MY VEHICLE, GBC4983Y INTO A PARKING LOT ALONG KANDAHAR STREET. WHILE REVERSING, MY VEHICLE ACCIDENTALLY GRAZED AGAINST THE LAMP POST WHICH IS LOCATED ALONG THE LEFT SIDE OF THE CARPARK LOT 23. TO MY BEST OF UNDERSTANDING, THERE ISN'T ANY VISIBLE DAMAGES FOUND TO THE LAMP POST ITSELF. THAT'S ALL. * INTER ACCIDENT REPORT TO BE REQUESTED FROM INSURED DIRECTLY.

Present Location: LIM TAN MOTOR PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	1,332.00
Miscellaneous Items	10.00
Labour	750.00
Paintwork Labour	400.00
Towing	0.00
Gross Total (S\$)	2,492.00
+ GST 7.00% (S\$)	174.44
Nett Amount (S\$)	2,666.44

This claim is handled by: ANG WEI GUANG, RICHARD

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 19 Jan 2018)**Parts:** M1-SUV SSANGYONG ACTYON SPORTS 2.0 D/CAB 2.0 AT AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Lim Tan Motor Pte Ltd/GBC4983Y/19/01/2018 15:56**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*N/S TAILLAMP	10.00	0.00	<i>CM</i> *380.00 FL ✓
2	1		*N/S REAR BODY PANEL	10.00	0.00	<i>A</i> *1,100.00 FL ✓
Sub Total (S\$)						1,480.00
- List Item Discount on L Items (S\$)						148.00
Total Parts (S\$)						1,332.00

F=Franchise part, L=ListItemDisc.

Lim Tan Motor Pte Ltd/GBC4983Y/19/01/2018 15:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/at/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO PUTTY AND SPRAY PAINTING.	New	300/ 400.00
<u>Labour Items</u>			
2	LABOUR CHARGES.	New	600/ 750.00
Gross Labour Cost (S\$)			1,150.00

Lim Tan Motor Pte Ltd/GBC4983Y/19/01/2018 15:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



Lim Tan Motor Pte Ltd

Block 176 Sin Ming Drive # 03-09/10/06 Sin Ming Autocare Singapore 575721

Tel : 65-64520893 Fax : 65-64589127 Email : sales@ltm.sg

Website : www.ltm.sg

Co.Reg No. : 199307277D GST Reg No. : M2-0119086-0

Survey By

INSURER: India International Insurance Pte Ltd (HQ)

Date / Time 22 JAN 2013

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	M486583	Date of Loss:	05/05/2017
Vehicle Reg. No.:	GBC4983Y	Driveable?	
Driver Age/Info:	63 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	URBAN REDEVELOPMENT AUTHORITY		
Driver:	FARALI KHAN BABU KHAN		

Make/Model:	SSANGYONG ACTYON SPORTS, 2.0 D/CAB 2.0 AT AIRBAG 2WD (A)	Vehicle Reg. Date:	20/09/2012
Vehicle Colour:	WHITE	Chassis No:	KPADA1ETSCP139735
Engine No:	67196022516120		
Odometer:	93449 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10/5		

Not Authored
6/1/17 @ ?
Resurvey After Paint
N/S Acc

Description of Accident/Loss

ON THE ABOVE DATE, TIME & LOCATION, I WANTED TO REVERSE MY VEHICLE, GBC4983Y INTO A PARKING LOT ALONG KANDAHAR STREET. WHILE REVERSING, MY VEHICLE ACCIDENTALLY GRAZED AGAINST THE LAMP POST WHICH IS LOCATED ALONG THE LEFT SIDE OF THE CARPARK LOT 23. TO MY BEST OF UNDERSTANDING, THERE ISN'T ANY VISIBLE DAMAGES FOUND TO THE LAMP POST ITSELF. THAT'S ALL. * INTER ACCIDENT REPORT TO BE REQUESTED FROM INSURED DIRECTLY.

Present Location: LIM TAN MOTOR PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	1,332.00
Miscellaneous Items	10.00
Labour	750.00
Paintwork Labour	400.00
Towing	0.00
Gross Total (\$\$)	2,492.00
+ GST 7.00% (\$\$)	174.44
Nett Amount (\$\$)	2,666.44

This claim is handled by: ANG WEI GUANG, RICHARD

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Jan 2018)

Parts: M1-SUV SSANGYONG ACTYON SPORTS 2.0 D/CAB 2.0 AT AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Lim Tan Motor Pte Ltd/GBC4983Y/19/01/2018 15:56

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*N/S TAILLAMP	10.00	0.00	<i>CM</i> *380.00 FL ✓
2	1		*N/S REAR BODY PANEL	10.00	0.00	<i>A</i> *1,100.00 FL ✓
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)						1,480.00
- List Item Discount on L Items (S\$)						148.00
Total Parts (S\$)						1,332.00

Lim Tan Motor Pte Ltd/GBC4983Y/19/01/2018 15:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

10.00

Sub Total (S\$)

10.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1 TO PUTTY AND SPRAY PAINTING.

New

300l 400.00

Labour Items

2 LABOUR CHARGES.

New

600l 750.00

Gross Labour Cost (S\$)

1,150.00

Lim Tan Motor Pte Ltd/GBC4983Y/19/01/2018 15:56. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Parfs \$ 1480.00

- 10% \$ 148.00

\$ 1332.00

Lab \$ 900.00

Misc \$ 10.00

\$ 2242.00

- 20% 448.40

\$ 1793.60

LS \$ 1750.00


 APPROVED
 16 APR 2018


 X \$600

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III18001332/KQD3N2

Date: 02/05/2018

REFERENCE

Insured/Claimant: URBAN REDEVELOPMENT AUTHORITY

Policy No: M486583

Date of Loss: 05/05/2017

Nature of Claim: OD

Claim No: MC20173204

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC4983Y

Make & Model: SSANGYONG ACTYON SPORTS, 2.0 D/CAB 2.0
AT AIRBAG 2WD (A)

Engine No: 67196022516120

Reg. Date: 20/09/2012 (Man. Year: 2012)

Chassis No: KPADA1ETSCP139735

Colour: White

Odometer: 94169 km

Engine Capacity: 1998 cc

Market Value/New Car Price: S\$44,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/70 R16

Rear Tyre Size: 225/70 R16

Front Left Side: Yokohama 9 mm

Rear Left Side: Maxxis 7 mm

Front Right Side: Yokohama 9 mm

Rear Right Side: Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,332.00	1,332.00	0.00	0.00
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	750.00	600.00	150.00	20.00
Paintwork Labour	400.00	300.00	100.00	25.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,492.00	2,242.00	250.00	10.03
Approved Total (Overridden) (S\$)		1,750.00		
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	2,492.00	1,150.00	1,342.00	53.85
+ GST 7.00/7.00% (S\$)	174.44	80.50	93.94	53.85
Nett Amount (S\$)	2,666.44	1,230.50	1,435.94	53.85

INSPECTION

Date of Assignment: 22/01/2018 Present Location:

Lim Tan Motor Pte Ltd (HQ)

Date Inspected: 22/01/2018 Inspected At:

Lim Tan Motor Pte Ltd (HQ)

Blk 176 Sin Ming Drive #03-09/10, Sin

Ming Auto Care

Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 May 2018)
Parts:	M1-SUV	SSANGYONG ACTYON SPORTS 2.0 D/CAB 2.0 AT AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC4983Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S TAILLAMP	Cracked	380.00 FL	*380.00 FL
2	1		*N/S REAR BODY PANEL	Bent	1,100.00 FL	*1,100.00 FL
F=Franchise part. L=ListItemDisc.						
				Sub Total (S\$)	1,480.00	1,480.00
				- List Item Discount on L Items 10.00/10.00% (S\$)	148.00	148.00
				Total Parts (S\$)	1,332.00	1,332.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO PUTTY AND SPRAY PAINTING.	New	400.00	300.00
<u>Labour Items</u>				
2	LABOUR CHARGES.	New	750.00	600.00
Gross Labour Cost (S\$)			1,150.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >