

Survivor:

ASSIGNMENT (Office)

CWS

From (Person):

Lurene Jaw

of

FCI

Date/Time:

3:36pm @ 22/1/18

Estimated Cost:

Bill to:

OD ☒ TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLU 894J

Insured:

SHC 0379Y

at Workshop m/s

Lim Tan Motor

Tel:

64520893

of 81k 176, Sin Ming Drive #03-09/10

Policy No:

Claim No:

D18000653MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18/01/2018

24hr/1hr @ After 10am

CA / REV / REP. / REV 24 HRS

'DS'

H.O.D. Endorsement:

Date/Time:

4:54pm @ 22/1/18

Person Contacted:

Richard

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLU 894J - X

SHC 0379Y - CS/FCI 17004825/R/rbn2

D.O.A: 19/02/17

25/1/18

Email preli revised to FCI

24/01/18

564894J

11 17

SLU 8941

Lim Tan Motor

Blk 176, Sing Ming Drive # 03-09/10

After 10 am

Hand ^(A) ver
m. Blue
2808

1496

Ru3

1261352

215/60R16

99
21118

9
9
24/1/18

17m d/s

25/1 1964 paper Catherine

Confirm \$3505.68, 3 days
Red = \$580.16, 14%.

30/1/2018

RECEIVED 30 JAN 2018

typist

☐	0 0 0 0 0 0 0 0 0 0
☒	0 0 0 0 0 0 0 0 0 0

Page 3

TP

131

3505.68

135
50
50
15

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18001348/Krd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-01-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 379Y	Veh. Inspected	SLU 894J
Policy No.		Coverage (\$)	0.00
Claim No.	D18000653MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	23/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/01/2018	Inspection Date
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	22-01-2018	Our Ref No. D18000653MFSH
Accident Date	18-01-2018	Claim Type. Third Party SLU 894J
Insured Vehicle	SHC0379Y	Third Party Vehicle. SJD6252K
Survey Location	BLK 176 SIN MING DRIVE #03-09/10/06 SIN MING AUTOCARE	
Contact Person.	RICHARD ANG	
Contact No.	64520893/ 0	Fax No. 64589127
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LIM TAN MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 25 January 2018 12:26 PM
To: 'Claim Workflow System'
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG;
LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000653MFSH/1, SLU 894J
Attachments: SLU 894J PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLU 894J
Date of survey: 24/1/2018
Number of days:3 days

Best Regards,

Veron Chen | Case Handler on behalf of Janice

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 22 January 2018 5:27 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
<sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000653MFSH/1

Dear Sir/Mdm,

As per my tele-conversation with the repairer,

The third party vehicle number is SLU 849J and not SJD 6252K.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 22 January 2018 3:36 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000653MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18000653MFSH
Our ref: CS/FCI18001348/Krd3

Date : 25/1/2018

The Motor Claims Department
M/s First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLU 894J


We thank for your instruction on 22/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24/1/2018 at the premises of M/s LIM TAN MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$4,085.84
Revised Estimate Amount	: S\$1,821.28
"Check" Items Amount	: S\$1,974.56
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front o/s portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Transaction ref 20171122150933872732

The owner and vehicle particulars for Vehicle No. SLU894J as at 22 Nov 2017 are as follows:

1.	Name	: SIMON HO KIN HENG (SIMON HE JINXING)
2.	Identification No. Type	: Singapore NRIC
3.	Identification No.	: S7308969G
4.	Place Of Passport Issue	: -
5.	Registered Address	: APT BLK 1A CANTONMENT ROAD #16-01 SINGAPORE 085101
6.	Mailing Address	: -
7.	Vehicle No.	: SLU894J
8.	Effective Date of Ownership	: 22 Nov 2017
9.	Original Registration Date	: 22 Nov 2017
10.	First Registration Date	: 22 Nov 2017
11.	Vehicle Type	: P10 - Passenger Motor Car
12.	Vehicle Scheme	: Normal
13.	Attachment 1	: No Attachment
14.	Attachment 2	: -
15.	Attachment 3	: -
16.	Vehicle Make	: HONDA
17.	Vehicle Model	: VEZEL HYBRID 1.5X AUTO
18.	Year of Manufacture	: 2017
19.	Primary Colour	: Blue
20.	Secondary Colour	: -
21.	Passenger Capacity	: 4
22.	Chassis/Trailer Chassis No.	: RU31261352 / -
23.	Propellant/Emission Standard	: Petrol-Electric / Euro VI
24.	Engine No./Motor No.	: LEB5961369 / H12374109
25.	Engine Capacity(cc)/Power Rating(kW)	: 1496 / 22.0
26.	Maximum Power Output(kW/bhp)	: 112.0 / 150
27.	Unladen Weight(kg)	: 1280
28.	Maximum Laden Weight(kg)	: 1555
29.	Open Market Value	: \$25,368.00
30.	PARF Eligibility	: Yes
31.	PARF Eligibility Expiry Date	: 21 Nov 2027
32.	Minimum PARF Benefit	: \$2,500.00
33.	IU Label No.	: -
34.	COE No.	: 2017100107000205N
35.	COE Expiry Date	: 21 Nov 2027
36.	COE Category	: E - Open - all except motorcycle
37.	Quota Premium/Prevailing Quota Premium	: \$48,005.00
38.	Actual Quota Premium/PQP Paid	: \$48,005.00
39.	Actual ARF Paid	: \$5,000.00
40.	CO2 Emission(g/km)	: 94.00
41.	Actual CEVS Rebate Utilised	: \$22,516.00
42.	CEVS Surcharge Paid	: -
43.	Actual Green Vehicle Rebate Utilised	: -
44.	Vehicle Lifespan Expiry Date	: -
45.	Road Tax Amount	: \$341.00
46.	Road Tax Start Date	: 22 Nov 2017
47.	Road Tax End Date	: 21 May 2018
48.	Remarks	: This vehicle is eligible for PARF. COE rebate, if applicable, will be based on the QP of \$48,005.00. This is the lower of QP from Category E and the corresponding Category B in the same tender exercise. To renew the COE, the Prevailing Quota Premium payable is that of Category B.

Not Authorised
1. B1
Putty B & paint
3 day,



ESTIMATE TO REPAIR

VEHICLE NO. : SLU 894 Z
MAKE : HONDA
MODEL : VEZEL HYBRID 1.5X AUTO
YEAR : 2017
CHASSIS NO : RU31261352

SURVEYOR NAME :
DATE OF SURVEY : 24 JAN 2019
TIME OF SURVEY :

DATE : 22-Jan-18
DATE OF ACCIDENT : 18-Jan-18
THIRD PARTY REF : SHC 379 Y / FIRST CAPITAL

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper			B1 \$	801.70
1 pc	Front Bumper Reinforcement			B1 \$	321.00
1 pc	O/S Front Bumper Retainer			D11 \$	22.00
1 pc	O/S Front Bumper Fog Lamp			SVU \$	327.70
1 pc	O/S Front Bumper Fog Lamp Cover			PA \$	45.00
1 pc	O/S Headlamp			mtg \$	1,784.50
1 pc	O/S Headlamp Lower Bracket			Ca \$	35.00
1 pc	O/S Front Fender Arch Granish			Bu \$	195.00
1 pc	O/S Front Fender "HYBRID" Emblem			Re \$	62.90
					\$ 3,594.80
	Less 20%				\$ 718.96
					\$ 2,875.84
1 set	Front Bumper Sensor	S.Nett		Net \$	280.00
	To putty & spray painting.			400 \$	500.00
	To check front wiring and focus headlamp.				\$ 30.00
	Labour Charges.				\$ 400.00
TG-RA/-					\$ 4,085.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #01-09 Sin Ming Autocare Singapore 570731

Tel: 65-64520803 Fax: 65-64520802

Website: www.LTM.sg

Co Reg No: 10930/277D

GST Reg No: M2-0018086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties, without the prior written consent of Lim Tan Motor Pte Ltd.

Kr
Not Authorise
1. B1
Resmy B4 paint
3 day

83505.68



ESTIMATE TO REPAIR

VEHICLE NO. : SLU 894 EJ
MAKE : HONDA
MODEL : VEZEL HYBRID 1.5X AUTO
YEAR : 2017
CHASSIS NO : RU31261352

SURVEYOR NAME :
DATE OF SURVEY : 24 JAN 2018
TIME OF SURVEY :

DATE : 22-Jan-18
DATE OF ACCIDENT : 18-Jan-18
THIRD PARTY REF : SHC 379 Y / FIRST CAPITAL

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper			B1 \$ 801.70	✓
1 pc	Front Bumper Reinforcement			\$B1 321.00	✓
1 pc	O/S Front Bumper Retainer			D11 \$ 22.00	✓
1 pc	O/S Front Bumper Fog Lamp			SVC \$ 327.70	✓
1 pc	O/S Front Bumper Fog Lamp Cover			DI \$ 45.00	✓
1 pc	O/S Headlamp			mg cda \$ 1,784.50	✓
1 pc	O/S Headlamp Lower Bracket			DI \$ 35.00	✓
1 pc	O/S Front Fender Arch Granish			Bu \$ 195.00	✓
1 pc	O/S Front Fender "HYBRID" Emblem			DI \$ 62.90	✓
	Less 20%			\$3232.10 LESS 20% \$646.42	
				\$2585.68	
1 set	Front Bumper Sensor	S.Nett	g/n	\$100.00	200.00
	To putty & spray painting.		labour	\$720.00	
	To check front wiring and focus headlamp.		ppp	\$3505.68	
	Labour Charges.		03 days	\$ 30.00	201
				\$ 400.00	3001
TG-RA/-					\$ 4,085.84

Estimate No. 116

Estimate No. 116

Estimate No. 116

Estimate No. 116

Estimate No. 116



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001348/Krd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 31-01-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 379Y	Veh. Inspected	SLU 894J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18000653MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	22/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31261352	Colour	METALLIC BLUE	
Odometer	2808	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	9 mm	
L/H Front Tyre	215/60 R16	DUNLOP	9 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	9 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/01/2018	Inspection Date	24/01/2018	
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 894J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	BENT	801.70	801.70
1	FRONT BUMPER REINFORCEMENT	BENT	321.00	321.00
1	O/S FRONT BUMPER RETAINER	DISTORTED	22.00	22.00
1	O/S FRONT BUMPER FOG LAMP	SERVICEABLE	327.70	-
1	O/S FRONT BUMPER FOG LAMP COVER	DENTED	45.00	45.00
1	O/S HEADLAMP	MTG CRACKED	1,784.50	1,784.50
1	O/S HEADLAMP LOWER BRACKET	NOT NECESSARY	35.00	-
1	O/S FRONT FENDER ARCH GARNISH	BUCKLED	195.00	195.00
1	O/S FRONT FENDER "HYBRID" EMBLEM	NECESSARY	62.90	62.90
	LESS 20% DISCOUNT		-718.96	-646.42
			2,875.84	2,585.68
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER SENSOR (SN)	DENTED	280.00	200.00
			280.00	200.00
<u>LABOUR</u>				
	TO PUTTY & SPRAY PAINTING.		500.00	400.00
	TO CHECK FRONT WIRING AND FOCUS HEADLAMP.		30.00	20.00
	LABOUR CHARGES.		400.00	300.00
			930.00	720.00
GRAND TOTAL			4,085.84	3,505.68
RECOMMENDED COST OF REPAIRS				3,505.68

Report Ref No. CS/FCI18001348/Krd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.