

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931, Tel: 6741-1730 / 731, Fax: 6744-5746, Email: liubro@gmail.com

Invoice/Ref No: YN7488K171216

Estimate

Customer		Date:	17-01-18
Name:	AXA Insurance Singapore Pte Ltd	Vehicle No:	YN7488K
Address:	Motor Claims Department 8 Shenton Way #27-01 AXA Tower Singapore 068811	Model/Make:	Mitsubishi Fuso FM65FM2RDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Side Guard <i>Ref</i> Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc To putty & spray painting & including touch up paint on accident affected areas	\$ 800.00 \$ 400.00 \$ 400.00	<i>S. Nept</i> 300 200

Total Parts & Labour of estimate for damaged vehicle

\$ 1,600.00

Total amount in Lump Sum Basis for repaired vehicle

\$ -

SDLS: _____



M/s Liu's Brother Auto Engrg Wks

Not Authorised
23/1/18

L/S \$1000
2 day.

Take photo after repair.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____