

REF: CS/MSG18001370/T19d392

REF: CS/MSG18001370/T19d392

Meinmen

Tau Hkh

ASSIGNMENT (Office)

MSG

23/1/18 4:11am

Entered Date

Entered

OT/TP/WS/TP RES / OD RES / EVA / DV / MV / CS

To Inspect Vehicle No. SLU 30622

at Workshop No. Performance

at 303 Alexandra Road

Police No. 29055425 QMY

Claim No. 546891

Sum Insured

Excess \$1,000.00

Make of Veh.

Date 19/01/2018

(Chassis Serial)

CA / REF. / REV 24 HRS

Date Time 9:50am @ 23/1/18

Person Contacted Menina

Vehicle Status

Date Time

Action / Instruction

✓

SLU 30622 - x

24/1/18 @ 3:57pm report to Jocelyn Ng via Meinmen.

24/1/18 @ 5:07pm Kenny Ong informed C/A via Meinmen.

24/1/18 @ 5:12pm informed Meinmen C/A B of: \$1000 by email.

26/1/18 @ 10:07pm confirmed with Caroline that my \$4075.40, 4 days by email.

(Ref to \$105.45, 562)

Est. Repairs

4 days

Res: Yes or No

D.O.A.

D.O.L.

23/1/18

Lim Sum

5

3 Val: Yes or No

Survey held at

PML

CA / REF. / REV. / 24 HRS

Vehicle IN/OUT

Des. of Damages: Frt / Rear / C/S / N/S / U/C / Rooftop or

Frt + N/S.

Date

Person Contacted

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

E-mail advise for before print print

Amir

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jan 2018		22 Jan 2018 16:11 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	SIME DARBY SERVICES PTE LTD , Co. Reg. No.: 197501065W, Tel: +6598238377		
Vehicle Reg. No.:	SLU3062Z	Date of Loss:	19/01/2018 15:00 - :59
Claim Type:	OD / 546891	Policy/Cover Note No.:	29055425QMY (Comprehensive) Coverage: 29/11/2017 - 28/11/2018
		Excess:	S\$1,000.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/01/2018]		
Driver/Custodian:	NG KIM YEONG CHRISTOPHER (49 / Male), NRIC: S68072711, Tel: +6598238377		
Adj Asg. Remarks:	Please revert, thank you. Owner waiting 10am tmr		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18001370/T1qd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 23-01-2018	
		Code : MSG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SLU 3062Z
Policy No.	29055425QMY	Coverage (\$)	0.00
Claim No.	546891	Excess (\$)	1,000.00
Assign From	MERIMEN (JOCELYN NG)	Assign Date	23/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	19/01/2018	Inspection Date	23/01/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 6 July 2018 10:02 AM
To: PBSP; Taufikh (LKKAUTO)
Cc: SUR
Subject: RE: FINAL REPORT / SLU3062Z

Dear Caroline,

WITHOUT PREJUDICE

Confirm final fig \$4,025.40 before excess \$1,000.00 & GST and 4 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Friday, 29 June 2018 3:09 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: Fw: FINAL REPORT / SLU3062Z

Gentle reminder

From: PBSP
Sent: Friday, 29 June 2018 12:27 PM
To: Taufikh (LKK Auto)
Subject: Re: FINAL REPORT / SLU3062Z

Dear Taufikh

As requested, please see attached before paint and kindly confirm COR.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	22 Jan 2018 14:35	Cln Veh Model Changed	(204171) BMW 116D 1.5 (A).		[I] Jocelyn Ng Shin Bun
2	22 Jan 2018 14:35	Cln Created	Reg No: SLU3062Z. Policy No: 29055425QMY. Acct Date: 2018/01/19. Claim Type: OD. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Performance Motors Limited (Alexandra). Ins.Status => Incoming Claim. Created from SAS:MPM L18009888		[I] Jocelyn Ng Shin Bun
3	22 Jan 2018 15:13	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please revert, thank you.		[I] Jocelyn Ng Shin Bun
4	22 Jan 2018 15:13	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/01/23		[I] Jocelyn Ng Shin Bun
5	22 Jan 2018 15:13	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.		[I] Jocelyn Ng Shin Bun
6	22 Jan 2018 15:17	Assignment 1st Accessed			[A] Ho Pei Fang
7	22 Jan 2018 16:09	Adj Assignment Cancelled	Survey - Owner waiting 10am tmr (ET-Morning appt full, AL-Unable to survey PML, DC-Morning station in office)		[I] Jocelyn Ng Shin Bun
8	22 Jan 2018 16:09	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment		[I] Jocelyn Ng Shin Bun
9	22 Jan 2018 16:11	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert, thank you. Owner waiting 10am t		[I] Jocelyn Ng Shin Bun
10	22 Jan 2018 16:11	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/01/23		[I] Jocelyn Ng Shin Bun
11	22 Jan 2018 16:11	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.		[I] Jocelyn Ng Shin Bun
12	23 Jan 2018 08:51	Assignment 1st Accessed			[A] Nivitha Govindasamy
13	23 Jan 2018 15:34	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID		[A] Nivitha Govindasamy
14	24 Jan 2018 15:48	Adj Rpt Initiated			[A] SHIAU CHAN
15	24 Jan 2018 15:50	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/21		[A] SHIAU CHAN
16	24 Jan 2018 15:50	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/21		[A] SHIAU CHAN
17	24 Jan 2018 15:52	Adj Mandate Request	Cur.Reg:7423.10:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE N OT AUTHORISE REPAIR.		[A] SHIAU CHAN
18	24 Jan 2018 17:07	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/21. Mandate Remarks: A IF C		[I] Keny Ong Thiam Beng
19	24 Jan 2018 17:07	Adj Mandate Set	Approved:3943.60:A IF C		[I] Keny Ong Thiam Beng
20	29 Jun 2018 16:52	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/21		[A] SHIAU CHAN
21	29 Jun 2018 16:53	Adj Mandate Request	Cur.Reg:4025.40:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APP ROVE ON CHECK ITEMS.		[A] SHIAU CHAN
22	04 Jul 2018 13:24	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/21. Mandate Remarks: A IF C		[I] Keny Ong Thiam Beng
23	04 Jul 2018 13:24	Adj Mandate Set	Approved:4025.40:A IF C		[I] Keny Ong Thiam Beng

Date From



Date To



Audit Type None

Go

ACTIVITY

[22/01/2018 15:22] Ho Pei Fang:

Merina confirmed survey appt 10am tmr, owner waiting.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1704511	24/01/2018 15:48	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLU3062Z		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 29 Jun 2018

Preliminary Advice

Vehicle No	: SLU3062Z	Accident Date	: 19/01/2018
Make	: BMW 116D	Policy No.	: 29055425QMY
Assignment Date	: 22/01/2018	Excess	: S\$1,000.00
Date of Inspection	: 23/01/2018	Est. Duration of Repair	: 4.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,130.85	
Revised Amount	:S\$	4,025.40	(INCLUSIVE OF CHECK ITEMS)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	4,025.40	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	56,994.00
Salvage Value	:S\$	
Margin for Repair	:S\$	68,006.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON CHECK ITEMS.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 24 January 2018 5:12 PM
To: Merina Chia San San
Cc: SUR
Subject: VEHICLE SLU 3062Z (DOA: 19/01/2018)

Dear Merina,

As instructed by our client, please proceed to repair the insured vehicle **SLU 3062Z (Excess \$1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	22 Jan 2018 14:35	Clim Veh Model Changed	(204171) BMW 116D 1.5 (A).	[I] Jocelyn Ng Shin Bun
2	22 Jan 2018 14:35	Clim Created	Reg No: SLU3062Z, Policy No: 29055425QMY, Acct Date: 2018/01/19, Claim Type: OD, Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Performance Motors Limited (Alexandra), Ins.Status => Incoming Claim. Created from SAS:MPML18009888	[I] Jocelyn Ng Shin Bun
3	22 Jan 2018 15:13	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please revert, thank you.	[I] Jocelyn Ng Shin Bun
4	22 Jan 2018 15:13	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/01/23	[I] Jocelyn Ng Shin Bun
5	22 Jan 2018 15:13	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Jocelyn Ng Shin Bun
6	22 Jan 2018 15:17	Assignment 1st Accessed		[A] Ho Pei Fang
7	22 Jan 2018 16:09	Adj Assignment Cancelled	Survey - Owner waiting 10am tmr (ET-Morning appt full, AL-Unable to survey P ML, DC-Morning station in office)	[I] Jocelyn Ng Shin Bun
8	22 Jan 2018 16:09	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Jocelyn Ng Shin Bun
9	22 Jan 2018 16:11	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert, thank you. Owner waiting 10 am tmr	[I] Jocelyn Ng Shin Bun
10	22 Jan 2018 16:11	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/01/23	[I] Jocelyn Ng Shin Bun
11	22 Jan 2018 16:11	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Jocelyn Ng Shin Bun
12	23 Jan 2018 08:51	Assignment 1st Accessed		[A] Nivitha Govindasamy
13	23 Jan 2018 15:34	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
14	24 Jan 2018 15:48	Adj Rpt Initiated		[A] SHIAU CHAN
15	24 Jan 2018 15:50	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/21	[A] SHIAU CHAN
16	24 Jan 2018 15:50	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/21	[A] SHIAU CHAN
17	24 Jan 2018 15:52	Adj Mandate Request	Cur.Req:7423.10:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	24 Jan 2018 17:07	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/21. Mandate Remarks: A IF C	[I] Keny Ong Thiam Beng
19	24 Jan 2018 17:07	Adj Mandate Set	Approved:3943.60:A IF C	[I] Keny Ong Thiam Beng

ACTIVITY

[22/01/2018 15:22] Ho Pei Fang:

Merina confirmed survey appt 10am tmr, owner waiting.

Merimen Billing for this case - Transaction History

Bill Ref.No	Bill Date	Acc Type	Acc Name	Cn Name (Branch)	Ref 1	Ref 2	Amount
1704511	24/01/2018 15:48	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLU3062Z		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 24 Jan 2018

Preliminary Advice

Vehicle No	: SLU3062Z	Accident Date	: 19/01/2018
Make	: BMW 116D	Policy No.	: 29055425QMY
Assignment Date	: 22/01/2018	Excess	: S\$1,000.00
Date of Inspection	: 23/01/2018	Est. Duration of Repair	: 4.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,102.05
Revised Amount	:S\$	3,943.60
Check Items (Estimated)	:S\$	3,480.10
Total	:S\$	7,423.70
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	56,994.00
Salvage Value	:S\$	
Margin for Repair	:S\$	68,006.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.
WE HAVE NOT AUTHORISE REPAIR.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1065W
Vehicle Details	
Vehicle No.:	SLU3062Z
Vehicle to be Exported:	No
Intended De-registration Date:	24 Jan 2018
Vehicle Make:	B.M.W.
Vehicle Model:	116D 5DR LED EU6
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	39845081B37D15A
Chassis No.:	WBA1V720005G87110
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$26,538.00
Original Registration Date:	29 Nov 2017
First Registration Date:	29 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$14,154.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2027
PARF Rebate Amount:	\$10,615.00
Intended COE Rebate Details	
COE Expiry Date:	28 Nov 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,112.00
COE Rebate Amount:	\$46,379.00
Total Rebate Amount:	\$56,994.00

The information contained herein is correct as at 24 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/01/2018 10:37
Date Of Accident	19/01/2018 15:35
Exact Location Of Accident	PIONEER ROAD NORTH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU3062Z
Insured/Policyholder	
Name Of Registered Owner	SIME DARBY SERVICES PTE LTD
Co Reg No	197501065W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98238377
Alternative Phone No	OFFICE-98238377

Vehicle Particulars

Manufacturer	BMW
Model	116
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	NG KIM YEONG CHRISTOPHER
NRIC No	S68072711
Date Of Birth	17/02/1968
Occupation	INDOOR
Date Of Driving Pass	05/03/1991
Driving Experience	26 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98238377
Fax Number	
Contact Number	
EMail Address	CHRIS_JAC68@YAHOO.COM

Address	BLK 516 JELAPANG ROAD #17-245
Postcode	670516
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ6350T
Vehicle Make/Model/Colour	LANCER EX/BLUE
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	SAIREE BIN SLNWAN
NRIC/Passport Number	S7933607F
Contact Number	91300516
Address	759 PASIR RIS STREET 71 #02-182
Postcode	510759
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. NO. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159942
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

260, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190588 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64786601 (AfterSales)
64786624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

22 JAN 2018

Estimate No. : b1 45587
Date Estimated : 22/01/2018
Prepared By : Merina Chia San San

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Sime Darby Services Private Limited
305 Alexandra Road
#02-01 Vantage Automotive Centre

Singapore 159942

- ACCOUNT -

66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU3062Z	5G87110	29/11/2017	116d	0

DESCRIPTION

VALUE

To replace front bumper including attachments etc and
to knock out dented area caused by accident

1700 2,550.00

To paint front bumper and front left fender

1153 1,923.00

To replace left or right headlight including program
and conduct tests for proper function.

451? 531.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150 177.00

Sundries.

MC? 80.00

Total Labour 1: 5,261.00

DESCRIPTION

QTY PRIC

VALUE

CLAMP
FRT BUMPER TOP MOUNT
FRT LH DEFORMATION ELEMENT
IMPACT ABSORBER TOP
FRT BUMPER LH INSERT
FRT BUMPER RH INSERT
FRT BUMPER PANEL PRIMED
SET PDC HOLDER FRONT
SET PMA HOLDERS FRT/REAR
EMBLEM GROMMET
FRT BUMPER LOWER MOUNT
PLAQUE 82MM
LH HEADLIGHT LED TECHNOLOGY
DECOUPLING RING PDC TORQUE CONVERTE
(DG) ADHESIVE SET K6

10	3.20	32 3.20
1	352.90	? 352.90
1	95.00	? 95.00
1	41.40	? 41.40
1	31.35	MC 31.35
1	31.35	MC 31.35
1	767.00	MC 767.00
1	22.55	MC 22.55
1	20.75	? 20.75
2	0.80	MC 1.60
1	124.90	? 124.90
1	67.80	MC 67.80
1	2,208.40	? 2,208.40
4	4.95	MC 19.80
1	53.05	MC 53.05

Total Parts : 3,841.05



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

180, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 62449770

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190833/830 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45587
Date Estimated : 22/01/2018
Prepared By : Merina Chia San San

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU3062Z	5G87110	29/11/2017	116d	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Callers / 3rd Party / Uninsured losses / Direct Settlements

Regn No.	Claim No.
Date & Time 23/1/18 21:10	Excess 1000
Surveyor's Name Taufik	Sp. 1000
Surveyor's Tel 97495749	Address 1000
Authorized Date	Time
RESURVEY PARTS PHOTO BY 30	PAID YAH / RM
Surveyor's Email Taufik@lkkauto.com	
No. of Working Days 4 days	

Signature
25/1/18

Labour 1	:	5,261.00
Parts	:	3,841.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	637.14
Grand Total	:	9,739.19

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 191401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45587
Date Estimated : 22/01/2018
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
Sime Darby Services Private Limited
305 Alexandra Road
#02-01 Vantage Automotive Centre
Singapore 159942

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SLU3062Z	5G87110	29/11/2017	116d	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments include making good the front LH fender and knocking out dents caused by the accident	1700.00		1,700.00	
To spray paint front bumper and front LH fender	1153.00		1,153.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
CLAMP	3.20	10.00		32.00
FRT BUMPER PANEL PRIMED	767.00	1.00		767.00
SET PDC HOLDER FRONT	22.55	1.00		22.55
PLAQUE 82MM	67.80	1.00		67.80
(DG) ADHESIVE SET K6	53.05	1.00		53.05

SUPPLEMENTARY ITEMS

Total Labour :	3,083.00
Total Parts :	942.40
Total Labour & Parts :	4,025.40
Deduction for Excess :	1,000.00
Total Repair Costs less Excess:	3,025.40
GST @7%:	211.78
Grand Total :	3,237.18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jan 2018		22 Jan 2018 16:11 Edit Adj Rpt	\$4,025.40 Edit Estimates	\$4,025.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SIME DARBY SERVICES PTE LTD , Co. Reg. No.: 197501065W, Tel: +6598238377								
Vehicle Reg. No.:	SLU3062Z	Date of Loss:	19/01/2018 15:00 - :59 [1 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 546891	Policy/Cover Note No.:	29055425QMY (Comprehensive) Coverage: 29/11/2017 - 28/11/2018						
		Excess:	\$1,000.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 21/02/2018]								
Driver/Custodian:	NG KIM YEONG CHRISTOPHER (49 / Male), NRIC: S68072711, Tel: +6598238377								
Adj Asg. Remarks:	Please revert, thank you. Owner waiting 10am tmr								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (04/07/2018): Alert - Adj Mandate Approved (\$4025.40) - SLU3062Z - Claim Handler: Jocelyn Ng ... MSIG_SG (24/01/2018): Alert - Adj Mandate Approved (\$3943.60) - SLU3062Z - Claim Handler: Jocelyn Ng ... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLU3062Z (546891)
OD
Jan 19 2018 3:00PM
[SIME DARBY SERVICES PTE LTD]
Performance Motors Limited

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)						Thumbnail	Print
1	20/01/18 10:52	Accident Statement					1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print
1	24/01/18 15:50	Adjuster Immediate Advice					1	Load HTM	
2	29/06/18 16:52	Adjuster Immediate Advice					1	Load HTM	
Photos/Images							3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print
1	24/01/18 15:51	Odometer Reading					1	Load JPG	<input checked="" type="checkbox"/>
2	24/01/18 15:51	Chassis Number					1	Load JPG	<input checked="" type="checkbox"/>
3	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
4	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
5	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
6	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
7	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
8	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
9	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
10	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
11	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
12	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
13	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
14	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
15	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
16	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
17	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
18	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
19	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
20	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
21	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
22	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
23	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
24	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
25	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
26	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
27	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
28	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
29	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
30	24/01/18 15:51	General View					1	Load JPG	<input checked="" type="checkbox"/>
31	04/07/18 11:04	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>
32	04/07/18 11:04	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>
33	04/07/18 11:04	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
					<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/01/18 14:39	PARF COE	1	Load PDF	
2	22/01/18 15:11	Estimate Repair Cost + GIA Report + DL + IC	2	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/01/18 15:52	ESTIMATE	1	Load PDF	
2	29/06/18 16:46	REVISED ESTIMATE	2	Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	20/01/18 10:52	Accident Statement	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	20/01/18 10:48	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	20/01/18 10:48	Accident Photo	2	Load JPG	<input checked="" type="checkbox"/>
3	20/01/18 10:48	Accident Photo	3	Load JPG	<input checked="" type="checkbox"/>
4	20/01/18 10:48	Accident Photo	4	Load JPG	<input checked="" type="checkbox"/>
5	20/01/18 10:48	Accident Photo	5	Load JPG	<input checked="" type="checkbox"/>
6	20/01/18 10:48	Accident Photo	6	Load JPG	<input checked="" type="checkbox"/>
7	20/01/18 10:48	Accident Photo	7	Load JPG	<input checked="" type="checkbox"/>
8	20/01/18 10:48	Accident Photo	8	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	20/01/18 10:49	Sketch Plan	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18001370/T1QD3Q2

Date: 13/07/2018

REFERENCE

Insured/Claimant: SIME DARBY SERVICES PTE LTD

Policy No: 29055425QMY

Date of Loss: 19/01/2018

Nature of Claim: OD

Claim No: 546891

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU3062Z

Make & Model: BMW 116D, 1.5 (A)

Engine No: 39845081B37D15A

Reg. Date: 29/11/2017 (Man. Year: 2017)

Chassis No: WBA1V720005G87110

Colour: Blue

Odometer: 2576 km

Engine Capacity: 1496 cc

Market Value/New Car Price: S\$125,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,949.85	1,022.40	2,927.45	74.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,181.00	3,003.00	2,178.00	42.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,130.85	4,025.40	5,105.45	55.91
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	8,130.85	3,025.40	5,105.45	62.79
+ GST 7.00/7.00% (S\$)	569.16	211.78	357.38	62.79
Nett Amount (S\$)	8,700.01	3,237.18	5,462.83	62.79

INSPECTION

Date of Assignment: 22/01/2018

Date Inspected: 23/01/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2018)
Parts: 144	BMW 116D 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLU3062Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	10		*CLAMP	Necessary	32.00 FS	*32.00 FS
3	1		*FRT BUMPER TOP MOUNT	Not Necessary	352.90 FS	*- FS
4	1		*FRT LH DEFORMATION ELEMENT	Not Necessary	95.00 FS	*- FS
5	1		*IMPACT ABSORNER TOP	Not Necessary	41.40 FS	*- FS
6	1		*FRT BUMPER LH INSERT	Not Necessary	31.35 FS	*- FS
7	1		*FRT BUMPER RH INSERT	Not Necessary	31.35 FS	*- FS
8	1		*FRT BUMPER PANEL PRIMED	Deformed	767.00 FS	*767.00 FS
9	1		*SET PDC HOLDER FRONT	Distorted	22.55 FS	*22.55 FS
10	1		*SET PMA HOLDERS FRT/REAR	Not Necessary	20.75 FS	*- FS
11	2		*EMBLEM GROMMET	Not Necessary	1.60 FS	*- FS
12	1		*FRT BUMPER LOWER MOUNT	Not Necessary	124.90 FS	*- FS
13	1		*PLAQUE 82MM	Necessary	67.80 FS	*67.80 FS
14	1		*LH HEADLIGHT LED TECHNOLOGY	Not Necessary	2,208.40 FS	*- FS
15	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	19.80 FS	*- FS
16	1		*(DG) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
Total Parts (S\$)					3,949.85	1,022.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER INCLUDING ATTACHMENTS ETC AND TO KNOCK OUT DENTED AREA CAUSED BY ACCIDENT	New	2,550.00	1,700.00
2	TO PAINT FRONT BUMPER AND FRONT LEFT FENDER	New	1,923.00	1,153.00
3	TO REPLACE LEFT OR RIGHT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION	New	531.00	0.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (\$\$)			5,181.00	3,003.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >