



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2005702
INV Date 19/08/2020
Reference CC6/CTI18001373/R1es3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. PA 8647L
Insured Veh. YP 7300H
Claim No. SNM18D00450C02/0
Policy No. DMCVSN1755231700
Accident Date 15/11/2017
Inspection Date 11/04/2018

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18001373/R1es3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 19-08-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 7300H	Veh. Inspected	PA 8647L
Policy No.	DMCVSN1755231700	Coverage (\$)	0.00
Claim No.	SNM18D00450C02/0	Excess (\$)	0.00
Assign From		Assign Date	11/04/2018

2. Vehicle Particulars & Condition

Make & Model	ISUZU LT134P	c.c	7790
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JALLT134P87000033	Colour	MULTI
Odometer	288434	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	11 R22.5	BRIDGESTONE	8 mm
L/H Front Tyre	11 R22.5	BRIDGESTONE	8 mm
R/H Rear Tyre	11 R22.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	11 R22.5 (D)	BRIDGESTONE	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/11/2017	Inspection Date	11/04/2018
Survey held at	SC AUTO INDUSTRIES (S) PTE LTD 51, SENOKO ROAD #03-01 SINGAPORE 758133		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 8647L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	BROKEN		
	RHS REAR VIEW MIRROR		1,980.00	1,980.00
			1,980.00	1,980.00
	<u>LABOUR</u>			
	LABOUR FOR WIRING.		150.00	30.00
	LABOUR FOR RHS REAR VIEW MIRROR .		640.00	320.00
	SPRAY PAINTING.		350.00	250.00
			1,140.00	600.00
GRAND TOTAL			3,120.00	2,580.00
RECOMMENDED COST OF REPAIRS				2,580.00

Report Ref No. CC6/CT18001373/R1es3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PA 8647L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PA 8647L

RE-INSPECTION

