

Please arrange to survey vehicle at  
8 KAKI BUKIT AVENUE 4 - GATE 2  
#07-48 PREMIER @ KAKI BUKIT  
SINGAPORE 415875



Date : 23/01/2018  
TP Vehicle No. : SKN-7731-Z  
To : AIG ASIA PACIFIC INSURANCE PTE LTD  
Attn : Motor Claim Department

LINDA LIAO  
ABWIN SERVICE PTE LTD  
DID: 67139417  
Fax: 67139415  
HP: 97519596

Owner : GOODMAN GLOBAL PRIVATE LIMITED  
NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Certificate No. : 5069110162-03  
Vehicle No. : GBD- 199-R  
Make & Model : TOYOTA DYNA 150 MANUAL 3SEATER

Accident Date: 19/01/2018

## ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

### List Item

1	FRONT BUMPER	\$396.20
1	FRONT BUMPER BRACKET RH	\$150.00
1	FRONT BUMPER BRACKET LH	\$150.00
1	LH HEADLAMP	\$593.20
1	RH HEADLAMP	\$593.20
1	RH HEADLAMP LOWER MOULDING	\$46.70
1	LH HEADLAMP LOWER MOULDING	\$46.70
1	FRONT GRILLE	\$470.00
1	FRONT GRILLE MOULDING	\$48.30
1	FRONT PANEL	\$921.40
1	FRONT PANEL TOP GARNISH CENTER	\$346.20
1	FRONT PANEL LOGO	\$71.60
1	FRONT PANEL "DYNA"	\$61.75
1	RH CORNER PANEL	\$282.20
1	RH CORNER PANEL TOP GARNISH	\$102.92
1	RH FRONT DOOR	\$1,549.20
1	RH FRONT DOOR INNER MOULDING	\$195.00
1	RH FRONTDOOR WEATHERSTRIP	\$185.00
<b>Sub Total</b>		<b>\$6,209.57</b>
<b>Discount 25% on Parts</b>		<b>(\$1,552.39)</b>
		<b>\$4,657.18</b>

### Special Nett

1	RH FRONT DOOR STICKER	\$65.00
1	RH FRONT NUMBER PLATE	\$65.00
<b>Sub Total</b>		<b>\$130.00</b>

### Labour & Misc

TO STRAIGHTEN AND PANEL BEAT ACCIDNET AREAS	\$1,500.00
TO SPRAY PAINT ON AFFECTED AREAS	\$1,500.00

LINDA LIAO  
ABWIN SERVICE PTE LTD  
DID: 67139417  
Fax: 67139415  
HP: 97519596

Date : 23/01/2018  
TP Vehicle No. : SKN-7731-Z  
To : **AIG ASIA PACIFIC INSURANCE PTE LTD**  
Attn : **Motor Claim Department**

Owner : GOODMAN GLOBAL PRIVATE LIMITED  
NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Certificate No. : 5069110162-03  
Vehicle No. : GBD- 199-R  
Make & Model : TOYOTA DYNA 150 MANUAL 3SEATER

Accident Date: 19/01/2018

## ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	TO CHECK ALL NECESSARY WIRINGS	\$150.00	
	<b>Sub Total</b>	<b>\$3,150.00</b>	
	<b>Sub Total</b>	<b>\$7,937.18</b>	
	<b>GST 7%</b>	<b>\$555.60</b>	
	<b>Total</b>	<b>\$8,492.78</b>	