

INS. CASE OWNER:

CC 3 / TP 1800

1381, K1203/1

LKK
IDAC:

Surveyor:

Kulvin

DOI:

ASSIGNMENT

27/1/18

Date / Time:

27/01/18

Registered in Merimen:

23/01/18

Pre-assign / CCU / FTE

SHB 2992T

X FCI



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess See II :S\$

D.O.A: 21-1-18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SHB 8792P



INSRS:

WSP: Premier

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: 46

S\$ 1,950.00 (3 days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ -

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search:

S\$ -

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost:

S\$ -

Total:

S\$ -

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ -

Name 1:

-

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

-

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

-

RECEIVED 8 MAR 2018

10% disc

5/3/18

CORP SENT 4/3/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4303.30

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

22-Jan-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8792 P

1 pc	n/s head lamp	✓ Broken	\$	1,028.00
1 pc	Front bumper	✓ Bkt	\$	531.00
1 pc	Front bumper lip	✓ ed	\$	52.00
1 pc	Front bumper n/s side retainer	✓ m	\$	16.00
1 pc	Front bumper n/s protector	✓ ed	\$	51.00
1 pc	Front bumper emblem	✓ me	\$	44.00
1 pc	Front bumper n/s fog lamp cover	✓ m	\$	66.00
1 pc	Front n/s fender	✓ rep-2	\$	384.00
1 pc	Front n/s fender inner shield	✓ bn	\$	120.00
			\$	2,292.00
			Less 10%	\$ 229.20
			\$	2,062.80

S/NETT

1 set	Front bumper clips	✓ me	\$	48.00
1 pc	Front n/s fender sticker	✓ m	\$	30.00
1 set	Front n/s fender inner shield clips	✓ m	\$	28.00
Sundry				
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front n/s fender				\$ 50.00
				20
				400
To putty and spray painting on front bumper, front n/s fender, bonnet				\$ 650.00
				360
To apply rustproofing on the repaired and replaced panels.				\$ 200.00
				\$ 3,668.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahoh 16/1/18

22/1/18 120.00

3 Dot

L/S

Add Repair photo

12/2/18

add 450/1950/347

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

22-Jan-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8792 P

1 pc	n/s head lamp ✓	\$	1,028.00
1 pc	Front bumper ✓	\$	531.00
1 pc	Front bumper lip ✓	\$	52.00
1 pc	Front bumper n/s side retainer ✓	\$	16.00
1 pc	Front bumper n/s protector ✓	\$	51.00
1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper n/s fog lamp cover X	\$	66.00
1 pc	Front n/s fender X 14.2	\$	384.00
1 pc	Front n/s fender inner shield ?	\$	120.00
		\$	2,292.00
	Less 10%	\$	229.20
		\$	2,062.80

S/NETT

1 set	Front bumper clips ✓	\$	48.00
1 pc	Front n/s fender sticker X	\$	30.00
1 set	Front n/s fender inner shield clips +	\$	28.00
	Sundry	\$	50.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front n/s fender	\$	20
	To putty and spray painting on front bumper, front n/s fender, bonnet	\$	400
	To apply rustproofing on the repaired and replaced panels.	\$	360
		\$	650.00
		\$	360
		\$	200.00
		\$	3,668.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahin 10/1/18

22/1/18 17.00 hrs.

3 Days

4/5

After Repair photo

Enquire Transaction History**Transaction History Details**

Log Date/Time:	16 Oct 2013 / 09:31:32	Receipt No.:	AACCK001-AX239-131016-000013
Asset Type:	Vehicle	Transaction Amount:	\$73,723.00
Asset ID:	SHB8792P	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20131016093132603312		
Vehicle No.:	SHB8792P		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	16 Oct 2013		
Original Registration Date:	16 Oct 2013		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414ME5447101		
Engine No.:	D4FDDH308089		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2013		
Open Market Value:	\$19,759.00		
Minimum PARF Benefit:	\$7,355.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	16 Oct 2013 09:31:32		
COE No.:	2013101601000830M		
COE Expiry Date:	15 Oct 2021		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$61,324.00		
Lifespan Expiry Date:	15 Oct 2021		
Owner ID Type:	Company		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

PREMIER AUTOMOTIVE SERVICES PTE LTD

Ref : CC3/TP18001381/K1ea3q2

23 CHANGI SOUTH AVENUE 2
#01-02 SINGAPORE 486443

Date : 12-03-2018



Code : TP451

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SHB 8792P
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	22/01/2018

2. Vehicle Particulars & Condition

Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KNAGM414ME5447101	Colour	SILVER
Odometer	577691	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	ACHILLES	7 mm
L/H Front Tyre	205/65 R16	ACHILLES	7 mm
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/01/2018	Inspection Date	22/01/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8792P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	N/S HEAD LAMP	BROKEN	1,028.00	1,028.00
1	FRONT BUMPER	DEFORMED	531.00	531.00
1	FRONT BUMPER LIP	CUT	52.00	52.00
1	FRONT BUMPER N/S SIDE RETAINER	CRACKED	16.00	16.00
1	FRONT BUMPER N/S PROTECTOR	CUT	51.00	51.00
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT BUMPER N/S FOG LAMP COVER	SERVICEABLE	66.00	-
1	FRONT N/S FENDER	TO REPAIR SEE LABOUR	384.00	-
1	FRONT N/S FENDER INNER SHIELD	TORN	120.00	120.00
	LESS 10% DISCOUNT		-229.20	-184.20
			2,062.80	1,857.80
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT N/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			156.00	68.00
	<u>LABOUR</u>			
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK-OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE FRONT N/S FENDER .INCLUSIVE OF THE REPAIR OF FRONT N/S FENDER .		650.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT N/S FENDER ,BONNET .		600.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	200.00	-
			-	-
			-	-
			-	-
			1,450.00	760.00
	GRAND TOTAL		3,668.80	2,485.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,950.00

Report Ref No. CC3/TP18001381/K1ea3q2



Report Ref No. CC3/TP18001381/K1ea3q2

A handwritten signature in black ink, appearing to be 'KALVIN'.

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.