

ASS. REC. BY:

REF: CS/FCI18001383/Uvd3n2

Special Instructions

21/1/18 Marcus

ASSIGNMENT (Office)

From (Person): Sithara of FCI Date/Time: 23/01/18

Estimated Cost: Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 5249A Insured: SHC 943 T

at Workshop m/s Pegasus Tel: 6858 1846

of 51 Defu Leine 10

Policy No: Claim No: D18000698MFSH

Sum Insured: Excess:

Make of Veh: DGA Date: 21/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

R.O.D. Indemnity

Date/Time: 4:20pm @ 23/1/18 Person Contacted: Alvin

Vehicle ☒ OUT

Date/Time: Action/Instructions ✓

SLS 5249A -X

SHC 943 T - CS/FCI18000137/Grb

D.O.A: 9/12/17

12/2/18 Email preli revised to FCI

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

Cath see email 12.40pm

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SL55249A
 at Workshop m/s Pago Su
 of _____
 Insured: SM/C 9437
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SL55249A Yr Regn: 9, 17
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or (A)
 Make: mazda 3 c.c. 1496
 Colour: blue A/C: Insured / Std / NI / NA
 Sp. Reading: 28968 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JM63N22A8140160634
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: NH / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 6 mm Rear: 6 mm
 R/Bal: _____ mm R/Bal: _____ mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. 21/1/18 D.O.I. 23/1/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Body
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction
13/2/18 confirmed LTA 52710
1/5 \$ 5750 with Sharon. (Red 6085.12, 5170)

RECEIVED 14 FEB 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 7Resurvey No. of Trip: 1

1) Date/Time, File Return to?

2) 142 - typistAdd Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: CWSLump Sum / I.B.I. (\$) 5750/2

170 + 15
50
50
89
374



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18000698MFSH
Our ref: CS/FCI18001383/Uvd3

DATE: 12/2/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SLS 5249A


We thank for your instruction on 23/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 23/1/2018 at the premises of M/s PEGASUS ENGINEERING & TRADING PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$11,835.12
Revised Estimate Amount	: S\$6,022.16
"Check" Items Amount	: S\$2,381.68
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
o/s body



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18001383/Uvd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 943T	Veh. Inspected	SLS 5249A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	CWS	Assign Date	23/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/01/2018	Inspection Date	23/01/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Survey Department Check List (Case Handler)

Reference No.: CS/FCI/8001383/Urd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A				
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages				

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

Case Handler

14/5/18

Date

*C: Critical *N: Non-Critical

21/05/20

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	23-01-2018	Our Ref No. D18000698MFSH
Accident Date	21-01-2018	Claim Type. Third Party
Insured Vehicle	SHC0943T	Third Party Vehicle. SLS5249A
Survey Location	51 DEFU LANE 10	
Contact Person.	ALVIN LOW	
Contact No.	68581846/ 0	Fax No. 64876070
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PEGASUS ENGINEERING & TRADING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234193)



PRI Documents



Close



PRI Header Details

Claim No	D18000698MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & PEGASUS PTE LTD
Workshop Name	PEGASUS ENGINEERING & TRADING PTE LTD (Contact Person : ALVIN LOW)	Survey Location & Contact Details	51 DEFU LANE 10 Mobile: 0 , Phone: 68581846 , Fax: 64876070 EmailId: CLAIMS@PEGASUSENGR.G.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0943T	TP Vehicle No	SLS5249A
PRI Recieved Date	23-01-2018 05:43:38 PM	Surveyor Appointed Date	30-01-2018 05:57:33 PM	Surveyor Accept Date	25-01-2018 0

Survey Report Upload

Surveyor Inspection Date *:	25-01-2018 	Surveyor Report Date	31-01-2018	Upload Survey Report *:	Choose File
------------------------------------	----------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name	Action
SLS5249A. FCIL JOB CANCELLED LKK SURVEY, VEH REPAIRED.PDF	

Surveyor Job Remarks

Remarks		Save
----------------	----------------------	-------------------------------------

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 12 February 2018 9:49 AM
To: 'Claim Workflow System'
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG;
JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000344MFSH/1, SKS 6605K
Attachments: SKS 6605K PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKS 6605K
Date of survey: 8/2/2018
Number of days:3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 18 January 2018 2:27 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
<sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000344MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 17 January, 2018 5:22 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000344MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1345N
Vehicle Details	
Vehicle No.:	SL55249A
Vehicle to be Exported:	No
Intended De-registration Date:	23 Jan 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	P520453035
Chassis No.:	JM6BN22A8H0160634
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,938.00
Original Registration Date:	27 Sep 2017
First Registration Date:	27 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$9,938.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Sep 2027
PARF Rebate Amount:	\$7,453.00
Intended COE Rebate Details	
COE Expiry Date:	26 Sep 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,778.00
COE Rebate Amount:	\$45,257.00
Total Rebate Amount:	\$52,710.00

The information contained herein is correct as at 23 Jan 2018

Text size + -

0% 25% 50% 75% 100%

Register New Vehicle (Acknowledgement)**Vehicle Particulars**

Vehicle No.:	SLS5249A		
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car	Vehicle Scheme:	Normal
Vehicle Attachment 1:	With Sun Roof		
Vehicle Attachment 2:	-	Vehicle Attachment 3:	-
Vehicle Make:	MAZDA	Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Chassis No.:	JM6BN22A8H0160634	Engine No.:	P520453035
Motor No.:	-	Trailer Chassis No.:	-
Propellant:	Petrol	Passenger Capacity:	4
Engine Capacity:	1496 cc	Power Rating:	-
Maximum Power Output: 88.0 kW (118 bhp)			
Unladen Weight:	1310 kg	Maximum Laden Weight:	1835 kg
Primary Colour:	Blue	Secondary Colour:	-
First Registration Date:	27 Sep 2017	Original Registration Date:	27 Sep 2017
Manufacturing Year:	2017	Open Market Value:	\$14,938.00
PARF Eligibility:	Yes	Minimum PARF Benefit:	\$4,969.00
No. of Transfers:	0	Additional Registration Fee Rate:	First \$14,938.00 (100%)
Actual ARF Paid:	\$9,938.00		

Owner Particulars

Owner Name:	GRAB RENTALS 2 PTE. LTD.
Owner ID Type:	Company
Owner ID:	201701345N
Registered Address Type:	Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.:	6
Registered Street Name:	SHENTON WAY
Registered Unit No.:	# 38 - 01
Registered Building Name:	-
Registered Postal Code:	068809
COE No. / Expiry Date:	2017090101000127H / 26 Sep 2027
COE Bid Category:	A - Car up to 1600cc & 97kW (130bhp)
QP Paid:	\$46,778.00

Transaction Details

Business Transaction Ref. No.:	20170927095652975381
Business Transaction Date:	27 Sep 2017
Business Transaction Time:	09:56:52

Message

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
539216

Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer :

GRAB RENTALS 2 PTE LTD
28, SIN MING LANE,
#07-71 MIDVIEW CITY
SINGAPORE 573969

Attn :
Tel :
Fax :

not about me
h/s \$5750
7 day
the price to the agent
23/1/18
23.01.2018 @ 1140

Quotation No : QO18/01-1164	Quotation Date : 22/01/2018	Terms : 30 DAYS
Vehicle No : SLS5249A	Chassis No : JM6BN22A8H0160634	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: FIRST CAPITAL, INSURED'S VEH NO: SHC943T, DATE OF ACCIDENT: 21.01.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	FRONT DOOR O/S <i>300g</i>	1	1,062.0000	1,062.00
2	FRONT DOOR INNER LOCK <i>2m/shell</i>	1	240.0000	240.00
3	FRONT DOOR INNER LOCK STRIKER <i>17</i>	1	26.0000	26.00
4	FRONT DOOR POWER WINDOW MOTOR <i>2142</i>	1	790.0000	790.00
5	FRONT DOOR REGULATOR <i>2m</i>	1	120.7000	120.70
6	FRONT DOOR OUTER WEATHERSTRIP MOULDING <i>17</i>	1	140.0000	140.00
7	FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP <i>17</i>	1	165.0000	165.00
8	FRONT DOOR OUTER HANDLE <i>17</i>	1	61.0000	61.00
9	FRONT DOOR OUTER HANDLE EXTENSION <i>17</i>	1	18.0000	18.00
10	FRONT DOOR OUTER HANDLE INNER BASE <i>Damaged</i>	1	33.0000	33.00
11	FRONT DOOR INNER TRIMBOARD <i>17</i>	1	844.0000	844.00
12	FRONT DOOR WEATHERSTRIP <i>2m</i>	1	107.0000	107.00
13	FRONT DOOR RUBBER STOPPER <i>2m</i>	2	20.0000	40.00
14	FRONT DOOR HINGE TOP <i>17</i>	1	42.0000	42.00
15	FRONT DOOR HINGE BOTTOM <i>17</i>	1	40.0000	40.00
16	FRONT DOOR CHECKER/ARRESTOR <i>17</i>	1	37.0000	37.00
17	FRONT DOOR WINDOW FRAME GARNISH TOP <i>17</i>	1	111.0000	111.00
18	FRONT DOOR WINDOW FRAME GARNISH REAR <i>17</i>	1	65.0000	65.00
19	DOOR CENTRE B PILLAR <i>300g</i>	1	880.0000	880.00
20	ROCKER PANEL O/S <i>300g</i>	1	360.0000	360.00
21	REAR DOOR O/S <i>300g</i>	1	1,006.0000	1,006.00
22	REAR DOOR INNER LOCK <i>2m/shell</i>	1	179.7000	179.70
23	REAR DOOR INNER LOCK STRIKER <i>17</i>	1	28.0000	28.00

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 28, SIN MING LANE, #07-71 MIDVIEW CITY SINGAPORE 573969 Attn : Tel : Fax :
---	---

Quotation No : QO18/01-1164	Quotation Date : 22/01/2018	Terms : 30 DAYS
Vehicle No : SLS5249A	Chassis No : JM6BN22A8H0160634	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: FIRST CAPITAL, INSURED'S VEH NO: SHC943T, DATE OF ACCIDENT: 21.01.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR DOOR POWER WINDOW MOTOR <i>1m</i>	1	290.0000	290.00
25	REAR DOOR REGULATOR <i>1m</i>	1	120.7000	120.70
26	REAR DOOR OUTER WEATHERSTRIP MOULDING <i>1m</i>	1	140.0000	140.00
27	REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP <i>1m</i>	1	117.0000	117.00
28	REAR DOOR INNER TRIM BOARD <i>Defence</i>	1	392.0000	392.00
29	REAR DOOR 1/4 GLASS PILLAR <i>1m</i>	1	110.0000	110.00
30	REAR DOOR 1/4 GLASS WEATHERSTRIP <i>1m</i>	1	41.6000	41.60
31	REAR DOOR WEATHERSTRIP <i>1m</i>	1	120.7000	120.70
32	REAR DOOR OUTER HANDLE INNER BASE <i>1m</i>	1	57.0000	57.00
33	REAR DOOR HINGE TOP <i>1m</i>	1	46.0000	46.00
34	REAR DOOR HINGE BOTTOM <i>1m</i>	1	42.0000	42.00
35	REAR DOOR CHECKER/ARRESTOR <i>1m</i>	1	58.0000	58.00
36	REAR FENDER O/S <i>2m/2ad300</i>	1	334.0000	334.00
37	REAR FENDER INNER LINER <i>1m</i>	1	70.0000	70.00
38	REAR FENDER INNER LINER CLIPS <i>1m</i>	1	5.0000	5.00
39	REAR WINDSHIELD GLASS WEATHERSTRIP <i>1m</i>	1	117.0000	117.00
40	LESS 20% (ITEM 1 - 39)	1	-1,691.2800	-1,691.28
41	REAR WINDSHIELD GLASS SEALANT <i>1m</i>	1	180.0000	180.00
42	REAR WINDSHIELD GLASS SPONGE <i>1m</i>	1	120.0000	120.00
43	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,800.0000	1,800.00
44	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,200.0000	1,200.00

C/F 0.00

Page 2 of 3

*P-56121
4488.68*

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :

Customer : GRAB RENTALS 2 PTE LTD 28, SIN MING LANE, #07-71 MIDVIEW CITY SINGAPORE 573969 Attn : Tel : Fax :

Quotation No : QO18/01-1164	Quotation Date : 22/01/2018	Terms : 30 DAYS
Vehicle No : SLS5249A	Chassis No : JM6BN22A8H0160634	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: FIRST CAPITAL, INSURED'S VEH NO: SHC943T, DATE OF ACCIDENT: 21.01.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
45	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	1	120.0000	11 X 120.00
46	TO RUST-PROOFING OF THE AFFECTED AREAS	1	220.0000	120 220.00
47	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	11 180.0000	X 180.00
48	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	350.0000	80 350.00
49	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND DIAGNOSTIC MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK	1	11 650.0000	X 650.00
50	TO TRANSFER OF O/S FRONT AND REAR DOOR FITTING, FIXTURE AND CONDUCT WATER SEEPAGE AND WINDS NOISE TEST	1	250.0000	120 250.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

2720
720868
5767

Sub Total	11,835.12
GST(7.00%)	828.46
Total (SGD)	12,663.58

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001383/Uvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-02-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 943T	Veh. Inspected	SLS 5249A	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18000698MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	23/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN22A8H0160634	Colour	BLUE	
Odometer	28968	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/01/2018	Inspection Date	23/01/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 5249A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR O/S	BADLY DENTED	1,062.00	1,062.00
1	FRONT DOOR INNER LOCK	TWISTED / SHORTED	240.00	240.00
1	FRONT DOOR INNER LOCK STRIKER	NOT NECESSARY	26.00	-
1	FRONT DOOR POWER WINDOW MOTOR	BENT / JAMMED	790.00	142.00
1	FRONT DOOR REGULATOR	BENT	120.70	120.70
1	FRONT DOOR OUTER WEATHERSTRIP MOULDING	NOT NECESSARY	140.00	-
1	FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	NOT NECESSARY	165.00	-
1	FRONT DOOR OUTER HANDLE	CUT	61.00	61.00
1	FRONT DOOR OUTER HANDLE EXTENSION	CUT	18.00	18.00
1	FRONT DOOR OUTER HANDLE INNER BASE	DAMAGED	33.00	33.00
1	FRONT DOOR INNER TRIMBOARD	NOT NECESSARY	844.00	-
1	FRONT DOOR WEATHERSTRIP	NECESSARY	107.00	107.00
2	FRONT DOOR RUBBER STOPPER @\$20.00	NOT NECESSARY	40.00	-
1	FRONT DOOR HINGE TOP	NOT NECESSARY	42.00	-
1	FRONT DOOR HINGE BOTTOM	NOT NECESSARY	40.00	-
1	FRONT DOOR CHECKER/ARRESTOR	NOT NECESSARY	37.00	-
1	FRONT DOOR WINDOW FRAME GARNISH TOP	NOT NECESSARY	111.00	-
1	FRONT DOOR WINDOW FRAME GARNISH REAR	NOT NECESSARY	65.00	-
1	DOOR CENTRE B PILLAR	BADLY DENTED	880.00	880.00
1	ROCKER PANEL O/S	BADLY DENTED	360.00	360.00
1	REAR DOOR O/S	BADLY DENTED	1,006.00	1,006.00
1	REAR DOOR INNER LOCK	TWISTED / SHORTED	179.70	179.70
1	REAR DOOR INNER LOCK STRIKER	NOT NECESSARY	28.00	-
1	REAR DOOR POWER WINDOW MOTOR	JAMMED	290.00	290.00
1	REAR DOOR REGULATOR	BENT	120.70	120.70
1	REAR DOOR OUTER WEATHERSTRIP MOULDING	NOT NECESSARY	140.00	-
1	REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	NOT NECESSARY	117.00	-
1	REAR DOOR INNER TRIM BOARD	DEFORMED / CRACKED	392.00	392.00

Report Ref No. CS/FCI18001383/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR DOOR 1/4 GLASS PILLAR	NOT NECESSARY	110.00	-
1	REAR DOOR 1/4 GLASS WEATHERSTRIP	NOT NECESSARY	41.60	-
1	REAR DOOR WEATHERSTRIP	NECESSARY	120.70	120.70
1	REAR DOOR OUTER HANDLE INNER BASE	NOT NECESSARY	57.00	-
1	REAR DOOR HINGE TOP	TWISTED	46.00	46.00
1	REAR DOOR HINGE BOTTOM	TWISTED	42.00	42.00
1	REAR DOOR CHECKER/ARRESTOR	TWISTED	58.00	58.00
1	REAR FENDER O/S	BUCKLED / BADLY DENTED	334.00	334.00
1	REAR FENDER INNER LINER	NOT NECESSARY	70.00	-
1	REAR FENDER INNER LINER CLIPS	NOT NECESSARY	5.00	-
1	REAR WINDSHIELD GLASS WEATHERSTRIP	NOT NECESSARY	117.00	-
	LESS 20% DISCOUNT		-1,691.28	-1,122.56
			6,765.12	4,490.24
	SPECIAL NETT ITEMS			
1	REAR WINDSHIELD GLASS SEALANT (SN)	NOT NECESSARY	180.00	-
1	REAR WINDSHIELD GLASS SPONGE (SN)	NOT NECESSARY	120.00	-
			300.00	-
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.		1,800.00	1,400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,200.00	1,000.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		220.00	120.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMMINGS,GARNISH AND OTHER,TO ENABLE REPAIR.		350.00	80.00
	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND DIAGNOSTIC MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	650.00	-

Report Ref No. CS/FCI18001383/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER O/S FRONT AND REAR DOOR FITTING, FIXTURE AND CONDUCT WATER SEEPAGE AND WINDS NOISE TEST.		250.00	120.00
			4,770.00	2,720.00
GRAND TOTAL			11,835.12	7,210.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,750.00

Report Ref No. CS/FCI18001383/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.