

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 6693T

MAKE :

MODEL : HYUNDAI i40

48 hrs Ended

AXA - CP/P

DATE 18/1/2018 (Thurs)

TS

LKK - Calvin

1600

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille			\$ 1,480.00
	Radiator Grille H Emblem X			\$ 290.80
	Radiator Grille Chrome Moulding X			\$ 395.50
	Front Bumper Cover X repair			\$ 1,052.20
	Front Bumper Sponge ?			\$ 142.20
	Front Bumper Reinforcement ?			\$ 526.10
	Front Bumper Bracket Top (LH/RH) >		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) ?		\$ 24.60	\$ 49.20
	SUB TOTAL			\$ 3,980.80
	LESS 20% DISCOUNTED TOTAL			\$ 796.16
				\$ 3,184.64
	Front Number Plate /			\$ 25.00 Nett
	Front No Plate Trim Cover /			\$ 30.00 Nett
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 380.00 ²⁰⁰
	Spray Painting Charge			\$ 200.00 ¹⁸⁰
	TOTAL LABOUR			\$ 580.00
	ESTIMATE TOTAL			\$ 3,819.64

Calvin LKK
 22/1/18 1615 hrs.
 2 Days
 PIP
 After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display data
- Parts prices
- Third party information
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

knowledge Repairer

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.