

15/5/2010

INS. CASE OWNER:

Lynn

CC4/EQ118001386/KUS3SV

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

23/1/18

Date / Time:

23/01/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBB 5413L

Claim No.:

Name of Insured:

SHADETIMES (PTE) LTD

Policy No.:

DMCPHQ17-006993

Insured Tel No.:

HP: 8182 2386

Make / Model:

NISSAN CABSTAR 3.0 5MT ABS 200

Excess Sec II :SS

D.O.A: 22/01/18

Place of Accident:

ALONG SISHAN ROAD

Is driver the owner?

(YES) (NO)

Nature of Accident:

If NO, Driver Name / Age: DNANDAPANI SALAGURU

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.: 8280 8161

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SGR 1905E



INSRS:

WSP: Hui Yang

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

26/3/18

Confirm with:

Marco Neo

Email

Call

Final Liability:

%

100

(

Agreed / Assessed)

BOLA S/N No.:

27

Repair Cost:

Inc. Ref

SS

5992.00

Loss of Rental (LOR):

SS

749.00

(

7

days) x 100

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

6743.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

6743.00

Name 1:

HUI YANG MOTOR PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF:

EG/

Ref: 1801386/Kuss

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

24/1 File pass to Customer

US - \$5600+ (Red: \$6509.85/541.)

Veh No:

SGR 1905E

Yr Regn:

02, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Verel

c.c.

1496

Colour

m. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

053704

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RUI

1018800

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

3

mm

Rear

R/Bal.

3

mm

L/Bal.

3

mm

L/Bal.

3

mm

D.O.A.

22/1/18

D.O.I.

23/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQI18001386/Kus3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 23-01-2018	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 5418L	Veh. Inspected	SGR 1905E	
Policy No.	DMCPHQ17-006993	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	23/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/01/2018	Inspection Date	23/01/2018	
Survey held at	HUI YANG MOTOR SERVICE BLOCK 176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Ku

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

EQ
23/01/18
(Tuesday)
LKK

22/01/2018

Owner: TAY MEI XIAN

Not Authorised
Achieving 84 points
61 Pp & 5600h
Galaxy

ESTIMATE TO REPAIR HONDA VEZEL - SGR1905E

1pc	rear tailgate	Rs	\$ 1,100.90	✓
1pc	rear tailgate "honda" logo	Rs	\$ 27.00	✓
1pc	rear tailgate "vezel" emble	Rs	\$ 55.10	✓
1set	rear tailgate windscreen moulding	Rs	\$ 120.00	✓
2pcs	rear tailgate number plate lamp @\$38.50	Sm	\$ 77.00	X
1pc	rear tailgate outer garnish	Rs	\$ 220.30	✓
2pcs	rear tailgate reflector @\$350.80	Rs	\$ 701.60	✓
1pc	rear tailgate inner lock	Rs	\$ 198.40	✓
1pc	rear tailgate inner rubber	Rs	\$ 135.20	✓
1pc	rear tailgate inner garnish	Rs	\$ 252.70	✓
1pc	rear tailgate inner handle garnish	Sm	\$ 20.70	X
1pc	rear tailgate wiper motor	Rs	\$ 250.90	✓
2pcs	rear tailgate absorber @\$180.90	Sm	\$ 361.60	X
2pcs	rear taillamp @\$460.60	Rs	\$ 921.20	✓
2pcs	rear taillamp inner panel @\$195.90	Rs	\$ 391.80	X
1pc	rear bumper	Rs	\$ 986.30	✓
2pcs	rear bumper side bumper @\$195.20	Rs	\$ 390.40	✓
2pcs	rear bumper side retainer @\$24.80	Sm	\$ 49.60	X
2pcs	rear bumper reflector @\$151.50	Sm	\$ 303.00	X
1pc	rear end panel	Rs	\$ 530.90	✓
1pc	rear end panel inner garnish	Rs	\$ 109.90	✓
1pc	rear end panel inner sensor	Rs	\$ 195.50	✓
1pc	rear end panel outer sensor	Sm	\$ 180.25	X
Balance c/f				\$ 7,580.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

22/01/2018

Owner: TAY MEI XIAN

ESTIMATE TO REPAIR HONDA VEZEL - SGR1905E

Balance b/f

\$ 7,580.25

2pcs	rear fender inner garnish @\$321.90
2pcs	rear fender protector @\$150.00
1pc	rear spare trye panel
1pc	rear spare trye cardboard
1pc	rear spare trye sponge
1pc	rear spare trye lower garnish

Pm	\$	643.80	X
cls Bu	\$	300.00	LT
R	\$	1,130.60	X
Sm	\$	300.40	X
cm	\$	320.40	~
in	\$	181.90	X

\$ 10,457.35

less 20%

\$ 2,167.50

\$ 8,289.85 8365.88

1 set	rear reverse sensor
1pc	rear reverse camera

Shan	s.nett	\$	280.00	2 cam
Shan	s.nett	\$	380.00	2 50sn

remove & refix rear windscreen glass
car-on-liner
wiring
tuffkote
sealant
spray painting
labour charges
Total

\$	120.00	✓
ru	\$	250.00 X
\$	150.00	201
\$	220.00	601
rac	\$	120.00 30sn
\$	1,200.00	8001
\$	1,100.00	7001
\$	12,109.85	

12185.88



輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

EQ
23/01/18
(Tuesday)
LKK

22/01/2018

Owner: TAY MEI XIAN

Not Authorised
Henry Bepain
6 days

ESTIMATE TO REPAIR HONDA VEZEL - SGR1905E

1pc	rear tailgate			R	\$ 1,100.90	✓
1pc	rear tailgate "honda" logo			m	\$ 27.00	✓
1pc	rear tailgate "vezel" emble			m	\$ 55.10	✓
1set	rear tailgate windscreen moulding			m	\$ 120.00	✓
2pcs	rear tailgate number plate lamp @\$38.50				\$ 77.00	?
1pc	rear tailgate outer garnish			m	\$ 220.30	✓
2pcs	rear tailgate reflector @\$350.80	<i>o/s car</i>	<i>n/s car</i>		\$ 701.60	✓
1pc	rear tailgate inner lock			m	\$ 198.40	✓
1pc	rear tailgate inner rubber			<i>DI 117</i>	\$ 135.20	✓
1pc	rear tailgate inner garnish				\$ 252.70	?
1pc	rear tailgate inner handle garnish			Sm	\$ 20.70	X
1pc	rear tailgate wiper motor				\$ 250.90	?
2pcs	rear tailgate absorber @\$180.90			Sm	\$ 361.60	X
2pcs	rear taillamp @\$460.60	<i>n/s ?</i>	<i>o/s car</i>		\$ 921.20	✓
2pcs	rear taillamp inner panel @\$195.90				\$ 391.80	?
1pc	rear bumper			Bm	\$ 986.30	✓
2pcs	rear bumper side bumper @\$195.20	<i>n/s car</i>	<i>o/s ?</i>		\$ 390.40	
2pcs	rear bumper side retainer @\$24.80			Sm	\$ 49.60	X
2pcs	rear bumper reflector @\$151.50			Sm	\$ 303.00	X
1pc	rear end panel				\$ 530.90	?
1pc	rear end panel inner garnish			m	\$ 109.90	✓
1pc	rear end panel inner sensor				\$ 195.50	?
1pc	rear end panel outer sensor				\$ 180.25	?
Balance c/f					\$ 7,580.25	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

22/01/2018

Owner: TAY MEI XIAN

ESTIMATE TO REPAIR HONDA VEZEL - SGR1905E

Balance b/f				\$ 7,580.25
2pcs	rear fender inner garnish @\$321.90	<i>Pr</i>	\$ 643.80	<i>X</i>
2pcs	rear fender protector @\$150.00	<i>cls Bu</i>	\$ 300.00	<i>LT</i>
1pc	rear spare tyre panel	<i>R</i>	\$ 1,130.60	<i>X</i>
1pc	rear spare tyre cardboard		\$ 300.40	<i>?</i>
1pc	rear spare tyre sponge		\$ 320.40	<i>?</i>
1pc	rear spare tyre lower garnish		\$ 181.90	<i>?</i>
			\$ 10,457.35	
less 20%			\$ 2,167.50	
			\$ 8,289.85	
1 set	rear reverse sensor	<i>Shan</i>	s.nett \$ 280.00	<i>2 cars</i>
1pc	rear reverse camera		s.nett \$ 380.00	<i>?</i>
remove & refix rear windscreen glass			\$ 120.00	<i>✓</i>
car-on-liner		<i>rr</i>	\$ 250.00	<i>X</i>
wiring			\$ 150.00	<i>201</i>
tuffkote			\$ 220.00	<i>601</i>
sealant			\$ 120.00	<i>301</i>
spray painting			\$ 1,200.00	<i>8001</i>
labour charges			\$ 1,100.00	<i>7001</i>
Total				
			\$ 12,109.85	





Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/EQI18001386/Kus3

Date: 25.01.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SGR 1905E


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23.01.2018 at the premises of M/s Hui Yang Motor Pte Ltd (Sin Ming) and have the following to report:-

Workshop Estimate Amount	: S\$	12,109.85
Revised Estimate Amount	: S\$	5,342.24
"Check" Items Amount	: S\$	3,050.04
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Tuesday, 23 January 2018 11:30 AM
To: assignments
Subject: FW: 3rd Party Claim for SGR1905E against GBB5418L(URGENT)
Attachments: SGR1905E 22.01.2018.pdf; GBB5418L 22.01.2018.pdf

11.57am @ 23/01/2018
vehicle in
person @ Bel
SUR @ Kenneth.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Bazlin Ahmad [mailto:bazlin.ahmad@eqinsurance.com.sg]
Sent: Tuesday, 23 January 2018 11:26 AM
To: Admin A <admin-a@lkkauto.com>
Cc: Janet Tan <janet.tan@eqinsurance.com.sg>; Elaine Cheong <elaine.cheong@eqinsurance.com.sg>; Bernadette Yeo <bernadette.yeo@eqinsurance.com.sg>
Subject: RE: 3rd Party Claim for SGR1905E against GBB5418L(URGENT)

Dear LKK

We refer to the above new assignment.
Kindly contact Hui Yang and please find attached both vehicles GIA reports for easy reference.

Thank You.

Regards,

Lynn Ahmad
Executive | Claims

eqnsurance


EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

 you've got a friend

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]
Sent: Tuesday, January 23, 2018 11:12 AM
To: Bazlin Ahmad
Cc: Janet Tan; Elaine Cheong; Bernadette Yeo
Subject: Re: 3rd Party Claim for SGR1905E against GBB5418L(URGENT)
Importance: High

URGENT

Hi Bazlin

We like to appoint **LKK Auto Consultants Pte Ltd** to conduct this survey.

**Kindly receipt of this email.*

Thank you & Regards,

Bel

Hp: 90473466

From: Hui Yang Motor <hui_yang_motor@hotmail.com>
Sent: Tuesday, January 23, 2018 10:39 AM
To: Bazlin Ahmad
Cc: Janet Tan; Elaine Cheong; Bernadette Yeo
Subject: Re: 3rd Party Claim for SGR1905E against GBB5418L(URGENT)

URGENT

Hi Bazlin

Kindly help to arrange surveyor by today as requested on yesterday email dated 22/01/2018.

Thank you & Regards,

Bel

Hp: 90473466

From: Tan Wei Yin <weiyin.tan@eqinsurance.com.sg>
Sent: Monday, January 22, 2018 2:03 PM
To: Bazlin Ahmad
Cc: Janet Tan; Elaine Cheong; Bernadette Yeo; hui_yang_motor@hotmail.com
Subject: FW: 3rd Party Claim for SGR1905E against GBB5418L

FYNA

Regards,

Tan Wei Yin
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9882 | tel 65 6223 9433 ext 882 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]
Sent: Monday, January 22, 2018 2:01 PM
To: Elaine Cheong <elaine.cheong@eqinsurance.com.sg>; Janet Tan <janet.tan@eqinsurance.com.sg>; Tan Wei Yin <weiyin.tan@eqinsurance.com.sg>

Subject: 3rd Party Claim for SGR1905E against GBB5418L
Importance: High

URGENT

Hi

Please refer to attached estimate and will pass surveyor the GIA report tomorrow.

Please arrange surveyor to survey vehicle SGR1905E on 23/01/2018 (Tuesday) and vehicle already in our workshop.

Thank you & Regards,

Bel

Hp: 90473466



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 02/04/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBB 5418L (Insd Veh)	Your Ref. No. : DMCPHQ17-006993
	SGR 1905E (TP Veh)	Our Ref. No. : CC4/EQ18001386/Kus3s2
Date of Accident	22/1/2018	

Liability	100%	
Final Repair Cost	: \$ 5,992.00	(W/GST)
Loss of Use	: \$	days
Rental (If any)	: \$ 749.00	7 days
Others:	: \$ 2.00	
	: \$	
	6,743.00	
Final Settlement Sum	: \$ 6,743.00	
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	HUI YANG MOTOR PTE LTD	: \$ 6,743.00
		: \$

NUR SHAQILAH
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQ18001386/Kus3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 02-04-2018



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 5418L	Veh. Inspected	SGR 1905E
Policy No.	DMCPHQ17-006993	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	LYNN	Assign Date	23/01/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	RU11016600	Colour	METALLIC BLUE
Odometer	053704	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	DUNLOP	3 mm
L/H Front Tyre	215/60R16	DUNLOP	3 mm
R/H Rear Tyre	215/60R16	DUNLOP	3 mm
L/H Rear Tyre	215/60R16	DUNLOP	3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/01/2018	Inspection Date	23/01/2018
Survey held at	HUI YANG MOTOR SERVICE BLOCK 176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 1905E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	BENT	1,100.90	1,100.90
1	REAR TAILGATE "HONDA" LOGO	NECESSARY	27.00	27.00
1	REAR TAILGATE "VEZEL" EMBLEM	NECESSARY	55.10	55.10
1	SET REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	120.00	120.00
2	REAR TAILGATE NUMBER PLATE LAMP @ \$38.50	SERVICEABLE	77.00	-
1	REAR TAILGATE OUTER GARNISH	DENTED	220.30	220.30
2	REAR TAILGATE REFLECTOR @ \$350.80	O/S CUT / N/S CRACKED	701.60	701.60
1	REAR TAILGATE INNER LOCK	DENTED	198.40	198.40
1	REAR TAILGATE INNER RUBBER	DISTORTED / DENTED	135.20	135.20
1	REAR TAILGATE INNER GARNISH	MTG DISTORTED	252.70	252.70
1	REAR TAILGATE INNER HANDLE GARNISH	SERVICEABLE	20.70	-
1	REAR TAILGATE WIPER MOTOR	JAMMED	250.90	250.90
2	REAR TAILGATE ABSORBER @ \$180.90	SERVICEABLE	361.60	-
2	REAR TAILLAMP @ \$460.60	N/S SERVICEABLE / O/S CUT	921.20	460.60
2	REAR TAILLAMP INNER PANEL @ \$195.90	TO REPAIR SEE LABOUR	391.80	-
1	REAR BUMPER	BUCKLED	986.30	986.30
2	REAR BUMPER SIDE BUMPER @ \$195.20	N/S SERVICEABLE / O/S CRACKED	390.40	195.20
2	REAR BUMPER SIDE RETAINER @ \$24.80	SERVICEABLE	49.60	-
2	REAR BUMPER REFLECTOR @ \$151.50	SERVICEABLE	303.00	-
1	REAR END PANEL	BENT	530.90	530.90
1	REAR END PANEL INNER GARNISH	DENTED	109.90	109.90
1	REAR END PANEL INNER SENSOR	CRACKED	195.50	195.50
1	REAR END PANEL OUTER SENSOR	SERVICEABLE	180.25	-
2	REAR FENDER INNER GARNISH @ \$321.90	SERVICEABLE	643.80	-
2	REAR FENDER PROTECTOR @ \$150.00	O/S BUCKLED	300.00	150.00
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,130.60	-
1	REAR SPARE TYRE CARDBOARD	SERVICEABLE	300.40	-

Report Ref No. CC4/EQ18001386/Kus3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TYRE SPONGE	CRACKED	320.40	320.40
1	REAR SPARE TYRE LOWER GARNISH	SERVICEABLE	181.90	-
	LESS 20% DISCOUNT		-2,091.47	-1,202.18
			8,365.88	4,808.72
	SPECIAL NETT ITEMS			
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR REVERSE CAMERA (SN)	SHORTED	380.00	250.00
1	SEALANT (SN)	NECESSARY	120.00	30.00
			780.00	480.00
	LABOUR			
	REMOVE & REFIX REAR WINDSCREEN GLASS.		120.00	120.00
	CAR-ON-LINER.	NOT NECESSARY	250.00	-
	WIRING.		150.00	20.00
	TUFFKOTE.		220.00	60.00
	SPRAY PAINTING.		1,200.00	800.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF REAR TAILLAMP INNER PANEL AND REAR SPARE TYRE PANEL.		1,100.00	700.00
			3,040.00	1,700.00
	GRAND TOTAL		12,185.88	6,988.72
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,600.00

Report Ref No. CC4/EQI18001386/Kus3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.