

# 輝陽汽車有限公司

## HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

E.O.  
23/01/18  
(Tuesday)  
LKK

22/01/2018

Owner: TAY MEI XIAN

Not Authorised  
Resurvey Bypassing  
6 days

### ESTIMATE TO REPAIR HONDA VEZEL - SGR1905E

|             |                                          |         |             |   |
|-------------|------------------------------------------|---------|-------------|---|
| 1pc         | rear tailgate                            | By      | \$ 1,100.90 | ✓ |
| 1pc         | rear tailgate "honda" logo               | me      | \$ 27.00    | ✓ |
| 1pc         | rear tailgate "vezel" emble              | me      | \$ 55.10    | ✓ |
| 1set        | rear tailgate windscreen moulding        | me      | \$ 120.00   | ✓ |
| 2pcs        | rear tailgate number plate lamp @\$38.50 |         | \$ 77.00    | ? |
| 1pc         | rear tailgate outer garnish              | me      | \$ 220.30   | ✓ |
| 2pcs        | rear tailgate reflector @\$350.80        | o/s car | \$ 701.60   | ✓ |
| 1pc         | rear tailgate inner lock                 | me      | \$ 198.40   | ✓ |
| 1pc         | rear tailgate inner rubber               | o/s car | \$ 135.20   | ✓ |
| 1pc         | rear tailgate inner garnish              |         | \$ 252.70   | ? |
| 1pc         | rear tailgate inner handle garnish       | me      | \$ 20.70    | X |
| 1pc         | rear tailgate wiper motor                |         | \$ 250.90   | ? |
| 2pcs        | rear tailgate absorber @\$180.90         | me      | \$ 361.60   | X |
| 2pcs        | rear taillamp @\$460.60                  | o/s car | \$ 921.20   | ✓ |
| 2pcs        | rear taillamp inner panel @\$195.90      |         | \$ 391.80   | ? |
| 1pc         | rear bumper                              | me      | \$ 986.30   | ✓ |
| 2pcs        | rear bumper side bumper @\$195.20        | o/s ?   | \$ 390.40   |   |
| 2pcs        | rear bumper side retainer @\$24.80       | me      | \$ 49.60    | X |
| 2pcs        | rear bumper reflector @\$151.50          | me      | \$ 303.00   | X |
| 1pc         | rear end panel                           |         | \$ 530.90   | ? |
| 1pc         | rear end panel inner garnish             | me      | \$ 109.90   | ✓ |
| 1pc         | rear end panel inner sensor              |         | \$ 195.50   | ? |
| 1pc         | rear end panel outer sensor              |         | \$ 180.25   | ? |
| Balance c/f |                                          |         | \$ 7,580.25 |   |


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# 輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721  
Tel: 64515752 (2 Lines) . Fax: 64514658  
Reg No. 201629438M

22/01/2018

Owner: TAY MEI XIAN

## ESTIMATE TO REPAIR HONDA VEZEL - SGR1905E

|             |                                      |              |                               |
|-------------|--------------------------------------|--------------|-------------------------------|
| Balance b/f |                                      |              | \$ 7,580.25                   |
| 2pcs        | rear fender inner garnish @\$321.90  | <i>P2</i>    | \$ 643.80 <i>X</i>            |
| 2pcs        | rear fender protector @\$150.00      | <i>clsbu</i> | \$ 300.00 <i>LT</i>           |
| 1pc         | rear spare trye panel                | <i>R</i>     | \$ 1,130.60 <i>X</i>          |
| 1pc         | rear spare trye cardboard            |              | \$ 300.40 <i>?</i>            |
| 1pc         | rear spare trye sponge               |              | \$ 320.40 <i>?</i>            |
| 1pc         | rear spare trye lower garnish        |              | \$ 181.90 <i>?</i>            |
|             |                                      |              | <hr/>                         |
|             |                                      |              | \$ 10,457.35                  |
| less 20%    |                                      |              | <hr/>                         |
|             |                                      |              | \$ 2,167.50                   |
|             |                                      |              | <hr/>                         |
|             |                                      |              | \$ 8,289.85                   |
|             |                                      |              |                               |
| 1 set       | rear reverse sensor                  | <i>Shon</i>  | s.nett \$ 280.00 <i>200sn</i> |
| 1pc         | rear reverse camera                  |              | s.nett \$ 380.00 <i>?</i>     |
|             |                                      |              |                               |
|             | remove & refix rear windscreen glass |              | \$ 120.00 <i>✓</i>            |
|             | car-on-liner                         | <i>ru</i>    | \$ 250.00 <i>X</i>            |
|             | wiring                               |              | \$ 150.00 <i>201</i>          |
|             | tuffkote                             |              | \$ 220.00 <i>601</i>          |
|             | sealant                              |              | \$ 120.00 <i>30sn</i>         |
|             | spray painting                       |              | \$ 1,200.00 <i>8001</i>       |
|             | labour charges                       |              | \$ 1,100.00 <i>7001</i>       |
|             | Total                                |              | <hr/>                         |
|             |                                      |              | \$ 12,109.85                  |

