

1/22/2018

Claim Portal



English (default) - NOVA AUTO MOTIVE PTE LTD -

[Home](#)
[SERVICE REQUESTS](#)
[MESSAGES](#)
[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)
[Vehicle & Driver Details](#)
[Vehicle Condition](#)
[Taxes & Ratio](#)
[Parts & Labour](#)
[Miscellaneous](#)
[Summary](#)

Parts

Add

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC QUANTITY	PART PRICE(NET)	ACTION (PARTS)	REMOVE
☐	1	1			FRONT BUMPER				935	Scd -	935	Reviewing	☐
☐	2	1			FRONT BUMPER SIGNAL LAMP RH - CHECK				0	Scd -	0	Reviewing	☐
☐	3	1			FRONT BUMPER SIDE GRILLE RH - CHECK				0	9	0	Reviewing	☐
☐	4	10			FRONT BUMPER CLIPS				4.5	Scd -	45	Reviewing	☐
☐	5	1			HEADLAMP RH - CHECK				0	7	0	Reviewing	☐

1/22/2018

3 / 7

Claim Portal

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC COUNT%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
☐	6	1			FRONT DOOR MIRROR RH				550	CR -	550	Reviewing	
☐	7	1			FRONT FENDER RH				400	CR -	400	Reviewing	
☐	8	1			FRONT FENDER COWLING RH				135	?	135	Reviewing	
☐	9	10			FRONT FENDER COWLING CLIPS				4.5 new		45	Reviewing	
☐	10	1			FRONT WHEEL RIM ALLOY RH - CHECK				0 ent		0	Reviewing	
☐	11	1			FRONT KNUCKLE ARM RH - CHECK				0		0	Reviewing	
☐	12	1			FRONT WHEEL HUB RH				165	?	165	Reviewing	
☐	13	1			FRONT WHEEL BEARING RH				210	?	210	Reviewing	

FAN YOONG

22-01-18:17:33

1/22/2018

Claim Portal

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISCOUNT	PART PRICE/NET	ACTION (PARTS)	REMOVE
	14	1			FRONT SUSPENSION LOWER ARM RH - CHECK				0.7		0	Reviewing	
	15	1			FRONT BALL JOINT LOWER ARM RH - CHECK				0.7		0	Reviewing	
	16	1			FRONT SHOCK ABSORBER RH - CHECK				0.7		0	Reviewing	
Labour					+ Rivet 20pcs + Front suspension link rod RH + Shock absorber top mount RH								
					+ Front absorber stopper RH + Door mirror lamp RH.								
EDIT	SR NO		REPAIR/REPLACE (LABOUR)		PART NAME		LABOUR RER	LABOUR REPAIR	PAINT		ACTION (LABOUR)	COMMENT	REMOVE
	1		TO KNOCK & STRAIGHTEN FRONT DOOR RH, REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. TO REALIGN ALL CONNECTION				0	600/400	0		Reviewing		
	2		TO SPRAY PAINT ON FRONT BUMPER FENDER RH, FRONT DOOR MIRROR RH, FRONT DOOR RH				0	500	650		Reviewing		
	3		TO REMOVE AND REPLACE FRONT SUSPENSION RH				0	200/120	0		Reviewing		

Labour

Add

1/22/2018

Claim Portal

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	4		TO COMPUTER WHEEL ALIGNMENT	0	80 / 60	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS

Assessment Details

Summary

Miscellaneous

Parts & Labour

Taxes & Ratio

Vehicle Condition

Vehicle & Driver Details

General & Workshop Details



EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	1	TOWING CHARGE	Reviewing	55 /	SPECIAL NET	
☐	2	FRONT TYRE RH - CHECK	Reviewing	0	0 punctured SPECIAL NET 160.00	



SERVICE REQUESTS

MESSAGES

CLAIMS

Assessment Details

Summary

Miscellaneous

Parts & Labour

Taxes & Ratio

Vehicle Condition

Vehicle & Driver Details

General & Workshop Details

Claim Amount \$4,070.00

CATEGORY

ESTIMATE

REVISED AMOUNT

Spare Parts

\$2,485.00

\$2,485.00

Labour

\$880.00

\$880.00

Paint

\$650.00

\$650.00

Miscellaneous

\$55.00

\$55.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey

Hy 20060068

5 days

1/P

excess: null

Authorized

Res by paint



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: AXA INSURANCE PTE LTD

Address: 8 SHENTON WAY, #24-01 AXA TOWER
SINGAPORE 068811
ATTN: GARNET 68804635T/68804838F

DELIVERED TO MOVA AUTOMOTIVE
15 FAN YONG ROAD

Tax Invoice No: SIN1551355

Date: 01/08/2018

Area Code: 6 INS

Credit Terms: 90DAYS

Kian Hua Sales: KEVIN

P/O No: SJQ3212C

No.	Description	Qty	Unit Price	Amount
Our D/O No: DO1009643				
1	BUMPER VW BEE FRT	1	692.00	692.00
2	BUMPER S/LAMP VW BEE F/RH	1	50.00	50.00
3	FENDER VW BEE F/RH	1	250.00	250.00
4	CLIP VW FENDER SHIELD	10	1.80	18.00
Our D/O No: DO1009651				
5	RIVET VW BEE PANEL/TOP	19	2.50	47.50
Our S/O No: SOR1009369 Your P/O No: SJQ3212C Our D/O No: DO1009674				
6	D/MIRROR ASSY VW BE2 RH	1	280.00	280.00
7	CLIP VW BE2 BUMPER	7	1.80	12.60
8	CLIP VW BE2 BUMPER	3	1.80	5.40
Our D/O No: DO1009729				
9	H/LAMP VW BE2 RH	1	290.00	290.00
10	LOWER ARM VW BE2 F/RH	1	180.00	180.00

Customer's Signature / Company Stamp

Products sold are not returnable.

Page: 1 of 3

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:

TIME:

KEVIN - 01/08/2018 4:22:46 PM

Authorised Signature



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: AXA INSURANCE PTE LTD

Address: 8 SHENTON WAY, #24-01 AXA TOWER
SINGAPORE 068811
ATTN: GARNET 68804635T/68804838F

DELIVERED TO MOVA AUTOMOTIVE
15 FAN YOONG ROAD

Tax Invoice No: SIN1551355

Date: 01/08/2018

Area Code: 6 INS

Credit Terms: 90DAYS

Kian Hua Sales: KEVIN

P/O No: SJQ3212C

No.	Description	Qty	Unit Price	Amount
11	BALL JOINT VW BE2 RH	1	58.00	58.00
12	WHEEL BRG VW BE2 FRT	1	92.00	92.00
13	ABSORBER VW BT2 FRT	1	90.00	90.00
Our D/O No: DO1009734				
14	S/LAMP VW BE2 D/MIRROR RH	1	52.00	52.00
Our S/O No: SOR1009369 Your P/O No: SJQ3212C Our D/O No: DO1009734				
15	SPORT RIM VW BE2 'DELTA SOLE' 15"	1	650.00	650.00
Our D/O No: DO1009736				
16	STAY ROD VW BE2 FRT	1	59.00	59.00
Our D/O No: DO1009743				
17	FENDER SHIELD VW BE2 F/RH	1	65.00	65.00
Our S/O No: SOR1009470 Your P/O No: SJQ3212C Our D/O No: DO1009788				
18	KNUCKLE ARM VW BE2 F/RH	1	320.00	320.00

Customer's Signature / Company Stamp
Products sold are not returnable.

Page: 2 of 3

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:

TIME:

KEVIN - 01/08/2018 4:22:46 PM

Authorised Signature



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: AXA INSURANCE PTE LTD

Address: 8 SHENTON WAY, #24-01 AXA TOWER
SINGAPORE 068811
ATTN: GARNET 68804635T/68804838F

DELIVERED TO MOVA AUTOMOTIVE
15 FAN YONG ROAD

Tax Invoice No: SIN1551355

Date: 01/08/2018

Area Code: 6 INS

Credit Terms: 90DAYS

Kian Hua Sales: KEVIN

P/O No: SJQ3212C

No.	Description	Qty	Unit Price	Amount
19	WHEEL HUB VW BETII F/RH	1	240.00	240.00
20	MTG VW BET2 F/SHK	1	39.00	39.00
21	SHK BOOT VW BET2 FRT	1	33.00	33.00

Our D/O No: DO1009793

SJQ3212C VW BEETLE

Products received and checked to be in good condition	Sub-Total:	SGD 3,523.50
	G.S.T(7%):	246.65
	Total :	SGD 3,770.15

Customer's Signature / Company Stamp
Products sold are not returnable.

Page: 3 of 3

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:
TIME:

KEVIN - 01/08/2018 4:22:46 PM

Authorised Signature



Service Request Details

Claim	S8M007L6
Reference	
CS/ASM18001394/R1qd3s2Date	
January 19, 2018	Request Date
January 23, 2018	Due Date
April 24, 2018	Vendor Name
LKK AUTO CONSULTANTS PTE LOSS LTD (OD)	Type of Services
Own Damage	Services

Next Step

PAST DUE: Report that your block modify the Expected Completion Date.

Complete Work More

Vehicle Information

Incident Vehicle

SJQ3212C

Registration #

Make

Service Address

VOLKSWAGEN

BEETLE 1.6

1008, , 159722

Blk

Primary Contact/Insured

WONG SOK FAN AMY MRS CHOO YOO KEONG
61 MOUNT SINAI DRIVE, 277113, Singapore
amywsf55@yahoo.com.sg

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
SJQ3212C REVISED ESTIMATE.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	February 7, 2018
SJQ3212C SUPPLEMENTARY.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	February 7, 2018
SJQ3212C IA.pdf	Other	Other	LKK AUTO CONSULTANTS PTE LTD (OD)	January 25, 2018
SJQ3212C ESTIMATE.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	January 25, 2018
SJQ3212C INSD GIA RPT.PDF	Reports & Statement	GIA Report	TEO Kitty	January 23, 2018
EMAIL OD.msg	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	January 23, 2018
POLICE REPORT.pdf	Reports & Statement	Police Report	MOVA AUTOMOTIVE PTE LTD	January 22, 2018
IC & DL.pdf	Forms / Claim Documents	Driver's License / IDP	MOVA AUTOMOTIVE PTE LTD	January 22, 2018

SERVICE REQUESTS

MESSAGES

CLAIMS



Service Request Details

Claim	S8M007L6	Vehicle Information	
Reference		Incident Vehicle	SJQ3212C
CS/ASM18001394/R1tdss2Date		Registration #	Service Address
January 19, 2018	Request Date	Model	VOLKSWAGEN BEETLE 1.6
January 23, 2018	Due Date		1008, , , 159722
April 24, 2018	Vendor Name	Primary Contact/Insured	
LKK AUTO CONSULTANTS PTE LTD (OD)	Type of Loss	WONG SOK FAN AMY MRS CHOO YOO KEONG	
Own Damage	Services	61 MOUNT SINAI DRIVE, 277113, Singapore	
		amywsf55@yahoo.com.sg	

Actions

Next Step

PAST DUE: Report that your block

Complete Work

More

modify the

Expected

Completion

Date.



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2009 VOLKSWAGEN BEETLE 1.6 (SJQ3212C)

Date of Loss

January 19, 2018

Time of Loss

19.15

Loss Description

SJQ3212C (INSD) C/W WC1305B

Comment

Workshop Details

Total Rebate Amount

10576

Nett Loss Amount

\$9,424.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

01/30/2018



Days of work completion *

7

Assessment Details

General & Workshop Details Vehicle & Driver Details Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SJQ3212C

Registration State
SINGAPORE

Mileage
112838

Purchase Date
mm/dd/yyyy

Registration Date *
04/30/2009

Age of Vehicle
8

CATEGORY Manufacturing Year

POLICY INFORMAT... 2009

ASSESSMENT INFO... 2009

Driver Details

CATEGORY Driver Name

FNOL INFORMATI... SOK FAN AMY WONG

POST SURVEY INF...

ASSESSMENT INFO...
WVWZZZ9CZ9M557592

CATEGORY Engine No
POLICY INFORMAT... BFS074106
ASSESSMENT INFO... LTA1701803

CATEGORY Engine Capacity
POLICY INFORMAT...
ASSESSMENT INFO... 1595 cc

CATEGORY Sum Insured
POLICY INFORMAT... 0
ASSESSMENT INFO... 0

CATEGORY Market Value
POLICY INFORMAT... 0
ASSESSMENT INFO... 20000

FNOL INFORMATI... 37

POST SURVEY INF...
CATEGORY Driver License #
FNOL INFORMATI... S1159224D
POST SURVEY INF...

CATEGORY License Type
FNOL INFORMATI... 3
POST SURVEY INF... ▼

CATEGORY License Issue Date
FNOL INFORMATI... April 23, 1981
POST SURVEY INF... mm/dd/yyyy

CATEGORY License Expiration Date
FNOL INFORMATI... April 23, 2000
POST SURVEY INF... mm/dd/yyyy

FNOL INFORMATI... S1159224D

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Front left side

MICHELIN 5mm

Rear left side

MICHELIN 5mm

Front right side

MICHELIN 5mm

Rear right side

MICHELIN 5mm

SERVICE REQUESTSMESSAGESCLAIMS

Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummaryParts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC CUNT%	SALV AGE%	PART PRICE(NET)	AC (P)
☐		1	1			FRONT BUMPER			Damaged	0				0	Rt
☐		2	1			FRONT BUMPER SIGNAL LAMP RH			Damaged	0				0	Rt
☐		3	1			FRONT BUMPER SIDE GRILLE RH (NPA)			Serviceable	0				0	Rt
☐		4	10			FRONT BUMPER CLIPS			Necessary	0				0	Rt
☐		5	1			HEADLAMP RH			Cracked	0				0	Rt
☐		6	1			FRONT DOOR MIRROR RH			Cracked	0				0	Rt
☐		7	1			FRONT FENDER RH			Cracked	0				0	Rt
☐		8	1			FRONT FENDER COWLING RH			Damaged	0				0	Rt

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
		2		TO SPRAY PAINT ON FRONT BUMPER FENDER RH, FRONT DOOR MIRROR RH, FRONT DOOR RH.	500	0	0	Reviewing	
		3		TO REMOVE AND REPLACE FRONT SUSPENSION RH.	120	0	0	Reviewing	
		4		TO COMPUTER WHEEL ALIGNMENT.	60	0	0	Reviewing	
		5		TOWING CHARGE.	55	0	0	Reviewing	

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR	Reviewing	5		
☐		2	PARTS SUPPLIED BY AXAS SUPPLIER \$3,523.50	Reviewing			
☐		3	FRONT TYRE RH	Reviewing	200	PUNCTURED	

SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary	Claim Amount	\$1,335.00	Claim Amount	\$1,335.00	

CATEGORY	ESTIMATE	REVISED AMOUNT
----------	----------	----------------

Labour	\$1,135.00	\$1,135.00
--------	------------	------------

Miscellaneous	\$200.00	\$200.00
---------------	----------	----------

Submit for Review