

LKK Auto Co. is to notify the Repairer of the following:

- To resurvey before or after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date: GST Reg. No: M28920628X

SERVICE ESTIMATE

6742 - C00001 SL: SERVICE SALES - PC
Mr Ow Chun Ming @ Victor Ow
850 Old Holland Road

Singapore 278691

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Ow Chun Ming @ Vi

Inv.No. . : B&P 0 Page 1
Inv.date. : 22/01/2018
WIP No. . : 41328
Veh.In/Out:
*Tel.No. . : Mobile: 96386933
Reg.No. . : SKF7878B
Reg.date . : 01/03/2012
Mileage ... : 0
Chassis No: SAJAC22F3CLV31111

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRT BUMPER, ALL BUMPER BRACKET, HEADLAMP, WHEELARCH, ETC	0	3600.00	0		3,600.00 S	1800
800	TO PUTTY SPRAYPAINT ON FRT BUMPER, LHF FENDER, ETC	0	3000.00	0		3,000.00 S	2000
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00 S	/
	BUMPER COVER FRT XJL RE	1.0 EA	2796.20			2,796.20 S	
	JC2D2819/MOUNTING-BR RE	1.0 EA	49.10			49.10 S	
	JC2D23098/WHEELARCH RE	1.0 EA	398.10			398.10 S	
	HEADLAMP RH XJL HID SCR	1.0 EA	3163.30			3,163.30 S	

4 Days.

Excess \$700

Not Authorised.

Guo Qiang - 82880282

Labour Total	7,086.00
Parts Total	6,406.70
Package Total	0.00

Gross Total.	13,492.70
Net.....	13,492.70
GST @ 7.0%	944.49
Total.....	14,437.20
Paid.....	0.00
Please Pay...	14,437.20

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

23/3/18

before paint photos.

After paint photos.

GuoQiang@lkkauto.com