

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0088/2018/JT
Date	:	22-Jan-17

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Sham Keat Min
Address	:	31 Mount Sinai Rise #16-07 Singapore 276953
Telephone	:	HP +65 8606 1181
Type of Claim	:	Own Damage Claims
Policy No.	:	170012497
Vehicle No	:	SCQ 6118 E
Model Code	:	Audi A4 Sedan 1.4 TFSI S-tronic
Model / Year	:	May-17
Engine No	:	CVN 038634
Chassis No	:	WAUZZZF4XA161793
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	18-Jan-18
Place of Accident	:	Commonwealth Avenue West

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCQ 6118 E.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N \$ 380.00	✓
2	To dismantle and renew rear bumper assy. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00	500
3	To respray rear bumper.	\$ 800.00	550
5	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>2,272.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCQ 6118 E.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>old</i>	\$ 1,907.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 63.00	X
3	REAR BUMPER SPOILER <i>cut</i>	\$ 216.00	✓
4	REAR BUMPER SECURING STRIP <i>new</i>	\$ 191.00	X
5	REAR REINFORCEMENT BEAM ?	\$ 786.00	?
6	REAR BUMPER OUTER GUIDE - LHS <i>2 new</i>	\$ 19.00	X
7	REAR BUMPER INNER GUIDE - LHS	\$ 211.00	X
8	REAR PARKING AID ?	\$ 215.00	?
9	REAR WHEEL HOUSE LINER - LHS <i>torn</i>	\$ 78.00	✓
10	REAR BUMPER LIGHT REFLECTOR - LHS <i>cracked</i>	\$ 35.00	✓
11	REAR BOOT LID CONTROL UNIT ?	\$ 362.00	?
12	REAR PARKING LID KICK OPEN SENSOR ?	\$ 184.00	?
13	CENTRE SILENCER ?	\$ 875.00	?
14	REAR SILENCER <i> Bent</i>	\$ 970.00	✓
15	DUAL CLIP ?	\$ 43.00	?
16	EXHAUST SILENCER BRACKET ?	\$ 37.00	?
17	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS CHARGES :		\$ 6,592.00	
TOTAL LABOUR CHARGES		\$ 2,272.00	
GRAND TOTAL		\$ 8,864.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ly
Surveyed Date : 23/01/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days.

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0088/2018/JT 23-Jan-18 Jeffery Tan 1 SCQ 6118 E Audi A4 Sedan 1.4 TFSI S-tronic
Quantity	Description	Unit Price	Amount
<u>LABORS</u>			
1	To cut out and renew mid silencer & rear silencer. To realign new silencer. (Special Nett)	\$ 480.00	/
	TOTAL	\$ 480.00	

For Premium Automobiles Pte Ltd

Adrian Ling
24/01/18.

Authorised Signature