

CWS Adrian ASSIGNMENT (Office)
 From (Person): Sithara of FCI Date/Time: 10:04am @ 23/1/18
 Estimated Cost: _____ Bill to: _____

OD ☒ WS ☐ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGF 8591T Insured: SHC0061M

at Workshop m/s: MG solution Tel: 62431373

of 23 kaki Bukit Ave 4 # 02-03

Policy No: _____ Claim No: D18000682MFSH

Sum Insured: _____ Excess: _____

Make of Vehr: _____ DOA: 20/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' MOD Reimbursement: _____

Date/Time: 10:19am @ 23/1/18 Person Contacted: Ms. Hong Vehicle ID: OUT

Date/Time: _____ Action/Inspection: ☒ SGF 8591T

SHC0061M - X

SGF 8591T - X

SHC0061M - X

Wump Sum \$4900 (Red: 5524.33 : 52%)

REF:

ASSIGNMENT

From _____ Date _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGF8591T Yr Regn: 2006 AprilType: M. Car M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Sunny o.c. 1597Colour: Blue A/C Insured / Std / NI / NASp. Reading: 408073 T. Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1CFAN1620100160Gen. Cond: Good Fair / Poor / BurntSteering: Inorder Jammed / Leaked / Burnt orBrake: Inorder Jammed / Leaked / Burnt orModi: Nil S/Rim / STD A/Rim orTyre Size: F: 195/60R15R: 195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 23/01/18Survey held at M & SolutionDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap

MV: 201K X

GV: 15K

Next: 5K

RECEIVED 19 MAR 2010

Date/Time, File Pass to?

1) 1913 Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report
☒ : Final Report
Days Of Repair: 7Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$:

Photos:

Other:

TOTAL:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format: TPLump Sum / I.B.I: (\$ 4900)

170

170

50

50

72

342

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	22-01-2018	Our Ref No. D18000682MFSH
Accident Date	20-01-2018	Claim Type. Third Party
Insured Vehicle	SHC0061M	Third Party Vehicle. SGF8591T
Survey Location	23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRE#02-03	
Contact Person.	SU WONG	
Contact No.	62431373/ 0	Fax No. 62431376
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MG SOLUTION PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234165)



PRI Documents



Close



PRI Header Details

Claim No	D18000682MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & MG SOLU
Workshop Name	MG SOLUTION PTE LTD (Contact Person : SU WONG)	Survey Location & Contact Details	23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRE#02-03 Mobile: 0 , Phone: 62431373 , Fax: 62431376 EmailId: MG3SOLUTION@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0061M	TP Vehicle No	SGF8591T
PRI Recieved Date	22-01-2018 09:22:49 PM	Surveyor Appointed Date	23-01-2018 10:03:46 AM	Surveyor Accept Date	23-01-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	23-01-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001412/Atd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-01-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 61M	Veh. Inspected	SGF 8591T
Policy No.		Coverage (\$)	0.00
Claim No.	D18000682MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	24/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	20/01/2018	Inspection Date	23/01/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18000682MFSH

Date: 19/3/2018

Our Ref: CS/FCI18001412/Atd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGF 8591T.

Please be informed that we had conducted the inspection of the abovementioned vehicle 23/01/2018 at the premises of M/s MG Solution. and have the following to report: -

Workshop Estimate Amount	: S\$ <u>10,424.33.</u>
Revised Estimate Amount	: S\$ <u>4,900.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at the rear.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Adrian

Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6028J
Vehicle Details	
Vehicle No.:	SGF8591T
Vehicle to be Exported:	Yes
Intended De-registration Date:	23 Jan 2018
Vehicle Make:	NISSAN
Vehicle Model:	SUNNY 1.6EXM
Primary Colour:	Blue
Manufacturing Year:	2006
Engine No.:	QG16408348
Chassis No.:	JN1CFAN16Z0100160
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$11,108.00
Original Registration Date:	25 Apr 2006
First Registration Date:	25 Apr 2006
Transfer Count:	0
Actual ARF Paid:	\$12,219.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Apr 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$23,039.00
COE Rebate Amount:	\$14,988.00
Total Rebate Amount:	\$14,988.00
Message	

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips

- GGMU 17/18 - New season
- Toyota wish queries
- Beware of 2nd Hand Car Dealers(Part 2) - Blacklist Her...

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 10 Year Coe Renewal Toyota Estima 2.4a



\$6800 Downpayment Monthly
From \$938 Onwards- Lowest
3.68% P.A @ GV Cars Financing.
GV Credit Pte Ltd StarAd

Free VICOM evaluation
Free grooming and 6 months maintenance
In-house workshop ensures quality service
Member of SVTA and hire purchase association
100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

11 vehicles

nissan sunny

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	nissan sunny		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Nissan Sunny 1.6A LE (COE till 03/2020)		\$19,999	\$9,150 /yr	20-Apr-2005	1,597 cc	107,490 km	Sedan	Available
Very Reliable, Accident Free Ride With New Pioneer Audio/DVD System With AUX Input. New Battery And New Tires. Includes Front And Rear Cameras. View To Believe. Viewings Strictly Via Appointment Only.									
Carro									
Posted: 12-Dec-2017 Tags: 2005 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan									
	Nissan Sunny 1.6A EX (COE till 04/2020)		\$18,000	\$7,930 /yr	25-May-2005	1,597 cc	125,000 km	Sedan	Available
1 Lady Owner. Purchased From Tan Chong. Low 125,000km. EX COE. Expire 4/2020. Full TC Auto Clinic Inspection Report. Replaced Original Key Parts By Tan Chong Motors. Others - New Brake Discs, Etc. Eng...									
Posted: 18-Jan-2018 Tags: 2005 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan									
	Nissan Sunny 1.6A EX (COE till 11/2020)		\$21,988	\$7,870 /yr	09-Nov-2005	1,597 cc	122,900 km	Sedan	Available
Lowest Depreciation \$19 Per Day Only. Well Maintained By Previous Owner. High Paper Value! Low Downpayment And Installment. Make An Appointment To View!									
Posted: 20-Jan-2018 Tags: 2005 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan									
	Nissan Sunny 1.6A EX (COE till 12/2020)		\$19,500	\$6,690 /yr	23-Dec-2005	1,597 cc	79,445 km	Sedan	Available
Well Maintained Vehicle Regularly Serviced. Very Low Mileage (79k km). Well Kept Condition Parked In Sheltered Parking! Good Air-conditioning, Very Quiet Engine.									
Posted: 07-Jan-2018 Tags: 2005 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan									
Car Buying Car Selling Car Aftermarket									
Car Ownership On The Move Lifestyle									
	Nissan Sunny 1.6A EX (COE till 12/2025)		\$48,800	\$6,150 /yr	29-Dec-2005	1,597 cc	102,000 km	Sedan	Available
Low Mileage And Recently Overhauled. Excellent Running Condition With New Tires (Yokohama), New Radiator And Hoses. New Paint In Original Factory Colour.									
Posted: 08-Jan-2018 Tags: 2005 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan									
	Nissan Sunny 1.6M EX (COE till 01/2021)		\$20,900	\$7,080 /yr	06-Jan-2006	1,597 cc	87,000 km	Sedan	Available
Sporty Fuel Efficient Sunny With A Factory Spoiler, Genuine Low Mileage (87k km), Well Kept Condition In And Out, On Time Regular Servicing, Tires Are Installed Just Before CNY And Paint Job Done Befo...									
Posted: 07-Dec-2017 Tags: 2006 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan									
	Nissan Sunny 1.6M EX (COE till 03/2026)		\$43,800	\$5,380 /yr	13-Mar-2006	1,597 cc	66,000 km	Sedan	Available
Good Condition. 1 Owner, Previously Converted From Off Peak Car. In House Loan Available.									
Posted: 19-Jan-2018 Tags: 2006 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan									

Buy Tyres Online!
Latest Special Offers from Tyrepac!



Nissan Sunny 1.6A EX (COE till 04/2021) **\$20,888** **\$6,410 /yr** **27-Apr-2006** **1,597 cc** **130,500 km** **Sedan** **Available**

Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Boeki Auto & Marine

Posted: 15-Jan-2018 Tags: 2006 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan



Nissan Sunny 1.6A EX (COE till 05/2021) **\$20,200** **\$6,140 /yr** **08-May-2006** **1,597 cc** **-** **Sedan** **Available**

Loan Up To 95%. Monthly Only \$654, No Gimmicks. All Our Vehicles Has Undergone A 120 Points Safety Check By Our In House Mechanics With Assessment Report And Come With One Year In House Warranty. Purc...

Posted: 12-Dec-2017 Tags: 2006 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan



Nissan Sunny 1.6A EX (COE till 05/2021) **\$19,280** **\$5,830 /yr** **16-May-2006** **1,597 cc** **-** **Sedan** **Available**

Low Mileage, Fantastic Condition, Flexible Repayment Scheme, Low Monthly Repayment As Low As \$488, low Maintenance, Practical Car For Family. Call Now For Viewing Now

PREMIUM AD

Posted: 14-Jan-2018 Tags: 2006 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan



Nissan Sunny 1.6A EX (New 5-yr COE) **\$29,800** **\$5,960 /yr** **21-Jan-2008** **1,597 cc** **75,688 km** **Sedan** **Available**

\$3,800 Down Payment, \$548 Monthly, Amazingly Low Mileage As It Was Previously An OPC Car, Super Duper Good Condition, Lowest Depreciation, \$500 Per Month. Don't Miss This Unit!

Posted: 22-Jan-2018 Tags: 2008 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used nissan sunny, nissan sunny Singapore, used nissan sunny Singapore, used nissan sunny, used vehicles Singapore or even buy used nissan sunny Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare [2]

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933 *

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO : FIRST CAPITAL INSURANCE LTD DATE : 22/01/2018
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM
ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO : SGF8591T
MODEL : NISSAN SUNNY 1.6
CHASSIS NO

Denise

INICFAN1620100160

ACCIDENT DETAILS DATE : 20-Jan-18
TIME : 10:35HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Detached</i>	1	\$ 690.00	\$ 690.00
2	REAR BUMPER <i>Detached</i>	1	\$ 483.80	\$ 483.80
3	REAR BUMPER MOULDING <i>for</i>	1	\$ 168.60	\$ 168.60
4	REAR BUMPER SPONGE <i>carld.</i>	1	\$ 160.00	\$ 160.00
5	REAR BUMPER BRACKET <i>Rit Detached</i>	2	\$ 96.70	\$ 193.40
6	REAR BUMPER SIDE RETAINER <i>for</i>	2	\$ 42.00	\$ 84.00
7	TAIL LAMP PANEL <i>Ryis</i>	2	\$ 289.70	\$ 579.40
8	REAR FENDER INNER TRIM <i>for</i>	2	\$ 255.30	\$ 510.60
9	REAR END PANEL <i>Detached</i>	1	\$ 433.20	\$ 433.20
10	REAR END PANEL TOP GARNISH <i>Detached</i>	1	\$ 98.80	\$ 98.80
11	REAR FLOOR PANEL <i>Ryis</i>	1	\$ 987.60	\$ 987.60

27257

1907.99

TOTAL PRICE \$ 4,389.40
LESS 30% \$ 1,316.82
SUB TOTAL PRICE \$ 3,072.58

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID LOGO <i>for</i>	1	\$ 55.20	\$ 55.20

2	BOOT LID EMBLEM 'SUNNY' <i>new</i>	1	\$ 77.40	\$ 77.40	✓
3	BOOT LID EMBLEM 'EX-SALOON' <i>new</i>	1	\$ 66.20	\$ 66.20	✓
4	BOOT LID EMBLEM 'CVTC' <i>new</i>	1	\$ 66.20	\$ 66.20	✓
5	BOOT LID EMBLEM 'E-THROTTLE' <i>new</i>	1	\$ 66.20	\$ 66.20	✓
6	BOOT LID HINGE <i>new</i>	2	\$ 76.60	\$ 153.20	✓
7	BOOT LID BOTTOM LOCK <i>new</i>	1	\$ 43.40	\$ 43.40	✓
8	BOOT LID WEATHERSTRIP <i>new</i>	1	\$ 179.20	\$ 179.20	✓
9	BOOTLID STOPPER <i>new</i>	4	\$ 39.90	\$ 159.60	✓
10	BOOT LID TOP LOCK <i>new</i>	1	\$ 139.40	\$ 139.40	✓
11	BOOT LID OUTER LOWER MOULDING <i>new</i>	1	\$ 193.80	\$ 193.80	✓
12	REAR BUMPER MUDFLAP <i>new</i>	2	\$ 92.70	\$ 185.40	✓
13	REAR TAIL LAMP <i>new</i>	2	\$ 383.20	\$ 766.40	✓ 566.40
14	REAR TAIL LAMP LOWER RETAINER <i>new</i>	2	\$ 37.00	\$ 74.00	✓
15	NUMBER PLATE GARNISH <i>new</i>	1	\$ 351.20	\$ 351.20	✓
16	NUMBER PLATE LAMP(SET) <i>new</i>	1	\$ 103.00	\$ 103.00	✓
17	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 177.70	\$ 177.70	✓

21677
1950-83

TOTAL PRICE \$ 2,857.50
LESS 10% \$ 285.75
SUB TOTAL PRICE \$ 2,571.75

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	✓
2	REAR BUMPER CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
3	TAIL LAMP CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
4	TAIL LAMP PANEL SEALANT <i>new</i>	2	\$ 80.00	\$ 160.00	✓
5	BOOT LID SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	✓
6	BOOT LID OUTER LOWER MOULDING CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
7	BOOT LID INSULATOR CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
8	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
9	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	✓
10	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 250.00	\$ 250.00	✓
11	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00	✓

320

TOTAL \$ 1,010.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	1000	
---	--	-------------	------	--

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	840	
3	TUFF COAT	\$ 250.00	40	
4	WIRING CHECK	\$ 120.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 180.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	
7	TRANSFER BOOTLID MECHANISM	\$ 80.00	60	
8	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x	
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x	

TOTAL

\$3,770.00

1940

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,654.33
TOTAL LABOUR COST : \$ 3,770.00
TOTAL REPAIR COST : \$ 10,424.33

Adrian G
23/01/18. total: 6118.92
L/s: 4.8k
L/s 07 days.

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :

SURVEYED BY :

CONTACT NUMBER :

FAX NUMBER :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001412/Atd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-03-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 61M	Veh. Inspected	SGF 8591T	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18000682MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	23/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SUNNY	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JN1CFAN16Z0100160	Colour	BLUE	
Odometer	408073	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/60 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/01/2018	Inspection Date	23/01/2018	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGF 8591T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	DENTED	690.00	690.00
1	REAR BUMPER	DEFORMED	483.80	483.80
1	REAR BUMPER MOULDING	NECESSARY	168.60	168.60
1	REAR BUMPER SPONGE	CRACKED	160.00	160.00
2	REAR BUMPER BRACKET @\$96.70	O/S DENTED	193.40	96.70
2	REAR BUMPER SIDE RETAINER @\$42.00	NECESSARY	84.00	84.00
2	TAIL LAMP PANEL @\$289.70	TO REPAIR SEE LABOUR	579.40	-
2	REAR FENDER INNER TRIM @\$255.30	TORN	510.60	510.60
1	REAR END PANEL	DISTORTED	433.20	433.20
1	REAR END PANEL TOP GARNISH	DEFORMED	98.80	98.80
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	987.60	-
	LESS 30% DISCOUNT		-1,316.82	-817.71
			3,072.58	1,907.99
NETT ITEMS				
1	BOOT LID LOGO (N)	NECESSARY	55.20	55.20
1	BOOT LID EMBLEM "SUNNY" (N)	NECESSARY	77.40	77.40
1	BOOT LID EMBLEM "EX-SALOON" (N)	NECESSARY	66.20	66.20
1	BOOT LID EMBLEM "CVTC" (N)	NECESSARY	66.20	66.20
1	BOOT LID EMBLEM "E-THROTTLE" (N)	NECESSARY	66.20	66.20
2	BOOT LID HINGE @\$76.60 (N)	NOT NECESSARY	153.20	-
1	BOOT LID BOTTOM LOCK (N)	DAMAGED	43.40	43.40
1	BOOT LID WEATHERSTRIP (N)	CUT	179.20	179.20
4	BOOTLID STOPPER @\$39.90 (N)	NOT NECESSARY	159.60	-
1	BOOT LID TOP LOCK (N)	DAMAGED	139.40	139.40
1	BOOT LID OUTER LOWER MOULDING (N)	CRACKED	193.80	193.80
2	REAR BUMPER MUDFLAP @\$92.70 (N)	NOT NECESSARY	185.40	-
2	REAR TAIL LAMP @\$383.20 (N)	CRACKED	766.40	566.40
2	REAR TAIL LAMP LOWER RETAINER @\$37.00 (N)	NOT NECESSARY	74.00	-
1	NUMBER PLATE GARNISH (N)	CRACKED	351.20	351.20

Report Ref No. CS/FCI18001412/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET NUMBER PLATE LAMP (N)	NOT NECESSARY	103.00	-
1	REAR FLOOR PANEL TOP BOARD (N)	TORN	177.70	177.70
	LESS 10% DISCOUNT		-285.75	-198.23
			2,571.75	1,784.07
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	SET TAIL LAMP CLIP (SN)	NECESSARY	20.00	20.00
2	TAIL LAMP PANEL SEALANT @\$80.00 (SN)	NOT NECESSARY	160.00	-
1	BOOT LID SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET BOOT LID OUTER LOWER MOULDING CLIP (SN)	NECESSARY	20.00	10.00
1	SET BOOT LID INSULATOR CLIPS (SN)	NOT NECESSARY	20.00	-
1	SET REAR END PANEL TOP GARNISG CLIPS (SN)	NECESSARY	20.00	10.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	150.00	60.00
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	250.00	-
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			1,010.00	320.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF TAIL LAMP PANEL AND REAR FLOOR PANEL.		1,400.00	1,000.00
	TO SPRAY PAINT AFFECTED AREA.		1,400.00	850.00
	TUFF COAT.		250.00	40.00
	WIRING CHECK.		120.00	30.00
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR.		180.00	60.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00
	TRANFER BOOTLID MECHANISM.		80.00	60.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	80.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			3,770.00	2,090.00

Report Ref No. CS/FCI18001412/Atd3n2



GRAND TOTAL		10,424.33	6,102.06
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,900.00

Report Ref No. CS/FCI18001412/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.