




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC3/EQI18001428/K1ea3s2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 30-04-2020		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBM 5706Y	Veh. Inspected	SHC 7183Z
	Policy No.	DMMPHQ17-000944	Coverage (\$)	0.00
	Claim No.	DM18HO00231	Excess (\$)	0.00
	Assign From		Assign Date	23/01/2018
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI I40	c.c	1685
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KMHLB41UMGU092399	Colour	YELLOW
	Odometer	266676	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	TRIANGLE	7 mm
	L/H Front Tyre	205/60 R16	TRIANGLE	7 mm
	R/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
	L/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION AND FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/01/2018	Inspection Date	23/01/2018
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	