

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

23-Jan-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6191 G

1 pc	Boot lid <i>x repair</i>	\$	1,119.00
1 pc	Boot lid lock ✓	\$	99.00
1 pc	Bootlid striker x	\$	21.00
1 pc	Bootlid emblem ✓	\$	27.00
1 pc	Bootlid CRDi ✓	\$	29.00
1 pc	Boot lid rubber weatherstrip x	\$	96.00
1 pc	Boot lid lower garnish <i>x repair</i>	\$	290.00
2 pcs	Bootlid hinge @ \$66.00 x	\$	132.00
1 pc	End panel ✓	\$	250.00
1 pc	End panel garnish ?	\$	74.00
1 pc	Spare tyre clamp ?	\$	6.00
1 pc	Rear muffler assy x	\$	1,009.00
1 pc	Rear exhaust pipe hanger x	\$	49.00
1 pc	Rear floorboard compartment panel ✓	\$	625.00
1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover ✓	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ✓	\$	58.00
1 pc	Rear bumper inner sponge ✓	\$	114.00
1 pc	Rear bumper reinforcement ✓	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ✓	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @\$18.00 ✓	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ✓	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 x	\$	92.00
1 pc	Support panel <i>x repair</i>	\$	645.00
1 pc	Bonnet grille ✓	\$	386.00
1 pc	Bonnet ✓	\$	979.00
1 pc	Front bumper ✓	\$	531.00
1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper centre grille ✓	\$	174.00
1 pc	Front bumper inner lower garnish x	\$	134.00
1 pc	Front bumper tow hook cover x	\$	14.00
1 pc	Front bumper lip x	\$	52.00
1 pc	Front bumper lower stiffer x	\$	134.00
1 pc	Front bumper inner sponge * ?	\$	110.00
1 pc	Front bumper reinforcement * ?	\$	328.00

23-Jan-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6191 G

2 pcs	Front bumper o/s & n/s side retainer @ \$16.00	X	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00	X	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00	X	\$	32.00
2 pcs	Front bumper o/s & n/s protector @ \$51.00	X	\$	102.00
2 pcs	n/s & o/s headlamp @ \$1028.00	n/s ✓ o/s X	\$	2,056.00
			\$	11,562.00
		Less 10%	\$	1,156.20
			\$	10,405.80

S/NETT

1 set	Rear bumper clips	✓	\$	48.00
1 set	End panel inner garnish clips	X	\$	30.00
1 set	Bootlid lower garnish clips	X	\$	60.00
1 set	Bootlid stickers	✓	\$	100.00
1 set	Reverse sensor	✓	\$	280.00 200
1 pc	Front no. plate with casing	✓	\$	50.00
1 pc	Front bumper clips	✓	\$	48.00
1 pc	Rear bumper top protector	✓	\$	80.00 50
1 set	Insulating padding	✓	\$	120.00
	Sundry		\$	50.00 20
	To dismantle / replace exhaust pipe		\$	120.00 50
	To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 50
	To top up aircon gas		\$	120.00 X
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, floorboard compartment. Including knock-out, straighten, repair, reshape and adjust of the same		\$	1,800.00 1200
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, front bumper, bonnet grille, bonnet.		\$	1,440.00 1440
	To apply rustproofing on the repaired and replaced panels.		\$	300.00 100
			\$	15,511.80

LKK
the #
• To
• Parts prices are subject to be
• Third party survey is on a "Without Prejudice" basis
• No illegal modifications is allowed
• Supplementary claim(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by
Date:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin (Clerk)
23/1/18 12:20hr.
8 Repair Days
L/S
After Repair photo.