

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45598
Date Estimated : 22/01/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Tong Mei Ling
770 Bedok Reservoir Road
#02-05

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 479250

REGN NO	CHASSI S NO	REGN DATE	MODEL	M LEAGE	
SLB9907Y	V259885	28/04/2016	216d CAT	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
To replace front bumper and attachments, LH fog lamp support, front LH door column 'B' cover, rear LH door column 'B' cover include making good the front LH door, rear LH door, rear LH fender and knocking out dents caused by the accident	2550.00		2,550.00		
To respray front bumper, front LH door, rear LH door, rear LH fender and LH wingmirror cover	3390.00		3,390.00		
To replace front LH door window glass include conducting water leak tests	413.00		413.00		
To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.	250.00		250.00		
Sundries.	80.00		80.00		

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
3M S/F CRYSTALLINE FRONT SIDE DOOR (A)	336.45	1.00		336.45
FRT BUMPER BOTTOM CARRIER	143.60	1.00		143.60
LH SUPPORT FOG LAMP (GESCHLOSSEN)	50.95	1.00		50.95
FRT BUMPER PANEL PRIMED (PMA)	842.00	1.00		842.00
LH ADDITIONAL TURN INDICATOR LAMP	61.80	1.00		61.80
FRT LH DOOR WINDOW GLASS	197.90	1.00		197.90
FRT LH DOOR COLUMN B COVER	59.95	1.00		59.95
COVER COLUMN B DOOR REAR LH	60.85	1.00		60.85
PLAQUE 82MM	69.50	1.00		69.50

SUPPLEMENTARY ITEMS

Total Labour :	6,683.00
Total Parts :	1,823.00
Total Labour & Parts :	8,506.00
Deduction for Excess :	0.00
Total Repair Costs less Excess:	8,506.00
GST @7%:	595.42
Grand Total :	9,101.42