

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHC4305J

Ref. No

TAX/01/18/2121

Reg. Date

Vehicle Type

22/11/2013

TAXI

Make

TOYOTA PRIUS

Model

PRIUS

Name of Driver

CHNG KENG YONG

Type of Accident

SIDE SWIPE

Date / Time of Accident

19/01/2018 07:45:00 PM

Accident Reported Date / Time :

20/01/2018 12:00:00 AM

Surveyor is Required?

Yes

Survey by

Yes

Vehicle is Towed Back? Towed Back Date/Time

19/01/2018

Replacement Vehicle issued? :

No

Accident Repair Job Card No :


000024094193

Special Instruction to ARC, if any :

TOWED \$60 / Ach / Remy after new

Prepared Date

20/01/2018 11:34:12 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKN36U20-5705522

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

676.00

0.00 0.00

0.00

0.00

0.00

1,952.27

Total Spray Painting Charges

756.00

Total Material Charges

1,913.22

Other Charges

424.00

Lum Sum Total

TOTAL

3,769.22

No. of Repair Days

3,750.00

5.00

Prepared / Adjusted By

Arc / Surveyor Sing Off Date

: 22/01/2018 09:31:03 AM

01/01/1900 12:00:00 AM

0.003 days/Luphu

22/01/18 01140

Prepared / Adjusted Date

Remarks

Prepared Date : 22/01/2018 09:31:03 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date :

Invoice Amount :

Prepared Date:

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if ar	plicable
TO REPAIR LH FRONT PORTION	676.00	0.00 3 50	
Total Labour	676.00	0.00	207020

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
TO REPSRAY FRONT BUMPER	378.00	0.00	200		
TO RESPRAY FRONT FENDER LH	378.00	0.00	ついし		
Total Spray Painting & Panel Beating	756.00	0.00			

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	84.00	0.00
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00 40
Total Other Costs	424.00	0.00

TAX/01/18/2121 Page: 3

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price	Discount	Final Price	ARC	Surveyor	Photos
T dilliou				li i	(\$)	(%)	(\$)	Recommen	Approved	Attached
52119- 47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	d Replace	Replace	-No
52116- 47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace	No
81521- 47050			LENS & BODY, FR TURN LH	1	511.80	10.00	460.62	Replace	Replace SCL /	No
81170- 47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace	No
53802- 47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace	
75374- 47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace		No
53876- 47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace	No
	TOTAL MATERIALS						2,440.35	2,440.34		
TOTAL MATERIALS(Discounted)						1,913.22	1,952.27			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

TAX/01/18/2121 Page: