

TP Direct Asia
Xiao Tong

SGA197C.

Mazda 3

JM6BK106100168482

Rear Number Plate	cauled	30(SN)	/
Rear Number Plate Assy	Reyd	121.80	/
Rear Bumper	Disbled	799	/
Rear Bumper Clips	~	30	/
Rear Bumper Side Holder x 02	m	$24.7 \times 2 = 49.40$	/
Rear Bumper Reflector x 02	HT m	$63 \times 2 = 126$	X
Rear Bumper Reinforcement	Best	374.50	/
Reverse Sensor	Reyd	250(SN)	200(SN)
Rear End Panel	Detsted	512.40	/
Rear End Panel Top Garnish	Rehd	162.10	/
Rear End Panel Sealant	m	60(SN)	/
Trunking x 02	RH cauled	$794.9 \times 2 = 1589.80$	754.80
Bootlid	Buckled	899.50	/
Bootlid Lock	Reyd	186.90	/
Bootlid Weatherstripe	ut	139.50	/
Bootlid Reflector x 02	HT m	$255 \times 2 = 510$	X
Mazda Logo	?	34.40	/
Mazda Wording	HT	25.70	/
3 Wording		24.50	/

SGA 197C.

Rear Fender Inner Trim x 02

Rear Fender Inner Trim Clips.

Rear Exhaust Pipe.

Rear Exhaust Mounting.

4154.60

332368

227.9 x 2 = 455.80

60

953.80

34.90

S.N. 1260

Panel Beating.

Spray Painting.

Wiring

To remove reverse sensor

To remove upholstery.

To undersell

To transfer bootlid fittings.

To remove exhaust pipe.

~~1200~~ 800

~~1200~~ 800

~~50~~ 30

~~100~~ 50

~~150~~ 40

~~150~~ 40

~~150~~ 60

~~150~~ X

1820

total: 5403.68.

2/8: AK.

06 Apr.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: