

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9769B - AIG

AAD1801-225

Not Notified
L1 Imp & 6300

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB9769B - JHOW

VF1ABL15AUC273294

RENAULT

LATITUDE

19.01.2018

AIG**PART****LIST**

1	1	BUMPER COVER REAR	\$	Sn 1,108.46	}
2	1	BUMPER LOWER REAR	\$	Sn 768.84	
3	1	BUMPER BRACKET CTR REAR	\$	Sn 113.47	
4	1	BUMEPR BRACKET SIDE RH REAR	\$	Sn 135.97	
5	1	BUMEPR RETAINER RH REAR	\$	Sn 44.99	
6	1	BUMPER REFLECTOR RH	\$	Sn 43.61	
7	1	BUMEPR BRACKET SIDE LH REAR	\$	Sn 135.97	
8	1	BUMEPR RETAINER LH REAR	\$	Sn 44.99	
9	1	ROCKER PANEL OUTER RH	\$	Bn 987.49	
10	1	SILL PANEL OUTER RH	\$	N 3,663.62	
11	1	SILL PANEL INNER RH	\$	N 732.33	}
12	1	FENDER PANEL REAR RH	\$	N 3,299.13	
13	1	WHEELARCH REAR RH	\$	Sn 543.47	}
14	1	TAILLAMP RH	\$	Sn 552.55	
15	1	TAILLAMP PANEL RH	\$	N 986.70	
16	1	EXHAUST REAR	\$	N 7,489.05	
17	1	EXHAUST CAP REAR	\$	N 230.49	
18	1	DOOR PANEL REAR RH	\$	Bn 2,844.66	
19	1	DOOR GUIDE REAR RH	\$	Sn 176.82	
20	1	DOOR HINGE UPPER RH	\$	N 274.50	
21	1	DOOR HINGE LOWER RH	\$	N 300.55	
22	1	DOOR CHECK REAR RH	\$	Sn 203.06	}
23	1	DOOR LOCK REAR RH	\$	N 908.75	
24	1	DOOR LOCK REAR RH	\$	N 908.75	
25	1	DOOR GRAB HANDLE REAR RH	\$	Sn 210.96	
26	1	DOOR HANDLE OUTER REAR RH	\$	Sn 126.49	
27	1	DOOR HANDLE CAP REAR RH	\$	Bn 35.52	
28	1	DOOR HANDLE SEAL REAR RH	\$	Sn 7.89	
29	1	DOOR HANDLE COVER REAR RH	\$	Sn 13.22	
30	1	DOOR HANDLE MODULE REAR RH	\$	Sn 133.60	
31	1	DOOR REGULATOR REAR RH	\$	N 1,135.10	}
32	1	DOOR REGUALTOR MOTOR REAR RH	\$	N 893.75	
33	1	DOOR FINISHER REAR RH	\$	Sn 423.10	
34	1	DOOR WHEATHESTRIIP REAR RH	\$	Sn 410.66	

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-225

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9769B - AIG

35	1	DOOR SEAL REAR RH	\$	<i>Sn</i>	162.02 X
36	1	DOOR WAIST SEAL OUTER REAR RH	\$	<i>Sn</i>	334.69 X
37	1	DOOR MOULDING REAR RH	\$	<i>Sn</i>	176.82 X
38	1	DOOR PANEL FRT RH	\$	<i>Bz</i>	2,844.66 ✓

TOTAL	\$	33,406.70
10%	\$	3,340.67
	\$	30,066.03

Special Nett

1	1SET	PARKING AID	\$	<i>Sn</i>	700.00	} X
2	1SET	REAR BUMPER CLIP	\$	<i>nn</i>	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i>	33.00	
4	1SET	BUMEPB BRACKET SIDE CLIP RH RR	\$	<i>nn</i>	10.00	
5	1SET	BUMEPB RETAINER RH CLIP RR	\$	<i>nn</i>	20.00	
6	1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i>	22.00	
7	1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i>	66.00	
8	1	EXHAUST MOUNTING REAR	\$	<i>Sn</i>	17.82	
9	1	TAILLAMP CLIP RH	\$	<i>nn</i>	5.00	
10	1SET	WHEELARCH CLIP RR RH	\$	<i>nn</i>	66.00	
11	2	REAR WINDSCREEN SELANT	\$	<i>nn</i>	80.00	
12	1	WINDSCREEN MOULDING	\$	<i>nn</i>	100.00	
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	
14	1	CAP HUB RH RR	\$	<i>Sn</i>	35.00	
15	1	RIM RH RR	\$	<i>Sn</i>	385.00	
16	1	TYRE RH RR	\$	<i>Sn</i>	330.00	
17	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i>	80.00 <i>605m</i>	
18	1	DOOR STICKER "Classic"	\$	<i>nn</i>	30.00 <i>155m</i>	
19	1	DOOR STICKER "6555-3333"	\$	<i>nn</i>	80.00 <i>605m</i>	

TOTAL	\$	2,225.82
TOTAL PARTS	\$	32,291.85

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>6601</i>
To reinstall rear bumper parking sensor.	\$	<i>nn</i> 170.00 X
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>901</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-225**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9769B - AIG

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	<i>8001</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
Towing Fees	\$	<i>nn</i> 120.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	<i>601</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	<i>1201</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	<i>nn</i> 380.00	<i>X</i>

TOTAL	\$	10,990.00
Over All Total	\$	43,281.85

(PARTS BY PARTS)**Repair Days****15 Days***5 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: