

**Meimien** *Tan* **ASSIGNMENT (Office)** **MSIG** **23/1/18 @ 10.25am**

From Person: Irene Tan of MSIG Date/Time: 23/1/18 @ 10.25am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD: HP WS: IP RES: OD RES: EVA / DN / MB / CS

To Inspect Vehicle No: SLK 8840P Insured: SJX 8662S

at Workshop no: Performance Tel: 63190174

of: 303 Alexandra Rd

Policy No: A28807739 QMY Claim No: 545477

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ Date: 10/01/2018

(Client's Record) lwp 29/01/2018

CA / REV / REP. / REV 24 HRS lwp 29/01/2018

Date/Time: 2.48pm @ 23/1/18 Person Contacted: Caroline Vehicle No: OUT

Date/Time: 23/1/18 Action/Remarks: ✓

SLK 8840P - X

SJX 8662S - X

30/1 - Report preli in meimien

Don't buy next SLK 22 2h. 5h max (Red 4466-hd)

REF: **MSLn**

# ASSIGNMENT

Form: **29012018**

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SLK 8840P**

at Workshop: **Performance**

of: **30S Alexandra Rd**

Insured

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Veh:

**Intirican**

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: **SLK 8840P** Yr Reg: **2016 July**

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

**BMW 216D**

CC: **1496**

Colour

**Grey**

A/C Insured / Std / NI / NA

Sp. Reading:

**28447**

Ti Radio Insured / Std / NI / NA

Eng No:

**W3A2B32090V791324**

C No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Mod: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

**205 / 60 R16**

R: **2**

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R. Bal:

**6**

mm

R. Bal:

**6**

mm

L. Bal:

**6**

mm

L. Bal:

**6**

mm

D.O.A.

D.O.I.

**29/1/18 @ 1420**

Survey held at:

**PM L**

Des. of Damages: Fnt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 29 JUN 2018

Date/Time: File Passed:



: Preli. Report



: Final Report

Date/Time: File Returned:

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

Add Fee:



Site Insp

\$



Interview

\$



Technical

\$



After-End

\$

Report Format:

**TP**

Lump Sum / L.B.I.:

**7623.80**



## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jan 2018		23 Jan 2018 10:25 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM KOK PENG, VINCENT (LIN GUOPING, VINCENT), ID: S8302240Z, Tel: +6598328351, Email: NOEMAIL		
Main Claimant:	Chu Mingshun, ID: S8239563F		
Vehicle Reg. No.:	SLK8840P	Date of Loss:	10/01/2018 18:00 - :59
Claim Type:	TP / 545477	Policy/Cover Note No.:	A28807739QMY(COMP) (Comprehensive) Coverage: 01/09/2017 - 31/08/2018
Vehicle Reg. No. (Insured):	SJX8662S	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/01/2018]		
Driver/Custodian (Insured):	LIM KOK PENG, VINCENT (LIN GUOPING, VINCENT) (34 / Male), NRIC: S8302240Z, Tel: +6598328351		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18001440/T1td3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 24-01-2018	
			Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJX 8662S		Veh. Inspected	SLK 8840P
Policy No.	A28807739QMY		Coverage (\$)	0.00
Claim No.	545477		Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)		Assign Date	24/01/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	10/01/2018		Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 30 Jan 2018

**Preliminary Advice**

Insured Vehicle No	: SJX8662S	Accident Date	: 10/01/2018
TP Vehicle No	: SLK8840P	Assignment Date	: 23/01/2018
Make	: BMW 216D	Est. Duration of Repair	: 5.00
Date of Inspection	: 29/01/2018		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,072.80
Revised Amount	:S\$	6,982.25
Check Items (Estimated)	:S\$	2,299.25
Total	:S\$	9,281.50

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( x ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/01/2018 07:26
Date Of Accident	10/01/2018 18:15
Exact Location Of Accident	KPE(TPE) BEFORE FORT ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK8840P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHU MINGSHUN
NRIC No	S8239563F
Email Address	MALCOLMCHU@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98386670
Alternative Phone No	OTHERS-98282152
<b>Vehicle Particulars</b>	
Manufacturer	BMW
Model	216D-1.5 D ACTIVE TOURER (F45) (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5087787894
Cover Note Number	

### Driver

Name of Driver	CHU MINGSHUN
NRIC No	S8239563F
Date Of Birth	22/11/1982
Occupation	INDOOR
Date Of Driving Pass	05/05/2008
Driving Experience	9 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98386670
Fax Number	
Contact Number	OTHERS-98282152
Email Address	MALCOLMCHU@GMAIL.COM

Address	310A PUNGGOL WALK #05-528
Postcode	821310
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PUNGGOL N.P.C
Police Station Address	ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT AND SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLA7689U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MOHAMED REDZUAN
NRIC/Passport Number	S7837184F
Contact Number	90476500
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJX8662S  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver VINCENT LIM  
NRIC/Passport Number S8302240Z  
Contact Number 98328351  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SJM5542H  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver MOHAMED KAMARULZAMAN  
NRIC/Passport Number S7901888J  
Contact Number 92393013  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)



## Sketch Plan


### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time: 11/01/2018  
0015


  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name: HAZIM  
NRIC/FIN No.: C7026928B

## Sketch Plan #2

### SKETCH PLAN

KPE (TPE) before Fort Rone Exit




### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


REFER TO REPORT NUMBER T/20180110/2194

However, I would like to clarify on line 4 of the report my car stopped completely and did not collide with the car in front (2M7629U). It was only after 3JX81623 collided into my car, that caused my car to move forward and lightly touch 2M7629U. The driver and passenger of 2M7629U came out to inspect their rear and there was no damage. Similarly there was no damage to the front of my car. I took down their details nonetheless so that they can provide an account of their story.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time: 8/8/2018  
0855

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name: HAZID  
NRIC/ID No: 92059218



Police Station Of Origin:  
Punggol N.P.C  
21A Tebing Lane SINGAPORE 828837  
Tel No: 1800-6049999

Report No: T/20180110/2194

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 10/01/2018 22:38	Vide Report No.:	Station Diary No.: 55
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: CHU MINGSHUN			Address: APT BLK 310A PUNGGOL WALK #05-528 SINGAPORE 821310		
ID Type / ID No.: NRIC NO / S8239563F			Contact No.: Home/Office: Mobile: 98386670		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 35	Date of Birth: 22/11/1982	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: CIVIL SERVANT			Driving Licence Information: Class: 2B,3A Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 10/01/2018 18:15	Type of Location: Straight Road
Location: Along Road 1 KALLANG PAYA LEBAR EXPRESSWAY  before Fort Road Exit 5 on lane 1				
Weather: Heavy rain		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJM5542H	Car				Seriously Damaged	1
SJX8662S	Car				Seriously Damaged	0
SLA7689U	Car				No Damage	3
SLK8840P	Car	BMW	216D ACTIVE TOURER D/AB LED	Grey	Slightly Damaged	0



**SINGAPORE  
POLICE FORCE**



T/20180110/2194

3 of 3

Police Station Of Origin:  
Punggol N.P.C  
21A Tebing Lane SINGAPORE 828837  
Tel No: 1800-6049999

Report No. T/20180110/2194

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: F / Sgt 2 WANG SHILING, ELVIN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 10/01/2018 22:38
Officer In Charge Of Case: TP / AEIT / SSI 2 SITIMARSITA BINTE BOHARI Contact No.: 65476219	Classification Of Case:  SN 085
Authentication Stamp NP168	 Singapore Police Force



Police Station Of Origin:  
Punggol N.P.C  
21A Tebing Lane SINGAPORE 828837  
Tel No: 1800-6049999

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLK8840P	NTUC Income Insurance Co-Operative Limited	5087787894	08/02/2017	07/02/2018

**Brief Details.**

On the 10/01/2018 at the 1815hrs, I was driving in my MPV bearing registration plate SLK8840P along KPE on the first lane. There was a car bearing registration plate SLA7689U ahead of me. We were driving along the lane for a while when suddenly the car SLA7689U jammed brake. Immediately I jammed brake too and my car stopped before colliding onto the car in front.

However shortly after I jammed brake, a car behind bearing registration plate SJX8662S collided upon the back of my car. Subsequently all drivers exit their vehicles. I then noticed that there was a forth car involved in this incident. I was informed by the driver behind me Vincent, the driver of SJX8662S that the reason he collided into was me was because a car bearing registration plate SJM5542H hit the back of his car, causing his car to hit mine. Vincent informed me that he was able to stop in time and avoid hitting my car when I jammed brake.

All four of us exchanged particulars. They are:

Driver of SLA7689U with three passengers (Car ahead of mine): Mohamed Redzuan bin Dolah S7837184F HP: 90476500

Driver of SJX8662S (Car directly behind): Lim Kok Peng, Vincent S8302240Z HP: 98328351

Driver of SJM5542H with one injured passenger (Car that hit SJX8662S): Mohamed Kamarulzaman bin Johari S7901888J HP: 92393013

An AETOS Corporal T06479 also came to assist us.

I notice that my rear bumper and rear door was damaged. There were scratches and dents on them. SJX8662S had a dent at the front and SJM5542H's front was heavily damaged. After I checked and exchanged particulars, I checked if my car is movable and depart the scene. Afterwards, I was informed via Whatsapp that the passenger at SJM5542H was injured and have to be conveyed to A&E.

There was no active in car camera installed inside my car. The driver of SLA7689U and SJX8662S have a in-car camera installed. The driver of SLA7689U informed he have to go to the workshop to extract the footage tomorrow. The driver of SJX8662S has video footage and will sent me the footage via whatsapp. The driver of SJM5542H and SJX8662S were arguing if the footage can be extracted right away however SJM5542H was unable to extract the footage.

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 157401559W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

290, Kampong Arang Road  
East Coast Centre  
Singapore 436180  
Tel. 63150888 (AfterSales)  
Fax. 67449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64756501 (AfterSales)  
64756524 (Motorrad)

29.01.2018  
Survey & repair



GST REG. NO : M2 - 0020081 - X

19 JAN 2018

## ESTIMATE

Estimate No. : b1 45557 Page No. : 1 of 2  
Date Estimated : 19/01/2018  
Prepared By : Inthiran A/L Thurasamy

## - ESTIMATE REPAIR FOR -

Chu Mingshun  
Blk 310A Punggol Walk  
#05-528

Singapore 821310

## - ACCOUNT - 40000

Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK8840P	V791324	12/07/2016	216d CAT	0

## DESCRIPTION

To replace rear bumper, tailgate, attachments and repair end panel.

1700 3,400.00

Painting rear bumper, tail gate and end panel.

1730 2,666.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

451 531.00

To remove and install rear windscreen glass including conduct water leak tests.

524 ✓ 649.00

To carry out body cavity preservation.  
(Per panel).

1100 118.00

Sundries.

80 / ? 150.00

Total Labour 1: 7,691.00

## DESCRIPTION

TRUNK LID  
REAR BUMPER PANEL PRIMED (PDC)  
REAR BUMPER CARRIER  
SUPPORT  
RR BUMPER LH INNER SIDE GUIDE  
RR BUMPER RH INNER SIDE GUIDE  
SET MOUNTS PDC SENSOR REAR  
BADGE (BMW)  
REAR FLAP TOWING EYE PRIMED  
DECOUPING RING PDC TORQUE CONVERTER  
ULTRASONIC SENSOR MINERALGRAU B39

QTY	PRIC
1	1,146.30
1	966.25
1	413.45
1	36.40
1	57.15
1	57.15
1	62.50
1	69.50
1	30.30
4	5.05
4	380.65

VALUE  
bt ✓ 1,146.30 ✓  
del ✓ 966.25 ✓  
bt? ✓ 413.45 ✓  
del ✓ 36.40 ✓  
del ✓ 57.15 ✓  
del ✓ 57.15 ✓  
un X 62.50 ✓  
del ✓ 69.50 ✓  
X 30.30 ✓  
del ✓ 20.20 ✓  
? 1,522.60 ✓

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438160  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 45557  
Date Estimated : 19/01/2018  
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK8840P	V791324	12/07/2016	216d CAT	0

Total Parts : 4,381.80

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 750 Policy / Uninsured Losses / Detail

Regn No. 291118 Claim No.           

Date & Time 29/1/18 Excess 50

Surveyor's Name Tan Jiah Sign Tan Jiah

Surveyor's Tel 97495749 Authorized Yes

Authorized Date            Time           

RESURVEY PARTS PHOTO BY SURVEYOR           

Surveyor's E-mail tanjiah@lkkauto.com

No. of Working Days Recommended 5 days

*Handwritten signature*  
30/1/18

Labour 1	:	7,691.00
Parts	:	4,381.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	845.10
Grand Total	:	12,917.90

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 45557  
Date Estimated : 19/01/2018  
Prepared By : Inthiran A/L Thurasamy

Page No. :

### REPAIR FOR -

Chu Mingshun  
Blk 310A Punggol Walk  
#05-528

Singapore 821310

### - ACCOUNT - 66

MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SLK8840P	V791324	12/07/2016	216d CAT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.60	3.00		7.80
# EXPANDING NUT *	1.00	2.00		2.00
# GROMMET *	0.75	2.00		1.50
# PLUG BLACK D=5MM *	0.90	7.00		6.30

Total Labour :	
Total Parts :	17.60
Total Labour & Parts :	17.60





## FINAL REPORT

Estimate No. : b1 45557  
Date Estimated : 19/01/2018  
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -  
Chu Mingshun  
Blk 310A Punggol Walk  
#05-528

- ACCOUNT - 66  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

Singapore 821310

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLK8840P	V791324	12/07/2016	216d CAT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, boot lid include knocking out dents caused by the accident	1700.00		1,700.00	
To spray paint rear bumper and boot lid	1730.00		1,730.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
To transfer lock mechanism from old to new boot lid include conducting checks on new bootlid central locking system for proper function	451.00		451.00	
To remove and install rear windscreen glass include conducting water leak tests	649.00		649.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.60	3.00		7.80
TRUNK LID	1,146.30	1.00		1,146.30
REAR BUMPER PANEL PRIMED (PDC)	966.25	1.00		966.25
# EXPANDING NUT *	1.00	2.00		2.00
REAR BUMPER CARRIER	413.45	1.00		413.45
SUPPORT	36.40	1.00		36.40
RR BUMPER LH INNER SIDE GUIDE	57.15	1.00		57.15
RR BUMPER RH INNER SIDE GUIDE	57.15	1.00		57.15
# GROMMET *	0.75	2.00		1.50
BADGE (BMW)	69.50	1.00		69.50
# PLUG BLACK D=5MM *	0.90	7.00		6.30

### # SUPPLEMENTARY ITEMS

Total Labour :	4,860.00
Total Parts :	2,763.80
Total Labour & Parts :	7,623.80
Deduction for Excess :	0.00
Total Repair Costs less Excess:	7,623.80
GST @7%:	533.67
Grand Total :	8,157.47

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jan 2018		23 Jan 2018 10:25 <a href="#">Edit Adj Rpt</a>	<b>S\$7,623.80</b> <a href="#">Edit Estimates</a>	<b>S\$7,623.80</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>LIM KOK PENG, VINCENT (LIN GUOPING, VINCENT)</b> , ID: S8302240Z, Tel: +6598328351, Email: NOEMAIL								
Main Claimant:	<b>Chu Mingshun</b> , ID: S8239563F								
Vehicle Reg. No.:	<b>SLK8840P</b>	Date of Loss:	10/01/2018 18:00 - :59 [17 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 545477</b>	Policy/Cover Note No.:	A28807739QMY(COMP) (Comprehensive) Coverage: 01/09/2017 - 31/08/2018						
Vehicle Reg. No. (Insured):	<b>SJX8662S</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Irene Tan Gek Ing</b> - 6594 2541]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 22/02/2018]								
Driver/Custodian (Insured):	<b>LIM KOK PENG, VINCENT (LIN GUOPING, VINCENT)</b> (34 / Male), NRIC: S8302240Z, Tel: +6598328351								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLK8840P (545477)

[SJX8662S]

TP

Chu Mingshun

Jan 10 2018 6:00PM

[LIM KOK PENG, VINCENT (LIN GUOPING, VINCENT)]

Performance Motors Limited

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View [View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/01/18 11:12	<b>Accident Statement</b> From: SC - Reg. No: SJX8662S, Claimant: LIM KOK PENG, VINCENT (LIN GUOPING, VINCENT)		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/01/18 17:06	<b>Adjuster Immediate Advice</b>		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/01/18 11:25	<b>accident photos</b>		Load JPG	<input checked="" type="checkbox"/>
2	22/01/18 11:25	<b>Accident Photos</b>		Load JPG	<input checked="" type="checkbox"/>
3	22/01/18 11:26	<b>Accident Photos</b>		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
2	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
14	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
20	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
21	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
22	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
23	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
24	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
25	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
26	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
27	29/06/18 10:37	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
28	29/06/18 10:38	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>
29	29/06/18 10:38	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>
30	29/06/18 10:38	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>
31	29/06/18 10:38	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>
32	29/06/18 10:38	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>
33	29/06/18 10:38	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>
34	29/06/18 10:38	<b>Reinspection Photo</b>		Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	29/06/18 10:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	29/06/18 10:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	29/06/18 10:39	Photo Before Spray	 Load JPG	<input checked="" type="checkbox"/>
38	29/06/18 10:39	Photo Before Spray	 Load JPG	<input checked="" type="checkbox"/>
39	29/06/18 10:39	Photo Before Spray	 Load JPG	<input checked="" type="checkbox"/>
40	29/06/18 10:39	Photo Before Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/01/18 11:12	TP GIA Report (SLK8840P) From: SC - Reg. No: 53X86625, Claimant: LIM KOK PENG, VINCENT (LIN GUOPING, VINCENT)	 Load PDF	
2	22/01/18 11:16	TP PRI with estimates	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001440/TD3Q2

Date: 29/06/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28807739QMY(COMP)

Claimant Vehicle No: SLK8840P Insured Vehicle No: SJX8662S

Date of Loss: 10/01/2018 Nature of Claim: TP Claim No: 545477

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SLK8840P**  
 Make & Model: BMW 216D, 1.5 D Active Tourer (F45) D/AB LED (A) Engine No: 33149601B37C15A  
 Reg. Date: 12/07/2016 (Man. Year: 2016) Chassis No: WBA2B32090V791324  
 Colour: Grey Odometer: 28449 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,549.40	2,843.80	1,705.60	37.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,541.00	4,780.00	2,761.00	36.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,090.40</b>	<b>7,623.80</b>	<b>4,466.60</b>	<b>36.94</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>846.33</b>	<b>533.67</b>	<b>312.66</b>	<b>36.94</b>
<b>Nett Amount (S\$)</b>	<b>12,936.73</b>	<b>8,157.47</b>	<b>4,779.26</b>	<b>36.94</b>

## INSPECTION

Date of Assignment: 23/01/2018

Date Inspected: 29/01/2018 Inspected At:

Performance Motors Limited (Alexandra)  
 303 Alexandra Road, Sime Darby  
 Performance Centre  
 Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2018)
<b>Parts:</b>	M1-MPV	BMW 216D 1.5 D Active Tourer (F45) D/AB LED (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLK8840P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*TRUNK LID	Bent	1,146.30 FS	*1,146.30 FS
3	1		*REAR BUMPER PANEL PRIMED (PDC)	Deformed	966.25 FS	*966.25 FS
4	1		*REAR BUMPER CARRIER	Bent	413.45 FS	*413.45 FS
5	1		*SUPPORT	Deformed	36.40 FS	*36.40 FS
6	1		*RR BUMPER LH INNER SIDE GUIDE	Deformed	57.15 FS	*57.15 FS
7	1		*RR BUMPER RH INNER SIDE GUIDE	Deformed	57.15 FS	*57.15 FS
8	1		*SET MOUNTS PDC SENSOR REAR	Not Necessary	62.50 FS	*- FS
9	1		*BADGE (BMW)	Necessary	69.50 FS	*69.50 FS
10	1		*REAR FLAP TOWING EYE PRIMED	Not Necessary	30.30 FS	*- FS
11	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.20 FS	*- FS
12	4		*ULTRASONIC SENSOR MINERALGRAU B39	Not Necessary	1,522.60 FS	*- FS
13	3		*BLIND RIVET NUT M6	Necessary	7.80 FS	*7.80 FS
14	2		*EXPANSING NUT	Necessary	2.00 FS	*2.00 FS
15	2		*GROMMET	Necessary	1.50 FS	*1.50 FS
16	7		*PLUG BLACK D= 5MM	Necessary	6.30 FS	*6.30 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>4,549.40</b>	<b>2,843.80</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER ,TAILGATE ,ATTACHMENTS AND REPAIR END PANEL	New	3,400.00	1,700.00
2	PAINTING REAR BUMPER ,TAIL GATE AND END PANEL	New	2,666.00	1,730.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
5	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS INCLUDING CONDUCT WATER LEAK TESTS	New	649.00	649.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (\$\$)			<b>7,541.00</b>	<b>4,780.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >