

CAR LIFE AUTO ENGINEERING SERVICES

w/s address: Blk 1002 Bukit Merah Lane 3 # 01-75 Singapore 159719

E-mail : autolife_sin@yahoo.com.sg

Tel: 6273 3810 Fax: 6278 7522

Date : 24.01.18

Address : MR LIM SOON KIAT JEFFREY
BLK 5 HOLLAND CLOSE
18-41
SINGAPORE 272005

Reference : TP 1143/01/18
Vehicle No : SGZ 7188B
Make/Model : HONDA ODYSSEY
Insurance Co. : AVIVA

RE : SUPPLYMENTARY QUOTATION REPAIRS TO SGZ 7188B FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>	<u>QTY</u>	<u>COST</u>	<u>AMT \$</u>
1) REVERSE SENSOR BUZZER	1		or ✓ \$95.00
2) REAR LICENSE CHROME LOWER	1		wt ✓ \$195.00

LIST PRICE TOTAL \$290.00
LESS DISCOUNT 25% 20% \$72.50
LIST PRICE TOTAL AFTER LESS \$217.50

NETT PRICE TOTAL \$0.00

TOTAL PARTS COST \$217.50

LABOUR AND MISCELLANEOUS CHARGES

pyllh
25/1/18

LABOUR TOTAL \$0.00

TOTAL ESTIMATED REPAIR COST \$ 217.50