

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB808G
 Ref. No : TAX/01/18/2140
 Reg. Date : 07/05/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : TAN AH SAN
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 23/01/2018 01:30:00 PM
 Accident Reported Date / Time : 23/01/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094252
 Special Instruction to ARC, if any :
 SHC2215Z (COMFORT) - III
 Prepared Date : 23/01/2018 04:29:59 PM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjun 97495744
 24/1/18 @ 220pm
 'WP' 02 days
 Lumpsum
 Resurvey after repair
 suv @ lkkauto.com

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis'No : JTDKN36UX05742057

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	0.00
Total Spray Painting Charges	: 378.00	0.00
Total Material Charges	: 504.86	515.16
Other Charges	: 280.00	0.00
TOTAL	: 1,500.86	0.00
Lum Sum Total	: 1,500.00	0.00
No. of Repair Days	: 3.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 23/01/2018 05:29:36 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 23/01/2018 05:29:36 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	0.00
Total Labour	338.00	0.00 200

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00
Total Spray Painting & Panel Beating	378.00	0.00 200

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	280.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No <i>de</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>rel</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>X</i>
	TOTAL MATERIALS							643.95	643.95	
TOTAL MATERIALS(Discounted)							504.86	515.16		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									