

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB808G

Ref. No : TAX/01/18/2140

Reg. Date : 07/05/2014

Vehicle Type : TAXI

Make : TOYOTA PRIUS

Model : PRIUS

Name of Driver : TAN AH SAN

Type of Accident : HEAD TO REAR

Date / Time of Accident : 23/01/2018 01:30:00 PM

Accident Reported Date / Time: 23/01/2018 12:00:00 AM

Surveyor is Required? : Yes

Survey by :

Vehicle is Towed Back? : No

Towed Back Date/Time :


Replacement Vehicle issued? : No

Accident Repair Job Card No : 000024094252

Special Instruction to ARC, if any:

SHC2215Z (COMFORT) - III

Prepared Date : 23/01/2018 04:29:59 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKN36UX05742057 Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC Adjusted by Surveyor, if applicable

Total Labout Charges: 338.000.00Total Spray Painting Charges: 378.000.00Total Material Charges: 515.16515.16

 Other Charges
 : 280.00
 0.00

 TOTAL
 : 1,511.16
 0.00

 Lum Sum Total
 : 1,500.00
 0.00

No. of Repair Days : 3.00 0.00

Prepared / Adjusted By :

Arc / Surveyor Sing Off Date : 23/01/2018 05:29:36 PM 01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 23/01/2018 05:29:36 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO REPAIR REAR PORTION	338.00	0.00		
Total Labour	338.00	0.00		

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO REPSRAY REAR BUMPER	378.00	0.00		
Total Spray Painting & Panel Beating	378.00	0.00		

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	280.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
52159- 47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
TOTAL MATERIALS					643.95 643.95			•		
	TOTAL MATERIALS(Discounted)						515.16	515.16		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
	TOTAL SUPPLEMENTARY MATERIALS								