

AS DEC 24

REF: CS/MSG18001443/Svd302

1. *What is the main purpose of the study?*
 2. *What are the research objectives?*
 3. *What is the research methodology?*
 4. *What are the results of the study?*
 5. *What are the conclusions of the study?*
 6. *What are the limitations of the study?*
 7. *What are the implications of the study?*
 8. *What are the future research directions?*
 9. *What are the contributions of the study?*
 10. *What are the key findings of the study?*

Sebastian ASSIGNMENT (Office)

Name: Sebastian ASSIGNMENT (Office)
 From (Person): Monica chung to MSIG Date: 20/1/18 @ 2:41pm

Estimated Cost: _____

OD/FP/WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No. EV 83382 Inspected SGF 34384

at Workshop no. Stuttard Auto Tel. 636 02845

12 Sungai Kandi Ave

Policy No: A80370498 MCX Claim No: 516880

— 1992 —

Make of Veh: _____ Date: 17/01/2018

(Client's Record) 23/1/18 @ 10-10:30 am

CA / REV / REP. REV 24 HRS 'wp'

Date/Time: 22/11/18 @ 3:40pm Person Checked: Erga Status: OUT

Date/Time: / /

EVR3332 - X

SGF34381-cs/MSG18000380/T1qdz D.O.A: 03/01/2018


25/1/18 Send preli revised by merimen

2/4/18 final fig \$ 22,220.26 (Red 8818.75, 289) confirmed by email

MS1G

MS1G

Ref: **MS1G** Date: **23/1/2018** File No: **EU 93557** Page: **11/11/2017**
 Estimated Cost: **TP RES / OD RES / EVA / INV / MV**
 To inspect vehicle no: **EZ 8338**
 at Workshop no: **TransEurokars**
 of: **12 Suranyi Radut Ave**
 Insured: **Eva**
 Policy No: **10-10-30am @ owner notifying**
 Claims No: **NS OS**
 Sum Insured: **Excess**
 (Client's Record)
 Make of veh: **10-10-30am @ owner notifying**
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal or Waver Value
 IDAC Accident Report: Consistent? : Yes or No
 BIA - PR Seen: Consistent? : Yes or No
 Est. Repairs: **8** days Res: Yes or No
 Cum Sum: % B/w: Yes or No
 OA / REV / REP. / 24 HRS
 Date: Person Contacted: Vehicle IN / OUT
 The LIC Chassis frame Body Structure affected due to collision



Type: **MCycle Bus Van Long Taxi Prime Mover**
 Truck / Trailer
 Make: **Borse** Model: **1984**
 Color: **Black** A/C: **Insured Std: N/A**
 Seating: **2497** TP: **Insured Std: N/A**
 Eng No: **WP1222 952368 03/08**
 Gen. Cond: **Good / Fair / Poor / Burnt**
 Steering: **In Order / Jammed / Leaked / Burnt**
 Brake: **In Order / Jammed / Leaked / Burnt**
 Mod: **SI / Rim / STD A/Rim**
 Tyre Size: **R: 195/40 R16**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or **Michelin**
 Front: **R Bal: 8 mm L Bal: 8 mm D.O.I: 17/1/18**
 Rear: **R Bal: 8 mm L Bal: 8 mm D.O.I: 13/1/18**
 Surveyed at: **TransEurokars**
 Des. of Damages: **Fr. / Rear / OS / N/A / UIC / Rooftop**
 The LIC Chassis frame Body Structure affected due to collision

RECEIVED 2 APR 2018

Date Time File Passed: ☐ Preli. Report
☐ Final Report
 Date Time File Returned:

Days Of Repair: **8**
 Resurvey No. of Trip: **1**

Survey Fee
 Transport Fee

2/4- typist

Add Fee: ☐ Site Insp: \$
☐ Night: \$
☐ Test: \$
☐ Lab: \$

Record Ref: **meriman**
 Lumber Stamp: **22, 220.26**

390
10
360

Survey Department Check List (Case Handler)

Reference No.: **CS MSG 1800 1443 Svd3**
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA / REV / REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: **VERON** **24/18**
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd
 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
 TEL: 6256 3561 FAX: 6256 4315
 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18001443/Svd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 24-01-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGF 3438L	Veh. Inspected	EV 8338Z	
Policy No.	A80370498MCX	Coverage (\$)	0.00	
Claim No.	546880	Excess (\$)	0.00	
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	24/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/01/2018	Inspection Date	23/01/2018	
Survey held at	STUTTGART AUTO PTE LTD 12 SUNGEI KADUT AVE. SINGAPORE 729648			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jan 2018		22 Jan 2018 14:41 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	UNITED WORKS PTE LTD, Co. Reg. No.: 200716702D		
Main Claimant:	JEE MENG HENG, ID: S7438455B		
Vehicle Reg. No.:	EV8338Z	Date of Loss:	17/01/2018 14:00 - :59
Claim Type:	TP / 546880	Policy/Cover Note No.:	A80370498MCX (TP, Fire & Theft) Coverage: 07/04/2017 - 06/04/2018
Vehicle Reg. No. (Insured):	SGF3438L	Policy No. (Claimant):	
		Excess:	
Repairer:	Stuttgart Auto Pte Ltd (HQ) 12 Sungei Kadut Ave, 729648 Sungei Kadut - Tel: 63602845		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/01/2018]		
Driver/Custodian (Insured):	VELLUNISWARAN S/O PANEERSELVAM (), NRIC: S8802360I, Tel: +6590068159		
Adj Asg. Remarks:	ON WP		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 25 Jan 2018

Preliminary Advice

Insured Vehicle No : SGF3438L

TP Vehicle No : EV8338Z

Make : PORSCHE MACAN

Date of Inspection : 23/01/2018

Inspection At : STUTTGART AUTO PTE LTD (HQ)
12 SUNGEI KADUT AVE
SINGAPORE 729648

Accident Date : 17/01/2018

Assignment Date : 22/01/2018

Est. Duration of Repair : 8.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,870.35
Revised Amount	:S\$	21,855.04
Check Items (Estimated)	:S\$	196.56
Total	:S\$	22,051.60

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/01/2018 13:19
Date Of Accident	17/01/2018 14:50
Exact Location Of Accident	AT UBI VIEW (PARALLEL PARKING LOT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	EV8338Z
Insured/Policyholder	
Name Of Registered Owner	JEE MENG HENG
NRIC No	S7438455B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94517554
Alternative Phone No	OTHERS-94517554
Vehicle Particulars	
Manufacturer	PORSCHE
Model	MACAN PDK CYP E6
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1770901700
Cover Note Number	
Driver	
Name of Driver	LAU KUM FOON
NRIC No	S1666334D
Date Of Birth	22/12/1964
Occupation	INDOOR
Date Of Driving Pass	13/03/1987
Driving Experience	30 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81638338
Fax Number	
Contact Number	
Email Address	MINILAU8338@GMAIL.COM

Address	430 ANG MO KIO AVE 3 #21-2596
Postcode	560430
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGF3438L
Vehicle Make/Model/Colour	MIT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	VELLUNISWARAN S/O PANEERSELVAM
NRIC/Passport Number	S8802360I
Contact Number	90068159
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


17/11/2018
16 15

Reporting Centre Personnel's Signature
Name:
NRIC/FN No.:

Janice Syn



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17/01/2018 around 1450 hrs. I was driving alone Ubi View, Sindolay vehicle B swung out from the parking lot & and hit into the left portion of my car without checking the ~~back~~ blind spot

DECLARATION



I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

17/1/2018
16 15

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

 
Janice Syn

STUTTGART AUTO
NO:12 SUNGEI KADUT AVE (S) 729648 (FAX NO. 63602899)
ESTIMATED COST OF REPAIRS

MSIG INSURANCE (SINGAPORE) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 S 068807		NAME : Mr Jee Meng Heng ADDRESS : 13 Telok Kurau Road #01-12 Parc Elegance Singapore 423912	WIP : 31121 DATE: 19.01.2018
ATTN : FAX :	MOTOR CLAIMS DEPT 62257402	TEL :	
VEH NO :	EV8338Z	DATE IN :	CONTACT PERSON : RICK 63602445
CHASSIS NO :	WP1ZZZ95ZJLB03108	MILEAGE :	TYPE OF CLAIM : TP AGAINST SGF3438L
MODEL :	Porsche Macan PDK	DATE REG. : 22-12-17	POLICY NO. :

NATURE OF WORKS

S/NO	Parts Description	QTY	PART NO	(NETT) PRICES
1	P95B-821-101-BY-GRV/WING, LOWER (LH) ✓ cut	1	P95B-821-101-DY-GRV	\$ 380.60 ✓
2	WHEEL-HOUSING LINER ✓ Deform	1	P95B-809-961-D -	\$ 253.60 ✓
3	P95B-825-101-A -1E0/LINING ✓ Deform.	1	P95B-825-101-E -1E0	\$ 107.00 ✓
4	LINING ✓ Deform.	1	P95B-807-221-A -G2X	\$ 868.10 ✓
5	FRONT SPOILER ✓ TN	1	P95B-807-061- -1E0	\$ 197.90 ✓
6	EXPANSION RIVET ✓ NEC.	16	PN -038-501-3 -	\$ 22.40 ✓
7	P95B-805-295- -/BRACKET, CHARGE AIR COO ? Deform	1	P95B-805-295-C	\$ 218.40 ✓
8	P95B-831-021- -GRV/DOOR SHELL (LH) ✓ Deform	1	P95B-831-021-A -GRV	\$ 1,867.90 ✓
9	P000-043-207-67-/SEALANT (W736) X NN	1	P000-043-305-32-	\$ 57.90 X
10	DAMPING ✓ NEC	2	P8K0-837-833-A -	\$ 47.00 ✓
11	DOOR SEAL ✓ NEC	1	P95B-837-911- -	\$ 225.50 ✓
12	BLIND RIVET NUT ✓ NEC.	1	PN -910-167-02-	\$ 1.70 ✓
13	CLIP ✓	1	P95B-831-719-A -	\$ 1.80 ✓
14	CLIP ✓ Nic.	3	P8K0-837-199- -	\$ 2.40 ✓
15	(WH03) SEAL ✓	2	PAKL-437-D40- -	\$ 1.40 ✓
16	GASKET ✓	2	P999-911-659-40-	\$ 1.60 ✓
17	CAVITY PRESERVATION X NN	1	P000-043-305-51-	\$ 79.60 X
18	COMBINATION SCREW (WH03) ✓ NEC.	2	PWHT-003-688- -	\$ 4.80 ✓
19	P95B-833-021- -GRV/DOOR SHELL REAR (LH) ✓ Deform	1	P95B-833-021-B -GRV	\$ 1,833.10 ✓
20	P000-043-207-67-/SEALANT (W736) X NN	1	P000-043-305-32-	\$ 57.90 X
21	INSULATION ✓ NEC.	1	P970-556-543-00-	\$ 8.70 ✓
22	DOOR SEAL OUTER ✓	1	P95B-839-911- -	\$ 219.90 ✓
23	CLIP ✓ Nic.	6	P8K0-837-199- -	\$ 4.80 ✓
24	GASKET ✓	2	P999-911-659-40-	\$ 1.60 ✓
25	COMBINATION SCREW (WH03) ✓	2	PWHT-003-688- -	\$ 4.80 ✓
26	CAVITY PRESERVATION X NN	1	P000-043-305-51-	\$ 79.60 X
27	DOOR SEAL C PILLAR ✓ NEC.	1	P95B-839-761-B -	\$ 168.60 ✓
28	NAMEPLATE MACAN ✓ NEC.	1	P95B-853-675- -	\$ 97.10 ✓
29	REPAIR KIT (Door Sticker) ✓ NEC.	1	P95B-898-633- -	\$ 99.10 ✓
30	COVER Door Garnish ✓ NEC.	1	P95B-898-565- -OK1	\$ 514.30 ✓
31	COVER	1	P95B-898-561- -OK1	\$ 539.40 ✓
32	STONE GUARD FILM LH ✓ NEC.	1	P95B-854-931- -	\$ 82.90 ✓
33	MOULDING ✓ NEC	1	P95B-839-475-E -A78	\$ 140.70 ✓
34	MOULDING ✓ NEC.	1	P95B-837-475-E -A78	\$ 147.90 ✓
35	SILL COVER ✓ SCR.	1	P95B-853-563- -1E0	\$ 235.30 ✓
36	SOUND ABSORBER ✓ NEC	1	P95B-857-993-A -	\$ 33.70 ✓
37	ALLOY WHEEL Front Left X NN	1	P95B-601-025-BG-OC6	\$ 3,312.50 X
38	ALLOY WHEEL Front ✓ cut	1	P95B-601-025-BF-OC6	\$ 3,190.00 ✓

			SUB TOTAL	\$ 15,111.50
			LESS 10%	\$ 1,511.15
			Total Parts	\$ 13,600.35
	<u>Labour Description</u>			
1	TO REMOVE / REPLACE DAMAGED FRONT BUMPER FRONT LH FENDER, LH FRT / REAR DOORS, & OTHER AFFECTED BODY PARTS INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE.			\$ 7,800.00 4680 ✓
2	TO SPRAY PAINT FRONT BUMPER, FRT LH FENDER, FRT / REAR DOORS			\$ 4,200.00 3800 ✓
3	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS.			NETT \$ 250.00 ✓
4	TO REMOVE / REFIT DOORS INCLUDE TRANSFER WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR & CHECK FUNCTION ABILITY			NETT \$ 1,560.00 ✓
5	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT ACCORDING TO SPECIFICATIONS.			NETT \$ 680.00 ✓
6	TO REMOVE REPLACE REFIT TYRES & RIMS @ \$60/-			\$ 120.00 60 ✓
7	TO SUPPLY 2 PCS TYRE \$980.00 ea			\$ 1,960.00 X
8	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR.			NETT \$ 600.00 ✓
9	SUNDRIES			\$ 100.00 50 ✓
			TOTAL LABOUR	\$ 17,270.00
			TOTAL PARTS	\$ 13,600.35
			GRAND TOTAL	\$ 30,870.35

Please note that this is **only an estimate**, base on our visual inspection. However should there be any additional work be found necessary in the course of repair and thus additional parts, materials and labor cost will be deem necessary, you will be inform accordingly prior to any action taken. In view of this, expected delays will be inevitable and therefore additional working days will be required. As such the loss of use and other incidentals will be adjusted accordingly.

31,039.01

8 days

Prepared By

Sebastian
23/1/18

Acknowledge By

[Signature]
25/1/18

- Part by part repair.
- Photo Before Paint.
- All items are LH side.
(RH typing error)
90036121

sebastianyeang@lkkauto.com

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

STUTTGART AUTO
NO:12 SUNGEI KADUT AVE (S) 729648 (FAX NO. 63602899)
FINALIZATION COST OF REPAIRS

MSIG INSURANCE (SINGAPORE) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 S 068807		NAME : Mr Jee Meng Heng ADDRESS : 13 Telok Kurau Road #01-12 Parc Elegance Singapore 423912		WIP : 31421 DATE: 19.01.2018	
ATTN. :	MOTOR CLAIMS DEPT	TEL :			
FAX :	62257402				
VEH NO :	EV8338Z	DATE IN :		CONTACT PERSON :	RICK 63602445
CHASSIS NO :	WP1ZZZ95ZJLB03108	MILEAGE :		TYPE OF CLAIM :	TP AGAINST SGF3438L
MODEL :	Porsche Macan PDK	DATE REG. :	22/12/2017	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description			REVISED	(NETT) PRICES
		QTY	PART NO		
1	P95B-821-101-BY-GRV/WING, LOWER (LH)	1	P95B-821-101-DY-GRV	\$ 380.60	\$ 380.60
2	WHEEL-HOUSING LINER	1	P95B-809-961-D -	\$ 253.60	\$ 253.60
3	P95B-825-101-A -1E0/LINING	1	P95B-825-101-E -1E0	\$ 107.00	\$ 107.00
4	LINING	1	P95B-807-221-A -G2X	\$ 868.10	\$ 868.10
5	FRONT SPOILER	1	P95B-807-061- -1E0	\$ 197.90	\$ 197.90
6	EXPANSION RIVET	16	PN -038-501-3 -	\$ 22.40	\$ 22.40
7	P95B-805-295- -/BRACKET, CHARGE AIR COO	1	P95B-805-295-C	\$ 218.40	\$ 218.40
8	P95B-831-021- -GRV/DOOR SHELL (LH)	1	P95B-831-021-A -GRV	\$ 1,867.90	\$ 1,867.90
9	P000-043-207-67-/SEALANT (W736)	1	P000-043-305-32-	\$ -	\$ 57.90
10	DAMPING	2	P8K0-837-833-A -	\$ 47.00	\$ 47.00
11	DOOR SEAL	1	P95B-837-911- -	\$ 225.50	\$ 225.50
12	BLIND RIVET NUT	1	PN -910-167-02-	\$ 1.70	\$ 1.70
13	CLIP	1	P95B-831-719-A -	\$ 1.80	\$ 1.80
14	CLIP	3	P8K0-837-199- -	\$ 2.40	\$ 2.40
15	(WH03) SEAL	2	PAKL-437-D40- -	\$ 1.40	\$ 1.40
16	GASKET	2	P999-911-659-40-	\$ 1.60	\$ 1.60
17	CAVITY PRESERVATION	1	P000-043-305-51-	\$ -	\$ 79.60
18	COMBINATION SCREW (WH03)	2	PWHT-003-688- -	\$ 4.80	\$ 4.80
19	P95B-833-021- -GRV/DOOR SHELL REAR (LH)	1	P95B-833-021-B -GRV	\$ 1,833.10	\$ 1,833.10
20	P000-043-207-67-/SEALANT (W736)	1	P000-043-305-32-	\$ -	\$ 57.90
21	INSULATION	1	P970-556-543-00-	\$ 8.70	\$ 8.70
22	DOOR SEAL OUTER	1	P95B-839-911- -	\$ 219.90	\$ 219.90
23	CLIP	6	P8K0-837-199- -	\$ 4.80	\$ 4.80
24	GASKET	2	P999-911-659-40-	\$ 1.60	\$ 1.60
25	COMBINATION SCREW (WH03)	2	PWHT-003-688- -	\$ 4.80	\$ 4.80
26	CAVITY PRESERVATION	1	P000-043-305-51-	\$ -	\$ 79.60
27	DOOR SEAL C PILLAR	1	P95B-839-761-B -	\$ 168.60	\$ 168.60
28	NAMEPLATE MACAN	1	P95B-853-675- -	\$ 97.10	\$ 97.10
29	REPAIR KIT	1	P95B-898-633- -	\$ 99.10	\$ 99.10
30	COVER	1	P95B-898-565- -OK1	\$ 514.30	\$ 514.30
31	COVER	1	P95B-898-561- -OK1	\$ 539.40	\$ 539.40
32	STONE GUARD FILM LH	1	P95B-854-931- -	\$ 82.90	\$ 82.90
33	MOULDING	1	P95B-839-475-E -A78	\$ 140.70	\$ 140.70
34	MOULDING	1	P95B-837-475-E -A78	\$ 147.90	\$ 147.90
35	SILL COVER	1	P95B-853-563- -1E0	\$ 235.30	\$ 235.30
36	SOUND ABSORBER	1	P95B-857-993-A -	\$ 33.70	\$ 33.70
37	ALLOY WHEEL	1	P95B-601-025-BG-OC6	\$ -	\$ 3,312.50
38	ALLOY WHEEL	1	P95B-601-025-BF-OC6	\$ 3,190.00	\$ 3,190.00
SUPPLEMENTARY PARTS					

1	ANTIFREEZE FOR COOLANT	5	PSAL-043-301-48	\$ 181.00	
2	BLIND RIVET NUT	2	PN-910-167-02	\$ 3.40	
3	EXPANDER NUT	2	PN-106-213-01	\$ 3.00	
			SUB TOTAL	\$ 11,711.40	\$ 15,111.50
			LESS 10%	\$ 1,171.14	\$ 1,511.15
			Total Parts	\$ 10,540.26	\$ 13,600.35
	Labour Description				
1	TO REMOVE / REPLACE DAMAGED FRONT BUMPER			\$ 4,680.00	\$ 7,800.00
	FRONT LH FENDER, LH FRT / REAR DOORS,				
	& OTHER AFFECTED BODY PARTS				
	INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS				
	& FITTINGS WHICHEVER NECESSARY INCLUDING				
	ALIGNMENT OF BODY STRUCTURE.				
2	TO SPRAY PAINT FRONT BUMPER, FRT LH FENDER,			\$ 3,800.00	\$ 4,200.00
	FRT / REAR DOORS				
3	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER			\$ 250.00	\$ 250.00
	FUNCTION ABILITY INCLUDING PARKING ASSIST				
	SENSORS.				
4	TO REMOVE / REFIT DOORS INCLUDE TRANSFER			\$ 1,560.00	\$ 1,560.00
	WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR				
	& CHECK FUNCTION ABILITY				
5	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL			\$ 680.00	\$ 680.00
	ALIGNMENT ACCORDING TO SPECIFICATIONS.				
6	TO REMOVE REPLACE REFIT TYRES & RIMS @ \$60/-			\$ 60.00	\$ 120.00
7	TO SUPPLY 2 PCS TYRE \$980.00 ea			\$ -	\$ 1,960.00
8	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES			\$ 600.00	\$ 600.00
	AFTER ACCIDENT REPAIR.				
9	SUNDRIES.			\$ 50.00	\$ 100.00
	TOTAL LABOUR			\$ 11,680.00	\$ 17,270.00
	TOTAL PARTS			\$ 10,540.26	\$ 13,600.35
	GRAND TOTAL			\$ 22,220.26	\$ 30,870.35
	GST 7 %			\$ 1,555.42	
	TOTAL AFTER GST			\$ 23,775.68	

NUMBER OF DAYS: 9 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN,PH)

LOSS OF USE ; \$180.00X 13DAYS = \$2,340.00

GIA SEARCH FEES ; \$2.00

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 2 April 2018 8:57 AM
To: 'jessicahs@eurokars.com.sg'
Cc: Admin A; stanley@eurokars.com.sg; SUR
Subject: RE: finalization MSIG TP - EV8338Z.xls

Dear Jessica,

Confirmed \$22,220.26 before GST.

No of days: 8 days

Final invoice and all supporting documents sent over to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg [mailto:jessicahs@eurokars.com.sg]
Sent: Wednesday, 28 March 2018 10:37 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; stanley@eurokars.com.sg
Subject: RE: finalization MSIG TP - EV8338Z.xls

Dear Veron,

The below matter refers.

Please let us have the confirmation by today.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

Eurokars Group of Companies

(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)

Eurokars Centre

12 Sungei Kadut Avenue

Singapore 729648

Tel: +65 63633003

DID: +65 63602863

Fax: +65 63602899

From: Jessica Harry Shastri
Sent: Monday, March 26, 2018 11:10 AM
To: 'Veron Chen (LKKAUTO)' <veronchen@lkkauto.com>
Subject: FW: finalization MSIG TP - EV8338Z.xls

Dear Veron,

FYA.

Thank you very much.

Regards,
Jessica Shastri
Admin Executive – Insurance Claims
Eurokars Group of Companies
(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)
Eurokars Centre
12 Sungei Kadut Avenue
Singapore 729648
Tel: +65 63633003
DID: +65 63602863
Fax: +65 63602899

From: Rick Teo Fu Shen
Sent: Monday, March 26, 2018 10:52 AM
To: Jessica Harry Shastri <jessicahs@eurokars.com.sg>; Eva Kok <eva.kok@eurokars.com.sg>
Cc: Stanley Ngu <stanley@eurokars.com.sg>
Subject: RE: finalization MSIG TP - EV8338Z.xls

Hi all, [

Fyna.

Best Regards.



Rick Teo
Insurance Claims Executive
Eurokars Centre
12 Sungei Kadut Ave
Singapore 729648
DID : (+65) 6360 2445
Fax : (+65) 6360 2899
Email : rickteo@eurokars.com.sg

From: Jessica Harry Shastri
Sent: Monday, 26 March, 2018 10:19

To: Eva Kok <eva.kok@eurokars.com.sg>; Rick Teo Fu Shen <rickteo@eurokars.com.sg>

Cc: Stanley Ngu <stanley@eurokars.com.sg>

Subject: FW: finalization MSIG TP - EV8338Z.xls

Dear Eva/ Rick,

Please assist.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

Eurokars Group of Companies

(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)

Eurokars Centre

12 Sungei Kadut Avenue

Singapore 729648

Tel: +65 63633003

DID: +65 63602863

Fax: +65 63602899

From: Sebastian Yeang (LKK Auto) [<mailto:SebastianYeang@lkkauto.com>]

Sent: Monday, March 26, 2018 10:17 AM

To: Jessica Harry Shastri <jessicahs@eurokars.com.sg>

Cc: CS A Team <cs-a@lkkauto.com>

Subject: RE: finalization MSIG TP - EV8338Z.xls

Dear Jessica

Good day,

Kindly provide me the photo of below mentioned.

1. Before paint photo.
2. P95B-805-295 BRACKET, CHARGE AIR COO (Question Mark Item)

Thank You

Best Regards,

Sebastian | Automotive Assessor

LKK Auto Consultants

phone: 6256-3561 | email: sebastianyeang@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg [<mailto:jessicahs@eurokars.com.sg>]

Sent: Monday, 12 March 2018 2:08 PM

To: Sebastian Yeang (LKK Auto)

Cc: CS A Team

Subject: finalization MSIG TP - EV8338Z.xls

Dear Sebastian,

Please find our computation attached for your agreement.

*COR: \$22,220.26 before GST

9 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirming the above as soon as possible.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

Eurokars Group of Companies

(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)

Eurokars Centre

12 Sungei Kadut Avenue

Singapore 729648

Tel: +65 63633003

DID: +65 63602863

Fax: +65 63602899

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jan 2018		22 Jan 2018 14:41 Edit Adj Rpt	S\$22,220.26 Edit Estimates	S\$22,220.26 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	UNITED WORKS PTE LTD , Co. Reg. No.: 200716702D								
Main Claimant:	JEE MENG HENG , ID: S7438455B								
Vehicle Reg. No.:	EV8338Z	Date of Loss:	17/01/2018 14:00 - :59 [26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 546880	Policy/Cover Note No.:	A80370498MCX (TP, Fire & Theft) Coverage: 07/04/2017 - 06/04/2018						
Vehicle Reg. No. (Insured):	SGF3438L	Policy No. (Claimant):							
		Excess:							
Repairer:	Stuttgart Auto Pte Ltd (HQ) 12 Sungei Kadut Ave, 729648 Sungei Kadut - Tel: 63602845								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 21/02/2018]								
Driver/Custodian (Insured):	VELLUNISWARAN S/O PANEERSELVAM (), NRIC: S8802360I, Tel: +6590068159								
Adj Asg. Remarks:	ON WP								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***EV8338Z (546880)**
[SGF3438L]
TP
JEE MENG HENG
Jan 17 2018 2:00PM
[UNITED WORKS PTE LTD]
Stuttgart Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	22/01/18 14:42	Accident Statement From: SC - Reg. No: SGF3438L, Claimant: UNITED WORKS PTE LTD					1	Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	25/01/18 14:42	Adjuster Immediate Advice					1	Load HTM		
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	25/01/18 14:25	General View					1	Load JPG	☒	
2	25/01/18 14:25	General View					1	Load JPG	☒	
3	25/01/18 14:25	General View					1	Load JPG	☒	
4	25/01/18 14:25	General View					1	Load JPG	☒	
5	25/01/18 14:25	General View					1	Load JPG	☒	
6	25/01/18 14:25	General View					1	Load JPG	☒	
7	25/01/18 14:25	General View					1	Load JPG	☒	
8	25/01/18 14:25	General View					1	Load JPG	☒	
9	25/01/18 14:25	General View					1	Load JPG	☒	
10	25/01/18 14:25	General View					1	Load JPG	☒	
11	25/01/18 14:25	General View					1	Load JPG	☒	
12	25/01/18 14:25	General View					1	Load JPG	☒	
13	25/01/18 14:25	General View					1	Load JPG	☒	
14	25/01/18 14:25	General View					1	Load JPG	☒	
15	25/01/18 14:25	General View					1	Load JPG	☒	
16	25/01/18 14:25	General View					1	Load JPG	☒	
17	25/01/18 14:25	General View					1	Load JPG	☒	
18	25/01/18 14:25	General View					1	Load JPG	☒	
19	25/01/18 14:25	General View					1	Load JPG	☒	
20	25/01/18 14:25	General View					1	Load JPG	☒	
21	25/01/18 14:25	General View					1	Load JPG	☒	
22	25/01/18 14:25	General View					1	Load JPG	☒	
23	25/01/18 14:25	General View					1	Load JPG	☒	
24	25/01/18 14:25	General View					1	Load JPG	☒	
25	25/01/18 14:25	General View					1	Load JPG	☒	
26	25/01/18 14:25	General View					1	Load JPG	☒	
27	25/01/18 14:25	General View					1	Load JPG	☒	
28	25/01/18 14:25	General View					1	Load JPG	☒	
29	25/01/18 14:25	General View					1	Load JPG	☒	
30	25/01/18 14:25	General View					1	Load JPG	☒	
31	25/01/18 14:25	General View					1	Load JPG	☒	
32	25/01/18 14:25	General View						Load JPG		

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	25/01/18 14:25	General View	Load JPG	☒
34	25/01/18 14:25	General View	Load JPG	☒
35	25/01/18 14:25	General View	Load JPG	☒
36	25/01/18 14:25	General View	Load JPG	☒
37	25/01/18 14:25	General View	Load JPG	☒
38	25/01/18 14:25	General View	Load JPG	☒
39	25/01/18 14:25	General View	Load JPG	☒
40	25/01/18 14:25	General View	Load JPG	☒
41	25/01/18 14:25	General View	Load JPG	☒
42	25/01/18 14:25	General View	Load JPG	☒
43	25/01/18 14:25	General View	Load JPG	☒
44	25/01/18 14:25	General View	Load JPG	☒
45	25/01/18 14:25	General View	Load JPG	☒
46	25/01/18 14:25	General View	Load JPG	☒
47	25/01/18 14:25	General View	Load JPG	☒
48	25/01/18 14:25	General View	Load JPG	☒
49	25/01/18 14:25	General View	Load JPG	☒
50	25/01/18 14:25	General View	Load JPG	☒
51	02/04/18 08:49	Reinspection Photo	Load JPG	☒
52	02/04/18 08:49	Reinspection Photo	Load JPG	☒
53	02/04/18 08:49	Reinspection Photo	Load JPG	☒
54	02/04/18 08:49	Reinspection Photo	Load JPG	☒
55	02/04/18 08:49	Reinspection Photo	Load JPG	☒
56	02/04/18 08:49	Reinspection Photo	Load JPG	☒
57	02/04/18 08:49	Reinspection Photo	Load JPG	☒
58	02/04/18 08:49	Reinspection Photo	Load JPG	☒
59	02/04/18 08:49	Reinspection Photo	Load JPG	☒
60	02/04/18 08:49	Reinspection Photo	Load JPG	☒
61	02/04/18 08:49	Reinspection Photo	Load JPG	☒
62	02/04/18 08:49	Reinspection Photo	Load JPG	☒
63	02/04/18 08:49	Reinspection Photo	Load JPG	☒
64	02/04/18 08:49	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/01/18 14:42	WE ASSIGN LKK TO SURVEY	Load PDF	
2	22/01/18 14:42	ESTIMATE	Load PDF	
3	22/01/18 14:42	TP GIA REPORT From: SC - Reg. No: SGF3438L, Claimant: UNITED WORKS PTE LTD	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/04/18 10:28	Supplementary	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001443/SVD3E2

Date: 04/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80370498MCX

Claimant Vehicle No : EV8338Z

Insured Vehicle No : SGF3438L

Date of Loss: 17/01/2018

Nature of Claim: TP

Claim No: 546880

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: EV8338Z

Make & Model: PORSCHE MACAN, 2.0 PDK (A)

Engine No: 085606

Reg. Date: 22/12/2017 (Man. Year: 2017)

Chassis No: WP1ZZZ95ZJLB03108

Colour: Black

Odometer: 2497 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/45 R20

Rear Tyre Size: 295/40 R20

Front Left Side: Michelin 8 mm

Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,869.01	10,590.26	3,278.75	23.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,170.00	11,630.00	5,540.00	32.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	31,039.01	22,220.26	8,818.75	28.41
+ GST 7.00/7.00% (\$\$)	2,172.73	1,555.42	617.31	28.41
Nett Amount (\$\$)	33,211.74	23,775.68	9,436.06	28.41

INSPECTION

Date of Assignment: 22/01/2018

Date Inspected: 23/01/2018

Inspected At:

Stuttgart Auto Pte Ltd (HQ)

12 Sungei Kadut Ave

Singapore 729648

Estimated Period of Repair: 8.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Apr 2018)

Parts: M1-SUV PORSCHE MACAN 2.0 PDK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for EV8338Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*P95B-821-101-BY-GRV/WING, LOWER (LH)	Cut	380.60 FL	*380.60 FL
2	1		*WHEEL-HOUSING LINER	Deformed	253.60 FL	*253.60 FL
3	1		*P95B-825-101-A -1E0/LINING	Deformed	107.00 FL	*107.00 FL
4	1		*LINING	Deformed	868.10 FL	*868.10 FL
5	1		*FRONT SPOILER	Torn	197.90 FL	*197.90 FL
6	16		*EXPANSION RIVET	Necessary	22.40 FL	*22.40 FL
7	1		*P95B-805-295- /BRACKET, CHARGE AIR COO	Deformed	218.40 FL	*218.40 FL
8	1		*P95B-831-021- -GRV/DOOR SHELL (LH)	Deformed	1,867.90 FL	*1,867.90 FL
9	1		*P000-043-207-67-/SEALANT (W736)	Not Necessary	57.90 FL	*- FL
10	2		*DAMPING	Necessary	47.00 FL	*47.00 FL
11	1		*DOOR SEAL	Necessary	225.50 FL	*225.50 FL
12	1		*BLIND RIVET NUT	Necessary	1.70 FL	*1.70 FL
13	1		*CLIP	Necessary	1.80 FL	*1.80 FL
14	3		*CLIP	Necessary	2.40 FL	*2.40 FL
15	2		*(WH03) SEAL	Necessary	1.40 FL	*1.40 FL
16	2		*GASKET	Necessary	1.60 FL	*1.60 FL
17	1		*CAVITY PRESERVATION	Not Necessary	79.60 FL	*- FL
18	2		*COMBINATION SCREW (WH03)	Necessary	4.80 FL	*4.80 FL
19	1		*P95B-833-021- -GRV/DOOR SHELL REAR (LH)	Deformed	1,833.10 FL	*1,833.10 FL
20	1		*P000-043-207-67-/SEALANT (W736)	Not Necessary	57.90 FL	*- FL
21	1		*INSULATION	Necessary	8.70 FL	*8.70 FL
22	1		*DOOR SEAL OUTER	Necessary	219.90 FL	*219.90 FL
23	6		*CLIP	Necessary	4.80 FL	*4.80 FL
24	2		*GASKET	Necessary	1.60 FL	*1.60 FL
25	2		*COMBINATION SCREW (WH03)	Necessary	4.80 FL	*4.80 FL
26	1		*CAVITY PRESERVATION	Not Necessary	79.60 FL	*- FL
27	1		*DOOR SEAL C PILLAR	Necessary	168.60 FL	*168.60 FL
28	1		*NAMEPLATE MACAN	Necessary	97.10 FL	*97.10 FL
29	1		*REPAIR KIT	Necessary	99.10 FL	*99.10 FL
30	1		*COVER	Necessary	514.30 FL	*514.30 FL
31	1		*COVER	Necessary	539.40 FL	*539.40 FL
32	1		*STONE GUARD FILM LH	Necessary	82.90 FL	*82.90 FL
33	1		*MOULDING	Necessary	140.70 FL	*140.70 FL
34	1		*MOULDING	Necessary	147.90 FL	*147.90 FL
35	1		*SILL COVER	Scratched	235.30 FL	*235.30 FL
36	1		*SOUND ABSORBER	Necessary	33.70 FL	*33.70 FL
37	1		*ALLOY WHEEL	Not Necessary	3,312.50 FL	*- FL
38	1		*ALLOY WHEEL	Cut	3,190.00 FL	*3,190.00 FL
39	5		*ANTIFREEZE FOR COOLANT	Necessary	181.00 FL	*181.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*BLIND RIVET NUT	Necessary	3.40 FL	*3.40 FL
41	2		*EXPANDER NUT	Necessary	3.00 FL	*3.00 FL
42	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					15,398.90	11,761.40
- List Item Discount on L Items 10.00/10.00% (S\$)					1,529.89	1,171.14
Total Parts (S\$)					13,869.01	10,590.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE / REPLACE DAMAGED FRONT BUMPER FRONT LH FENDER, LH FRT / REAR DOORS & OTHER AFFECTED BODY PARTS INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE	New	7,800.00	4,680.00
2	TO SPRAY PAINT FRONT BUMPER, FRT LH FENDER FRT / REAR DOORS	New	4,200.00	3,800.00
3	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS	New	250.00	250.00
4	TO REMOVE / REFIT DOORS INCLUDE TRANSFER WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR & CHECK FUNCTION ABILITY	New	1,560.00	1,560.00
5	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT ACCORDING TO SPECIFICATIONS	New	680.00	680.00
6	TO REMOVE REPLACE REFIT TYRES & RIMS @ \$60/-	New	120.00	60.00
7	TO SUPPLY 2 PCS TYRE \$980.00 EA	New	1,960.00	0.00
8	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR	New	600.00	600.00
Gross Labour Cost (\$\$)			17,170.00	11,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >