



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Kindly Help to arrange
Surveyor to survey this
vehicle
Thanks

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT18000356	Page	1
Registration No	: SGK4180X	Date	: 23. Jan 2018		
Chassis No	: MRHFB1630FP000086	Customer No.	: WZI007		
Model	: 2015 CIVIC 1.6L AUTO (EURO 4)	Svc Advisor	: LIM CHOU SIONG		
Owner's Name	: CHNG HAK PENG (ZHUANG)	Engine No	: R16B25100177		
Ins Policy No.	:	Date Time	: 23. Jan 2018 7:18:39 PM		
Date of Accident	: 14/1/2018	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: CHNG HAK PENG (ZHUANG XUEPENG)						
	OWNER INSURER: NTUC INCOME INS CO-OPERATIVE LTD						
	ACC DATE: 14/1/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD						
	TP VEH: SHA3782G						
04715-TR0-G10ZZ	FACERR.BUMPER <i>DO/ae</i>	1	700.70	25	525.52	36.79	562.31
71593-TR0-A02	SPACERR.RR.BUMPER SIDE <i>sent</i>	1	18.30	25	13.72	0.96	14.68
71598-TR0-A02	SPACERL.RR.BUMPER SIDE <i>sent</i>	1	18.30	25	13.72	0.96	14.68
91505-TM8-003	CLIPBUMPER <i>ner</i>	2	2.00	25	3.00	0.21	3.21
91506-S9A-003	CLIP BBUMPER <i>ner</i>	2	2.40	25	3.60	0.25	3.85
	Sum Item				559.56	39.17	598.73
BOSUN	SUNDRIES	1	30.00	<i>ner</i>	30.00	2.10	32.10
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BKBU02R	REPLACE RR BUMPER, REPAIR RR BUMPER LOWER SPOILER,	1	1200.00	<i>560</i>	1200.00	84.00	1284.00
BP03R	SPRAY PAINTING ON RR BUMPER, RR BUMPER LOWER 1		1500.00	<i>900</i>	1500.00	105.00	1605.00
	Sum Labor				2810.00	196.70	3,006.70

Survey By

Date & Time

Excess

Status

Signature

Marcus Hahn
25/1/18
not authorized
Take photo before party.
3 day.

Total Amount 3,369.56 235.87 3,605.43

Total (Inclusive of GST) 3,605.43

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SGK4180X

Chassis No : MRHFB1630FP000086

Model : 2015 CIVIC 1.6L AUTO (EURO 4)

Owner's Name : CHNG HAK PENG (ZHUANG)

Ins Policy No. :

Date of Accident : 14/1/2018

Document No. : SQT18000356 **Page** 2

Date : 23. Jan 2018

Customer No. : WZ1007

Svc Advisor : LIM CHOU SIONG

Engine No : R16B25100177

Date | Time : 23. Jan 2018 7:18:39 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incl GST
------	-------------	-----	------------	--------	--------	------------	--------------------

C S Lim
81006303 (HP)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 23/1/2018 7:30:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)