

FZ - DVA

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,349.50
	Boot Lid Rubber ✓			\$ 110.90
	Boot Lid Hinge (LH/RH) ✓		\$ 170.60	\$ 341.20
	Boot Lid Lock Upper ✓			\$ 132.10
	Boot Lid Lock Lower ✓			\$ 30.30
	Boot Lid Key Lock ✓			\$ 78.20
	Boot Lid Sonata Plate ✓			\$ 43.60
	Boot Lid Hyundai Plate ✓			\$ 24.20
	Boot Lid 'H' Emblem ✓			\$ 26.10
	Boot Lid CRDI Plate ✓			\$ 22.70
	Boot Lid Lamp (LH/RH) LH ✓ RH?		\$ 230.20	\$ 460.40 ✓
	Boot Lid Trimboard ✓			\$ 165.40
	Boot Lid Trimboard Clips (10pcs) ✓			\$ 11.00
	Rear Bumper ✓			\$ 578.40
	Rear Bumper Reinforcement ✓			\$ 483.30
	Rear Bumper Clip ✓			\$ 22.00
	Rear Bumper Bracket (LH/RH) ✓		\$ 49.00	\$ 98.00
	Rear Bumper Sponge ✓			\$ 137.40
	Rear Bumper Under Cover ✓			\$ 185.80
	Rear Bumper Protector (LH/RH) ✓		\$ 38.00	\$ 76.00
	Tail Lamp (LH/RH) LH ✓ RH?		\$ 344.00	\$ 688.00 ✓
	Tail Lamp Quarter Panel (LH/RH) LH ✓ RH x repair		\$ 93.80	\$ 187.60 ✓
	Rear Panel ✓			\$ 391.80
	Rear Panel Garnish ✓			\$ 95.80
	Spare Tyre Holder ?			\$ 27.60
	Tail Lamp Panel Top (LH) ?			\$ 217.40
	Spare Tyre Panel ?			\$ 863.00
	Spare Tyre Panel Cushion ?			\$ 200.30
	Rear Towing Hook ?			\$ 135.30
	Member Assy- Rear Floor Centre ?			\$ 163.60
	Panel Assy-Rear Floor Side (LH) ?			\$ 88.55
	Rear Floor Chassis Member (LH/RH) ?		\$ 1,280.50	\$ 2,561.00
	Exhaust Pipe Insulator ?			\$ 56.10
	Exhaust Silencer ✓			\$ 723.00
	Exhaust Pipe Hanger ?			\$ 56.10
	Rear Fender (LH/RH) LH ✓ RH x repair		\$ 1,935.90	\$ 3,871.80 ✓
	Rear Fender Inner Panel (LH) ✓			\$ 1,255.00
	Rear Fender Inner Lining (LH) ✓			\$ 74.10
	Rear Fender Corner Hardboard Cover (LH) ?			\$ 204.30
	Rear Tray Lugg Side (RH) ?			\$ 37.40
	Rear Fender Air-Duct ?			\$ 49.40
	Rear Fender Mudflap (LH) ?			\$ 15.50
	Rear Fender Trim Board (LH/RH) ?		\$ 180.90	\$ 361.80
	Rear Windscreen Glass ?			\$ 639.00
	Rear Windscreen Moulding ✓			\$ 60.00
	Fuel Tank Sub Hose ?			\$ 78.20
	Fuel Tank Upper Neck ?			\$ 221.60

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Wheel Hub-Cap (LH) ✕			\$ 145.00	
	Fire Extinguisher Holder ?			\$ 35.00	
	SUB TOTAL			\$ 17,879.75	
	LESS 20%			\$ 3,575.95	
	DISCOUNTED TOTAL			\$ 14,303.80	
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00	Nett
	Boot Lid Advertisement Logo ✓			\$ 100.00	Nett
	Rear No. Plate ✓			\$ 25.00	Nett
	Rear Bumper Reverse Sensor ✕			\$ 135.70	Nett
	Rear Bumper Advertisement Logo ✓			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
	Rear Windscreen Sealant ✓			\$ 46.00	Nett
	Rear Door Advertisement Logo (LH) ✕			\$ 100.00	Nett
	Rear Door Tel No. Sticker (LH) ✕			\$ 10.00	Nett
	Rear Tyre (LH) ✕			\$ 207.00	Nett
				\$ 903.70	
	Labour Charge				
	Panel Beating			\$ 3,000.00 ¹²⁰⁰	
	Spray Painting Charge			\$ 1,600.00	1080
	Wiring Charge			\$ 100.00	20
	Tuff Kote			\$ 150.00	50
	Towing Charge			\$ 50.00	—
	Rear Chassis Alignment Charge			\$ 400.00	— ✕
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	50
	Remove/Refix Rear Windscreen Glass			\$ 120.00	100
	Remove/Refix Fuel Tank			\$ 150.00	50
	Remove/Refix Exhaust Pipe			\$ 150.00	50
	Rear Wheel Alignment			\$ 120.00	60
	TOTAL LABOUR			\$ 5,990.00	
	ESTIMATE TOTAL			\$ 21,197.50	
Kalin LKK 24/1/18 1045hrs. TBA Repair Dep. 4/5 check Book value.					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged parts for resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company Acknowledged by Repairer Signature: _____ Date: _____					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					