

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTRR%	DISC QUNT%	SALV AGE%	PART PREC(MET)	ACTION (PARTS)	REMOVE
		13	10		REAR BUMPER UNDERCOVER UNDERCOVER CLIPS			Serviceable	0		10		0	Reviewing	
		14	1		REAR BUMPER TOW COVER			Serviceable	0		10		0	Reviewing	
		15	1		SET REVERSE SENSOR			Shorted	1024		10		921.6	Reviewing	
		16	1		REVERSE SENSOR WIRE			Serviceable	0		10		0	Reviewing	
		17	2		REAR FENDER COWLING L+R			Serviceable	0		10		0	Reviewing	
		18	10		REAR FENDER COWLING CLIPS L+R			Serviceable	0		10		0	Reviewing	
		19	2		REAR FENDER INNER TRIM L+R			Serviceable	0		10		0	Reviewing	
		20	10		REAR FENDER INNER TRIM CLIPS L+R			Serviceable	0		10		0	Reviewing	
		21	1		REAR END PANEL			Repair	0		10		0	Reviewing	
		22	1		REAR END PANEL TOP GARNISH			Bent	174		10		156.6	Reviewing	
		23	10		REAR END PANEL TOP GARNISH CLIPS			Cracked	5		10		45	Reviewing	
		24	2		REAR BUMPER PROTECTOR L+R			Cracked	110		10		198	Reviewing	
		25	2		REAR BUMPER PROTECTOR CHROME MOULDING L+R			Necessary	136		10		244.8	Reviewing	
		26	1		REAR BUMPER SCUFF PLATE			Necessary	224		10		201.6	Reviewing	
		27	1		EXHAUST PIPE			Cracked	938		10		844.2	Reviewing	
		28	1		EXHAUST PIPE GASKET			Serviceable	0		10		0	Reviewing	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	PNOL INFORMATION	POST SURVEY INFORMATION
Sum Insured		0	License Type		
Market Value		0	License Issue Date		mm/dd/yyyy
			License Expiration Date		mm/dd/yyyy
			Address	21 HILLVIEW TERRACE #06-12, 669232, Singapore	
			Address type	Personal Correspondence	
			Gender	Male	
			Marital status	Unknown	
			Identification #	57624093J	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	7/31/18 5:47 PM	4400	4400	Open	Share	Clone
LOH Cynthia	1/24/18 11:46 AM	5613.1	5613.1	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
AXA MANDATE REQUEST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 1, 2018
TP LOD.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 1, 2018
LKK AFTER REPAIR PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 1, 2018
LKK INSPECTION REPORT.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 1, 2018
LKK REINSPECTION REPORT.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 1, 2018
GIA LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 1, 2018
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 1, 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	August 1, 2018
Preliminary_Advice.PDF	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	February 20, 2018
TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	February 20, 2018
TP_ESTIMATE_MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	February 20, 2018
INSD GIA_SKN7441K.PDF	Reports & Statement	GIA Report	LOH Cynthia	February 1, 2018
SLF1462U GIA.PDF	Forms / Claim Documents	Claim Form	PATIL Anmol	January 23, 2018
SKN1339M TP GIA.PDF	Forms / Claim Documents	Claim Form	PATIL Anmol	January 23, 2018
SKN7441K INSD GIA.PDF	Forms / Claim Documents	Claim Form	PATIL Anmol	January 23, 2018