

ASS. REC. BY: ma REF: CS3/MSG17018250 Amvb-1 Range

CLIENT: ma ASSIGNMENT (Office)

From (Person): Fievel Foo of MSIG Date/Time: 23012018

Estimated Cost: Bill to

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJG 5935 P Insured: GBC 109 G

at Workshop n/s: Target Auto Tel: 8228 8881

of 14 Sin Ming Ind Est Sect B #01-05, 575658

Policy No: B28671718 MKF Claim No: 530129

Sum Insured: Excess:

Make of Veh: D.O.A. 20/9/2017

(Client's Record): CA / REV / REP. / REV 24 HRS 'wp' 25.09.2017 @ after 10am 160 Sin Ming #07-10

Date/Time: 22/9/17 1017am Person Contacted: Ana H.O.D. Endorsement: Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>Do Not Finalize</u>
	<u>SJG 5935 P - CCB / A1909021911 / Ubr I - D.O.A. 27/9/2009</u>
	<u>GBC 109 G - X</u>
	<u>After repair: 27092017</u>

24.10.17 355pm Email to Fievel Foo thru interim

08/02/18 - To submit L/S 3350/- with 4 days of rep (Real 3650, 4490)

- hit by lorry. Damage to TP would not be so low, pass the parallel dend in height.
- PRB photos seen

[Signature]

RECEIVED 08 FEB 2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG17018250/M1vb-1		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 24-01-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 109G	Veh. Inspected	SJG 5935P	
Policy No.	B28671718MKF	Coverage (\$)	0.00	
Claim No.	530129	Excess (\$)	0.00	
Assign From	MERIMEN (FIEVEL FOO)	Assign Date	23/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/09/2017	Inspection Date	24/01/2018	
Survey held at	TARGET AUTO PTE LTD 160 SIN MING DRIVE #07-17 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Sep 2017		22 Sep 2017 10:10 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GARDENIA FOODS (S) PTE LTD, Co. Reg. No.: 197801714R, Tel: +6581806455		
Main Claimant:	CHUA ENG TIAM, ID: S0033386G		
Vehicle Reg. No.:	SJG5935P	Date of Loss:	20/09/2017 07:00 - :59
Claim Type:	TP / 530129	Policy/Cover Note No.:	B28671718MKF (Comprehensive) Coverage: 01/01/2017 - 31/12/2017
Vehicle Reg. No. (Insured):	GBC109G	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Target Auto Pte Ltd (HQ) 14 Sin Ming Industrial Estate Sector B, #01-05, 575658 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 25/01/2018]		
Driver/Custodian (Insured):	LEE YIK HOW (30 / Male), NRIC: G8012424X, Tel: +6581806455		
Adj Asg. Remarks:	Please contact MS ANA @ 8228 8881 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (23/01/2018): Report Send Back Alerts - SJG5935P (TP)



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/09/2017 13:36
Date Of Accident	20/09/2017 07:00
Exact Location Of Accident	AT BLK 134 LORONG AH SOO CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG5935P
Insured/Policyholder	
Name Of Registered Owner	CHUA ENG TIAM
NRIC No	S0033386G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92301505
Alternative Phone No	OFFICE-92301505

Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MW005570-R02
Cover Note Number	

Driver

Name of Driver	CHUA ENG TIAM
NRIC No	S0033386G
Date Of Birth	15/05/1950
Occupation	INDOOR
Date Of Driving Pass	30/09/1970
Driving Experience	46 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92301505
Fax Number	
Contact Number	OFFICE-92301505
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLIDED INTO PARKED VEHICLE

Weather Conditions AFTER RAIN

Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

refer attached report.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC109G

Vehicle Make/Model/Colour VAN

Details Of Properties

Name of Driver LEE YIK HOW

NRIC/Passport Number G8012424X

Contact Number 81806455

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time:

Driver's Signature (If driver is not the policyholder) / Date & Time:

Witnessed by Reporting Centre Personnel

Sketch Plan

A - 3JG 5935P
B - GBC 1096




Describe Circumstances of the Accident

On 20/9/2017 at 7.00 AM, I was travelling along
 BIK 134 Lorong th Soo car park. Suddenly a van
 GBC 1096 reverse out of the parking lot and hit on to
 my vehicle SJ65935P

TP claim


Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
 Time

Driver's Signature (If driver is not the policyholder) / Date
 & Time



Witnessed by Reporting Centre
 Personnel

AUTO PERFORMANCE APPRAISAL

APA

TAX INVOICE

Chua Eng Tiam
C/O Target Auto Pte Ltd
160 Sin Ming Drive
Sin Ming AutoCity #07-17
Singapore 575722

INVOICE NO : APA17001378

DATE : 05/10/2017

VEHICLE NO : SJG5935P
JOB REFERENCE NO : 17/001473
ACCIDENT DATE : 20/09/2017
SURVEY DATE : 25/09/2017

<u>DESCRIPTION</u>	<u>AMOUNT</u>
Survey Fees Inclusive Of Transportation	\$440.00
Photographs (\$1) Per Copies : 28	\$28.00

TOTAL AMOUNT : \$468.00

Notes :

All cheque payment should be "Crossed" and made payable to "Auto Performance Appraisal"

Auto Performance Appraisal



AUTO PERFORMANCE APPRAISAL

APA

VEHICLE SURVEY REPORTS																																
<p>Chua Eng Tiam C/O Target Auto Pte Ltd 160 Sin Ming Drive Sin Ming AutoCity #07-17 Singapore 575722</p>																																
1	Reference Job Reference No : 17/001473 Claim No : - Claim Type : Third Party Accident Date : 20/09/2017 Survey Date : 25/09/2017 Survey Report Date : 05/10/2017																															
2	Particulars Of Vehicle Vehicle Registration No : SJG5935P Make & Model : Toyota Estima Aeras 2.4 A Vehicle Registration Date : 09/07/2008 Chassis No : ACR507060851 Engine No : Blocked Colour : Grey																															
3	Condition Of Vehicle And Tyres <table border="1"><thead><tr><th><u>Mileage (KM)</u></th><th><u>Brakes</u></th><th><u>Steering</u></th><th><u>Modification</u></th></tr></thead><tbody><tr><td>239119</td><td>Serviceable</td><td>Serviceable</td><td>None</td></tr><tr><td colspan="4"><u>Tyres</u> <u>Make</u> <u>Size</u> <u>Balance (MM)</u></td></tr><tr><td>Front RHS</td><td>Falken</td><td>225/50R17</td><td>5</td></tr><tr><td>Front LHS</td><td>Falken</td><td>225/50R17</td><td>5</td></tr><tr><td>Rear RHS</td><td>Falken</td><td>225/50R17</td><td>6</td></tr><tr><td>Rear LHS</td><td>Falken</td><td>225/50R17</td><td>6</td></tr></tbody></table>				<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>	239119	Serviceable	Serviceable	None	<u>Tyres</u> <u>Make</u> <u>Size</u> <u>Balance (MM)</u>				Front RHS	Falken	225/50R17	5	Front LHS	Falken	225/50R17	5	Rear RHS	Falken	225/50R17	6	Rear LHS	Falken	225/50R17	6
<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>																													
239119	Serviceable	Serviceable	None																													
<u>Tyres</u> <u>Make</u> <u>Size</u> <u>Balance (MM)</u>																																
Front RHS	Falken	225/50R17	5																													
Front LHS	Falken	225/50R17	5																													
Rear RHS	Falken	225/50R17	6																													
Rear LHS	Falken	225/50R17	6																													
4	Description Of Damages The vehicle sustained damages at rear left hand portion. (For information of damages please refer to Parts/Labour/Photographs attached)																															
5	Instruction This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.																															

AUTO PERFORMANCE APPRAISAL

Annex A

Vehicle Assessment Reports

Ref No : 17/001473

Damage And Repair Cost Adjustment

<u>S/No</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Comments/condition</u>	<u>Workshop Estimate (\$)</u>	<u>Our Assessment (\$)</u>
<u>List Items</u>					
1	1	Rear bumper	Deformed/broken	1,124.00	1,124.00 <i>PL</i>
2	1	Rear bumper LH side retainer	Deformed	120.30	120.30 <i>SVC</i>
3	1 set	Rear bumper clips	Necessary	40.00	40.00 <i>SVC</i>
4	1	Rear LH fender	Buckled	1,610.00	1,610.00 <i>✓</i>
5	1	Rear LH fender lower protector	Cut/necessary	184.00	184.00 <i>SVC</i>
6	1	Rear LH fender glass moulding	Necessary	402.90	402.90 <i>✓</i>
7	1	LH sliding door	Buckled	1,569.30	1,569.30 <i>✓</i>
8	1	LH sliding door lower protector	Cut/necessary	682.80	682.80 <i>SVC</i>
9	1	LH sliding door front rubber	Necessary	88.90	88.90 <i>SVC</i>
10	1	LH sliding door bottom rubber	Necessary	74.25	74.25 <i>SVC</i>
11	1	LH sliding door inner trim board	Reuse	743.90	-
12	1 set	LH sliding door inner trim board clips	Necessary	50.00	50.00 <i>SVC</i>
				6,690.35	5,946.45
Less discount 25% <i>3582.20</i>				1,672.59	1,486.61
Total :				5,017.76	4,459.84
<u>Special Nett Items</u>					
13	1	Rear LH fender glass sealant	Necessary	40.00	40.00 <i>✓</i>
14	1 set	LH sliding door protector (C/w 1 set)	Deformed	200.00	200.00 <i>SVC</i>
15	1	Rear LH sports rims	Cut/warped	550.00	550.00 <i>NH</i>
16	1	Rear LH tyre <i>401-</i>	Reuse	260.00	-
Total :				1,050.00	790.00
Total Spare Parts :				6,067.76	5,249.84

AUTO PERFORMANCE APPRAISAL

Annex B

Vehicle Assessment Reports

Ref No : 17/001473

Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>
1	To remove, cut out damaged parts, jack out, align, panel beating, welding, renew replaced parts.	1,200.00	800.00 600/-
2	To putty and respray painting on affected areas.	1,300.00	1,000.00 600/-
3	To remove, refix rear LH fender glass.	140.00	100.00 80/-
4	To rewire and check wirings.	40.00	20.00 ✓
5	To remove, refix LH sliding door fittings to facilitate repair.	120.00	80.00 ✓
6	To remove, refix roof linings, rear seats, carpet and trims.	200.00	150.00 80/-
7	To conduct computerise wheel alignment test.	80.00	60.00 NH
8	To supplied and applied anti rust treatments.	100.00	60.00 40/-

Total Labour : 3,180.00 2,270.00

Total Spare Parts : 6,067.76 5,249.84

Total Labour : 3,180.00 2,270.00

Total Repair Costs : 9,247.76 7,519.84

4226.65
4153350/-

Assessor's Recommendation

Repairer Estimate : 9,247.76
Our Adjustment : 7,519.84

4 days

Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$6,000.00, with a repair period of 7 working days.

Surveyed By:



Lek Boon Hwee
Automobile Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Sep 2017		22 Sep 2017 10:10 Edit Adj Rpt	S\$3,350.00 Edit Estimates	S\$3,350.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GARDENIA FOODS (S) PTE LTD, Co. Reg. No.: 197801714R, Tel: +6581806455		
Main Claimant:	CHUA ENG TIAM, ID: S0033386G		
Vehicle Reg. No.:	SJG5935P	Date of Loss:	20/09/2017 07:00 - :59
Claim Type:	TP / 530129	Policy/Cover Note No.:	B28671718MKF (Comprehensive) Coverage: 01/01/2017 - 31/12/2017
Vehicle Reg. No. (Insured):	GBC109G	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Target Auto Pte Ltd (HQ) 14 Sin Ming Industrial Estate Sector B, #01-05, 575658 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 25/01/2018]		
Driver/Custodian (Insured):	LEE YIK HOW (30 / Male), NRIC: G8012424X, Tel: +6581806455		
Adj Asg. Remarks:	Please contact MS ANA @ 8228 8881 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (23/01/2018): Report Send Back Alerts - SJG5935P (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


Claim Documents

***SJG5935P (530129)**
[GBC109G]
TP
CHUA ENG TIAM
Sep 20 2017 7:00AM
[GARDENIA FOODS (S) PTE LTD]
Target Auto Pte Ltd






























Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/09/17 10:02	Accident Statement From:SC - Reg. No: GBC109G, Claimant: GARDENIA FOODS (S) PTE LTD	 Load HTM	

Photos/Images

			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
15	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
16	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
17	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
18	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
19	25/09/17 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/10/17 15:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
21	24/10/17 15:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
22	24/10/17 15:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
23	24/10/17 15:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
24	24/10/17 15:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
25	24/10/17 15:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
26	24/10/17 15:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
27	24/10/17 15:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
28	24/10/17 15:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
29	24/10/17 15:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
30	24/10/17 15:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

31	24/10/17 15:34	Photo After Spray	1	Load JPG	✓
32	24/10/17 15:34	Photo After Spray	1	Load JPG	✓
Documentation				1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/09/17 10:03	TPD SJG5935P E-FILE, DL & IC	1	Load PDF	
2	22/09/17 10:09	TPD SJG5935P - PRI	1	Load PDF	
3	09/11/17 13:25	SURVEY REPORT & PHOTOS	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/02/18 16:40	PRS INVOICE	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17018250/DVBS2-1
Date: 08/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B28671718MKF
Claimant Vehicle No : SJG5935P **Insured Vehicle No :** GBC109G
Date of Loss: 20/09/2017 Nature of Claim: TP Claim No: 530129

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJG5935P**
Make & Model: TOYOTA ESTIMA, 2.4 AERAS (A) Engine No: 2AZF151747
Reg. Date: 09/07/2008 (Man. Year: 2008) Chassis No: ACR507060851
Colour: Silver Odometer: 239119 km
Engine Capacity: 2362 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R17 Rear Tyre Size: 225/50R17
Front Left Side: Falken 7 mm Rear Left Side: Falken 7 mm
Front Right Side: Falken 7 mm Rear Right Side: Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,067.76	2,726.65	3,341.11	55.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,500.00	1,680.00	52.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,247.76	4,226.65	5,021.11	54.30
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	9,247.76	3,350.00	5,897.76	63.78
+ GST 7.00/7.00% (S\$)	647.34	234.50	412.84	63.77
Nett Amount (S\$)	9,895.10	3,584.50	6,310.60	63.77

INSPECTION

Date of Assignment: 22/09/2017
Date Inspected: 25/09/2017 Inspected At: Target Auto Pte Ltd (HQ)
14 Sin Ming Industrial Estate Sector B, #01-05
Singapore 575658
Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_print&caseid=640242&extid=251499&CFID=28225775&C... 1/4

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2018)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG5935P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,124.00 FL	*- FL
2	1		*REAR BUMPER LH SIDE RETAINER	Serviceable	120.30 FL	*- FL
3	1		*SET REAR BUMPER CLIPS	Serviceable	40.00 FL	*- FL
4	1		*REAR LH FENDER	Buckled	1,610.00 FL	*1,610.00 FL
5	1		*REAR LH FENDER LOWER PROTECTOR	Serviceable	184.00 FL	*- FL
6	1		*REAR LH FENDER GLASS MOULDING	Necessary	402.90 FL	*402.90 FL
7	1		*LH SLIDING DOOR	Buckled	1,569.30 FL	*1,569.30 FL
8	1		*3LH SLIDING DOOR LOWER PROTECTOR	Serviceable	682.80 FL	*- FL
9	1		*LH SLIDING DOOR FRONT RUBBER	Serviceable	88.90 FL	*- FL
10	1		*LH SLIDING DOOR BOTTOM RUBBER	Serviceable	74.25 FL	*- FL
11	1		*LH SLIDING DOOR INNER TRIM BOARD	Reuse	743.90 FL	*- FL
12	1		*SET LH SLIDING DOOR INNER TRIM BOARD CLIPS	Serviceable	50.00 FL	*- FL
13	1		*REAR LH FENDER GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
14	1		*SET LH SLIDING DOOR PROTECTOR	Serviceable	200.00 FS	*- FS
15	1		*REAR LH SPORTS RIMS	Not Necessary	550.00 FS	*- FS
16	1		*REAR LH TYRE	Reuae	260.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,740.35	3,622.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,672.59	895.55
Total Parts (\$\$)	6,067.76	2,726.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CUT OUT DAMAGED PARTS, JACK OUT, ALIGN, PANEL BEATING, WELDING, RENEW REPLACED PARTS.	New	1,200.00	600.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.	New	1,300.00	600.00
3	TO REMOVE, REFIX REAR LH FENDER GLASS.	New	140.00	80.00
4	TO REWIRE AND CHECK WIRINGS.	New	40.00	20.00
5	TO REMOVE, REFIX LH SLIDING DOOR FITTINGS TO FACILITATE REPAIR.	New	120.00	80.00
6	TO REMOVE, REFIX ROOF LININGS, REAR SEATS, CARPET AND TRIMS.	New	200.00	80.00
7	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST.	New	80.00	0.00
8	TO SUPPLIED AND APPLIED ANTI RUST TREATMENTS.	New	100.00	40.00
Gross Labour Cost (\$\$)			3,180.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >